PHIL JELPHIA ELECTRIC COM .NY

2301 MARKET STREET

PHILADELPHIA, PA. 19101

12151 841-4000

January 22, 1979

Mr. Boyce U. Grier, Director
Office of Inspection and Enforcement.
Region I
United States Muclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

bear Mr. Grior:

SUBJECT: Licensee Event Report Marrative Description

. The following occurrence was reported to Mr. Greenman, Region I. Office of Inspection and Enforcement on January 9, 1973.

Reference:

Pocket Numbers 50-277

Report No: Report Date: Occurrence Date: LER 2-79-2/1T January 22, 1979 January 8, 1979

Occurrence Date: Facility:

Peach Bottom Atomic Power Station

R.C. 1, Delta, PA 17314

Technical Specification Reference:

Technical Specification 3.14.8.4 states in part that if the requirements of 3.14.8.1, 2, or 3 cannot be met, establish a continuous fire watch with back-up fire suppression equipment for the unprotected area (MPCI, Caule Spreading, Computer, Diesel Generator) within one hour.

Description of the Event:

The cable spreading room cardox system was disabled on the morning of 1/8/79 so that construction workers could perform cable work in the overhead. A firewatch was posted at that time. Then the cable work was completed for the day at about 4:30 Pd, the working group supervision failed to notify operating personnel that they were finished. The firewatch left the room

RECULTORY DOCKET FILE COPY

790201 0110

A002/1

ra ogen in Grier Against 1971 when the dig's work was completed. In the next which as part of a normal surveillance of the area, operation shirt erroung!

noticed the arror on them placed the cardon at ther in arrive.

Consequences of Event:

The consequences of this event are considered wini al because the fire detection system was fully operable and numerous people were in and out of the area durin; the 5-1/2 hour period in which the firewatch was not present.

Cause of Event:

The cause of this occurrence was a personnel error. Supervision of construction personnel working in the cable spreading room failed to notify shift supervision when the cable work was completed for the day.

Corrective action:

Construction personnel were instructed in the importance of notifying shift supervision anytime that working conditions change in an area so that shift personnel can take appropriate action if required.

Yours brule.

Generation Division-Muclear

Attachment

Director, MRC - Office of Inspection and Enforcement Mr. Morman I. Weller, MRC - Office of Wann tement & Program Analysis