The Honorable Lane Evans July 28, 1992 United States House of Representatives 'Washington, D.C. 20515

Dear Congressman Evans:

In our letter to you of May 25, 1990, we committed to keep you informed on the cracks in the reactor vessel head at the Quad Cities Station, Unit 2, by sending you additional documents as they become available. We have already sent you several relevant documents with our letters of August 6, 1990, and October 22, 1990. Enclosure 1 is a letter from Commonwealth Edison presenting the results of the inspections performed during the last refueling outage and a plan for future inspections. Enclosure 2 is our letter to Commonwealth Edison approving the future inspection plan.

The licensee found no new flaws, no apparent change in the existing flaws, no pitting in cavities when base metal was exposed, and no apparent change in flaws which were associated with cavities. The future inspection plan will adequately monitor reactor vessel head condition. Therefore, we continue to believe that operation of Quad Cities, Unit 2, with the flaws poses no safely concerns. I trust that this additional information satisfies our commitment to you.

> Sincerely, Original Signed By: James M. Taylor James M. Taylor Executive Director for Operations

	U.S. Nuclear	Edison, eonard N. Olshan, Regulatory		RC FRLE CENTE	r sopy
Commission, J <u>DISTRIBUTION</u> : EDO#0005437 J. Sniezek 17G21 T. Murley/F. Miraglia B. Boger J. Scinto, OGC T. Gibbons S. Wiens PDIII-2 Green File R. Hermann W. Russell *See previous concurrent		Docket File (50-265) EDO Reading File (5437) J. Blaha 17G21 J. Partlow J. Zwolinski CCA NRR Mail Room (EDO#0005437) 12G18 L. Olshan B. Clayton A. B. Davis, RIII		NRC & Local PDRs J. Taylor 17G21 H. Thompson 17G21 PDIII-2 r/f R. Barrett OCA SECY (00-0486) C. Noore A. Thadani F. Gillespie Bev Clayton	
OFC	LA: ROIII-2	PM: PDIII-2	10:00121/2	TECH EDITOR	ADR3:DRPW
NAME	TEMODRE	C LOLSHAN: jar	REARREPT	JMAIN*	JZWOLINSKI
DATE	11/1/92	- / (7 /92	17/92	09/92	7/16/92
OFC	DRPW	ADT : NRR	ADP:NRR	D:MAB	IED& OC
NAME	IBBOGER	WRUSSEAL	JPARTLOW	TMUGLEY	JJTAYLOR
DATE	7/17/92	7~92	7 10/92	7.12/162	or /n//92
920 PDR P	B030030 920727 ADDCK 050002	65 R	mare		PPOI



Commonwealth Edison 1400 Opus Place Downers Grove, Illinois 60515

May 11, 1992

Dr. Thomas E. Murley, Director Office of Nuclear Reactor Regulation U.S. Nuclear Regulatory Commission Washington, D.C. 20555

ATTN: Document Control Desk

SUBJECT: Quad Cities Station Uni ; 1 and 2 Results of Reactor Head Inspection; Future Reactor Head Examination Plan NRC Docket Nos. 50-254 and 50-265

REFERENCES:

- (a) J.L. Schrage (CECo) to T.E. Murley letter dated September 30, 1991.
- (b) Teleconference between CECo (J.L. Schrage et al) and NRC (L.N. Olshan et al) on March 5, 1992.
- (c) Conference between CECo (J.L. Schrage) and NRC (L.N. Olshan, W. Koo, B. Elliott) on March 19, 1992.

Dear Dr. Murley:

On April 19, 1990 members of the Nuclear Reactor Regulation's (NRR) and Commonwealth Edison Company's (CECo's) staff conducted a technical meeting to discuss the cracks identified in the Quad Cities Unit 2 Reactor Vessel Head. During that meeting, CECo committed to perform inspections of the Reactor Vessel Heads at each of its Boiling Water Reactor (BWR) Plants.

In Reference (a), CECo described the Reactor Head and Upper Shell Inspection Plan for Quad Cities Station Unit 2 for the winter refuel outage (Q2R11). This inspection plan was implemented during the outage. The purpose of this letter is to describe the results of that inspection and provide the Quad Cities Unit 2 Reactor Head and Upper Shell Inspection Plan for future refuel outages.

The results of the inspection were discussed with your staff in a teleconference on March 5, 1992 (Reference(b)), and are described in Attachment 1. The inspection resulted in the following conclusions:

- There were no new flaws detected in the cladding and base metal.
- There were no apparent changes in length and depth of the existing flaws.

9205180132-

ENCLOSURE 1

There was no pitting in cavities where base metal was exposed.

- 2 -

 There were no apparent changes in length and depth of flaws which were associated with cavities.

The proposed Reactor Head and Upper Shell Inspection Pian for future Unit 2 refuel outages was also presented to your staff during the March 5, 1992 teleconference (Reference (b)). The staff raised questions during that teleconference regarding the proposed UT sizing of existing cracks. CECo revised the proposed inspection plan to address these questions, and presented this revision to your staff during a conference on March 19, 1992 (Reference(c)) The revised plan required UT sizing of three surface penetrating cracks and three embedded cracks, including the deepest crack. During the March 19, 1992 conference, the staff indicated that the revised inspection plan adequately addressed the questions which were raised during the March 5, 1992 teleronference. Therefore, the final Reactor Head and Upper Shell Inspection Plan for future Quad Cities Unit 2 refuel outages is submitted for your staff's review (Attachment 2).

If there are any questions or comments on either the results of the recent inspection, or the Reactor Head and Upper Shell Inspection Plan for future Unit 2 outages, please contact John L. Schrage at 708-515-7283.

John L: Schrage

Nuclear Licensing Administrator

Attachment

cc:

- A. Bert Davis, Regional Administrator RIII
- L. N. Olshan, Project Manager NRR
- T. E. Taylor, Senior Resident Inspector Quad Cities
- B. J. Elliot, NRR Technical Staff

## ATTACHMENT 1

## QUAD CITIES UNIT-2 RPV HEAD EXAMINATION RESULTS (Q2R11)

 VT-3 100% OF RPV HEAD ID, OUTSIDE THE 12" WIDE BAND CENTERED ON THE RPV HEAD-TO-FLANGE WELD.

Result: A Section from 100° to 125° on the ID of the RPV Head Dollar weld had heavier rust appearance.

2. VT-1 OF ALL EXCAVATED CAVITIES (WHERE BASE METAL EXPOSED).

Result: No pitting, insignificant rust spots in base metal.

3. PT

a. SECTION FROM 100° to 125° OF RPV HEAD DOLLAR WELD ID,

Result: No relevant indications.

b. 12" WIDE BAND CENTERED ON ID OF RPV HEAD-TO-FLANGE, INCLUDING EXCAVATED LOCATIONS WITHIN THE BAND AND AT 60" & 25" ABOVE FLANGE SURFACE.

<u>Result</u>: No apparent increases in number of flaws or in length of existing flaws.

4. UT FROM OD OF RPV HEAD-TO-FLANGE USING ENHANCED TECHNIQUE.

<u>Result</u>: UT detected 20 crack-like indications that resulted in approximately 197" total flaw length or 25% of weld length using OD measurements. In 1990, similar UT detected 21 crack-like indications that resulted in proximately 255" total flaw length or 32% of weld length. Changes in the evaluation of clad roll and crack signals account for the majority of the difference in total flaw length.

5. UT SIZING FROM ID (14 FLAWS AT 18 LOCATIONS).

<u>Result</u>: Maximum flaw depth is <u>0.24</u>" into base metal. Maximum flaw depth in 1990 was 0.22" into base metal.

6. CONCLUSION:

- a. No new flaws detected in cladding and base metal.
- b. No apparent changes in length and depth observed on existing/old flaws.
- c. No pitting observed in cavities where base metal is exposed. No apparent changes in length and depth of flaws that are associated with cavities.

## ATTACHMENT 2

## QUAD CITIES UNIT-2 FUTURE RPV HEAD EXAMINATION PLAN

The following examination plan will be implemented in lieu of the successive examination requirements of ASME Section XI IWB-2420 (b) on the Quad Cities Unit 2 RPV head every other scheduled refueling outage, beginning with Q2R13 which is currently scheduled for September 1994:

- Visually examine (VT-3) 100% the inside surface of the Reactor Pressure Vessel (RPV) Head. Conditions to be examined for and recorded:
  - a. New cracks and linear indications.
  - b. Existing cracks that show a definite increase in length.
  - c. Heavy/unusual rust streaks.

10.1

1

- Visually examine (VT-1) all excavates chvities, where base metal is exposed, for pitting and cracking of the low alloy steel material.
- If necessary, liquid dye penetrant tesi (PT) may supplement the visual examinations of activities 1 and/or 2.
- Ultrasonically test (UT), from the ID and/or OD as allowed by surface condition to determine flaw depth, the following:
  - a. All cracks found by activities 1 and 2.
  - b. Six locations (stamped with low stress markers) with existing cracks which are in the 12 inch wide band centered (nominally) on the ID of the RPV head-to-flange weld. At least three of the six locations to be monitored are associated with ID surface penetrating cracks as determined by PT.
- 5. The flaw characteristics found by activity 4.b. will be compared to the 1992 as-left flaw characteristics to determine crack growth. Modification to this examination plan may be necessary if significant crack initiation or significant crack growth is observed during future RPV head examination.



UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D.C. 20055

June 23, 1992

Docket No. 50-265

Mr. Thomas J. Kovach N.clear Licensing Manager Commonwealth Edison Company-Suite 300 OPUS West III 1400 OPUS Flace Downers Grove, Illinois 60515

Dear Mr. Kovach:

SUBJECT: PLAN FOR FUTURE EXAMINATIONS OF THE QUAD CITIES, UNIT 2, REACTOR HEAD (TAC NO. M76437)

During the Quad Cities, Unit 2, refueling outage of Spring 1990 (Q2R10), flaws were found on the region head. As a result, you committed to perform inspections of the reactor head during the following refueling outage (Q2R11). By letter dated May 11, 1992, you presented the results of these inspections and a plan for future inspections. The inspections found no new flaws, no apparent change in the existing flaws, no pitting in cavities where base metal was exposed, and no apparent change in flaws which were associated with cavities.

Your proposed future inspection plan, which incorporates our suggestions from a March 19, 1992 conference call, includes ultrasonic (UR) sizing of three surface penetrating cracks and three embedded cracks, including the deepest crack.

We have reviewed your proposed future inspection plan for the Quad Cities, Unit 2, reactor head and find it acceptable. This completes activities associated with TAC No. M76437.

Sincerely.

Lean a.

Leonard N. Olshan, Project Manager Project Directorate III-2 Division of Reactor Projects III/IV/V Office of Nuclear Reactor Regulation

cc: See next page

Mr. Thomas J. Kovach Commonwealth Edison Company

cc:

Mr. Stephen E. Shelton Vice President Iowa-Illinois Gas and Electric Company P. O. Box 4350 Davenport, Iowa 52808

Michael I. Miller, Esq. Sidley and Austin One First National Plaza Chicago, Illinois 60690

Mr. Richard Bax ftation Manager Quad Cities Nuclear Power Station 22710 206th Avenue North Cordova, 111inois 61242

Resident Inspector U. S. Nuclear Regulatory C. mission 22712 206th Avenue North Cordova, Illinois 61242

Chairman Rock Jsland County Board of Supervisors 1504 3rd Avenue Rock Island County Office Bldg. Rock Island, Illinois 61201

Illinois Department of Nuclear Safety Office of Nuclear Facility Safety 1035 Outer Par' Drive Springfield, 1.linois 62704

Regional Administrator, Region III U. S. Nuclear Regulatory Commission 799 Roosevelt Road, Bldg. #4 Glen Ellyn, Illinois 60137

Robert Neumann Office of Public Counsel State of Illinois Center 100 W. Randolph Suite 11-300 Chicago, Illinois 60601 Quad Cities Nuclear Power Station Unit Nos. 1 and 2