

ENCLOSURE 1

BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2  
NRC DOCKET NO. 50-324  
OPERATING LICENSE NO. DPR-62  
NUREG-0619 FEEDWATER NOZZLE AND SPARGER EXAMINATION RESULTS

FEEDWATER SPARGER  
CIRCUMFERENTIAL CRACKING EVALUATION  
FOR BRUNSWICK UNITS 1 AND 2  
General Electric Report GE NE-523-112-1191  
November 1991

(Corrected Copy)

GE-NE-523-112-1191

DRF 137-0010

November 1991

FEEDWATER SPARGER  
CIRCUMFERENTIAL CRACKING  
EVALUATION FOR  
BRUNSWICK UNITS 1 AND 2

Prepared by: T. A. Caine  
TA Caine, Senior Engineer  
Materials Monitoring &  
Structural Analysis Services

Verified by: HS Mehta  
HS Mehta, Principal Engineer  
Materials Monitoring &  
Structural Analysis Services

Reviewed by: S. Ranganath  
S Ranganath, Manager  
Materials Monitoring &  
Structural Analysis Services



GE NUCLEAR ENERGY

IMPORTANT NOTICE REGARDING  
CONTENTS OF THIS REPORT

Please Read Carefully

The only undertaking of the General Electric Company (GE) respecting information in this document are contained in the purchase order between Carolina Power & Light and GE, and nothing contained in this document shall be construed as changing the purchase order. The use of this information by anyone other than Carolina Power & Light, or for any purpose other than that for which it is intended under such purchase order is not authorized; and with respect to any unauthorized use, GE makes no representation or warranty, and assumes no liability as to the completeness, accuracy, or usefulness of the information contained in this document, or that its use may not infringe privately owned rights.

## TABLE OF CONTENTS

	<u>Page</u>
1.0 EXECUTIVE SUMMARY	1-1
2.0 BACKGROUND	2-1
3.0 FEEDWATER SPARGER ANALYSIS	3-1
3.1 Critical Flaw Size	3-1
3.2 Crack Growth Analysis	3-2
3.3 Allowable Flaw Size	3-3
3.4 Loose Parts Considerations	3-4
4.0 FEEDWATER NOZZLE CRACKING IMPACT	4-1
4.1 Methods	4-1
4.2 Assumptions	4-2
4.3 Results	4-3
5.0 CONCLUSIONS	5-1
5.1 Unit 2 Inspections Results	5-1
5.2 Operation Justified	5-1
6.0 REFERENCES	6-1

## APPENDICES

A FEEDWATER NOZZLE BLEND RADIUS AND SPARGER INSPECTION	A-1
--	-----

## 1.0 EXECUTIVE SUMMARY

Carolina Power & Light (CP&L) requested that analysis be done to address circumferential cracking along welds at the feedwater sparger arm-to-tee connections, to identify allowable conditions for operation one additional cycle. The analysis involved determination of the maximum allowable flaw size, consideration of loose parts issues and estimation of maximum nozzle cracking for a hypothetical sparger crack leak directly onto the nozzle.

A preliminary analysis was performed prior to sparger inspection [1]. The sparger inspections for Unit 2 were subsequently performed [2]. The results of the evaluation and inspections are summarized below:

- The critical flaw size for the circumferential tee weld cracking is 14.1 inches on the outside surface.
- The crack growth in one cycle could be as large as 3.16 inches, due to IGSCC, so the allowable flaw size for the inspection is 10.9 inches.
- Complete separation of the sparger arm at the tee weld would not overstress the vessel bracket connection, and such a separation would be detected by the operator, so there is no loose parts concern for this particular cracking in the spargers.
- Analysis of the hypothetical case of sparger leakage on the nozzle blend radius indicates that a crack would grow no deeper than 0.85 inches due to the leakage thermal cycling. Including system fatigue crack growth for one cycle of 0.05 inches, a crack no deeper than 0.9 inches could be developed in one cycle of operation.
- The Unit 2 inspection showed the longest circumferential crack to be about 2 inches long. Comparison of inspection results from this outage and the previous outage for one of the cracks indicates that no significant crack growth occurred during the last cycle.

## 2.0 BACKGROUND

The feedwater (FW) spargers in Units 1 and 2 at the Brunswick plants have the originally designed flow holes in the side of the sparger arm pipes, which have demonstrated rapid thermal cycle cracking after a few cycles of operation. As a result, and in compliance with NUREG-0619, CP&L has regularly performed penetrant test (PT) inspections of the flow holes, and has found and monitored flow hole cracking. In the process of performing PT inspections during the last outage, indications were also found along the circumferential welds which connect the sparger arms to the tee. While these indications were not measured for length, some pictures show circumferential indications at least 2 inches long on the visible side of the sparger (see Figure 2-1). Therefore, CP&L requested an evaluation of the structural integrity of the spargers for the next cycle of operation. The evaluation specifically addresses the circumferential cracking along the welds between the sparger arms and tee, and applies to both Units.

The evaluation consists of several aspects, as described below:


- The critical flaw size for failure of the sparger is determined.
- Maximum expected crack growth is predicted, based on consideration of intergranular stress corrosion cracking (IGSCC) and fatigue.
- The likelihood of complete failure of a sparger tee weld resulting in loose parts is addressed.
- For the worst case scenario where feedwater leaks through the circumferential crack directly onto the blend radius of the feedwater nozzle, the maximum possible nozzle crack depth is predicted.

Inspection results for Unit 2 are presented and conclusions concerning continued operation are made.



GE NUCLEAR ENERGY

BRUNSWICK STEAM ELECTRIC PLANT  
EIGHTH REFUELING OUTAGE, OCTOBER 1989  
INVESSEL LIQUID PENETRANT PHOTOGRAPH



135° HOLE # 17, & 18




Figure 2-1. Results of 1989 Sparger PT Inspection

### 3.0 FEEDWATER SPARGER ANALYSIS

The analysis process used to determine allowable flaw size for one cycle of operation is as follows. The critical crack size, the crack size at which sparger failure can realistically be expected, is calculated, along with the associated stress intensity factors,  $K$ . These  $K$  values are used with crack growth correlations for fatigue and stress corrosion cracking (SCC) to determine the amount of crack growth possible during one cycle. Subtracting the crack growth from the critical crack size gives the allowable crack size that can be detected during the outage. The details of each step in this process are described below.

#### 3.1 CRITICAL FLAW SIZE

The critical flaw size was determined using methods similar to those presented in ASME Cod. Section XI Non-Mandatory Appendix C, "Evaluation of Flaws in Austenitic Piping." The methods use a net section collapse approach where the remaining section of a cracked pipe is evaluated for failure due to the primary membrane and bending loads. For the FW spargers, primary loads were considered due to sparger weight, vertical and horizontal seismic loads, loading of impinging downcomer flow and hydraulic loads due to flow turning in the tee.

The following assumptions were made in determining critical flaw size:

- Counteracting hydraulic forces from the flow holes were conservatively neglected.
- Support from the thermal sleeve connection to the safe end, either welded or slip fit, was conservatively assumed to be zero.
- The sparger was conservatively modeled as a straight beam equal to the curved length, with pinned-pinned end conditions.
- The weld toughness correction factor  $Z_1 = 1.449$  for shielded metal arc or submerged arc welds, which amplifies the bending stress, was included in the net section collapse analysis.



The only loading resulting in membrane stress in the sparger is the differential pressure of about 15 psig. The bending stress loads calculated for the feedwater sparger were both vertical and horizontal. The vertical loads were the weight, 500 lbs., the downcomer flow impingement, 225 lbs. and the vertical seismic load, 80 lbs. The horizontal loads were the sparger flow turning load, 535 lbs. and the horizontal seismic load, 600 lbs. All loads act as distributed loads except the flow turning load, which was treated as a point load. The sparger was treated as a pinned-pinned beam, with no center support. The resulting vertical and horizontal bending stresses were combined by SRSS to get the maximum. The results show primary membrane stress of 0.06 ksi and primary bending stress of 2.58 ksi.

The net section collapse method, described in Non-Mandatory Appendix C in ASME Code Section XI, is based on plastic yielding occurring in the remaining ligament of uncracked pipe. Figure 3-1 shows schematically the geometric quantities  $\alpha$ ,  $\beta$ ,  $d$  and  $t$  in the equation below:

$$\beta = [(\pi - \alpha d/t) - \pi P_m / \sigma_f] / 2 \quad (3-1)$$

$$P_b' = 2\sigma_f / \pi (2 \sin \beta - d/t \sin \alpha) \quad (3-2)$$

For the sparger case, assuming a through-wall crack,  $d/t = 1$ . The flow stress,  $\sigma_f$ , is three times the allowable membrane stress intensity,  $S_m = 16.9$  ksi for 304 stainless steel.  $P_m$  is the membrane stress.  $P_b'$  is the bending stress  $P_b$ , modified by a factor  $Z_1$  to account for lower toughness of shielded metal arc and submerged arc welds as follows:

$$P_b' = Z_1 (P_m + P_b) \cdot P_m \quad (3-3)$$

$$\text{where } Z_1 = 1.449$$

Equations 3-1 and 3-2 were solved on a repeated trial basis for the crack half-angle  $\alpha$ . The results show that the critical crack size is a through-wall crack around 244° of the sparger circumference. On the FW sparger, with an outside diameter of 6.625 inches, this means a crack length on the outside surface of 14.1 inches.

### 3.2 CRACK GROWTH ANALYSIS

As shown in Figure 2-1, it is likely that the circumferential weld cracking is initiated from flow hole thermal cycling cracks. Although the initial crack growth in the early stages is due to thermal fatigue, the driving force decreases with crack length, and the crack growth is likely to be less than 0.5 inches. Thus, cracks as long as shown in Figure 2-1 are not expected to be due to the flow hole cycling phenomenon. For the FW spargers, which are as-welded 304 stainless steel, the most likely cause of subsequent crack extension is IGSCC, starting at the crack tip caused by flow hole cycling fatigue. The approach to determining an allowable flaw is to subtract crack growth from the critical flaw size, which in this case results in a rather large allowable flaw size. Since the cracks are assumed to have grown a considerable distance from the flow hole initiation sites, it is appropriate to consider only IGSCC growth.

For IGSCC growth, both the sustained primary and secondary stresses are important. The secondary stresses include thermal bending due to the temperature difference through the sparger wall and weld residual stresses. Based on the thermal stress relationship  $\sigma = E\alpha\Delta T/(1-\nu)$ , with  $\Delta T = 130^\circ\text{F}$ , the thermal bending secondary stress is 22 ksi, tensile on the inside surface. The weld residual stress is expected to be near the yield strength of about 30 ksi, also tensile on the inside surface. Therefore, stresses are assumed to be equal to the yield strength for the analysis of IGSCC growth.

The model used to calculate stress intensity factor,  $K$ , is for a longitudinal crack in a cylindrical shell subjected to bending  $\sigma_b$  through the thickness [3], as shown in Figure 3-2. The  $K$  computed for the surface of the pipe wall where bending and membrane effects add is given by

$$K = (C_m + C_b) \sigma_b \sqrt{\pi a} (1+\nu)/(3+\nu) \quad (3-4)$$

where  $C_m$  and  $C_b$  are membrane and bending factors, between 0 and 1, from [3]. Use of this expression is expected to be conservative for this application, based on comparison of flat plate and cylindrical shell models used to evaluate circumferential vessel flaws. The resulting relationship of  $K$  versus crack length  $2a$  is shown in Figure 3-3.

The IGSCC growth rate relationship used is that provided in Figure 2 of Appendix A of NUREG-0313:

$$da/dt = 3.59 \times 10^{-8} K^{2.161} \text{ inches/hour.}$$

Crack growth is calculated by assuming an initial crack length,  $a$ , computing  $K$  and  $da/dt$ , determining crack growth  $\Delta a$  for a given time interval, and then repeating the process for a new crack length of  $a + \Delta a$ . For the crack lengths of interest, the  $K$  values are fairly constant between 40 and 45 ksi $\sqrt{\text{in}}$ , so time intervals of 50 hours were used. The total time evaluated is 13150 hours, corresponding to 18 months of constant operation.

The results of the IGSCC growth analysis are shown in Figure 3-4. The largest allowable crack which would reach the critical flaw size in one cycle is 10.9 inches. This initial flaw size experiences 3.16 inches of IGSCC, using the methods above. The calculated crack growth rate is a maximum of  $1.3 \times 10^{-4}$  inches/hour. However, this rate is a function of crack length.

#### 3.4 LOOSE PARTS CONSIDERATIONS

The issue of loose parts is a consideration if the sparger weld fails completely, potentially resulting in two sparger pieces suspended from the vessel bracket pins. Analysis of the bracket pin and sparger connection pieces was done to determine if loads were large enough for the cantilever condition to result in failure of the pin connection.

The sparger connection bracket is shown schematically in Figure 3-5. Four locations were evaluated: The one inch bolts connecting the bracket to the sparger, the slotted bracket plates, the welds connecting the slotted bracket plates to the bolted plates, and the bracket pins. Only vertical loads were considered, based on the restraint conditions for the pin and bracket for the assumed condition of the sparger arm being severed from the tee.

The loads applied to the sparger arm cantilever were the weight, impingement flow load and vertical seismic load. The resulting maximum stresses for each location evaluated are below:

One inch bolts:	1807 psi
Slotted bracket plate:	740 psi
Slotted plate welds:	815 psi
Bracket pin:	2624 psi

Maximum stresses are less than 3 ksi. The fatigue endurance limit is about 13 ksi, so fatigue failure of the pin connection hardware is very unlikely.

Complete failure of the sparger weld would disrupt feedwater flow to the extent that several operational abnormalities should be detectable. The flow to that sparger would be changed so that total flow would increase, but almost all the flow would go out of the broken sparger opening, with its lower flow resistance. The change in feedwater distribution would cause changes in the recirculation loop temperatures and local variations in subcooling to the core, which would effect the power distribution. Therefore, changes in feedwater flow, the recirculation loop temperature and core power distribution would all provide indications to the operator which would likely result in plant shutdown. The broken sparger condition would not be prolonged during operation to the point that flow induced vibration could cause complete failure.

Given the low likelihood of IGSCC causing complete severance of the sparger arm from the tee, and the further low likelihood of complete severance of the sparger arm resulting in a loose part, there is no need to evaluate loose parts due to the circumferential cracking which has occurred. Other potential loose parts due to flow hole cracking have been evaluated in other reports.




Figure 3-1. Geometric Model for Net Section Collapse Method




Figure 3-2. K Model for Secondary Bending in a Cracked Pipe




Figure 3-3. K vs. 2a for Cracks in Circumferential Sparger Weld




Figure 3-4. IGSCC Growth Predicted for 18 Month Cycle







Figure 3-5. Schematic of Sparger Arm Bracket Connection

## 4.0 FEEDWATER NOZZLE CRACKING IMPACT

In the unlikely event that the sparger weld cracks opened so that feedwater was flowing directly onto the blend radius of a FW nozzle, rapid cycling could cause crack initiation and crack growth. The nature of the damage to the nozzle is similar to two documented cracking phenomena: FW thermal sleeve leakage rapid cycling and flow hole rapid cycling.

Extensive testing and analysis of the thermal sleeve leakage rapid cycling was conducted in the process of designing the triple thermal sleeve. Among the analyses done was an evaluation of the expected crack growth in the blend radius due to rapid cycling [4]. The results showed that  $\Delta K$  values associated with the rapid thermal cycling drop as a crack proceeds into the nozzle until the crack arrest  $\Delta K$  threshold of 3 ksi- $\sqrt{\text{in}}$  (for high R-ratios) is reached. The depth of the arrested crack is a function of the frequency of the cycling, as shown in Figure 4-1.

Similar analysis was done for the flow hole cycling phenomenon [5]. Again, the  $\Delta K$  values drop as a function of distance from the flow hole, until the crack arrest  $\Delta K$  threshold is reached. In this case, with low R-ratio, the threshold is 5 ksi- $\sqrt{\text{in}}$ .

The frequencies and magnitudes of thermal cycles for the case of sparger leakage onto the nozzle are unknown, so any fatigue crack growth calculation would be based on arbitrary assumptions. Instead, the maximum expected crack depth is determined based on the same  $\Delta K$  attenuation and  $\Delta K$  threshold approach used for the thermal sleeve leakage and flow hole cases.

### 4.1 METHODS

The method used to estimate the crack arrest depth follows the methods used for the blend radius in [4], benchmarked by the actual cracking seen in the sparger flow holes. The flow hole cracks have been found to be as large as 0.5 inches, so the benchmark of the  $\Delta K$  vs. depth calculation is that the curve should pass through 5 ksi- $\sqrt{\text{in}}$  at 0.5 inch depth.

The feedwater nozzle blend radius was modeled, as shown in Figure 4-2, for finite element analysis by ANSYS. The model was subjected to cycles of 130°F step changes between 550°F and 420°F at varying frequencies, and thermal and stress computations were performed. The ANSYS results were used with the  $\Delta K$  relationship from [4]:

$$K_I = 1.12 \sqrt{\pi a} [A_0 + A_1 \cdot 2a/\pi + A_2 \cdot a^2/2 + A_3 \cdot 4a^3/3\pi] \quad (4-1)$$

where  $A_0$  through  $A_3$  are coefficients to the cubic polynomial curve fit of stress versus depth in the nozzle blend radius, obtained from ANSYS.

#### 4.2 ASSUMPTIONS

The following assumptions were made for the purposes of conservatively simplifying the problem of leakage flow from the sparger onto the blend radius:

- Leakage flow from the cracked sparger would have similar thermal cycling characteristics to those of the sparger flow through the flow holes.
- Radial thermal cycling cracks currently shown at the flow holes with a length of 0.5 inches represent the maximum cracking due to steady state flow fluctuations. Further growth of these cracks is due to transient events such as feedwater flow initiation. This is conservative, as these cracks have already been seen over ten years of transient events.
- Magnitudes of temperature fluctuations at the flow holes are greater than fluctuations expected from leakage onto the blend radius.

### 4.3 RESULTS

Stress range and  $\Delta K$  profiles were developed for frequencies of 1/8, 1/4 and 1/3 Hz. The 1/4 Hz case was found to come closest to meeting the benchmark condition of 5 ksi- $\sqrt{\text{in}}$  at 0.5 inches. The stress range profile is shown in Figure 4-3. The stress range profile was fit with a cubic polynomial, and then the coefficients were adjusted slightly until the benchmark conditions were met. The resulting  $\Delta K$  vs. depth plot is shown in Figure 4-4. The curve extends to the high mean stress threshold of 3 ksi- $\sqrt{\text{in}}$  at a depth of 0.85 inches. Therefore, rapid cycling behavior which causes a crack of 0.5 inches at the flow holes is predicted to cause a crack of 0.85 inches in the blend radius.

In addition to the possible crack growth due to rapid cycling, system cycling crack growth could occur. In the most recent NUREG-0619 analysis for Unit 2 [6], which has the greater crack growth rate, the system cycling crack growth for 18 months of operation with a crack 0.85 inches deep is 0.05 inches. Therefore, the maximum expected crack depth for sparger leakage into the nozzle is 0.9 inches. While this is significant, it is less than the flaw depth allowed in NUREG-0619 of 1.0 inch.




Figure 4-1. Schematic of Frequency Dependency on Crack Arrest Length




Figure 4-2. ANSYS Model of Feedwater Nozzle Blend Radius




Figure 4-3. Stress Range Profile for Cyclic Leakage on Nozzle




Figure 4-4. Attenuation of  $\Delta K$  with Depth into Nozzle



## 5.0 CONCLUSIONS

The results of this report are intended to provide justification for operation for one additional cycle given circumferential cracks less than the maximums allowed in this report. The inspections were done for Unit 2 in October, as discussed below. Conclusions can be drawn for Unit 2, based on those inspection results. If the inspection results for Unit 1 are similar to those for Unit 2, the same conclusions apply.

### 5.1 UNIT 2 INSPECTION RESULTS

The Unit 2 feedwater nozzles and spargers were inspected according to the requirements of NUREG-0619. The documented results are included in Appendix A. The blend radius of each feedwater nozzle was liquid penetrant (LP) tested, showing no indications.

The circumferential welds were LP tested and ultrasonically tested (UT). The LP tests show the longest crack to be 2 inches. The UT results show that the crack lengths inside the spargers are no more than the LP indications on the outside surfaces. Comparison of a crack length measured during the last outage and during this outage shows that no significant crack growth has occurred.

### 5.2 OPERATION JUSTIFIED

The analysis in Section 3 provides an allowable through-wall crack length of 10.9 inches, based on 3.16 inches of IGSCC growth in one cycle. The inspection results for Unit 2 show much shorter cracks, about 2 inches, and little if any IGSCC growth. Therefore, operation for the next cycle is justified.

Once crack lengths and IGSCC growth rates are shown to be acceptable by inspection of the Unit 1 spargers, operation for one additional cycle will be justified.

## 6.0 REFERENCES

- [1] Letter No. ADK-91-079, dated October 4, 1991, AD Ketcham of GE to EA Bishop of CP&L, "Feedwater Sparger Circumferential Cracking Evaluation."
- [2] Letter, dated October 20, 1991, JE Gales of CP&L to AD Ketcham of GE, "Unit 2 Feedwater Nozzle Blend Radius and Sparger Inspection."
- [3] Cartwright, D.J. and Rooke, D.P., Compendium of Stress Intensity Factors, Her Majesty's Stationery Office, publisher, London, 1976, pages 320-322.
- [4] Fife et al, "Boiling Water Reactor Feedwater Nozzle/Sparger Interim Program Report," GE Report NEDC-21480, July 1977.
- [5] Riccardella, P.C. and Sharma, S.R., "Feedwater Sparger Hole Thermal Stress Analysis," GE Report RSA-76-04, March 1976.
- [6] Stevens, G.L., "Brunswick Unit 2 Feedwater Nozzle Fracture Mechanics Analysis," GE Report NEDC-30633, Revision 1, May 1991 (proprietary).

APPENDIX A

FEEDWATER NOZZLE BLEND RADIUS  
AND SPARGER INSPECTION

# CP&L

Carolina Power & Light Company

October 20, 1991


TO: A. D. Ketcham  
GE Site Services Manager

FROM: J. E. Gates  
NED Responsible Engineer

SUBJECT: Unit 2 Feedwater Nozzle Blend Radius and Sparger Inspection

On October 12, 1991 CP&L inspected the Unit 2 feedwater nozzle inner blend radius in accordance with Nureg 0619 and also performed an LP examination of the feedwater spargers to document the flow hole cracking and circumferential weld cracking. The results of the inspection are as follows:

1. No relevant indications were found on the nozzle inner blend radius.
2. Crack growth continues on the flow holes but no pieces have separated. Note: The pieces did not separate during the hydrolase cleaning operation using a 20,000 psi plus hydrolaser unit prior to the examination. In addition to the horizontal piece between the flow holes which has been previously addressed by GE, the size of other potential loose pieces is as shown. The largest of which has also been previously addressed by GE.




POTENTIAL FEEDWATER SPARGER LOOSE PART

3. The eight circumferential welds connecting the sparger tee to the arms and the four welds connecting the thermal sleeve to the tee were LP examined. No relevant indications were found on the thermal sleeve attachment welds. Indications were found on the tee to arm circumferential welds. Some of these ran into the welds and some were circumferentially oriented following the heat affected zone. The longest circumferentially oriented indication found by LP examination was 2 inches long. Following the LP examination, five of the eight welds were UT examined for the full circumference to determine the ID length of the OD indications. No indications were found to extend beyond the OD indications. By the direction of the cracks they all seem to have originated from the flow hole cracks and are now following the heat affected zone of the weld. They are all growing downward towards the lower half of the sparger arm. No evidence of any other cracking was found in the joint. The longest crack on the right side of the 135° tee did not show significant growth from the last LP examination.

Please prepare the final report for the feedwater spargers incorporating this information into the report. A copy of the inspection documentation is attached (except for the photographs of the LP indications). If you need additional information please contact me at extension 3600.

Sincerely,

  
James E. Gates, Jr  
NED Engineering

JEG/jeg

cc:

S. L. Bertz  
E. A. Bishop  
J. W. Crider  
P. S. Gore

BRUNSWICK STEAM ELECTRIC PLANT UNIT 2  
NINETH REFUELING OUTAGE - OCTOBER, 1991  
INVESSEL VISUAL INSPECTION (IVVI)  
INSPECTION REPORT AND VIDEO REVIEW

NUREG. 0619 INSPECTION

THIS REPORT SUMMARIZES THE INVESSEL VISUAL INSPECTION AND THE VIDEO TAPE REVIEW THAT WAS PERFORMED DURING THE NINETH REFUELING OUTAGE AT BRUNSWICK UNIT 2. THE INSPECTIONS WERE PERFORMED BY GENERAL ELECTRIC COMPANY PERSONNEL.

THE FOLLOWING IDENTIFIES THE WORKSCOPE THAT WAS PERFORMED AND THE VIDEO TAPE REVIEW:

1. FEEDWATER SPARGER  
FLOW HOLES

THE FEEDWATER SPARGERS WERE VISUALLY INSPECTED (VT-3) PRIOR TO THE LIQUID PENETRANT EXAMINATION FOR GROSS CRACKING. THE VISUAL EXAM RESULTED IN NO ADDITIONAL HOLES TO LP EXAMINE. A TOTAL OF 55 OF 144 HOLES WERE INSPECTED BY THE LIQUID PENETRANT METHOD. THE FLOW HOLES HAVE LINEAR INDICATIONS WITH GROWTH CONTINUOUS. SEE PHOTOS FOLLOWING THIS REPORT.

2. FEEDWATER NOZZLE  
INNER RADIUS

AN LP EXAMINATION WAS ALSO PERFORMED ON THE NOZZLE INNER RADIUS'S @ 45, 135, 225, AND 315 DEGREES RESULTING IN NO RECORDABLE INDICATIONS.

3. FEEDWATER SPARGER  
TEE BOX WELDS

THE 12 FEEDWATER TEE BOX CIRCUMFERENTIAL WELDS WERE FIRST LP EXAMINED TO DETERMINE CRACKING EXTENDING FROM THE FLOW HOLES AND TO DETERMINE THE OD LENGTHS. AFTER A REVIEW OF THE VIDEO, FIVE OF THE EIGHT TEE TO SPARGER ARM CIRC WELDS WERE DETERMINED TO HAVE LINEAR CRACKING. THOSE FIVE CIRC WELDS WERE THEN ULTRASONICALLY INSPECTED TO DETERMINE ID LENGTHS. DUE TO THE CONFIGURATION OF THE FLOW HOLES IN RELATION TO THE CRACKING, ONLY TWO OF THE CIRC WELD CRACKS COULD BE ULTRASONICALLY "SIZED" ON THE ID. SEE THE FOLLOWING UT DATA.