

Arizona Public Service Company

RECEIVED
NRC

1984 NOV -5 AM 9:08
November 1, 1984
ANPP-31031-TDS/TRB

REGION VISE

U. S. Nuclear Regulatory Commission
Region V
Creekside Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. T. W. Bishop, Director
Division of Reactor Safety and Projects

Subject: Interim Report - DER 84-78
A 50.55(e) Potentially Reportable Deficiency Relating To
Valcor Solenoid Valves.
File: 84-019-026; D.4.33.2


Reference: Telephone Conversation between D. Hollenbach and T. Bradish on
October 4, 1984

Dear Sir:

The NRC was notified of a potentially reportable deficiency in the
referenced telephone conversation. At that time, it was estimated that a
determination of reportability would be made within thirty (30) days.

Due to the extensive investigation and evaluation required, an Interim
Report is attached. It is now expected that this information will be
finalized by November 16, 1984, at which time a complete report will be
submitted.

Very truly yours,



E. E. Van Brunt, Jr.
APS Vice President
Nuclear Production
ANPP Project Director

EEVB/TRB/nj
Attachment

cc: See Page Two

8411200039 841101
PDR ADOCK 05000528
S PDR

IE-27

Mr. T. W. Bishop
DER 84-78
Page Two

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
D. B. Karner
W. E. Ide
D. B. Fasnacht
A. C. Rogers
L. A. Souza
D. E. Fowler
T. D. Shriver
C. N. Russo
J. Vorees
J. R. Bynum
J. M. Allen
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
H. D. Foster
D. R. Hawkinson
R. P. Zimmerman
L. Clyde
M. Woods
T. J. Bloom

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, GA 30339

INTERIM REPORT - DER 84-78
POTENTIAL REPORTABLE DEFICIENCY
ARIZONA PUBLIC SERVICE COMPANY (APS)
PVNGS UNIT 1

I. Potential Problem

During startup testing, four Valcor safety-related solenoid valves failed to operate or failed while operating. These valves are the blowdown sample valves 1J-SGA-UV-227, 1J-SGB-UV-228, and the pressurizer sample containment isolation valves 1J-SSA-UV-204, -205. As documented by Nonconformance Report (NCR) No. SE-4933, normal troubleshooting identified inoperative valve coils as the cause of the valve failures.

II. Approach To and Status Of Proposed Resolution

Bechtel Engineering is currently evaluating this deficiency to determine the reportability and technical justification for corrective action.

III. Projected Completion of Corrective Action
and Submittal of the Final Report

The complete evaluation and final report are forecast to be completed by November 16, 1984.