NRC ---- 344

8411200385 841107 PDR ADDCK 05000247 S PDR

1.

..

## U.S. NUCLEAR REQULATORY COMMISSION

## LICENSEE EVENT REPORT (LFR)

and the second se	INDIA	AN POINT	UNIT	2			0	1510101	0121417	1 OF 2
L& (4)	100 .									
EVENT DATE	openants of the owner owne	VOLT BRE	and the second se	INDERVOL'	Contract of Contract on the Owner of Contract of Contr	RELA		DINT SCILITIES INVOLV		
NTH DAY		I MOULATAL			TEAR			• 1	OCKET NUMBER	(\$)
					_				0 15 10 10	1011
0 0 7	8 48 4	$ - _{0 1 4}$	-0 10	1 1 0 78	3 4		•		0 15 0 10	1011
		HOAT IS SUBMITTE	D PUREUANT T		TE OF 10.	11	60.73iai(2)(ie)	the fairewing) (11)	73,71(6)	
MOWER LEVEL	28	40614141110		50.36(eit1)			60.73(e)(2)(r)		72,71(4)	
1101 01	- Van Van Maria			50.36(e)(2)		X	50.73(a)(2)(vii)		DEIDE OTHER ISO	Test, NAC Fe
		408 (a)(1)(iii)	-	60.73(a)(2)(8)		H	\$0.73ta1(2)(vili)(8)			
	and the second	408(a)(1)(r)		90.7 3ta1(2)(III)	1.15	-	50 73/ait2)(at			
				ICENSEE CONTACT	OR THIS	LER (12)			TELEPHONE NUM	45.5
-4								AREA CODE	· ELEPHONE NOR	
М	ICHAEL I	BLATT						91114	1 21 61 5	1 11 217
		COMPLETE	ONE LINE FOR	EACH COMPONENT	FAILURE	-	D IN THIS REPORT	(13)		
AUSE SYSTEM	COMPONENT	MANUFAG TURER	ASPORTABLE TO HEROS		CAUSE	SYSTEM	. COMPONENT	TURER	TO NPROS	
DJIC	WILIY	N 1 1 2 0	M				1 1 1	LILL		
1.		1		12.00	1.11		1.1.1			
		1 1 1 1	1							
		SUPPLEM	ENTAL REPORT	EXPECTED -14		11111			MONT	HI CAY
7.45.111.00				-				EXPECTI SUBMISSI DATE II	CN T	
		BUPPLEN O SUBMISSION OAT	e	- NO				buamissi	CN T	
		O SUSMISSION CAT	e	- NO				buamissi	CN T	
		O SUSMISSION CAT	e	- NO				buamissi	CN T	
	m 1400 water ( K.	O SUBMISSION GAT.	E) a unga ance typ	- NO	ar	efue	ling ma	DATE II		
	While outag	at cold	l shute	down for d that t	he u	nder	voltage	intenan relay	ce	
	While outag setpo	at cold e it was	d shuto s found the 41	down for d that t 80 V bus	he u es w	nder ere	voltage not in	intenan relay complia	ce	
	While outag setpo with	at cold e it was int for the Tech	l shuto the 41 nnical	down for d that t 80 V bus Specifi	he u es w cati	nder ere on.	voltage not in This o	intenan relay complia bservat	ce nce	
	While outag setpo with was m	at cold e at cold e it was int for the Tech ade duri	l shute s found the 41 nnical ing a 1	down for d that t 80 V bus Specifi routine	he u es w cati surv	nder ere on. eill	voltage not in This of ance te	intenan relay complia bservat st. Th	ce nce ion	
	While outag setpo with was m cause	at cold e it was oint for the Tech ade duri of the	l shuto s found the 40 nnical ing a 1 defic	down for d that t 80 V bus Specifi routine iency wa	he u es w cati surv s an	nder ere on. eill err	voltage not in This of ance te or on t	intenan relay complia bservat st. Th he data	ce nce ion e	
	While outag setpo with was m cause sheet	at cold e it was int for the Tech ade duri of the . There	l shuto s found the 4 nnical ing a defic e was n	down for d that t 80 V bus Specifi routine iency wa no safet	he u es w cati surv s an y ha	nder ere on. eill err zard	voltage not in This of ance te or on t as the	intenan relay complia bservat st. Th he data deviat	ce ince ion ie	
	While outag setpo with was m cause sheet	at cold e it was int for the Tech ade duri of the . There o slight	l shuto s found the 4 nnical ing a defic e was n	down for d that t 80 V bus Specifi routine iency wa	he u es w cati surv s an y ha	nder ere on. eill err zard	voltage not in This of ance te or on t as the	intenan relay complia bservat st. Th he data deviat	ce ince ion ie	
	While outag setpo with was m cause sheet was s	at cold e it was int for the Tech ade duri of the . There o slight	l shuto s found the 4 nnical ing a defic e was n	down for d that t 80 V bus Specifi routine iency wa no safet	he u es w cati surv s an y ha	nder ere on. eill err zard	voltage not in This of ance te or on t as the	intenan relay complia bservat st. Th he data deviat	ce ince ion ie	
	While outag setpo with was m cause sheet was s	at cold e it was int for the Tech ade duri of the . There o slight	l shuto s found the 4 nnical ing a defic e was n	down for d that t 80 V bus Specifi routine iency wa no safet	he u es w cati surv s an y ha	nder ere on. eill err zard	voltage not in This of ance te or on t as the	intenan relay complia bservat st. Th he data deviat	ce ince ion ie	
	While outag setpo with was m cause sheet was s	at cold e it was int for the Tech ade duri of the . There o slight	l shuto s found the 4 nnical ing a defic e was n	down for d that t 80 V bus Specifi routine iency wa no safet	he u es w cati surv s an y ha	nder ere on. eill err zard	voltage not in This of ance te or on t as the	intenan relay complia bservat st. Th he data deviat	ce ince ion ie	
	While outag setpo with was m cause sheet was s	at cold e it was int for the Tech ade duri of the . There o slight	l shuto s found the 4 nnical ing a defic e was n	down for d that t 80 V bus Specifi routine iency wa no safet	he u es w cati surv s an y ha	nder ere on. eill err zard	voltage not in This of ance te or on t as the	intenan relay complia bservat st. Th he data deviat	ce ince ion ie	
	While outag setpo with was m cause sheet was s	at cold e it was int for the Tech ade duri of the . There o slight	l shuto s found the 4 nnical ing a defic e was n	down for d that t 80 V bus Specifi routine iency wa no safet	he u es w cati surv s an y ha	nder ere on. eill err zard	voltage not in This of ance te or on t as the	intenan relay complia bservat st. Th he data deviat	ce ince ion ie	
	While outag setpo with was m cause sheet was s	at cold e it was int for the Tech ade duri of the . There o slight	l shuto s found the 4 nnical ing a defic e was n	down for d that t 80 V bus Specifi routine iency wa no safet	he u es w cati surv s an y ha	nder ere on. eill err zard	voltage not in This of ance te or on t as the	intenan relay complia bservat st. Th he data deviat	ce ince ion ie	
	While outag setpo with was m cause sheet was s	at cold e it was int for the Tech ade duri of the . There o slight	l shuto s found the 4 nnical ing a defic e was n	down for d that t 80 V bus Specifi routine iency wa no safet	he u es w cati surv s an y ha	nder ere on. eill err zard	voltage not in This of ance te or on t as the	intenan relay complia bservat st. Th he data deviat	ce ince ion ie	
	While outag setpo with was m cause sheet was s	at cold e it was int for the Tech ade duri of the . There o slight	l shuto s found the 4 nnical ing a defic e was n	down for d that t 80 V bus Specifi routine iency wa no safet	he u es w cati surv s an y ha	nder ere on. eill err zard	voltage not in This of ance te or on t as the	intenan relay complia bservat st. Th he data deviat	ce ince ion ie	
	While outag setpo with was m cause sheet was s	at cold e it was int for the Tech ade duri of the . There o slight	l shuto s found the 4 nnical ing a defic e was n	down for d that t 80 V bus Specifi routine iency wa no safet	he u es w cati surv s an y ha	nder ere on. eill err zard	voltage not in This of ance te or on t as the	intenan relay complia bservat st. Th he data deviat	ce nce ion ie ion re	
	While outag setpo with was m cause sheet was s	at cold e it was int for the Tech ade duri of the . There o slight	l shuto s found the 4 nnical ing a defic e was n	down for d that t 80 V bus Specifi routine iency wa no safet	he u es w cati surv s an y ha	nder ere on. eill err zard	voltage not in This of ance te or on t as the	intenan relay complia bservat st. Th he data deviat	ce nce ion ie ion re	

NRC Farm Juda 13431	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION					US NUCLEAR ALGULATONY COMMISSION APPROVED ONE NO. 3150-0104 EXPIRES 8/31/85				
FACILITY NAME (1)		OCCKET NUMBER (2)	LER NUMBER			:61			PAGE 131	
									_	
		0 15 10 10 10 1 1 1	1	_	1.1	1_	, ]	÷.,	OF	

During the conduct of a routine surveillance test of the voltage setpoint of the 480 volt breaker undervoltage relays it was determined that setpoints (Buses 2A, 3A, 5A and 6A) were at a value lower than permitted by the Technical Specifications. The minimum per Technical Specification is 398 volts. The "as found" values for Buses 2A, 3A, 5A and 6A were as follows:

Bus	Relay Location 27-S1	Relay Location 27-S2
2A	396	392
3A	396	395.2
5A	396	396
6A	388	396

The cause of the above deficiency is a test procedure which correctly quotes the Technical Specification limit in the text of the procedure but contains an erroneously specified value on the data sheet. The "as found" values were all consistent with the erroneous value in the data sheet at the time of the last surveillance test and were never revised to the correct Technical Specification value. The incorrect data sheet has since been revised.

The discovery of the incorrect setpoints occurred while the plant was in a cold shutdown for a refueling maintenance outage. Therefore, there was no impact on safety. However, even if a low voltage condition existed while at power there would have been negligible safety consequences. Of the eight relays involved, two deviated from the Technical Specification limit by 2% while the remaining 6 were within 1% of the required setting. Plant operation under these circumstances would have had no impact on safety-related equipment.

A-2

John D. O'Toole Vice President

+ .

Consolidated Edison Company of New York, Inc. 4 Irving Place, New York, NY 10003 Telephone (212) 460-2533

November 7, 1984

Re:

Indian Point Unit No. 2 Docket No. 50-247 LER-84-014-00

Document Control Desk U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Dear Sirs:

The attached Licensee Event Report LER-84-014-00 is hereby submitted in accordance with the requirements of 10 CFR Part 50.73.

Very truly yours,

Richard P. Remshaw For D. O'Toole

attach.

CC:

4

Dr. Thomas E. Murley, Regional Administrator-Region I U. S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, Pa. 19406

Senior Resident Inspector U. S. Nuclear Regulatory Commission P. O. Box 38 Buchanan, New York 10511