SUSQUEHANNA STEAM ELECTRIC STATION PO BOX 467, BERWICK, PA 18603

November 5, 1984

Dr. Thomas E. Murley Regional Administrator, Region I U.S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION

SPECIAL REPORT - "C" DIESEL POWER FLUCTUATIONS
ER 100450 FILE 841-23

PLAS-005

Docket No. 50-387 License No. NPF-14

Dear Dr. Murley:

All Diesel Generator Unit failures, valid or invalid, are to be reported as required by Regulatory Guide 1.108, Section C.3.b, and Technical Specification 4.8.1.1.3.

At 1023 on October 6, 1984, one-half hour into a one hour loaded run, performed in accordance with Surveillance S0-024-001, the "C" Diesel tripped and alarms indicated over excitation. Upon restart the diesel was again loaded. During the run the output varied from 2 to 5.5 MW. Although the output was fluctuating, the one hour loaded run was completed. The electronic governor was determined to be the problem for the power fluctuating. The governor was replaced by Work Authorization (WA) #S48198. At 1813, the diesel was started and successfully loaded for one hour.

The governor has been sent to Woodward Governor Co. for evaluation. Until a report is received, a determination can not be made whether the governor problem will affect the diesel in the emergency mode of operation. If the electronic governor problem can be definitely attributed to a malfunction of equipment that is not operative in the emergency operative mode, this would not be considered a valid test or failure as indicated in Regulatory Guide 1.108, Section C.2.e.(2).

The problem with the electronic governor has been only noted on the "C" Diesel. The remaining three diesels have not had problems with power output fluctuations.

There have been four failures in the last one hundred starts. The diesel test interval is one start every three days, per Regulatory Guide 1.108, Section C.2.d.

8411210276 841105 PDR ADOCK 05000387 PDR PDR

16:10

This will be re-evaluated pending further investigation of the governor problem. This report will be updated upon completion of the determination.

N Kein

H.W. Keiser Superintendent of Plant-Susquehanna

RWS/pjg

cc: Mr. R.H. Jacobs
Senior Resident Inspector
U.S. Nuclear Regulatory Commission
PO Box 52
Shickshinny, PA 18655

U.S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555