LICENSEE EVENT REPORT (LER)							U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/85											
FACILITY NAME (1)								DOCKE	NUMBER	(2)	-	PAC	GE (3)					
			arth 7	nna Powo	v Chahi					0 15	10101	0131	31 9	1 OF	012			
TITLE (4)		740	of CII P	nna Powe	I Stati	OII	-				1-1-	1-1-1	- 13 1	213		1012		
	21	II DD	a meete															
EVE	NT DATE	THE RESERVE TO BE ADDRESS OF THE PARTY.	G Trip	LER NUMBER		96	PORT DA	TE (7)		OTHER	FACILI	TIES INVOL	VED (8)					
MONTH	DAY	YEAR	SEQUENTIAL		REVISION	MONTH DAY		YEAR		FACILITY NA			DOCKET NUMBER(S)					
MUNTH	UAT	YEAR	TEAR	NUMBER	NUMBER	MONTH	DAY	TEAN						010				
	11.5												0 101	0 0	101			
110	110	ol a	014	- 01,1,	- 010	. 1 .	-1.	1.1					A . E .	0 . 0	. 0 .			
1 0	1 3	8 4	8 4	0 1 1	00	1 1 1	1 4	8 4					0 5	0 10	101			
	RATING DE (9)			AT IS SUBMITTE	D PURSUANT 1			ENTS OF 10	CFR 9: 10		or the re	illowing/ (11						
14			-	20.402(b)			20.408(e)			50.73(a)(2)(iv)			73.71(b)					
POWER LEVEL			_	20.405(a)(1)(i)			50.38(e)(1)			50.73(a)(2)(v)			73,71(e)					
(10) 0 0 10				20.406(a)(1)(ii)							50.73(a)(2)(vii)			X OTHER (Specify in Abstract below and in Text, NRC Form				
			-	6(a){1){iii}		50.73(a				50.73(a)(2)(viii)			366	AJ				
			20.40	20.406(a)(1)(iv)			50,73(a)(2)(ii)			50,73(a)(2)(viii)(8)								
			20.40	6(a)(1)(v)		50.73(a)(2)(111)			50.73(a)(2)(x)								
					ı	ICENSEE	CONTAC	T FOR THIS	LER (12)									
NAME							EA CODE T	TELEPHONE NUMBER										
											200	EA CODE						
	E	. Way	me Ha	rrell							7	1013	8 19 K	-	15 1	1511		
				COMPLETE	ONE LINE FOR	EACH C	OMPONEN	T FAILURE	DESCRIBE	D IN THIS REPO	RT (13)							
CAUSE	SYSTEM	COMP	DNENT	MANUFAC	REPORTABLE TO NPROS		CAU		SYSTEM	COMPONENT	MANUFAC		REPORTABLE					
				TURER	TO NPHUS		5.55				TURER		TO NPROS					
				111						111		11						
	1	-1		111						1.1.1		11						
				SUPPLEME	NTAL REPORT	EXPECT	ED (14)					EXPECTE		MONTH	DAY	YEAR		
								SUBMISSION DATE (15)										
				UBMISSION DATE	4		NO					UM 15 115		112	311	814		

ABSTRACT

On October 19, 1984, while running the "2H" Emergency Diesel Generator for a 24 hour surveillance test, the diesel tripped on high jacket coolant temperature. The temperature switch was calibrated and the diesel was started for troubleshocting. The diesel tripped on high crankcase pressure. A technical representative inspected the diesel and had one air start valve gasket replaced. The diesel was again started for troubleshooting and tripped after 11 hours on October 22, 1984 with the high jacket coolant temperature alarm in. The lube oil strainer was cleaned, and the diesel was then tested satisfactorily. On November 2, 1984, the diesel tripped on high crankcase pressure. The crankcase ejector was cleaned, and the diesel was then tested satisfactorily.

8411260054 841114 PDR ADDCK 05000339 S PDR

IE22

NRC Form 388A (9-83)	LIGHTON FLORE CONTRACT (LEGISTRATION CONTRACTOR)									GULATORY COMMISSION DMB NO. 3150-0104 31/85				
FACILITY NAME (1)		DOCKET NUMBER (2)	T	LE	R NUMBER (6)	ASER (6)			PAGE (3)					
			YEAR		SEQUENTIAL NUMBER		REVISION NUMBER							
North	Anna Power Station	0 15 10 10 10 1 3 1 3 19	B A	_	0 1 1	_	010	0 1	2 OF	012				

TEXT Iff more space is required, use additional NRC Form 366A's) (17)

On October 19, 1984, while performing the 24 hour surveillance run required by T.S. 4.8.1.1.2(c.8) on the "2H" Emergency Diesel Generator, the diesel tripped on high jacket coolant temperature. The temperature switch was subsequently calibrated and the diesel was retested.

On October 20, 1984, during the retest, the diesel tripped on high crankcase pressure. In an effort to troubleshoot the diesel, a technical representative from Fairbanks-Morse was called in. The upper and lower crankcase covers were removed and the diesel was inspected for mechanical problems and debris. No debris was found. However, while the diesel was being turned over with starting air, one of the air start valve gaskets was found to be leaking. The gasket was replaced. No cylinder leakage was detected during this test and the crankcase covers were replaced.

The diesel was started again on October 22, 1984, for the 24 hour surveillance run. The diesel ran for approximately eleven hours and tripped on either high crankcase pressure or high jacket coolant temperature. The exact cause of the trip could not be determined since the annunciator clears automatically after 22 seconds. The relays that caused the diesel trip could have been visually verified to determine which condition initiated the trip but this data was not obtained. The diesel technical representative had the lube oil strainer cleaned and re-installed. The diesel was then started for the 24 hour surveillance and completed the run without incident.

On November 2, 1984, during another surveillance run, the diesel tripped after 20 minutes on high crankcase pressure. The crankcase ejector was subsequently disassembled, cleaned and re-assembled. The diesel then satisfactorily passed the surveillance test required by T.S. 4.8.1.1.2(a).

The cause of all four trips appears to be spurious instrumentation problems (non valid failures). No significant diesel engine problems have been found. Since both the high jacket coolant temperature and the high crankcase pressure trips are blocked on an emergency start, neither of these trips would occur on an ESF start. An investigation of these events is ongoing. If further significant information develops, an update report will be submitted. This event is reportable pursuant to T.S. 4.8.1.1.4.

VIRGINIA ELECTRIC AND POWER COMPANY NORTH ANNA POWER STATION P. O. BOX 402 MINERAL, VIRGINIA 23117 November 14, 1984 Serial No. N-84-030 U. S. Nuclear Regulatory Commission Document Control Desk NO/DAH: 11 016 Phillips Building Docket No. 50-339 Washington, D.C. 20555 License No. NPF-7 Dear Sirs: The Virginia Electric and Power Company hereby submits the following License Event Report applicable to North Anna Unit No. 2. Report No. LER 84-011-00 This report has been reviewed by the Station Nuclear Safety and Operating Committee and will be forwarded to Safety Evaluation and Control for their review. Very Truly Yours E. Wayne Marrell

Mr. James P. O'Reilly, Regional Administrator

U. S. Nuclear Regulatory Commission

101 Marietta Street, Suite 2900

Atlanta, Georgia 30303

Enclosures (3 copies)

Region II

Station Manager