Georgia Power Company Post Office Box 439 Baxley, Georgia 31513 Telephone 912 367-7781 912 537-9444

04 0C7 31 P/:/>
Nuclear Plant

Georgia Power

Edwin I. Hatch Nuclear Plant

October 25, 1984 GM-84-919

PLANT E. I. HATCH Special Report Docket No. 50-366

United States Nuclear Regulatory Commission Office of Inspection and Enforcement Region II Suite 3100 101 Marietta Street Atlanta, Georgia 30303

ATTENTION: Mr. James P. O'Reilly

Attached is Special Report No. 50-366/1984-02. This report is required by Hatch Unit 2 Technical Specifications Section 3.3.6.8, ACTION b.

H.C. Nix

General Manager

HCN/TLE/djs

XC:

R. J. Kelly

G. F. Head

J. T. Beckham, Jr.

P. D. Rice

K. M. Gillespie

S. B. Tipps

R. D. Baker

Control Room

Document Control

8411260481 841025 PDR ADDCK 05000366 PDR OFFICIAL COPY

IE- 221

## SPECIAL REPORT 50-366/1984-002

LICENSEE : GEORGIA POWER COMPANY

FACILITY NAME : EDWIN I. HATCH

DOCKET NUMBER : 50-366

## DESCRIPTION OF EVENT:

On September 24, 1984, at approximately 1230 CDT, with Unit 2 in steady-state operation at 1638 MWt (approximately 67% power) the fire detectors (2T43-N034 A&B) located in the drywell around the A&B recirculation pump motors failed. This caused the respective fire detection channel for both of the recirculation pumps to fail in its alarm condition. Thus, the plant was unable to meet the requirements of Tech. Specs. section 3.3.6.8.

The plant is presently complying with the LCO requirements of Tech. Specs. section 4.3.6.8.3 (i.e., primary containment temperature checked once per hour for abnormal indications). Due to the nitrogen inerted containment in Unit 2 during operations, a proposed change to Tech. Specs. has been approved onsite and is expected to be submitted to the NRC to request the deletion of the fire detectors in the drywell from Tech. Specs. section 3.3.6.8.

The health and safety of the public were not affected by this non-repetitive event.

This Special Report was signed one day late.