

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Susquehanna Steam Electric Station - Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 3 8 7	PAGE (3) 1 Of 0 2
------------------------------------------------------------------	--------------------------------------	----------------------

TITLE (4)  
Rod Scram Time Measurements.

EVENT DATE (5)			LER NUMBER (8)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)																																																																																															
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)																																																																																													
0 6	1 3	8 4	8 4	0 4 4	0 0	1 1	1 6	8 4			0 5 0 0 0																																																																																													
<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td colspan="12">THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)</td> </tr> <tr> <td colspan="3">OPERATING MODE (9) 1</td> <td colspan="3">20.402(b)</td> <td colspan="3">20.406(c)</td> <td colspan="3">80.73(a)(2)(iv)</td> <td colspan="3">73.71(b)</td> </tr> <tr> <td colspan="3">POWER LEVEL (10) 1 1 0 1 0</td> <td colspan="3">20.406(a)(1)(i)</td> <td colspan="3">80.38(a)(1)</td> <td colspan="3">80.73(a)(2)(v)</td> <td colspan="3">73.71(c)</td> </tr> <tr> <td colspan="3"></td> <td colspan="3">20.406(a)(1)(ii)</td> <td colspan="3">80.38(a)(2)</td> <td colspan="3">80.73(a)(2)(vi)</td> <td colspan="3" rowspan="4">OTHER (Specify in Abstract below and in Text, NRC Form 366A)</td> </tr> <tr> <td colspan="3"></td> <td colspan="3">20.406(a)(1)(iii)</td> <td colspan="3">X 80.73(a)(2)(i)</td> <td colspan="3">80.73(a)(2)(vii)(A)</td> </tr> <tr> <td colspan="3"></td> <td colspan="3">20.406(a)(1)(iv)</td> <td colspan="3">80.73(a)(2)(ii)</td> <td colspan="3">80.73(a)(2)(vii)(B)</td> </tr> <tr> <td colspan="3"></td> <td colspan="3">20.406(a)(1)(v)</td> <td colspan="3">80.73(a)(2)(iii)</td> <td colspan="3">80.73(a)(2)(viii)</td> </tr> </table>												THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)												OPERATING MODE (9) 1			20.402(b)			20.406(c)			80.73(a)(2)(iv)			73.71(b)			POWER LEVEL (10) 1 1 0 1 0			20.406(a)(1)(i)			80.38(a)(1)			80.73(a)(2)(v)			73.71(c)						20.406(a)(1)(ii)			80.38(a)(2)			80.73(a)(2)(vi)			OTHER (Specify in Abstract below and in Text, NRC Form 366A)						20.406(a)(1)(iii)			X 80.73(a)(2)(i)			80.73(a)(2)(vii)(A)						20.406(a)(1)(iv)			80.73(a)(2)(ii)			80.73(a)(2)(vii)(B)						20.406(a)(1)(v)			80.73(a)(2)(iii)			80.73(a)(2)(viii)		
THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)																																																																																																								
OPERATING MODE (9) 1			20.402(b)			20.406(c)			80.73(a)(2)(iv)			73.71(b)																																																																																												
POWER LEVEL (10) 1 1 0 1 0			20.406(a)(1)(i)			80.38(a)(1)			80.73(a)(2)(v)			73.71(c)																																																																																												
			20.406(a)(1)(ii)			80.38(a)(2)			80.73(a)(2)(vi)			OTHER (Specify in Abstract below and in Text, NRC Form 366A)																																																																																												
			20.406(a)(1)(iii)			X 80.73(a)(2)(i)			80.73(a)(2)(vii)(A)																																																																																															
			20.406(a)(1)(iv)			80.73(a)(2)(ii)			80.73(a)(2)(vii)(B)																																																																																															
			20.406(a)(1)(v)			80.73(a)(2)(iii)			80.73(a)(2)(viii)																																																																																															

LICENSEE CONTACT FOR THIS LER (12)

NAME R.W. Stanley	TELEPHONE NUMBER AREA CODE 7 1 1 7 5 4 2 1 - 3 9 3 1 0
----------------------	--------------------------------------------------------------

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
N/A									

SUPPLEMENTAL REPORT EXPECTED (14)

<input checked="" type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE: <input type="checkbox"/> NO	EXPECTED SUBMISSION DATE (15) MONTH DAY YEAR 0 1 1 3 1 0 8 1 5
--------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

During the performance of SR-155-003 'Scram Time Measurement of Rods Every 120 Days', following the Reactor Scram of June 13, 1984, the average scram insertion time required per T.S. 3.1.3.4 was not met for the insertion of the three (3) fastest rods in the following 2x2 array to position 45 [Rods: 38-39, 38-43, 42-39, and 42-43]. Due to an oversight during the review of the computer analysis results, one group of four (4) control rods out of 2,496 analyzed exceeded its T.S. 3.1.3.4 L.C.O. by .012 seconds.

All other Acceptance Criteria for SR-155-003 for the June 13, 1984 scram was met. When procedure SR-155-003 was performed on July 15, 1984, all control rods scrambled within Technical Specification Limitations, including the 2x2 array which failed the June surveillance.

To prevent recurrence, these actions have been taken:

- 1) Each Control Rod Scram Pilot Valve has been examined and modified to improve reliability.
- 2) Following modifications, each Control Rod on both units has been scram tested and found to be within the required scram time specifications.
- 3) Procedure SR-155-003 and the computer print out used with this procedure are scheduled to be revised by 12/31/84.
- 4) The Reactor Engineering Group has attended training on this incident.

8411280475 841116  
PDR ADOCK 05000387  
S PDR

IE22  
11

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Susquehanna Steam Electric Station Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 3 8 7 8 4 - 0 4 4 - 0 0 0 2	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	0 2	OF 0 2
		8 4	- 0 4 4	- 0 0		

TEXT (If more space is required, use additional NRC Form 366A's) (17)

During the performance of SR-155-003, 'Scram Time Measurement of Rods Every 120 Days', following the Reactor Scram of June 13, 1984, the average scram insertion time required per T.S. 3.1.3.4 was not met for the insertion of the three (3) fastest rods in the following 2x2 array to position 45 [Rods: 38-39, 38-43, 42-39, and 42-43]. Due to an oversight during the review of the computer analysis results, one group of four (4) control rods out of 2,496 analyzed exceeded Technical Specification 3.1.3.4 Limits by .012 seconds, .462 seconds vs. .450 as required by Acceptance Criteria.

Technical Specification 3.1.3.2, 'Individual Scram Insertion Speeds to Position 05', and Technical Specification 3.1.3.3, 'Average Rod Insertion Speeds to Position 05, 25, 39, and 45', were in full compliance for each of the 185 control rods analyzed.

Had the insertion speeds to position 45 for the above four (4) control rods been identified in June, retesting would have been performed immediately. Based on 10/6/84 data, the root cause of the slower than allowed control rod scram times was identified to be the sticking of the disc in the scram pilot valves. Therefore, due to the nature of the failure mechanism, even if the slow rod scram times had been identified, an immediate retest would have been within the Technical Specification Limits. Additionally, during the reactor scram of July 15, 1984, SR-155-003 was performed and all control rods parameters were within Technical Specification Limitations, including the 2x2 array which failed the June surveillance.

Since the average scram insertion speeds to position 39 were within specifications on 6/13/84, the value  $\tau$  (Tau) used in the determination of M.C.P.R. per Technical Specification 3.4.2.3 was not affected.

To prevent recurrence, these actions have been taken:

- 1) Each Control Rod Scram Pilot Valve has been examined, and modified to improve reliability by replacement of the polyurethane disc holder sub-assembly with one made of Viton, which is a more resilient material.
- 2) Each control rod on both units has been scram tested and found to be within the required scram time specifications during the plant startups following modifications.
- 3) The Scram Analysis Computer Program is scheduled to be modified to specify all Technical Specifications violations on page one (1) of the output by 12/31/84.
- 4) The Reactor Engineering Group has attended training on this incident to review the causes and corrective actions.
- 5) The Reactor Engineering Group has attended training to review each engineers responsibilities during the performance of surveillances.
- 6) All Reactor Engineering Surveillances are scheduled to be reviewed, and revised as necessary to include an 'AS FOUND' Column for each acceptance criteria by 12/31/84.



SUSQUEHANNA STEAM ELECTRIC STATION  
PO BOX 467, BERWICK, PA 18603

November 16, 1984

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION  
LICENSEE EVENT REPORT 84-044-00  
ER 100450 FILE 841-23 Docket No. 50-387  
PLAS-010 License No. NPF-14

Attached is Licensee Event Report 84-044-00. This event was determined reportable per 10CFR50.73(a)(2)(i), in that a Technical Specification Limit was exceeded.

H.W. Keiser  
Superintendent of Plant-Susquehanna

RWS/pjg

cc: Dr. Thomas E. Murley  
Regional Administrator, Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

Mr. R.H. Jacobs  
Senior Resident Inspector  
U.S. Nuclear Regulatory Commission  
P.O. Box 52  
Shickshinny, PA 18655

IE22  
1/1