

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) **McGuire Nuclear Station Unit 2** DOCKET NUMBER (2) **0500037101** PAGE (3) **1 OF 05**

TITLE (4)
Reactor Trip on Inadvertent Control Bank Drop

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)
1	0	23	84	84	026	00	11	26	84	05000

OPERATING MODE (9) **1**

POWER LEVEL (10) **100**

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)

<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.405(a)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)
<input type="checkbox"/> 20.405(a)(1)(i)	<input type="checkbox"/> 50.36(a)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(e)
<input type="checkbox"/> 20.405(a)(1)(ii)	<input type="checkbox"/> 50.36(a)(2)	<input type="checkbox"/> 50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 365A)
<input type="checkbox"/> 20.405(a)(1)(iii)	<input type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)	
<input type="checkbox"/> 20.405(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)	
<input type="checkbox"/> 20.405(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME **W. H. McDowell- Licensing** TELEPHONE NUMBER **704 373-8878**

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE) NO

EXPECTED SUBMISSION DATE (15)

MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On October 23, 1984, the Unit 2 reactor tripped due to a power range negative high flux rate. This occurred when Instrument and Electrical (IAE) personnel caused Group One of Control Rod Bank B to fall into the core while troubleshooting the Full Length Rod Control System.

The cause of this event was attributed to a procedural deficiency because no procedure was available to give troubleshooting guidelines for the Rod Control System. A contributing cause was due to the IAE Specialist involved not having received available system training.

Unit 2 was in Mode 1 at 100% power when the event occurred.

8412010091 841126
PDR ADOCK 05000370
S PDR

IE22
111

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)

DOCKET NUMBER (2)

LER NUMBER (6)

PAGE (3)

McGuire Nuclear Station Unit 2

0	5	0	0	0	3	7	0	8	4	-	0	2	6	-	0	0	0	3	OF	0
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	----	---

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Several conditions were contributing factors to the event. Since the equipment being checked was not safety related, a troubleshooting procedure was not required and did not exist. The IAE specialist had all the available manuals and drawings. An available vendor manual included the following warning:

"Before printed circuit cards, fuses or power components are replaced, the associated stationary gripper coils must be held on the D. C. hold supply cabinet to avoid dropping the rods."

This warning is located within the paragraphs of a troubleshooting section and was not read by IAE Specialist A prior to troubleshooting. Under the circumstances of this event, it is unrealistic to expect that personnel would read through the vendor manuals prior to troubleshooting due to time involved. IAE Specialist A was under the impression that he was working under the Action Statement of T. S. 3.1.3.1. This action statement requires placing the unit in hot standby within six hours of declaring more than one full length rod inoperable. No rods were declared inoperable because they were still capable of being tripped. This misunderstanding created an unnecessary sense of urgency. If a procedure existed with the same warning as the vendor manual, this event may have been avoided.

IAE Specialist A has over five years of experience working with the Rod Control System but has not received formal training on the system. A two week training course on the rod control system has been available, and other IAE personnel have taken it. Since IAE Specialist A works primarily on this system, it would have been appropriate for him to have received the training.

The problems with Control Rod Bank B and S/D Banks C and D were determined after the unit trip. A faulty integrated circuit on the Bank Overlap Decoder Card in the logic cabinet caused S/D Bank B to move when Control Bank B was selected. With this faulty card, any signal to either Control Bank B or S/D Bank B would have been sent to S/D Bank B. The reason for S/D Banks C and D not moving is believed to have been faulty cable shielding. Thirty volts AC existed on a cable associated with the lift coils on S/D Bank E, rod M-8. This produced a false signal indicating this rod was moving. S/D Banks C, D, and E are interlocked such that only one bank can move at a time (except in the event of reactor trip). The signal on S/D Bank E prevented S/D Banks C and D from moving. The source of this voltage could not be determined. Normally, the cable shielding grounds any voltage induced from magnetic fields which the cable may experience. With faulty shielding, a voltage could have been induced on the cable. To resolve this problem IAE personnel bypassed the subject cable using a jumper.

CORRECTIVE ACTION: IAE personnel replaced the faulty bank overlap decoder card for Control Rod Bank B. All cards in the Rod Control System are currently scheduled to be functionally verified during every refueling outage. IAE personnel also used a jumper to bypass the bad cable associated with S/D Bank E.

A general troubleshooting procedure will be written for the Rod Control System. Also the IAE group will implement an employee training and qualification on systems program. This program will identify tasks performed by IAE personnel and ensure personnel meet qualification requirements prior to working on systems or equipment.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) McGuire Nuclear Station Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 3 7 0	LER NUMBER (5)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8 4	— 0 2 6	— 0 0	0 4	OF 0 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

SAFETY ANALYSIS: Prior to the event McGuire Unit 2 was operating at 100% power. All four Reactor Coolant pumps and both feedwater pumps were in operation. The steam generators were being fed through the lower feedwater nozzles. The B centrifugal charging pump was in operation for Reactor Coolant makeup. The turbine load was \sim 1195 MWe. The Rod Control station was in manual with Control Bank B selected. All other control stations were in automatic.

Reactivity was properly controlled by the reactor trip. Pressurizer pressure responded as expected, dropping to a minimum of 2209 psig before recovering and stabilizing at its reference value of 2235 psig. The pressurizer PORV's and Code Safety Valves were not challenged. Reactor coolant loop average temperatures responded as desired, dropping to \sim 560°F. The temperature settled out at 558°F thirty minutes after the reactor trip. This is within one degree of the expected no-load value of 557°F. Wide range hot and cold leg temperatures also responded as designed. Pressurizer level control was normal. The level dropped immediately after the reactor trip to \sim 37%, and slowly decreased toward its no-load value (25%). The pressurizer level stabilized at 24% about 30 minutes after the reactor tripped. Steam pressure peaked at 1127 psig in Steam Generator C, and stabilized at \sim 1084 psig. The A Steam Generator PORV opened at 1111 psig decreasing and closed at 1086 psig decreasing. (The PORV setpoints are $1125 \pm 1\%$ psig and $1092 \pm 1\%$ psig for opening and closing respectively). The B Steam Generator PORV did not open. This response is acceptable as peak pressure was 1118 psig in this steam generator. The Steam Generator C PORV also did not open. The peak pressure of 1127 psig was within the tolerance of the valve. The Steam Generator D PORV opened at 1117 psig, within the setpoint tolerance of the valve.

Steam Generator level dropped immediately after the trip to the minimum level of \sim 30%. All three Auxiliary Feedwater Pumps were initiated on indicated low-low level in two out of four steam generators. Actual level remained above the post trip low-low level setpoint (12%). Main Feedwater flow was isolated at 04:47:10 on reactor trip with coincident low average primary coolant temperature. Both main feedwater pumps tripped two seconds later on high pump discharge pressure. The operators reset the auxiliary feedwater control valves and adjusted the flows to each steam generator as the level had rapidly recovered to the no-load target value of 38%. Subsequently, the level remained stable at $38\% \pm 7\%$. The Turbine Driven Auxiliary Feedwater pump was secured at 04:51:46. The B Main Feedwater Pump was reset at 05:11:23, and the Motor Driven Auxiliary Feedwater Pumps were secured at 05:19:00. Main Feedwater was used to maintain Steam Generator level after the Auxiliary Feedwater pumps were secured. The levels were well controlled at all times. Minimum level post-trip was 30% in Steam Generator C, which is well above the post-trip low-low setpoint of 12%.

Safety Injection was not actuated during this event. The pressurizer PORVs and Code Safety Valves were not challenged. Indicated pressurizer and steam generator levels remained on scale. The primary cooldown rate was approximately 30°F per hour, well within the Technical Specification Limit of 100°F per hour. No abnormal release of radioactivity occurred during this event, and there was no abnormal primary leakage.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)

DOCKET NUMBER (2)

LER NUMBER (6)

PAGE (3)


McGuire Nuclear Station Unit 2

0 5 0 0 0 3 7 0

YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	PAGE (3)	
84	026	00	05	05

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Figure 1
ROD CONTROL MECHANISM



DUKE POWER COMPANY

P.O. BOX 33180
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

November 26, 1984


Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Subject: McGuire Nuclear Station, Unit 2
Docket No. 50-370
LER 370/84-26

Gentlemen:

Pursuant to 10 CFR 50.73 Sections (a)(1) and (d), attached is Licensee Event Report 370/84-26 concerning a reactor trip on Inadvertent Control Rod Bank Drop, which is submitted in accordance with §50.73 (a)(2)(iv). This event was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,



Hal B. Tucker

WHM/mjf

Attachment

cc: Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

M&M Nuclear Consultants
1221 Avenue of the Americas
New York, New York 10020

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

American Nuclear Insurers
c/o Dottie Sherman, ANI Library
The Exchange, Suite 245
270 Farmington Avenue
Farmington, CT 06032

IE22
1/1