


I-MOSBA-95

15/102

Interoffice Correspondence

Georgia Power 

DOCKETED
USNRC

DATE: August 23, 1990

'95 OCT 20 P4:58


RE: Vogtle Electric Generating Plant
NRC Areas of Concern
Log: SRBS-00044
Security Code: NC

OFFICE OF SECRETARY
DOCKETING & COMPLIANCE
BRANCH
Exhibit 95, page 1 of 43

FROM: M. J. Ajluni

TO: Distribution

Attached for your information is a copy of the recent NRC Operational Safety Inspection areas of concern and VEGP's position.



M. J. Ajluni

MJA/ghj

- cc: W. B. Shipman
- G. Bockhold, Jr.
- S. C. Ewald
- L. K. Mathews
- C. C. Miller ✓
- W. C. Ramsey
- P. D. Rushton
- NORMS
- SRB File

9512280229 950922
PDR ADOCK 05000424
G PDR

NUCLEAR REGULATORY COMMISSION

Docket No. 50-424/425-OLA-3 EXHIBIT NO. II-95
 In the matter of Georgia Power Co. et al., Vogtle Units 1 & 2
 Staff Applicant Intervenor Other _____
 Identified Received Rejected Reporter SB
 Date 9/22/95 Witness _____

INTERVENOR
EXH. #65
7-18-94 CWR

92 PROJECT
045529

AUGUST 17, 1990

<u>AREAS OF CONCERNS</u>	<u>NRC</u>	<u>VEGP CONTACT</u>	<u>CORPORATE CONTACT</u>
* D/G Records Starts/Failures	Pete Taylor	G. Frederick	
* 3/1/90 S R Monitor Inop Mode Change	Neal Hunemuller	JES/D. Carter	
" Missed Surv. Cont. Isol.	Neal Hunemuller	JES/S. Swanson	
* March 15 RHR Train B	Ron Aiello	JES/J. Gasser	P. D. Rushton
* Temp. Change Notice to AOP 18028-C-7-90-1	Robert Carrol	JES/J. Cash	
* ESFA Sequencer Out of Service	Robert Carrol	JES/Horton	J. A. Bailey
* Alternate Radwaste Building	Ron Aiello	Ron LeGrand/JES	P. D. Rushton
* Snubber Reduction/ LCO Action Statement	Larry Garner	Gus Williams	Ward/Stringfellow
* Cont. Integrity Hydrogen Monitor Valve Opened	Morris Branch	Dean Gustafson	Ward/Stringfellow
* Precision Heat Balance	Morris Branch	Gus Williams	B. Florian
* Personnel Accountability Methodology for Reporting	C. VanDenburgh	JES/GB	
* Tech. Spec. 3.0.3 Philosophy	J. D. Wilcox	J. E. Swartzwelder	J. Stringfellow
* ESFAS Reportability	J. D. Wilcox	R. M. Odom	J. A. Bailey
* Plant Review Board (PRB) Composition	C. VanDenburgh	G. Bockhold	
* Tech. Specs. Interpretation	Morris Branch	J. E. Swartzwelder	J. Stringfellow
* Overtime/Training & Qualification	Larry Garner	J. E. Swartzwelder	
* Electrical Separation Zone 80	Larry Garner	M. Horton	P. D. Rushton
* T. S. 3.4.7.3 CCW	J. D. Wilcox	J. E. Swartzwelder	

92 PROJECT
045530

- * Training Department Comments on OSTI
- * Shift Experience
- * Plant Equipment Operator Morale
- * Shift Communications
- * Analyzer Operation Following SI
- * Chilling Affect/Intimidation of PRB Members
- * Quality Concern Program
- * Conflicting Statements
- * While Containment Cooler is Inoperable
DGIB is Rendered Inoperable
- * Exit of Diesel Generator LCO
- *

NRC Concern

1. The NRC is concerned about the incorrect number of diesel starts reported in LER 1-90-06 and the number of starts presented to the NRC on April 9, 1990 and in the confirmation response letter of April 9, 1990. The major issue remaining is to try and determine through personal interviews, how the number of 19 for diesel 1B was arrived at in the April 9 letter to the NRC. The NRC believes the intent of the April 9 letter and the presentation discussed consecutive successful starts. The revised response to LER 90-06 did not clarify the number of starts reported to the NRC April 9, and did not clarify that the 19 starts were not consecutive.
2. The inspector noted that documentation provided by Operations to support diesel trending (14980-C and 13145-C data sheets) does not contain an adequate description of what happens during the start attempt. The plant is not interpreting Reg Guide 1.108 properly with regard to reporting valid and non-valid failures. There may be valid and non-valid failures that were not reported. The NRC does not consider the current status of reporting diesel failures to be in compliance with commitments made to the NRC in Violation 50-424/87-57.

NRC Documentation

The NRC has reviewed the diesel start log and supporting documentation (14980-C and 13145-C data sheets). The NRC currently believes some problems identified on 14980's and 13145's should be classified as non-valid failures and reported to the NRC. The NRC has requested and received written analysis to explain the disposition of the following 1B diesel starts: #'s 123, 124, 132, 133, 134, 136, 160, 161, 162, 164, 165, and 190. LER 1-90-06, revision 1; QA Audit Report OP26-90/33; QA Audit Report OPO9-90/31; and Special Report 1-90-05, dated August 7, 1990; GPC confirmatory action letter dated April 9, 1990.

VEGP Position

1. The error made in the number of diesel starts reported to the NRC on April 9, 1990, and in LER 1-90-06 is attributed to two factors:
 - a. The testing as described in LER 90-06, revision 0, was in the "context of" and "in reference to" the diesel control systems. The first two sentences of the 5th paragraph explain actions taken with regard to sensor calibrations and control system testing. In this context, the test program correlates to testing discussed with the NRC on April 9, 1990, and reported in the April 9, 1990, confirmatory letter. The LER 90-06 comment of "subsequent to the test program" was not intended to exclude successful diesel starts before declaring the diesel operable. As a result, diesel starts after testing of the control systems, but before a declaration of operability were counted. The transmittal letter for LER 90-06, revision 1, describes the confusion and attempts to clarify the concern by redefining the types of starts and the point of counting.

DIESEL STARTS AND FAILURE REPORTING

Page 2 of 2

- b. LER 90-06, revision 1, was intended to clarify any inadvertent "misleading" of the NRC on successful operation of the diesel control systems. When Vogtle Management was aware of the problem in LER 90-06, revision 0, management notified the NRC Residents. Also at the corporate office on 6/11/90, W. Shipman contacted Ken Brockman and on about 6/11/90, W. G. Hairston, III, contacted Mr. S. Ebnetter of NRC Region II. The revised LER was submitted on 6/29/90.

The 19 starts discussed on April 9 were based on operator assessments of the starts as successful using VEGP procedures. Additional review of these starts by both the NRC and Vogtle personnel indicates start #134, performed on March 23, 1990, could be counted as unsuccessful. If start #134 is not counted, only 14 successful starts occurred before April 9, 1990. This start will be reviewed in detail and an appropriate report to clarify the number of starts reported April 9, 1990 will be made.

2. After a thorough review of Reg Guide 1.108, Engineering Support (Mike Horton) agreed that all diesel start problems have not been reported as failures. GPC's response to NRC Violation 424/87-57 committed to report such equipment problems as failures; however, due to internal administrative problems, the commitment was not implemented. Engineering Support intends to review diesel start records for any unreported failures.

VEGP Documentation

- o LER 1-90-06, revision 1; QA Audit Report OP26-90/33; QA Audit Report OP09-90/31; and Special Report 1-90-05, dated August 7, 1990; GPC confirmatory action letter dated April 9, 1990.
- o 1B diesel start analysis available 8/15/90 and Reg Guide 1.108 position from Engineering Support.

Response to NRC Question Concerning
Diesel Starts Reported on April 9, 1990
and in LER 90-06, Revisions 0 and 1

8/22/90
Time: 13:00

Question #1

1. Who prepared the slide for the 4/9/90 presentation?
Answer: G. Bockhold, Jr., J. P. Cash, and K. Burr working as a group.
2. Who approved use of the slide?
Answer: G. Bockhold, Jr.

Question #2

1. Who prepared the confirmatory letter of April 9, 1990?
Answer: C. K. McCoy, J. A. Bailey, W. G. Hairston, III as a group.
2. Who approved the letter?
Answer: W. G. Hairston, III

Question #3 (with regard to LER 90-06, revision 0, dated 4/19/90)

1. Who prepared the LER?
Answer: Several draft revisions of the LER were prepared by Tom Webb and others of the NSAC group of the Vogtle Site Technical Support. These drafts were reviewed and commented on by the Plant Review Board. The final revision of LER 90-06, revision 0 was prepared by a phonecon between site management and corporate management. Those participating are believed to be G. Bockhold, Jr., A. L. Mosbaugh, J. G. Aufdenkampe, W. Shipman.
2. Who reviewed the LER?
Answer: All revisions of the LER were reviewed by the PRB and the General Manager-Plant Vogtle.
3. Who approved the LER?
Answer: The LER was approved by W. G. Hairston, III

Question #4

1. Who prepared the cover letter for LER 90-06, revision 1?
Answer: The cover letter was prepared by H. W. Majors of the corporate staff. This letter was prepared under the guidance of W. G. Hairston.
2. What was the purpose (intent) in the wording of the cover letter with regard to the number of diesel starts?
Answer: The cover letter was intended to document discussions with NRC Region II to clarify the starts documented in LER 90-06, revision 0. By picking a well defined point to specify "subsequent to the test program" it was possible to identify a substantial number of successful diesel starts. This was intended to remove any additional ambiguity.

Question #5

1. Who in corporate added the words "subsequent to the test program" in LER 90-06, revision 0?
Answer: Corporate Licensing personnel in conjunction with the phone conversation described above made editorial changes as directed. Those present during the phone conversation are thought to be W. Shipman, G. Bockhold, Jr., A. L. Mosbaugh, J. G. Aufdenkampe, and J. Stringfellow.

92 PROJECT
045534

LER 1-90-004

Original NRC Concern

To determine if Technical Specification 3.0.4. was violated, when Unit 1 entered Mode 6 from Mode 5 while Source Range 1N31 was out of service for an 18 month calibration, solely for the purpose of progress on the critical path schedule; if the shift was subsequently congratulated for making that progress; and if the Shift Superintendent demonstrated a willingness to violate Technical Specifications for the sake of schedule.

Found to be unsubstantiated

NRC Concern

The inadequacy of the root cause determination and corrective actions of LER 1-90-004, in that, human factor problems involving the LCO sheet may have contributed to the Shift Superintendent's failure to note the LCO mode change restriction.

NRC Documentation

Technical Specification 3.9.2
Deficiency Card 1-90-0050
LER 1-90-004
12007-C, Refueling Entry (Mode 5 to Mode 6)
Unit 1 Control Log
Unit 1 Shift Supervisor Log (2/28/90 and 3/1/90)
LCO Status Sheet 1-90-152
LCO Log (10008-C, P.8 of 11, dated 2/28/90)
14000-1, Operations Shift and Daily Surveillance Logs, dated 2/28/90
1R2 Outage Schedule (actual vs. schedule)
Turnover Checklist (11870-C, dated 2/28/90)
Completed Procedures, dated 2/28/90 - 12007-C, 14000-1, 11871-C and 11872-C

VEGP Position

VEGP's position is that human factor problems with the LCO sheet was not a significant contributing causal factor in this event. However, due to a number of human factor concerns noted during the 1R2 refueling outage, VEGP has revised procedure 10008-C twice, to enhance usability and human factoring. Furthermore, VEGP will review Procedure 10008-C to determine if further enhancements are warranted.

LER 1-90-004

VEGP Documentation

LER 1-90-004
12007-C, Refueling Entry (Mode 5 to Mode 6)
Unit 1 Control Log, 2/27/90 to 3/2/90
Unit 1 Shift Supervisor Log, 2/27/90 to 3/2/90
Unit SS Relief Checklists, 2/28/90 and 3/1/90
Support SS Relief Checklists, 2/28/90 and 3/1/90
Operations Supervisor Relief Checklist, 2/28/90 and 3/1/90
RO Relief Checklists, 2/28/90 and 3/1/90
BOP Relief Checklists, 2/28/90 and 3/1/90
14000-1, Operations Shift and Daily Surveillance Logs, 2/28/90
1R2 Outage Schedule, 2/23/90 thru 3/3/90
10008-C, Recording Limiting Conditions for Operation, Rev. 12

MISSED SURVEILLANCE ON
"CONTAINMENT INTEGRITY VERIFICATION
VALVES OUTSIDE CONTAINMENT"

NRC CONCERN: Required Tech Spec actions may have been delayed by initiating an investigation. Was management pressure a contributing factor?

Concern: Potential concealment of correct Tech Spec LCO entry time to prevent a forced shutdown and immediate notification of the NRC.

Finding: The correct T.S. LCO entry was not concealed.

Concern: Cause for confusion over the Surveillance Task Sheet.

Finding: The cause for the confusion was an inconsistent use of equipment identification numbers on these sheets. Corrective actions adequate.

Concern: Extent of emphasis on keeping the plant in operation and limiting NRC notifications.

Finding: There was no indication of unreasonable emphasis on keeping the plant in operation or limiting NRC notifications.

NRC DOCUMENTATION:

D.C. 2-90-022

Surveillance 14475-201 Jan 3, 1990, Feb 1, 1990,
Feb 28, 1990

Unit II LER 90-001

Control Room Logs from Feb 27 and Feb 28, 1990

NRC Inspection Report 90-10

RHR PUMP 1B VIBRATION

Original NRC Concern

A non-conservative decision was made concerning the operability of the 1B RHR pump in order to avoid substantial impact to the outage critical path schedule

Found to be unsubstantiated

NRC Concern

A Deficiency Card was not generated in a timely fashion concerning the 1B RHR pump cooler leak and elevated vibration levels.

NRC Documentation

Unknown

VEGP Position

VEGP concurs that a Deficiency Card was not generated in a timely fashion. Since the occurrence of this event, VEGP management has taken positive action to improve the effectiveness of the Deficiency Card Program. These improvements include:

1. Revision of Reactor Trip Review Procedure, 10006-C to specifically require a sign-off indicating a Deficiency Card has been written.
2. Address by General Manager to the PRB stressing the necessity for timely Deficiency Card generation, and memo to all managers from the Technical Support Manager stressing the requirements for timely submittal of Deficiency Cards.

In addition, the Deficiency Card Program has received increased management attention and oversight to ensure Deficiency Cards are generated in a timely fashion. This will ensure that operability and reportability determinations and appropriate engineering evaluations are performed.

VEGP Documentation

Letter, Manager, Technical Support to Department Managers dated 6/22/90.

RHR PUMP 1B VIBRATION

Original NRC Concern

A non-conservative decision was made concerning the operability of the 1B RHR pump in order to avoid substantial impact to the outage critical path schedule

Found to be unsubstantiated

NRC Concern

A Deficiency Card was not generated in a timely fashion concerning the 1B RHR pump cooler leak and elevated vibration levels.

NRC Documentation

Unknown

VEGP Position

VEGP concurs that a Deficiency Card was not generated in a timely fashion. Since the occurrence of this event, VEGP management has taken positive action to improve the effectiveness of the Deficiency Card Program. These improvements include:

1. Revision of Reactor Trip Review Procedure, 10006-C to specifically require a sign-off indicating a Deficiency Card has been written.
2. Address by General Manager to the PRB stressing the necessity for timely Deficiency Card generation, and memo to all managers from the Technical Support Manager stressing the requirements for timely submittal of Deficiency Cards.

In addition, the Deficiency Card Program has received increased management attention and oversight to ensure Deficiency Cards are generated in a timely fashion. This will ensure that operability and reportability determinations and appropriate engineering evaluations are performed.

VEGP Documentation

Letter, Manager, Technical Support to Department Managers dated 6/22/90.

IMPROPER TCP PROCESSING

NRC Concern

TCP 18028-C-7-90-1 was "back-dated" to avoid violating section 6.7.3.c of Technical Specifications.

NRC Documentation

TCP 18028-C-7-90-1
DC 1-90-282
DC 1-90-283
PRB Minutes 90-81 and 90-82
Procedure 00052-C

VEGP Position

A violation of Section 6.7.3.c of the VEGP Technical Specifications occurred. However, the cover sheet of TCP 18028-C-7-90-1 was not dated 6-12-90 to avoid this violation.

TCP 18028-C-7-90-1 (written against Rev. 7 of the permanent plant procedure), Loss of Instrument Air, was approved by the Operations Manager on 5-31-90. On 6-8-90 the PRB tabled this TCP to allow the Operations Department to determine if additional instructions for Modes 3, 4, 5, and 6 should be added to the revision to strengthen the AOP. Revision 8 of the permanent procedure was prepared by Operations and approved by the PRB on 6-12-90. This revision addressed both TCP 18028-C-7-90-1 and additional instructions for a Loss of Instrument Air in Modes 3, 4, 5, and 6. The Acting Operations Manager understood that the TCP would not be used in the field once Rev. 8 was issued. Upon approval of Rev. 8 of the permanent procedure by the PRB, verbal instructions were given by the Acting Operations Manager to the procedure coordinator to void TCP 18028-C-7-90-1. The TCP was next in the procedure coordinator's possession on 6-15-90. On that date the acting Operations Manager signed the TCP cover sheet and dated it 6-12-90 to reflect his understanding, based on discussions with the procedure coordinator and his verbal instructions of 6-12-90, that the TCP was voided on 6-12-90.

The Acting Operations Manager assumed that the approval of Rev. 8 of the permanent procedure (which he assumed occurred on 6-12-90) resulted in the voiding of the TCP, and that his verbal instruction to the Operations staff was adequate to close-out required paperwork. This was an error and resulted in a failure to comply with Procedure 00052-C, Section 4.6.2 in a timely manner. GPC notes that the minutes of PRB meeting 90-82 indicate the TCP "was voided" on 6-12-90 which reflected the understanding of the Acting Operations Manager.

IMPROPER TCP PROCESSING

On 6-18-90, the Operations Manager instructed the Acting Operations Manager to write a DC on the inaccurate dating of the TCP close-out sheet and a failure to meet the 14 day period set under Procedure 00052-C, Section 3.2.4. This instruction was a result of normal Technical Support Group review and verification close-out of TCPs.

On 6-22-90 two DCs were written by Technical Support. On the same date the (former) Acting Operations Manager, in preparing a DC on the inaccurate dating of the TCP cover sheet, determined that the permanent procedure, Rev. 8, was not issued until 6-13-90, that the TCP was pulled from the Control Room on 6-13-90 and that the 14 day limit under Procedure 00052-C had been exceeded.

SEQUENCER INOPERABILITY

NRC Concern

Inadequate information exists for shift personnel to determine which Technical Specification to apply if the sequencer is inoperable. In addition, previous verbal guidance was inadequate.

NRC Documentation

1. Sequencer related work orders
2. Previous sequencer LCO sheets
3. Control room narrative logs
4. Sequencer related surveillances

VEGP Position

The NRC position is accurate in that no Tech. Spec. interpretation exists. Previous guidance connected sequencer inoperability to diesel generator inoperability. Recent information has demonstrated that sequencer inoperability should also be tied to "actuation logic and actuation relays", as found in the instrumentation specifications. VEGP will further review and evaluate this issue to ensure an adequate interpretation exists for the shift personnel.

We intend to develop a clear interpretation with input from Operations, Engineering, and Maintenance. Based on that development a Tech Spec Interpretation will be written and a Tech Spec change requested to clarify this issue.

VEGP Documentation

As above

ALTERNATE RADWASTE BUILDING

NRC Concern

Concerned that the FAVA system was installed without performing adequate engineering and safety evaluation (50.59), because the fabrication and quality of the system did not meet the RG-1.143 and ASME code requirements.

Concluded that the FAVA system was originally installed without an adequate safety evaluation. As a result of a VEGP QA finding in early 1989 involving a breakdown in the procurement and failure to meet FSAR commitments, the system was removed from service. Subsequently the system was returned to service following two SEs (dated 11/89 and 2/90) which adequately addressed the use of PVC piping with respect to radiation degradation and pipe rupture. Although these SEs did not address the effects of a break in the hoses (which could result in wall spray down or leakage), the use of hoses and effects of hose breaks (i.e., airborne activity and puddling) were addressed in SER Supplements 3 and 4. Although these SEs did not address high temperature effects our interview indicated that these effects were considered in performance of the SE.

Concluded that the SE performed on 6/90 at the request of RII to evaluate the effects of a FAVA system wall spray down and wall leakage to an unrestricted area have been adequately addressed for the use of the FAVA system, because the FAVA System has a protective cover. However, the June 90 safety evaluation inadequately addresses the potential effects of wall spray down from any other source in the ARB due to erroneous assumptions concerning the release path and the dilution volumes. This is a potentially unreviewed safety question concerning the use of the alternate radwaste building. And as such will be followed as an unresolved item pending further review and evaluation. (Unresolved item concerning unreviewed safety question).

NRC Documentation

IEC 80-18
SSER 3 Section 11.4
SSER 4 Section 11.4
SSER 8 Section 11.4

VEGP Position

The safety evaluation for the FAVA microfiltration system was adequate for use of the system. The calculation performed to evaluate the "spray accident" in the ARB was flawed due to erroneous assumptions regarding the release path. These flawed assumptions do not affect the 50.59 evaluation made for the FAVA unit. The analysis of the "spray accident" in the ARB should not have been included as a revision to the safety evaluation in the FAVA unit. Doing so confused these two separate issues and was not appropriate.

During the plant licensing process, details of the construction of the ARB were provided to the NRC. NRC personnel visually inspected the as-built condition of the ARB and associated solid waste processing steams and interface connections that tie other support systems to the equipment in the ARB. Flexible hoses and couplings were in use in the facility at the time of this inspection. The NRC found the facility acceptable for use based on our submittal and their visual inspection with one exception which was subsequently corrected and had to do with exhaust air filtration. This information is well documented in the SER Supplements 3, 4, and 8.

NRC concerns with wall spray-down from the FAVA System have been adequately addressed by the installation of a protective cover. VEGP considers previous analysis and NRC SER Supplements adequate with respect to the ARB. Since the configuration of the ARB and the hoses in question is the same as that addressed by such previous analysis and SER Supplements, no unreviewed safety question exists.

VEGP Documentation

Safety Evaluation dated 2/26/90
Other documentation same as NRC

Date: August 22, 1990
Time: 1300

Snubber Reduction and Use of the Appropriate
Technical Specification and LCO Action Statement
Entry to Implement Design Change

NRC Concern

Voluntary entry into a LCO action statement is acceptable for the purpose of surveillance testing but is discouraged for modification work. (See NRC internal correspondence Murley to Martin dated May 18, 1990). NRC has determined that applying the action statement associated with Specification 3.7.8 and then applying the action statement of the applicable system is a correct interpretation of Technical Specification requirements. Specification 3.7.8 is intended for broken snubbers or functional testing and not for other purposes. With respect to snubber reduction you must have a valid safety evaluation which considers the ramifications of performing the modification at power. If the modification renders the system inoperable during the installation, as determined by analysis, then the applicable system action statement must be applied.

Entering a LCO action statement should represent a net safety benefit and be warranted by operational necessity, not just by convenience. The practice should not be abused by repeated entry into and exit from the LCO. Implementation of snubber reduction during power operation is non-conservative.

NRC Documentation

LCO's

Safety Evaluations for DCP's 88-V1N0114, 89-V1N0047
Copies of MWO's for NSCW "A" Train
Letter from Murley to Martin, dated 5/18/90
Letter from W. C. Ramsey to C. C. Miller, dated 8/15/90
Letter from Denton to Norelius, dated 5/27/90

VEGP Position

Voluntary entry into a LCO action statement for the purpose of implementing a design change is acceptable provided the activity is accomplished within the provisions of the Technical Specification and proper consideration has been given to the impact on plant safety. This position is supported by NRC Standard Technical Specification interpretation which actually endorses voluntary entry into an action statement condition on the basis that the NRC "has structured the Technical Specifications to permit the licensee to exercise judgement within the latitude permitted by the Action Statement language in the Technical Specification".

VEGP implements design changes on safety related systems for the purpose of improving system reliability and thereby enhancing plant safety. VEGP maintains that voluntary entry into a LCO action statement to implement a design change is acceptable and desirable in specific cases. VEGP considers this consistent with industry practice.

VEGP agrees with the NRC position that applying the action statement associated with specification 3.7.8 then applying the associated system action statement is the appropriate way to implement Technical Specification requirements. In addition, VEGP agrees that when performing a modification a Safety Evaluation must be performed. If the evaluation determines the system is rendered inoperable during the installation process then the action statement associated with the system must be followed and 3.7.8 cannot be applied.

Since snubber reduction increases system reliability by eliminating potential failure modes, implementation of snubber reduction during power operation is conservative.

VEGP Documentation

LCO's
Safety Evaluations for DCP's 88-V1N0114, 89-V1N0047
Copies of MWO's for NSCW "A" Train
STS, Section 3.0 Voluntary Entry into Action Statements,
dated 1/1/82
Letter from Murley to Martin, dated 5/18/90
Letter from W. C. Ramsey to C. C. Miller, dated 8/15/90
Letter from Denton to Norelius, dated 5/27/90

CONTAINMENT HYDROGEN MONITORS

CONCERNS:

- I. OPENING VALVES AT POWER
 - II. ANALYZER OPERATION FOLLOWING SI
-
- I. OPENING H2 MONITOR VALVES AT POWER

NRC QUESTION

Are the following valves considered containment isolation valves?

HV-2792A
HV-2792B
HV-2793B
HV-2791B

NRC CONCERN

NRC feels they are based on:

FSAR Table 6.2.4-1
FSAR Table 16.3-4

VEGP POSITION

Yes, the above identified valves are containment isolation valves for the A-Train Containment H2 Monitor.

NRC QUESTION

If they are containment isolation valves does Tech Spec 3.6.3 apply to the operation of these valves?

NRC CONCERN

NRC feels Tech Spec 3.6.3 applies for the following reasons:

- ° Tech Spec 3.6.3 applies to containment isolation valves.
- ° We say they are containment isolation valves in Tech Spec interpretation to 3.6.3 (1-18-90).
- ° Operations Procedure 13130-2 page 4 "Caution" statement.
- ° Maintenance Procedure 24932-2 step 3.2 "Prerequisites or Initial Conditions"
- ° FSAR 6.2.4.2.3

VEGP POSITION

Tech Spec 3.6.3 applies to containment isolation valve operability. Opening these valves to perform channel calibration of the H2 analyzer does not render the valve inoperable and therefore Tech Spec 3.6.3 is not entered. If one of these valves became inoperable (e.g. would not close, leaked excessively, etc.), then Tech Spec 3.6.3 would apply to that valve and the associated containment penetration.

Tech Spec 3.6.3 interpretation (1-18-90) applies to hydrogen monitor valves as described above.

Procedure 13130-2 confirms the way we want to operate these valves.

Procedure 24932-2 was only recently revised to include the reference to the LCO condition. The LCO condition was with reference to breaching the piping boundary outside containment.

FSAR 6.2.4.2.3 states these essential lines are normally closed and remain closed during power operation. The configuration of these valves are normally closed during power operation. Opening these valves to perform calibration does not conflict with the system description in the FSAR.

CALIBRATION PROCEDURE 24551-2

NRC QUESTION

Do we feel step 2.9 still valid, precautions/limitations "may be performed in any plant mode"?

VEGP POSITION

Yes, precaution 2.9 is valid. The procedure for H2 monitor calibration is required to be performed every 92 days on a staggered test basis (i.e. one channel must be tested approximately every 46 days), per Tech Spec 4.6.4.1. Thus Tech Specs recognize this surveillance as one that can be and should be performed at power.

NRC QUESTION

Do we feel it is necessary to open the isolation valves to perform calibration?

VEGP POSITION

Yes, for the following reasons:

- 1) By establishing a flow path to and from containment we are verifying an open flow path exists.
- 2) Verification that pump will operate in the normal flow path configuration is confirmed.
- 3) ALARA concerns associated with positioning the vent valves.
- 4) Risk associated with vent valve manipulations.

NRC QUESTION

Was operations involved in review and approval of the procedure?

VEGP POSITION

No

NRC QUESTION

Was the 50.59 safety evaluation performed adequately?

VEGP POSITION

Yes

NRC QUESTION

When this issue was pointed out 8/7/90 on Unit 2, why was test performed on Unit 1 the next day?

VEGP POSITION

When the issue was brought up with the Operations Manager, he began gathering information on the issue. At the time he felt our procedures were correct and did not review the next day's activities. When shift personnel were made aware of the NRC concern the test was terminated immediately.

NRC QUESTION

What Tech Spec requires LLRT testing of the system?

24910

24930

24931

24932

24933

VEGP POSITION

Procedures 24930, 24931, 24932, 24933 satisfy the requirements of Tech Spec 4.6.1.2.d for components defined in FSAR Table 6.2.4-1. Procedures 24910 and 24932 satisfy the requirements of leakage assessment of Tech Spec 6.7.4.A.

NRC QUESTION

Is leak rate testing performed on these containment isolation valves added to overall containment leak rate?

VEGP POSITION

Leak rate for these isolation valves is added to the total type B and C leakage. It is not added to type A results.

NRC QUESTION

Evaluate applicability of Tech Spec 6.7.4.A to this system

VEGP POSITION

The piping outside containment is covered under the leakage assessment program as addressed in Tech Spec 6.7.4.A.

NRC QUESTION

Do we feel we violated Tech Spec 3.6.3 on the following two occasions?

Unit 2 0411 8/6/90 to 0122 8/7/90

21 hrs. 11 min.

Unit 1 2053 8/7/90 8/8/90

18 hrs. 47 min.

VEGP POSITION

No, the containment isolation valves were not inoperable on these dates. Further, in the past calibrations have been scheduled in accordance with Tech. Spec. requirements (approximately every 90 days).

II. ANALYZER OPERATION FOLLOWING SINRC QUESTION

Are the analyzers placed in service 30 minutes after a safety injection?

Requirement: NUREG 0737 IIF1 Attachment 6
TMI requirement

Provide station position relative to NUREG 0737 also provide proof of implementation.

NRC has looked the following places:

19000-C

19251-C

Loss of primary & secondary coolant

Reference SER 6-4

VEGP POSITION

Procedure 19010-C (Loss of Primary or Secondary Coolant) step 12 currently addresses obtaining containment H2 samples following an SI. VEGP intends to enhance this procedure relative to placing the H2 analyzers in service for this purpose.

Date: August 16, 1990
Time: 1600

Precision Heat Balance

NRC Concern

The corrective actions associated with LER 90-015 (Failure to Calibrate Computer Points Prior to Precision Heat Balance Flow Measurements) are technically correct, the decision not to re-perform the surveillance test was non-conservative.

NRC Documentation

LER 90-015-00
DC cards, RCN's Reactor Engineering Calculations
Completed test procedures

VEGP Position

The decision not to reperform the surveillance was conservative, based on Engineering evaluation of available data. Additionally, all associated data was reanalyzed assuming potential calibration errors. This reanalysis verified the initial engineering analysis.

When Unit 1 final feedwater temperature instrumentation was determined to be out of calibration, examination of the data indicated sufficient margin to address the out of calibration condition. Reanalysis of the data considering the out of calibration condition confirmed the conclusion.

For Unit 2 the calibration of final feedwater temperature was never suspect. Again, examination of calibration data taken after the test indicated sufficient margin to address potential miscalibration problems. Reanalysis of the data also confirmed this conclusion.

VEGP Documentation

None

8/16/90
1600

PERSONNEL ACCOUNTABILITY

NRC Concern

Holding shift supervision accountable for the number of reactor trips, LER's, and ESFAS actuations has a potential negative influence on plant safety because personnel might not be open about reporting these types of plant problems.

NRC Documentation

Typical Shift Superintendent Accountabilities

VEGP Position

These accountabilities enhance reactor safety because they focus personnel attention on safety and compliance issues. Reporting problems is required to achieve good SALP ratings and is part of shift supervision accountabilities.

VEGP Documentation

Typical Shift Superintendent Accountabilities
1990 Organizational Goals
Performance Appraisal Forms

92 PROJECT
045552

3.0.3 1 HR. ACTIONS

NRC Concern

Inadequate documentation exists to demonstrate all actions taken during the first hour after entry into Technical Specification 3.0.3.

NRC Documentation

Control Room Narrative Logs

VEGP Position

Documentation of all actions taken during the first hour after entry into Technical Specification 3.0.3 does not exist as stated by the NRC. However, this information (documentation) is not procedurally required, nor is it a regulatory compliance issue. Appropriate actions have been taken in the past 3.0.3 entries to meet the time table of the action statement.

VEGP Documentation

As Above

Date: August 16, 1990
Time: 1600

ESFAS REPORTABILITY ISSUE

NRC Concerns

In regard to reportability of ESF actuation NRC has developed a position that "If, for any reason (except expected responses to testing) the ESF components are caused to operate, then an ESF actuation did occur". This position was formulated in response to GPC Corporate internal memo (June 11, 1987) which provides guidance concerning ESF actuation reportability.

NRC Documentation

1. Internal NRC memo dated July 12, 1990 from Charles E. Rossi to Gus C. Lainas.
2. Internal GPC memo dated June 11, 1987 from R. Baker to L. T. Gucwa.

VEGP Position

The June 11, 1987 letter was written by a member of the Corporate Nuclear Safety and Licensing Department to his Supervisor. The information contained in the attachment to this letter was intended to be used as guidance when determining ESF actuation reportability. This information was never adopted by the Vogtle Electric Generating Plant (VEGP) to be used for reportability guidance. The Vogtle practice has been to report the ESF actuation regardless of "what caused the actuation" or "how the actuation occurred". Based on discussions with individuals who review deficiencies for reportability and a review of past deficiency evaluations identified no instances where the position described in the June 11, 1987 letter was utilized in ESFAS reportability determination at VEGP.

VEGP Documentation

1. W. F. Kitchens memo to OSOS dated June 9, 1987
RE: ESF Actuation
2. Sort of DC's by keyword "ESFAS"
3. List of ESFAS LER's for Vogtle

92 PROJECT
045554

8/16/90
1600

PLANT REVIEW BOARD (PRB) COMPOSITION

George Bockhold, Jr.

NRC Concern

The Tech Specs may not allow the Manager Technical Support to be the PRB member for both Quality Control (QC) and Nuclear Safety & Compliance (NSAC).

NRC Documentation

Tech Spec 6.4.1.2 - PRB Composition
Tech Spec Interpretation - 6.4.1.2

VEGP Position

When the Company restructured the PRB, we raised the Level of the PRB members to be line managers to enhance board activities. Our plant organization had been restructured, and the Manager Tech Support was responsible for both QC and NSAC, and should be their representative on the PRB.

VEGP Documentation

Tech Spec 6.4.1.2 - PRB Composition
Tech Support Interpretation - 6.4.1.2
Nuclear Operations Organization - FSAR Fig. 13.1.2-1
Manager Technical Support - Details

Resolution:

C. VanDenburgh dropped the issue on 8/14/90. We should consider a Tech Spec revision at the next update.

92 PROJECT
045555

8/17/90
1000

TECHNICAL SPECIFICATION INTERPRETATIONS

NRC Concern

1. The control of the generation, approval and distribution is not formal enough.
2. The level of review and approval of Tech. Spec. interpretations is not a high enough level (i.e. PRB review and concurrence should be required). In fact, Tech. Spec. 6.4.1.6 a or d may apply.
3. If NRC guidance is used, author of guidance should be sent a "Info Copy".

NRC Documentation

None

VEGP Position

Since VEGP Tech. Spec. interpretations are not designed to modify the intent or breadth of the Technical Specification but merely to clarify the specification for the on-shift operations crews, a formal process is not required and T.S. 6.4.1.6 a and d are not applicable. The Operations Manager, being the senior member of plant management required to maintain a Senior Reactor Operators License, is the appropriate approval authority for the Technical Specification interpretations generated. As required by subject matter, input from other sections including Nuclear Safety and Compliance, is utilized in the development of the interpretations.

VEGP Documentation

None

92 PROJECT
045556

OVERTIME

NRC Concern

No provision exists in our procedures that would prevent operators from working an excessive amount of overtime during an extended period of time, i.e. monthly or yearly. Our restriction of no more than 72 hours worked in a seven day period would not prevent excessive overtime on a monthly or yearly basis.

NRC Documentation

None

VEGP Position

Operations department personnel use established procedures and guidelines, based on existing regulatory guidance, that limit the possibility of this situation occurring and ensure compliance with the regulations governing overtime.

Procedure 00005-C gives the overtime guidelines and requires the department head to evaluate and approve the consistent use of overtime. The GMNP, or designee is also required to review excess overtime assigned to individuals each month to ensure proper authorization per Figure 1 of this procedure. Also, he reviews the overtime to ensure that assignment of excess overtime does not become routine.

For operators working under the union contract, additional guidance is provided for overtime assignment and equalization in the Memorandum of Agreement, paragraph 49.

Based on review of overtime records, LER's, Reactor Trips, and ESFAS Actuations, no conclusions can be drawn that indicate excessive overtime has caused operator fatigue or an increased frequency of operator errors. However, VEGP intends to review this item for potential enhancements.

The timely completion of required documentation was identified as a problem by a Quality Assurance audit. Corrective action from that audit has improved performance in documentation.

VEGP Documentation

Week at a Glance
Paragraph 40, Memorandum of Agreement
Procedure 00005-C

92 PROJECT
045557

NON-LICENSED OPERATOR TRAINING

NRC Concern

1. The PEO training program does not include under-instruction watches for building qualification.

2. The training program may not be adequate to train and evaluate the ability to make routine rounds; some operators may not have completed their actual rounds task properly.

NRC Documentation

In NRC interviews with new building operators some said they did not actually perform their rounds in training.

VEGP Position

1. Qualification is based on the successful completion of required knowledges and skills, which are arrived at through the analysis phase of a systematic approach to training (SAT) process. The INPO accredited program does not rely on any arbitrary number of under-instruction shifts for qualification. However, due to requests from Plant Equipment Operators surveyed, VEGP will re-evaluate the addition of under-instruction watches to the building operator qualification checklists.

2. The routine conduct of rounds is an identified task with associated supporting knowledges in the PEO training and qualification program. A comprehensive instructional unit provides sufficient information and guidance to assure that operators have the ability to perform routine rounds. A specific weakness has been identified in the implementation of the evaluation process for the task conducting rounds. This weakness will be handled through the SAT feedback process.

VEGP Documentation

Procedure 11958-C, "Auxiliary Building Operator Training Qualification Checklist"

Qualification Signoff Criteria Cluster 51 - NLO Administrative Duties

VEGP Instructional Unit NL-IU-51401-001-C, Conduct Auxiliary Building Rounds

VEGP Instructional Unit NL-IU-51401-002-C, Conduct Control Building Rounds

Management Observation Report (MORE) - TQ.3, "On-The-Job-Training"

OPERATOR ROUNDS GENERAL INSPECTION

NRC Concern

There are differences in the depth of general inspections performed by operators during their rounds.

NRC Documentation

NRC observation of rounds by new Auxiliary Building Operators.

VEGP Position

The general inspection is intended to identify any type of abnormal condition which may develop. The procedural guidelines are accordingly very broad. It is not our intent to detail every possible check which the operator could make in our procedures. The guidance in Operations Procedure 10001-C "Logkeeping", describes the overall areas of inspection required of the Plant Equipment Operators.

We expect there will be differences in the focus of different operators based on their personal experience and shift supervision instructions. This diversity is a plus to increase the breadth of the general inspection.

For the rest of 1990, VEGP will increase the number of supervisors and managers doing Management Observation Reports on operator rounds, during both day and night shifts. These observations will be reviewed to establish a baseline performance standard and any needed corrective actions will be implemented in procedures, training and practice.

VEGP Documentation

Procedure 10001-C, Logkeeping
Training Cluster 51-NLO Administrative Duties

8/16/90
16:00

ELECTRICAL SEPARATION ZONE 80

NRC Concern

Upon an LOSP a postulated fire in Zone 80 would render Train A inoperable, and may trip the Train B Diesel Generator output breaker. VEGP should insure that no equipment required to cope with this condition would be damaged by the fire while the diesel generator output breaker is being reclosed.

NRC Documentation

DC 1-90-299 and 2-90-080

VEGP Position

1. The design requirement for a fire in this area is to be able to shut down the plant using Train "B" equipment (FSAR 9A.1.40.L.1a). This scenario does not affect our ability to safely shut down the plant, is not a condition outside our design basis, and is therefore not a reportable condition.
 - A. The postulated fire scenario would not damage the Train "B" safety related equipment necessary for safe shutdown of the plant. The D/G would continue to run and an annunciator would indicate D/G trouble.
 - B. The operator would be required to observe a loss of power on the "B" Train safety related bus, recognize there was a fire in the room where the attached non-safety related bus is located, separate the nonsafety related bus from the safety related bus, and reclose the D/G output breaker. There is adequate time for the operator to take these actions.
2. As a conservative measure, the feature which could cause the D/G output breaker to open in this scenario is being eliminated so as not to rely on operator action to reclose the breaker.
3. VEGP intends to provide additional information to support these conclusions.

VEGP Documentation

FSAR 9A.1.40.L.1a
Letter #SG-9471
Letter #SG-9510
DC 1-90-299
DC 2-90-080

92 PROJECT
045560

CCW VALVE SURVEILLANCE

NRC Concern

Tech Spec surveillance of CCW Valves is not conducted monthly as required by T.S. 4.7.3.a

NRC Documentation

Tech Spec 4.7.3.a CCW Valve Surveillance

VEGP Position

Vogtle Technical Specifications Section 4.7.3.a requires that all valves in the Component Cooling Water System that are not locked, sealed, or otherwise secured in position be verified in the correct position once every 31 days. A surveillance is not required for any CCW flowpath valves at Vogtle because all CCW flowpath valves are included in the Vogtle locked valve program. This program ensures control of the valves locked status through the Locked Valve Verification Checklist 11867-1,2 and Shift Supervisors administrative control of locking and unlocking of the valves per Control of Safety Related Locked Valves, 10019-C.

All valves required for system operability are locked, no surveillance is required. The valves not locked are minor system valves which do not effect operability.

VEGP Documentation

Procedure 11715-1/2 CCW Alignment Procedure

Training Department Comments on OSTI

NRC Concern

Repeat backs and communications were different between shifts. (In one instance the BOP had to request a repeat back from the USS to establish closed loop communications)

VEGP Position

Communications is an area that is stressed in both simulator training and evaluation. During this segment of PEO continuing training a listening course is being taught. There is a Management Observation on the control room that addresses communications. Communications is an area that requires constant attention and feedback.

(Comment on observation of differences between shifts and adequacy of "lowest level" of performance) QPS

Additional facts about PEO Rounds Training:

- 1 Contract training instructors rather than qualified Ops Dept SROs were doing evaluation due to SRO shortage.
- 2 The PEOs were given direction to conduct the rounds with a qualified PEO and get the qualified PEO to sign the rounds sheet. This was done due because it was felt that a qualified PEO had a better feel for conducting the rounds than the instructor. Few PEOs fully complied with this direction.
- 3 All other evaluations were directly observed by the instructor.
- 4 The instructors observed that each rounds sheet had been signed off and asked the trainee if they had any questions or problems. The instructors thought the trainees had gone with a qualified PEO.

SHIFT EXPERIENCE
J. E. Swartzwelder

NRC Concern

Backshift operators are relatively inexperienced.

NRC Documentation

Unknown

VEGP Position

The collective bargaining agreement covering union employees does result in an imbalance in experience on shift with less experienced personnel on night shifts. However, the personnel are fully qualified for their assignments.

VEGP Documentation

Union contract - shift picks

PLANT EQUIPMENT OPERATOR MORALE

NRC Concern

Plant Equipment Operators (PEOs) complained to the NRC Inspector of low morale due to lack of advancement opportunity.

NRC Documentation

Unknown

VEGP Position

The Operations organization is filled with ex-operators at all levels up to Shift Superintendent. In addition, two Reactor Operators recently accepted promotions/transfers to other departments and Assistant Plant Operators are interviewing with other departments.

The opportunities are there, but may not appear fast enough to the PEO's. Promotion is expected to slow down as the plant staff stabilizes. We intend to promote personnel to maintain a mixture of ex-operators and engineers in supervision. We intend to encourage participation in the ATI degree program to provide a path for ex-operators to progress into management.

VEGP Documentation

None

SHIFT COMMUNICATIONS

NRC Concern

1. Shift briefings are not heard by all personnel due to room crowding/overflow and noise.
2. Safety meetings are not covered in Operations shift briefs as planned.

NRC Documentation

Unknown

VEGP Position

1. We intend to increase management observation of shift briefings and consider modifications of the facility to improve briefing audibility.
2. We intend to increase safety meetings in shift briefs.

II ANALYZER OPERATION FOLLOWING SI

NRC QUESTION

Are the analyzers placed in service 30 minutes after a safety injection?

Requirement: NUREG 0737 IIF1 Attachment 6
TMI requirement

Provide station position relative to NUREG 0737 also provide proof of implementation.

NRC has looked the following places:

19000-C

19251-C

Loss of primary & secondary coolant 19010-C

Reference SER 6-4

VEGP POSITION

Procedure 19010-C (Loss of Primary or Secondary Coolant) step 12 currently addresses obtaining containment H2 samples following an SI. Procedure 19251-C (Response to High Containment Pressure) step 7 currently addresses obtaining containment H2 samples with elevated containment pressure (Red or orange paths on CSFSTs). VEGP intends to comply with NUREG 0737 relative to placing the H2 analyzers in service for these purposes.

However, the current language and procedure order may not meet the 30 minute in service requirement of NUREG 0737. We intend to revise our Emergency Operating Procedure to improve the timeliness of this action.

Chilling Affect / Intimidation of PRB Members

NRC Concern

Intimidation of PRB members.

NRC Position

The presence and comments of the Project General Manager in the PRB meeting has affected the voting some of members. This was a new item identified during the 08/17/90 NRC exit.

VEGP Position

While this may be a recently identified item with the special NRC Operations Safety Team Inspection, it was previously identified to the Quality Concern Program. It's documented as part of 90V0015. The investigation consisted of interviewing the voting members of PRB meeting 90-15. During the interviews one individual did expressed some, hesitancy of being "true and candid" because of Bockholds presence. This was later addressed by Bockhold to all PRB members in one of their meetings. He reinforced the commitment of their independence and said that neither he or anyone else should ever influence someone's vote...that if any of the members ever felt they were incapable of functioning freely and independently, they should be excused and assign someone else this responsibility.

As a result of renewed interest in this subject a new inquiry was made. This time members (25 of 27 were contacted, two were unavailable), both voting and non-voting, were questioned on their opinion of intimidation. Each was afforded the protection of confidentiality and briefed on the history of the allegation.

This investigation found no evidence of persuasion by presence, intimidation or coercion by the Plant Manager toward PRB members. It's believed that any evidence of this allegation pertained strictly to the issue previously identified in quality concern 90V0015.

Quality Concern Program

NRC CONCERN

1. At the exit the NRC expressed a concern about the independence of investigations performed on issues reported to the Quality Concern Program.
2. The NRC felt there was a compromise of confidentiality within the Quality Concern Program by having employees other than its own performing exit interviews.

NRC Position

1. After reviewing procedure 00015 and discussions with QCP members, the NRC questioned our method of investigating concerns. They disagree with assigning investigations to department managers who are directly associated with the allegation. This method of business is perceived by them as conflicting and unethical.
2. In discussions with the NRC they inquired into the confidentiality of exit interviews when conducted by individuals other than representatives of the Quality Concern Program. They felt that a potential exists for a breach and that business conducted in this fashion did not afford the submitter total confidentiality.

VEGP Position

1. We agree that the assignment of investigations to involved parties is not ethical. To protect against this practice the QCP Coordinator considers this when assigning an investigator. However, it has always been our practice to use site resources in these investigations. This arrangement was conceived primarily because of the knowledge and understanding that a department manager would have in the subject matter. Unless directly involved in the allegation, these managers are not perceived as having biased opinions or conflict.

As recognized in the program's developmental stages, a weakness may exist if the sole resolution of concerns was dependent upon departmental input. Because of this one of the primary responsibilities of the QCP coordinator is to assure independence. So that he can function in this capacity he reports to no department other than Plant Manager (reference procedure, 00015, section 4.4.2). Evidence of the QCP coordinators responsibility toward independence is found in procedure 00015, sections 3.2.d & j, 4.5.4.1.

If the QCP coordinator is doubtful of independence, as an alternative investigations can be assigned to someone from off site. Many examples of this can be found in past concerns.

As a final step in the assurance of independence, submitters of quality concerns are contacted for closure. Steps for closure with the submitter is found in section 4.6 of the QCP procedure. This is done not as a convenience to the submitter, but primarily as a check to the program for concern coverage (i.e., thoroughness and accuracy).

2. To eliminate this issue the concern program would have to employ personnel around the clock. As an alternative we have elected to train those conducting QCP exits on the subject of confidentiality. Currently there is only a very small select group of individuals assisting in this capacity. This has been the method of business for several years and to date has not posed any problems. Aside from this upon entry on site each individual is introduced to the Quality Concern Program and the various ways of which they may submit concerns. Should there be a problem of confidentiality upon exiting the site, they can always call the QCP representative at their leisure.

Conflicting Statements

NRC Concern

"Conflicting information from cognizant managers and operators on several occasions."

NRC Position

In the exit the NRC reported several instances of conflicting information. Areas of conflict were identified as being in:

- 1 Cont. Integrity Hydrogen Monitor Valve Opened
- 2 Snubber Reduction / LCO Action Statement
- 3 Reportability Requirements
- 4 Required or Anticipated Actions With Tech. Spec. 3.0.3.

Details of Research

In an attempt to understand the NRC's position the Quality Concern Coordinator was requested to question involved individuals. The following ^{is} the facts as determined through these interviews.

- 1 To assess this issue Dean Gustafson and Jim Swartzwelder were interviewed.

Gustafson reported that his involvement in this matter did not begin until the second week. Prior to this Swartzwelder was speaking with the NRC. His (Gustafson) only involvement during this time was the supplying of information to Swartzwelder. Swartzwelder wanted to know:

- 1 \ How do we test these monitors?
- 2 Were they included in the ILRT test?

In the second week of their review he began speaking to NRC inspector, Morris Branch. Branch asked very specific questions relative to the hydrogen monitors (ref. previous response). At this time Gustafson said there was not an exchange of information, he merely received Branch's questions and made sure he understood his issues. These issues and our response was later reviewed with Branch in detail by both Gustafson and Swartzwelder two days prior to the exit. During this time several questions were asked by Branch of which Jeff Davis was brought in and answered. This summarizes Gustafsons involvement, at no time was he aware of any controversial statements between himself and Swartzwelder. He felt if there was a problem that it was before his involvement.

In the interview with Swartzwelder he agreed with Gustafson in that he was not involved and that any comment by the NRC was in reference to their initial investigation. He believes that the confusion was started when a shift supervisor during the initial tour of the control room informed Morris Branch that the containment hydrogen monitor isolation valve received a containment isolation phase A signal. Later on there was a discussion between a shift superintendent and Branch on this same issue. At this time the superintendent said that regardless of whether they get a signal or not the system had been LLRTed to design accident pressure. It's Swartzwelders belief that either the shift superintendent accidentally said ILRT or that Branch understood ILRT.

Another confusing issue was that whether the hydrogen monitors are or are not, containment isolation valves. Swartzwelder told them that they were in the list of containment isolation valves because they are valves that are physically located in the given system nearest the containment. However, he was also told that they did not receive containment isolation signal and that the system was designed to withstand accident pressure. Swartzwelder is not sure where the confusion came but its thought that it was sometime during this discussion.

Date: August 22, 1990
Time: 1300

While Containment Cooler is Inoperable DG1A
is Rendered Inoperable

NRC Concern:

The NRC reviewed the event that made the Diesel Generator 1A inoperable while a containment cooler on "B" Train was inoperable for application to Tech Spec 3.0.3. Their review concluded that it was appropriate not to enter Tech Spec 3.0.3 when the DG1A was discovered inoperable on 6-20-90 at 0121 CDT since the LCO for the "B" Train containment cooler had been exited at 1415 CDT on 6/19/90 even though the diesel had been inoperable since the installation of the tape on 6/18/90.

NRC Documentation:

LER 90-014

VEGP Position:

We concur that we are not required to back date entry into Tech Spec 3.0.3 for this or similiar situations.

VEGP Documentation:

LER 90-014