	NUCLEAR REGULATORY COMMISSION
	I - MOSION (101) Docker No. 30 42 9100 Units 1 & 2
	Staff Applicant Intervenor Other
	Date 18/6/95 Witness HCHDA
	SA FRUDADY
1 2	INT. EXH. 118 A GPC 45 001 20 P5:12 TAPE 24A
3 4	Date: 3-30-90
5	Location: Engineering Conference Room OFFICE OF SECRETARY Service Building - 3rd FloorDOCKETING & SERVICE
67	BRANCH
8 9	VOICE: They are preparing the diesel 1A for the bubble
10	test (Inaudible).
11	VOICE: They took all the temp switches out last night,
12	cal'd them, and they found one switch, high tube oil temperature,
13	had a little leak around the cover and O-ring and they also
14	mentioned that the switch was appearing to stick.
15	VOICE: I couldn't find out (Inaudible). Is this in
16	our favor or [Inaudible].
17	HORTON: You can't say for a fact that it is. You've
18	got a number of pneumatic lines with .006 inch orifices that are
19	passing 60 pound pressure through that orifice. And its, its
20	anybody's guess as to whether or not this leak is sufficient to
21	have drug down the pressure low enough to have caused the P3
22	trip. I think it is, based on the faith I have in the I&C tech
23	this morning, his description of the leak being significant
24	enough to where "snoop" would not even bubble. It was just
25	blowing back in his face.
26	WILLIAMS: Blowing all That's a hell of a
27	HORTON: That's enough to allow a .006 orifice to not
28	provide enough pressure to keep a minimum of 45 pounds in the
29	line. But yeah, I think we lucked out on the UV test yesterday
30	morning. A number of things, see they tightened up some lines
31	between your UV yesterday and the original condition. We did not
	9512280233 951006

PDR ADOCK 05000424

*

1	have the original	conditions as	far	as the	pneumatic	lines	goes
2	yesterday when we	did the UV.					
3							

6 (penland & \wpdocs\tlp\license pro\tapes.int\24A-ex.ll8

.