

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Callaway Plant Unit 1 DOCKET NUMBER (2) 0 5 0 0 0 4 8 3 1 OF 0 2

TITLE (4) Unplanned Reactor Trip and Feedwater Isolation Signal

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0	9	23	84	84	042	0	20	31	48	5	0 5 0 0 0

OPERATING MODE (9)	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)									
3	20.402(b)		20.405(c)		X		50.73(a)(2)(iv)		73.71(b)	
POWER LEVEL (10) 0.00	20.405(a)(1)(i)		50.36(c)(1)				50.73(a)(2)(v)		73.71(c)	
	20.405(a)(1)(ii)		50.36(c)(2)				50.73(a)(2)(vi)		OTHER (Specify in Abstract below and in Text, NRC Form 366A)	
	20.405(a)(1)(iii)		50.73(a)(2)(i)				50.73(a)(2)(vii)(A)			
	20.405(a)(1)(iv)		50.73(a)(2)(ii)				50.73(a)(2)(vii)(B)			
	20.405(a)(1)(v)		50.73(a)(2)(iii)				50.73(a)(2)(ix)			

LICENSEE CONTACT FOR THIS LER (12)
NAME Charles D. Naslund - Superintendent, I&C TELEPHONE NUMBER 314 676 1815010

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)									
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDs	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDs

SUPPLEMENTAL REPORT EXPECTED (14)
YES (If yes, complete EXPECTED SUBMISSION DATE) X NO
EXPECTED SUBMISSION DATE (15) MONTH DAY YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 9/23/84 at 0805 CDT an unplanned reactor trip and feedwater isolation signal (FWIS) occurred during testing of Power Range Nuclear Instrumentation. The incident occurred prior to initial criticality with the plant in Mode 3 at 0% power.

Technicians were performing a surveillance test on Power Range channel SE-N43. During the test, the high voltage and detector input cables were incorrectly removed from channel SE-N44 instead of SE-N43. When the cables to SE-N44 were reconnected a spike was generated which caused a reactor trip and FWIS.

All control rods and shutdown banks were verified to be fully inserted into the core, SE-N43 and SE-N44 were returned to normal and by 0825 the FWIS was reset.

Corrective actions include changing the Power Range cabinet locks to be specific for each channel. Also, supervisory personnel have met with the technician and stressed that the utmost of caution must be utilized when testing to avoid inadvertently upsetting plant equipment.

No radiation above normal background was present and this event has in no way affected the health or safety of the public.

8503250407 850314
PDR ADDOCK 05000483
S PDR

IE 22 111

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104
EXPIRES: 8/31/85

FACILITY NAME (1)

Callaway Plant Unit 1

DOCKET NUMBER (2)

0500048384

LER NUMBER (6)

YEAR SEQUENTIAL REVISION

NUMBER NUMBER

84 042 02

PAGE (3)

02 OF 02

TEXT (If more space is required, use additional NRC Form 386A's) (17)

On 9/23/84 at 0805 CDT an unplanned reactor trip and feedwater isolation signal (FWIS) occurred while Instrumentation and Control (I&C) technicians were testing Power Range Nuclear Instrumentation. The incident occurred prior to initial criticality with the plant in Mode 3, Hot Standby, at 0% power.

I&C technicians were performing a channel calibration surveillance test on Power Range channel SE-N43. As part of the procedure, SE-N43 is placed in test, its high flux rate bystates tripped, and the high voltage and detector input cables are disconnected. However, a technician mistakenly removed the high voltage and detector input cables to channel SE-N44. When the technician reconnected the cables to SE-N44 a spike was generated which satisfied the two of four coincidence logic for a Power Range High Flux Rate Reactor Trip. The reactor trip caused a FWIS.

Also at the time of the event an Engineering Test Procedure, Rod Drop Time Measurement (Hot, No Flow) was in effect. Shutdown Bank "A" was withdrawn for the test and was tripped as a result of the reactor trip signal.

All control rods and shutdown banks were verified to be fully inserted into the core, SE-N43 and SE-N44 were returned to normal and by 0825 the FWIS was reset.

Corrective actions have included extending individualized key and lock controls to protection system cabinets. Prior to this event any of the Power Range cabinets could be opened with one key thus increasing the possibility of accessing the wrong Power Range channel. These key and lock controls were initiated 10/1/84 and completed 3/14/85. Also, I&C supervisors have reviewed and discussed this incident with the technician. The supervisors stressed that the utmost of caution must be utilized when performing tests to avoid inadvertently upsetting plant equipment.

No radiation above normal background was present and this event has in no way affected the health or safety of the public.

Previous occurrences: none

UNION ELECTRIC COMPANY
CALLAWAY PLANT

MAILING ADDRESS:
P. O. BOX 620
FULTON, MO. 65251

March 14, 1985


U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

ULNRC-1057

Gentlemen:

DOCKET NUMBER 50-483
CALLAWAY PLANT UNIT 1
FACILITY OPERATING LICENSE NPF-30
LICENSEE EVENT REPORT 84-042-02
UNPLANNED REACTOR TRIP WITH FEEDWATER ISOLATION SIGNAL

The enclosed Licensee Event Report is submitted to amend
the corrective action implementation schedule for LER 84-042-01
transmitted via ULNRC-968, dated November 8, 1984.


S. E. Miltenberger
Manager, Callaway Plant

WRR/RCW/drs
Enclosure

cc: Distribution attached

IE22
1/1

cc distribution for ULNRC-1057

Mr. James G. Keppler
Regional Administrator
Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

American Nuclear Insurers
c/o Dottie Sherman, Library
The Exchange Suite 245
270 Farmington Avenue
Farmington, CT 06032

Records Center
Institute of Nuclear Power Operations
Suite 1500
1100 Circle 75 Parkway
Atlanta, GA 30339

NRC Resident Inspector
Missouri Public Service Commission
D. F. Schnell
J. F. McLaughlin
J. E. Davis (Z40LER)
D. W. Capone/R. P. Wendling
F. D. Field
R. L. Powers
A. C. Passwater/D. E. Shafer/D. J. Walker
G. A. Hughes
W. R. Robinson (QA Record)
J. M. Price
R. A. McAleenan
L. K. Robertson (470) (NSRB)
Merlin Williams, Wolf Creek
SEM Chrono
3456-0021.6
3456-0260
Z40ULNRC
G56.37
N. Date