P-63)	-				LIC	ENSE	E EVEN	NT RE	PORT (	LER)			0 0000 NO		
	ISADE	NIIC	T.FAR	PT.ANT							0   5   0   0		21515	1 OF	01
TITLE (4)												1			
		-	Set L	ess Than			_	-	ons Li	THE REAL PROPERTY AND ADDRESS OF THE PARTY O					
EVENT DATE (S) LER NUMBER (S)			HEFORT DATE 177				FACILITY NA	FACILITIES INVO			(4)				
MONTH	DAY	PASY	YEAR	NUMBER	NUMBER	NEVERN MONTH DAY YEAR			N/			0 15 10 10 10 1 1			
1 1 1	019	3   4	8 1 4	0 2 3	012	0 3	20	8   5	N/			0 15	1010	101	1 1
OPE	RATING		-	AT IS SUBMITTE	D PURSUANT	TO THE R	EQUIREME	NTS OF 10	CFR & /C	hack one or more	of the following) (1	1)			
Constant O TO TO		N O 1 O	20.46	20.406(a)(1)(i) 20.406(a)(1)(ii) 20.406(a)(1)(iii) 20.406(a)(1)(iii)			80.38(a)(1) X 80.38(a)(2) X		80.73(a)(2)(iv) X 90.73(a)(2)(v) X 90.73(a)(2)(viii) 80.73(a)(2)(viii)(A)			73.71(a)  OTHER (Specify in Abstract before and in Text, NRC Form 306.4)			
			-	15 (a) (1) (iv) 16 (a) (1) (v)	X	80.736 80.736		in i		90.73(a)(2)(via)( 80.73(a)(2)(x)	•)				
					- 1	CEMBEE	CONTACT	FOR THIS	LER (12)			75: 500	GNE NUM		
Das	vid W	ROF	ers:	Technica	l Engin	eer:	Palis	ades			6 1 11 6	Π.		18 19	11.13
-		1.00				COLUMN TO SERVICE STATE OF THE PARTY OF THE	THE RESERVE OF THE PARTY OF THE	-	DESCRIBE	O IN THIS REPO		1110		10 12	
CAUSE	SYSTEM	сомго	NENT	MANUPAC TURER	TO NPROS			CAUSE	SYSTEM	COMPONENT	MANUFAC TURER		MTABLE NPRDS		
				111						111	111				
		1.1	1	111						111	111				
				SUPPLEM	ENTAL REPORT	EXPECT	ED (14)				expec	180	MONTH	DAY	YEA
							_				BLIBMISE	ION			

On November 9, 1984, with the Plant in cold shutdown, the Reactor Protection System (RPS) low-flow-trip for four (4) primary coolant pumps (PCP) operation was determined to be set incorrectly. On December 13, 1984, evaluation of the four-pump trip setting revealed that the RPS low flow trip for three (3) PCP operation was also not set correctly. In addition, the evaluation has shown that the three-pump setpoint is calculated by incorrect methods. As a result, a Technical Specifications safety system setpoint limit was exceeded during previous plant operation.

The incorrect trip settings occurred when a low-flow-trip calibration procedure was not performed and resulted in incorrect values in an RPS surveillance procedure. The incorrect calculation method originated with the controlling procedure and resulted from a misunderstanding of primary coolant flow characteristics.

The calibration procedure was performed and the correct four-pump trip values provided for the surveillance procedure. The calibration procedure requirements will be included in the RPS surveillance procedure. The three-pump low-flow trip has been reset and will result in a trip for any three-pump flow configuration. A corrected three-pump trip calculation will be determined and incorporated in procedures. The trip will be adjusted to allow three-pump operation. Special test procedures will be reviewed and appropriate scheduling provided.

B503280775 B50320 FDR ADDCK 05000255

TELL

. LICENSEE EVEN	T REPORT (LER) TEXT CONTIN	NUATION	EXPIRES M	OMB NO 3150-0104
FACILITY NAME (1)	DOCKET NUMBER (2)	LE	A NUMBER (6)	PAGE (3)
		YEAR	NUMBER NUMBER	
PALISADES NUCIEAR PLANT	0  5  0  0  0  2  5	5814-	0 2 3 - 0 1 2	0 2 OF 0 14

U.S NUCLEAR REGULATORY COMMISSIO

On November 9. 1984, with the plant in cold shutdown, the Reactor Protection System [JC] low primary coolant flow trip was determined to be set incorrectly for four primary coolant pumps [AB;P] operation. Technical Specifications Table 2.3.1, Item 2, requires the four-pump low-flow-trip setpoint to be greater than or equal to 95 percent of the nominal four-pump primary coolant

flow. During the operating period from July 1984 to September 1984, the trip setpoint did not meet this criteria.

On December 13, 1984, subsequent engineering evaluation revealed that the Reactor Protection System low primary coolant flow trip for three primary coolant pump operation was also set incorrectly. In addition, it was determined that the procedural method for calculating the trip setpoint results in a value that does not meet Technical Specifications limits for three-pump operation. Technical Specifications Table 2.3.1, Item 2, requires the three-pump low-flow trip setpoint to be greater than or equal to 71 percent of the nominal four-pump primary coolant flow. The exact date of occurrence of the calculation error cannot be determined, but is believed to have occurred in the early 1970's. In recent operation, a three-pump condition occurred on September 16, 1984 (reference Licensee Event Report 84-021, dated October 31, 1984), as a result of a primary coolant pump seal [AB; SEAL] failure.

The Reactor Protection System (RPS) low-flow-trip consists of four independent channels. Each channel utilizes a separate set of differential pressure (dp) detectors [JC;PDT]. Flow in each of the four coolant loops is determined by a measurement of pressure drop from inlet to outlet of the steam generators [AB;SG]. The total flow through the reactor core is measured by summing the loop pressure drops across the steam generators and correlating the pressure sum with the pump calibration flow curves. A reactor trip is initiated by two-out-of-four coincidence logic from any of the four independent measuring channels when the flow function falls below a preselected value. Pretrip alarms are initiated if the coolant flow function approaches the minimum required for reactor operation at the corresponding power level. The low-flow-trip setpoint is manually changed for the selected pump configuration by means of a setpoint selector switch.

Test Procedure T-69, "RPS Low Flow Trip Calibration", is used to determine the correlation between steam generator dp and total coolant flow. T-69 also determines the correct dp values for the low-flow-trip. These values are then used in Technical Specifications Surveillance Procedure MI-2, "Reactor Protection Trip Units", to set or verify the low-flow-trip such that it occurs at the setpoint calculated in T-69. Test Procedure T-69 is performed to incorporate changes in steam generator dp that do not correlate to flow changes.

NAC Form MAA

MRC	-	-	264A	
10.81		-	-	

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S NUCLEAR REGULATORY COMMISSIO APPROVED OMB NO 3150-0104 EXPIRES 8/31/85

PACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)					PAGE (3	(3)	
			YEAR		SEQUENTIAL NUMBER	NUMBER			
PALISADES NUCLEAR PLANT	0  5  0  0  0  2   5	15	8 14	_	0   2   3	-0 12	0   3 OF	0 4	

TEXT IN more apace is required, use additional NRC Form 386A's) (17)

Test Procedure T-69 was required to be performed in December 1981 during the plant startup following the 1981 refueling outage. A scheduling error by the plant support staff omitted this test. In addition, Surveillance Procedure MI-2 did not reference T-69 to ensure the correct trip values were available. As a result, the low primary coolant flow trip settings were not updated to account for steam generator do changes that resulted from tube plugging.

An analysis was performed to determine the operating periods affected by the error in the low-flow-trip setpoint. The analysis has shown that the four-pump low-flow trip setpoint was within Technical Specifications limits, except for the period of operation from July 1984 to September 1984. During the period, all four low-flow-trip setpoints were found to be less than the required minimum value of 95 percent. Using conservative calculations, the greatest error was determined to have been a setpoint of 94.37 percent. It is estimated, based on the extrapolation of the current safety analysis, that the consequences of a four-pump loss of flow would still be acceptable (ie, above minimum departure from nucleate boiling ratio limit), even assuming a trip at 92.37 percent (94.37 - 2 percent uncertainty).

Continued evaluation of the low-flow-trip revealed a similar setpoint error occurred in the three-pump low-flow-trip, as a result of failing to perform Test Procedure T-69. Although the Technical Specifications limit for the three-pump low-flow-trip setpoint was not met, three pump operation has occurred only once in recent operation. Specifically, on September 16, 1984, a primary coolant pump (PCP) was tripped concurrent with plant shutdown, in response to a PCP seal failure.

The analysis performed to evaluate the three-pump low-flow-trip setpoint resulted in additional review of Test Procedure T-69. These reviews identified that the calculational method specified by T-69 to determine the three-pump low-flow-trip setting would result in a trip value that would not meet the Technical Specifications limit for three-pump operation.

T-69 specifies that the three-pump trip be set at 90 percent of the three-pump measured flow. Technical Specifications Table 2.3.1 requires the three-pump low-flow-trip to occur at greater than or equal to 71 percent of the four-pump measured flow. In correlating the three-pump measured flow to the four-pump measured flow, the presence of reversed loop flow in the idle loop was not considered. Also, the steam generator dp detectors provide a positive output for both normal forward flow or reversed loop flow. Neither of these effects were considered when Test Procedure T-69 was originated in 1974. However, calculations using actual three-pump loop flow measurements, based on PCP dp and pump flow curve: taken in 1975, indicate that the low-flow-trip would have been set 1.8 percent below the Technical Specifications limit using Test Procedure T-69. A thermal margin analysis has determined that the minumum departure from nucleate boiling ratio limit would be satisfied during a three-pump loss of flow with the RPS trip set with this error. In addition, Technical Specification 3.1.1(c) requires the Plant to be in hot standby within 24 hours with one or more pumps out of service. Three-pump operation is prevented from being a prolonged operating condition by this requirement. Any reliance placed on the three-pump low-flow-trip would have been limited in duration.

я		_				m	-		-	
и	m	м	€.	,	81	m	-	14	•	
8	-									

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMS NO 3150-0104 EXPIRES 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6)					PAGE (3)		
		YEAR	F	SEQUENTIAL		REVISION				
PALISADES NUCLEAR PLANT	0  5   0   0   0   2   5	5 814	1-	0 2 1 3	-	012	01	L OF	014	

Test Procedure T-69 was performed on November 15, 1984, during plant startup. The correct four-pump low-flow-trip setpoints have been established. The three-pump low-flow-trip setpoints have been adjusted to cause a trip if the setpoint selector switch is placed in the three-pump position. Three-pump operation is thereby precluded until all concerns relating to T-69 calculations have been resolved.

Surveillance Procedure MI-2 will be revised to include requirements to ensure Test Procedure T-69 is performed as required, and that the correct trip values are available and referenced. A corrected calculation method will be determined for the three-pump low-flow-trip. Procedures will be revised to include the corrected calculation. The three-pump low-flow-trip will be adjusted to allow three-pump operation following determination of the proper setpoint. All special test procedures will be reviewed to determine the tests that will require future performance. Additional action will be provided to ensure performance of the tests identified by the review.

As noted, the four-pump low-flow-trip setpoint error was identified on November 9, 1984. The details of this occurrence were reported in Revision 0 to this LER on December 10, 1984. During evaluation of the four-pump low-flow-trip setpoint, additional areas were identified that would require notification. Although the additional items were intitially discovered on Pecember 13, 1984, it was not until January 10, 1985 that the details were made available and the reportability determined. On January 10, 1985, notification was made to the NRC by telephone to identify these new concerns.



General Offices: 1945 West Parnall Road, Jackson, MI 49201 • (517) 788-0550

March 20, 1985

US Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

DOCKET 50-255 - LICENSE DPR-20 - PALISADES PLANT - LICENSEE EVENT REPORT 84-023, REVISION 2 - REACTOR TRIP SET LESS THAN TECHNICAL SPECIFICATION LIMIT

Licensee Event Report 84-023, Revision 2 (Reactor Trip Set Less than Technical Specification Limit) is attached. The revision provides the results of a thermal margin analysis for the incorrect three-pump low-flow-trip. This event is reportable to the NRC per 10CFR50.73(a)(2)(i),(a)(2)(ii) (a)(2)(v) and (a)(2)(vii).

Ralph R Frisch

Senior Licensing Analyst

CC Administrator, Region III, USNRC NRC Resident Inspector - Palisades

Attachment

1E22