ACILITY					cic	ENSEE EN	ENT HE	PUHI	(LER)		EXPINES - 9/	
	-								10	OCKET NUMBER	(2)	PAGE IS
		Lime	rick	Gene	rating	Stati	on-Un	it 1		0 5 0 0	0131.51	21 OF 0
		Inral	dof	icion	w in	the da	ilv ei	irvoi	illance	100		
_	NT DATE	And in case of the local division of the loc	the second s	LEA NUMBER	and the second se	ALPONT O	and the second design of the s	II vel	And in case of the local division of the loc	ACILITIES	VED (I)	
NONTH	DAY	YEAR Y	EAR	SEQUENTIAL NUMBER	ALVERN		YEAR		FACILITY NAM		DOCKET NUMBE	RISI
											0 15 10 10	1010
0	2 7	8 4 8	1 1	0 0 1	-010	Land and the state	6 84				0 15 10 10	1011
	DATING OF IN	5	20.4021		O PURBUANT	20.406(e)	EMENTS OF 1	CFR § 10	60,73(a)(2)(iv)	t the fallowing) [11	73,71(5)	
PONE			20.406	a la companya da companya d	-	60.34(a)(1)			60.73(a)(2)(v)		73,71(4)	
LEVEL (10)		o d	20.4061	*)(1)[#]		90.34(c)(2)			50.73(a)(2)(+H)			ancity in Abstract in Tass, NAC For
352			29,4061	•1(1){m}	X	60.73(+1(2)(1)			50.73(a)(2)(+iii)(A	3	3664	
			-	a){1}{]{}	-	80.73(a)(2)(#;			60.73(r)(2)(*ik)(8	•		
11.03	1.1.0.01		20.404	*){1){1}		BO.734121(11)	CT 105 T		60.73(a)(2)(a)			
AME						ICCHARTE CONTA	CI FUR THIS	CCR IIII		1	TELEPHONE NUT	MBER
							5 G 1	1.5		AREA CODE		
в.	L. (Clark,	, Sr	. Eng:	ineer,	Speci	al Pro	pject	ts	21115	84114	151011
				COMPLETE	ONE LINE FOR	EACH COMPON	ENT FAILURE	DESCAIBE	D IN THIS REPOR	1131		
CAUSE	SYSTEM	COMPONE	NT 1	TURER	REPORTABLE TO NPROS		CAUSE	SYSTEM	COMPONENT	MANUFAC TURER	REPORTABLE TO NPADS	1. · · · ·
	1	1.1		111								
	1	1.1		1.1.1	1.0.0	See Server	88 - J	1	TIT	1111		and the
				BUPPLEME	NTAL REPORT	EXPECTED (14)			and an observed and	EXPECTE	MONT	H CAY YE
										SUBMISSIC DATE IS	ON	
	On (load with (rei leve exha the omis Surv	ding ndrawn fuelin el tra aust d plant ssions veilla peilla	er 2 pr h wh hg), ansm luct t's s, c ance	cior t ile the chann itters radia Techni hannel Log S actio	34 at o init he rea hel ch ation ical S L chec ST-6-1	ctor w ecks o the fo monito pecifi ks wer 07-591 These	itica as in f the ur ref cation e peri , was revis	lity oper four fuels re no forme revisions	30 p.m. , a sin rational r scram ing area of perfo Upon di ed and ised to were fo w Commi	gle condi discha a venti ormed a iscover the Dai clarif ormally	trol r rge vo lation s requ y of t ly y thes appro	lume ired by hese e ved by
	1984	4.								IE	~ 1	

. •

1

	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION						
FACILITY NAME (1)	DOCKET NUMBER 121	1	ER NUMBER (6)		,		31
Limerick Generating Station		YEAR	SEQUENTIAL		Π		
Unit 1 TERT III mare space is required, use additional NAC Form J6(2) (17)	0 15 10 10 10 1 315 12	814-	-01011-	-0 10	012	OF	014

Description of the Event:

On October 27, 1984, at approximately 1:30 p.m. with the facility at zero percent power level during the initial core loading, a single control rod was withdrawn while in operational condition 5 (refueling). Table 4.3.1.1-1(8a) of the Technical Specifications requires that in operational condition 5, with any control rod withdrawn, a 12-hour channel check must be performed on the four scram discharge volume (SDV) level transmitters. However, channel checks to the four SDV level transmitters as required per Surveillance Test ST-6-107-591-1 'Daily Surveillance Log' were not performed on the 7 a.m. to 3 p.m. shift of October 27, 1984, because, at the time the operator took the reading and marked it "N/A", no control rods were withdrawn. Channel checks of the SDV level transmitters were performed on the prior 11 p.m. to 7 a.m. shift and the subsequent 3 p.m. to 11 p.m. shift.

In addition, Table 4.3.2.1-1(7c) of the Technical Specifications requires that the four refueling area ventilation exhaust duct radiation monitors must be channel checked every twelve hours during Core Alteration. However, this surveillance requirement was not identified in the Daily Surveillance Log ST-6-107-591-1. As a result, the channel checks for the four refueling area ventilation exhaust duct radiation monitors were not performed prior to the 3 p.m. to 11 p.m. shift of October 27, 1984.

Following the discovery of the failure to perform the channel checks of the four SDV level transmitters and the four refueling area ventilation exhaust duct radiation monitors, a temporary procedure change (TPC) was made to the daily surveillance log surveillance test ST-6-107-591-1 and channel checks were performed for both the SDV level transmitters and the refueling area ventilation exhaust duct radiation monitors during the 3 p.m. to 11 p.m. shift of October 27, 1984. Unfortunately, the format of the TPC lacked clarity and as a result, the subsequent shift misinterpreted the TPC and did not perform the channel checks of the four refueling area ventilation exhuast duct radiation monitors during the period 11 p.m. to 7 a.m. ending October 28, 1984. This omission was recognized on the 7 a.m. to 3 p.m. shift of October 28, 1984 and the refueling area ventilation exhaust duct radiation monitor channel checks were resumed at that time. The format of the TPC regarding the refueling area ventilation exhaust duct radiation monitor channel checks was subsequently improved for clarity.

IFRC Form 346A 15-831	LICENSE	E EVENT REPO	RT (LER) TEXT CONTINU	ATIO	N	U.8		PROVED O PIRES 8/3			
Timorick	Generating	Station	DOCKET NUMBER (2)		LE	A NUMBER IS	h		PAGE 131		
Unit 1						NUMBER		ALVISION		П	
			0 15 10 0 0 1 3 1 5 2	8 4	-	0 0 1	-	0 10	013	OF	0 4

Consequences of the Event:

The results of the channel checks of the four SDV level transmitters revealed a zero percent level in the SDV during the shift prior to and the shift immediately following the shift in which the SDV level transmitter channel checks were not performed. In addition, since startup activities at this time cause all control rods to be fully inserted except for friction tests of single rods, no reactor conditions could have taken place to require a scram.

The results of the channel checks of the four refueling area ventilation exhaust duct radiation monitors revealed measured quantities indicative of normal fluctuations of background radiation. Since the reactor has not been critical, only background radiation is possible in the plant at this time.

Cause of the Event:

The failure to perform the required channel checks of the SDV level transmitters was caused by a misinterpretation by operations personnel of the Surveillance Test ST-6-107-591-1 "Daily Surveillance Log".

The failure to perform the required channel checks of the refueling area ventilation exhaust radiation monitors was caused by a procedural deficiency (Surveillance Test ST-6-107-591-1 did not include this channel check) and a misinterpretation by operations personnel of the temporary procedure change to the Surveillance Test ST-6-107-591-1.

	-					18.1	
	LER NUMBER (6)				PAGE (3)		
YEAR	T	SEQUENTIAL REVISION			Π		
12 8	4-	01011	-010	014	OF	014	
		12 81 4 -	NUMBER	NUMBER NUMBER	NUMBER NUMBER		

As stated above, following discovery of the missed SDV level transmitter channel checks and the refueling area ventilation exhaust duct radiation monitor channel checks, a TPC was made to ST-6-107-591-1 during the 3 p.m. to 11 p.m. shift on October 27, 1984 to clarify the requirements of performing channel checks to the SDV level transmitters during operational condition 5. This change now requires performance of SDV level transmitter channel checks when in operational condition 5, whether or not control rods are being withdrawn.

The same TPC also added the requirements of performing channel checks to the refueling area ventilation exhaust duct radiation monitors. This latter change requires channel checking during operational conditions 4 (Cold Shutdown) and 5 (Refueling).

The modified SDV level transmitter channel check requirement and the requirement to perform refueling area ventilation exhaust duct radiation monitor channel check were formally approved by the Limerick Generating Station Plant Operational Review Committee as revision 5 to ST-6-107-591-1 on October 30, 1984. In addition, a review of the Technical Specifications against the written Surveillance Tests has been initiated.

PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

P.O. BOX 8699

PHILADE_PHIA. PA. 19101

(215) 841-4000

November 26, 1984

Docket No. 50-352

Document Control Desk U.S. Nuclear Regulatory Commission Washington, DC 20555

SUBJECT: Licensee Event Report

This LER concerns a procedural deficiency in the Daily Surveillance Log pertaining to performance of scram discharge volume level transmitter and refueling area ventilation exhaust duct radiation monitor channel checks as required by the Technical Specifications 4.3.1.1 and 4.3.2.1 respectively.

Reference:	Docket No. 50-352
Report Number:	84-001
Revision Number:	00
Event Date:	October 27, 1984
Report Date:	November 26, 1984
Facility:	Limerick Generating Stat.on
	Box A, Sanatoga, PA 19464

This LER is submitted pursuant to the requirements of 10 CFR 50.73 (a)(2)(i).

Very truly yours,

In Wellack

W. T. Ullrich Superintendent Nuclear Generation Division

cc: Dr. Thomas E. Murley, Administrator Region I, USNRC

See Attached Service List

cc: Judge Helen F. Hoyt Judge Jerry Harbour Judge Richard F. Cole Judge Christine N. Kohl Judge Gary J. Edles Judge Reginald L. Gotchy Troy B. Conner, Jr., Esq. Ann P. Hodgdon, Esq. Mr. Frank R. Romano Mr. Robert L. Anthony Ms. Phyllis Zitner Charles W. Elliott, Esq. Zori G. Ferkin, Esq. Mr. Thomas Gerusky Director, Penna. Emergency Management Agency Angus Love, Esq. David Wersan, Esq. Robert J. Sugarman, Esq. Martha W. Bush, Esq. Spence W. Perry, Esq. Jay M. Gutierrez, Esq. Atomic Safety & Licensing Appeal Board Atomic Safety & Licensing Board Panel Docket & Service Section James Wiggins Timothy R. S. Campbell