																					P	WO	28-1	06-01	-01
9-83)	348									LIC	ENSE	EEVE	NT RE	PORT	(LER)			U	A E	CLEA PPRO XPIRI	A REC IVED C	OULATI	DRY COM 3150-0	MISBION
			-			-	-		-							-	Ip	OCKE	TNU	MRER	(2)			PA	GE (3)
ACILITY	NAME (SI	JRR	Y PO	WE	R	STAT	10	N, U	NIT 2						0	15	10	10	10	2 1	811	1 0	F o la
ITLE (4)			PE	AC	TOR	TR	IP	(L(DAD	SHE	DDING	ACTU	ATED)								_				1-1-
EVE	NT DATE	(6)	-			LER	NUN	BER	6)		RE	PORT DA	TE (7)			01	HER F	ACILI	TIES	INVOI	VED	(8)			
MONTH	DAY	YE	TEAR YEAR SEQUENTIAL					П		MONTH	DAY	YEAR	FACILITY NAMES					DOCKET NUMBER(S)							
		-			-	+	-			AD WREN											0	51	0 1 0	101	1.1
1 0	2 9	8	4	8	4-	0	1	5	-	00	1 1	2 8	84								0	510	010	101	1.1
085	PATING	-		THIS	REPOR	TIS	SUB	MITTE	D PUP	SUANT	TO THE R	EQUIREN	ENTS OF 1	CFR \$: (Check on		more of	the f	ilow	ing) (11	1)		-		
MODE (9) N				20.402	(b)	-				20.405	e)		11	50.73	(*)(2)	(iv)					73.7	1(b)			
POWER 20.406(a)(1)(i)					50.38ia	1(1)			50.73	(a)(2)	(v)					73.7	1(e)								
(10)	1	0	0	20.405(a)(1)(ii) 50.36(c)(2) 50.73(a)((*)(2)	(vii)			- 34		OTH	ER ISP	city in At	atract						
					20.405	(a)(1)	(111)				50.73ta)(2)(i)			50.73	(s)(2)	(viii)(A).		- 1		366.4	V		
					20.405	(a)(1)	(iv)				60.73(a)(2)(ii)			50.73	(*)(2)	(viii)(à			11					
	<u> </u>				20.406	(#)(1)	(y)				50.73ie)(2)(iii)			50.73	(.)(2)	(x)								
											LICENSEE	CONTAC	T FOP	LER (12)											
VAME																		-		0.05	TELE	PHON	E NUM	BER	
																			EAL	.002					
1	R. F.	S	AUP	DE	RS,	ST	AT	ION	MAI	NAGE	R							8	10	4	3	5	7 -	3 1	8 4
	-	-	_		-	0	OM	LETE	ONEL	INE FOR	R EACH CO	OMPONEN	TFAILURE	DESCRIBE	D IN TH	415 P	EPORT	(13)			-				······
CAUSE	SYSTEM	c	OMP	DNEN	τ	MAN	REP	e.	REPO	NPRDS			CAUSE	SYSTEM	COM	COMPONENT		MANUFAC TURER			REPORTABLE TO NPRDS				
E	IG		1	R	i W	11	1	2 10		Y			E	AB	1	1	P	w	1	210	,	Y			
E	BA		R		YW	1	1	2 0		Y				1	1	1		1	1	1					
						-	SUP	PLEME	NTAL	REPOR	TEXPECT	ED (14)					-	-			-		NONTH	DAY	YEAR
																			SUE	MISSI	ON	F			
YE	5 ilt yes i	compi	ece E	XPEC	TED SU	81115	SION	DATE	0			NO						12.5	0,	12 11	21		1	1	11
ABSTRA	CT (Limit	ro 14	CD 80		# #pon	un im	#t#/y	titteen	single	space typ	written in	nes/ (16)										-		Annes and	

On October 29, 1984, unit 1 was in refueling shutdown and unit 2 was at full power. The "D" transfer bus was deenergized for unit 1 breaker testing being conducted by Control Operations. The load shed selector switch was in enable with testing in progress. As a result of this testing, load shedding was initiated. The unit 2 "A" main feedpump (2-FW-P-1A) tripped as a result of load shedding leading to a low steam generator level and a reactor trip.

The main contributing factor to this event was inadequate procedures. These procedure problems have been or are being corrected.

IE22

8412060207 841128 PDR ADDCK 05000281 S PDR

EPORT (LER) TEXT CONTIN	UATIO	N		U.S	API EX	PROVED C	GULAT	081	50-0	4MISSION
DOCKET NUMBER (2)	1	LF	R NU	MBER (6	0			PA	GE (3)
	YEAR		SEQU	UENTIAL		NUMBER				
0 5 0 0 0 2 8 1	8 4	_	0	1 5	-	0 0	0	2	OF	0 4
	EPORT (LER) TEXT CONTIN	EPORT (LER) TEXT CONTINUATIO	EPORT (LER) TEXT CONTINUATION	EPORT (LER) TEXT CONTINUATION	US EPORT (LER) TEXT CONTINUATION DOCKET NUMBER (2) LER NUMBER (2) VEAR SEQUENTIAL VEAR SEQUENTIAL NUMBER (2) 0 5 0 0 0 2 8 1 8 4 - 0 1 5	U.S. NUC EPORT (LER) TEXT CONTINUATION AP EX DOCKET NUMBER (2) LER NUMBER (6) VEAR SEQUENTIAL O 0 5 0 5 0 5 0 2 8 4 0 1 5 - 0 1 5 - 0 5 0 0 5 0 0 5 0 0 0 0 0 0 0 0 0 0	EPORT (LER) TEXT CONTINUATION APPROVED C EXPIRES 8/2 DOCKET NUMBER (2) LER NUMBER (6) VEAR SEQUENTIAL NUMBER REVISION NUMBER 0 5 0 0 2 8 1 8 4 0 1 5 0 0	U.S. NUCLEAR REGULAT APPROVED OMB NO EXPIRES 8/31/85 DOCKET NUMBER (2) DOCKET NUMBER (2) U.S. NUCLEAR REGULAT APPROVED OMB NO EXPIRES 8/31/85 U.S. NUMBER (3) U.S. NUCLEAR REGULAT APPROVED OMB NO EXPIRES 8/31/85 U.S. NUMBER (3) U.S. NUMBER (4) U.S. NUMBER (6) U.S. NUMBER (6)	EPORT (LER) TEXT CONTINUATION U.S. NUCLEAR REGULATORY APPROVED OMB NO. 31 EXPIRES 8/31/85 DOCKET NUMBER (2) LER NUMBER (6) YEAR SEQUENTIAL NUMBER (2) VEAR SEQUENTIAL NUMBER 0 5 0	EPORT (LER) TEXT CONTINUATION U.S. NUCLEAR REGULATORY COMPROVED OMB NO. 3150-00 EXPIRES 8/31/85 DOCKET NUMBER (2) LER NUMBER (6) PAGE (VEAR 0 5 0 0 2 8 1 8 4 0 1 5 0 0 2 0

1. Description of the Event

On October 29, 1984, unit 1 was in refueling shutdown and unit 2 was at full power. The "D" transfer bus (See figure 1) was deenergized for unit 1 breaker testing being conducted by Control Operations. The load shed selector switch was in enable with testing in progress. As a result of this testing, load shedding was initiated. The unit 2 "A" main feedpump (2-EW-P-1A) tripped as a result of load shedding leading to a low steam generator level and a reactor trip.

POW 28-06-01-01

The following secondary events also occurred on unit 2:

During the trip, control rod M-10 appeared to momentarily stick at 30 steps.

Nuclear Instrumentation channel NI-32 failed to automatically reinstate, and its initial response after reinstatement was abnormal.

Relay AFP-YB failed which caused the following:

SOV-MS-202B	(Steam	Supply f	for Aux.	Feed Pump)	-	Failed	Open
MOV-FW-251B,	D, F	(Aux. Fee	ed Disch.	MOV's)	-	Failed	Open
TV-BD-200B.	D. E (S/G Blowd	lown Trip	Valves)	-	Failed	Closed

When the auto transfer from station service to reserve station service occurred, "A" reactor coolant pump (RCP) lost power because the "D" transfer bus was deenergized for testing.

The operators noted that all other control and protection systems functioned properly.

2. Safety Consequences and Implications

The control rods are rapidly inserted (tripped) into the core upon initiation of a reactor trip to shutdown the reactor. The UFSAR states that the reactor will be shutdown even if the most reactive rod was stuck at the fully withdrawn position. Since rod M-10 indicated a momentary sticking at 30 steps and it is suspected that the indicator was the problem, this is not a safety concern.

The source range channel NI-32 was manually reinstated. The redundant channel remained operable.

The values controlled by relay AFP-YB repositioned to perform their safety function when the relay failed. These values could not be repositioned to their normal position when plant conditions had stabilized. The redundant values for each non-functioning value remained operable.

NRC Form 366A (9-83;	LICENSEE EVENT REPO	RT (LER) TEXT CON	U.S. NUCLER TINUATION APPRO	AR REGULATORY COMMISSION VED OMB NO. 31500104 ES: 8/31/85
FACILITY NAME (1)		DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)
			YEAR SEQUENTIAL RE	VISION

SURRY POWER STATION, UNIT 2 TEXT (If more space is required, use additional NRC Form 366A's) (17)

> In addition, all other safety related systems remained operable during the event and plant parameters remained within the bounds of the accident analysis. Therefore this event did not constitute an unreveiwed safety question and the health and safety of the public remained unaffected.

0 |5 |0 |0 |0 |2 |8 |1 |8 |4 -

0 1 5

POW 28-06-01-01

0 10 0 3 OF 0 4

3. Cause

The load shed switch should have been in bypass since unit 1 was shutdown and all of its large electrical loads were deenergized. If it had been in bypass, the unit would not have tripped.

The Control Operations procedures for breaker testing did not contain instructions relating to load shedding.

The problem with control rod M-10 is suspected to have been with the rod position indicator (RPI) although no specific problem with the rod or the RPI was found.

The NI-32 reinstating problem is suspected to be in the "crowbar" circuit that is internal to the power supply. The erratic operation was attributed to a detector failure.

The relay failed when one of the coil leads opened.

4. Immediate Corrective Actions

The Operators performed all appropriate emergency and function restoration procedures to ensure that the plant was returned to stable conditions.

The Control Operations personnel stopped work in their procedure.

Also, the STA performed the status tree reviews to ensure that specific parameters were noted and the appropriate procedures were used to maintain these parameters within safe bounds.

5. Additional Corrective Actions

The "D" transfer and "A" station service electrical buses were reenergized to return the station electrical distribution to normal. The load shed switch was also placed in the bypass position.

The circuitry for centrol rod M-10 was checked. Rod drop testing was performed on rod M-10 with the primary system temperature at approximately 280^{0} F and 500^{0} F. No faults or problems were found and the failure was not reproducable.

Source range channel NI-32 was manually reenergized. The initial response of the detector was erratic. The detector was replaced prior to unit startup.

The failed relay and its coil were replaced.

NRC Form 366A (9-83)	LICENSI	EE EVE	NT REP	OHT	LE	R) т	EX	т	co	NT	IN	UA	TIC	N			U.S.	APP EXF	POVI	REC ED 0	GULA MB 1 1/85	NO 3	Y CO	MMIS	SION
FACILITY NAME (1)				20	CKI	ETN	UM	BER	(2)		-		Т	1	LI		UMBE	R (6				-	P	AGE	3)	_
													E	EAR		SEO	UENT	TAL		REVIS	BER					
SURRY POW	R STATION	UNIT	2	0	15	5	0	0	0	2	8	1	8	14	-	0	1	5	_	0	0	0	4	OF	0	4

DOW 22.05.01.01

6. Action Taken to Prevent Recurrence

A plant specific Control Operations staff is being developed. Surry will revise the appropriate operating procedures to clear up any ambiguities relating to bypassing and enabling the load shed system.

Control Operations will identify and change, where necessary, all relay testing series procedures to address load shedding. A Control Operations' procedure coordinator position was created and filled to improve thoroughness of their procedures.

The power supply for NI-32 will be replaced when a replacement is obtained. It is planned to send relay AFP-YB to an independent testing facility to have the failure mechanism analyzed.

7. Ceneric Implications

None.

FIGURE 1

• • • • • •



LEGEND · 22:CV/4160V STATION SERVICE(S) TRANSFORMER

- 4160V PREAKER



VIRGINIA ELECTRIC AND POWER COMPANY Surry Power Station P. O. Box 315 Surry, Virginia 23883

84-037

NOV 2 8 1984

Serial No: Docket No: 50-281

License No: **DPR-37**

U. S. Nuclear Regulatory Commission Document Control Desk 016 Phillips Building Washington, D.C. 20555

Gentlemen:

Pursuant to Surry Power Station Technical Specifications, the Virginia Electric and Power Company hereby submits the following Licensee Event Report for Surry Unit 2.

REPORT NUMBER

84-015-00

This report has been reviewed by the Station Nuclear Safety and Operating Committee and will be reviewed by Safety Evaluation and Control.

Very truly yours,

R& Saunders

R. F. Saunders Station Manager

Enclosure

cc: Mr. James P. O'Reilly Regional Administrator Suite 2900 101 Marietta Street, NW Atlanta, Georgia 30323

1622