LICENSEE EVENT REPORT (LER)												APPROVED ONS NO. 3180-0104 EXPIRES 8/31/85					
PACILITY MARE (1)												DOCKET MANGER (2)					
Joseph M. Farley - Unit 2											0 6 0 0 0 3 6 4 1 0 0 1						
VITLE IA		Watc	h Es	tablish	ed 1	Incurre	ctly										
EVENT DATE IS: LER NUMBER IS:							R					R PACILITIES INVOLVED IS					
MONTH	DAY	YEAR	YEAR	BEGUE	LAITH	REVERS	MONTH	DAY	YEAR	PACILITY NAMES			DOCKET NUMBER(8)				
													0 16	0 0	101		
013	011	8 5	8 5	-010	17	-010	0 3	2 17	8 5				0 6	010	101	ш	
-	RATING		THIS R	-	MITTED	PURBUANT T	O THE (REQUIREM	ENTS OF 16	CFR & 10	Check one or more	of the following: (1)	1)				
Court of o				30.405 (a)(1)(D 30.405 (a)(1)(D 30.405 (a)(1)(B) 30.405 (a)(1)(B) \$0.405 (a)(1)(B) \$0.405 (a)(1)(B) \$0.405 (a)(1)(B)			20.495 (c) 90.35 (c) (2) 90.35 (c) (2) 90.73 (c) (2) (1) 90.73 (c) (2) (M)			90.73(a) (2) (n) 90.73(a) (2) (v) 90.73(a) (2) (viii) 90.73(a) (2) (viii) (A) 90.73(a) (2) (viii) (B) 90.73(a) (2) (x)			73.71(a) 73.71(a) 73.71(a) GTHER (Spacify in Abstract bace and in Test, NAC Form 306A)				
						L	CEMBE	CONTAC	FOR THIS	LER (12)			TELEPHO	NE NUM			
	J. D. Woodard COMPLETE ONE LINE FOR EACH COMPONENT PAILURE DESCRIBED IN THIS REPORT														15 11	5,6	
				COM	LETE O	NE LINE FOR	BACH C	OMPONEN	T PAILURE	DESCRIBE	D IN THIS REPO	AT (12)	_				
CAUSE	8787EM	COMPO	THEM	MANUFA		TO MPADE			CAUSE	-	COMPONENT	MANUFAC	TO	PADS			
											111	111					
	1			111						1	111	1111					
	SUPPLEMENTAL REPORT EXPECTED (14											BXPECT	ED	MONTH	DAY	APTO	
YES III PM. MANN EXPECTED SUBMISSION DATE!										DATE (16:			1	1			

At 2330 on 3-1-85, while reviewing Limiting Condition for Operation (LCO) forms during shift turnover, it was discovered that fire watch requirements had been determined incorrectly for an inoperable fire barrier. Technical Specification 3.7.12 requires that either a continuous fire watch be established or the operability of fire detectors on at least one side of the non-functional fire barrier must be verified and an hourly fire watch patrol established. Hourly fire watch patrols had been established on 2-27-85 for an inoperable fire barrier. However, Fire Protection System 2A-48 which covers both sides of the non-functional fire barrier was made inoperable on 2-22-85 to add an additional smoke detector. At the time the hourly fire watches were established, system 2A-48 was still inoperable. Upon discovery, continuous fire watches were established immediately and maintained until no longer required. Health/safety of the public was not affected.

This event was caused by personnel error in that the Shift Foreman who initiated the LCO failed to check the status of the fire protection system prior to initiating fire watch requirements. Further, other Shift Foremen failed to ensure required actions were performed while the LCO was in effect. The individuals involved have been counseled.

B504050300 850327 PDR ADOCK 05000364 TEDO

Mailing Address
Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Alabama 35291
Telephone 205 783-6090

R. P. McDonald Senior Vice President Flintridge Building



March 27, 1985

Docket No. 364

Document Control Desk U. S. Nuclear Regulatory Commission Washington, D.C. 20555

Dear Sir:

Joseph M. Farley Nuclear Plant, Unit 2, Licensee Event Report No. LER 85-007-00 is forwarded in accordance with 10CFR50.73 to provide 30 day written notification of the occurrence.

If you have any questions, please advise.

Yours very truly,

R. P. McDonald

RPM/DSM:sam

Enclosure

xc: IE, Region II

IEST.