NRC Form 366 (9-63)			LIC	ENSEE EV	ENT RE	PORT	(LER)	U.S. NU AI E)	CLEAR REGULAT	ORY COMMISSION 0. 3150-0104		
FACILITY NAME	1)							DOCKET NUMBER	(2)	PAGE (3)		
Brown	s Ferr	y - Unit	1					0 5 0 0	0 2 5 9	1 OF 0 2		
TITLE (4)	identi	fied Lesk	age Th	Dryvel	1							
EVENT DAT	E (B)	LER NUMBER	age In	REPORT	DATE (7)		OTHER	FACILITIES INVOL	VED (8)			
MONTH DAY YEAR YEAR SEQUENTIAL REVISION				MONTH DAY YEAR FACILITY NAMES				VES	DOCKET NUMBER	R(S)		
					11				0 15 0 0	10111		
0 1 2 1	8 58	5 0 0 1	0 1	0 3 2	985				0 1510 10	10111		
OPERATING MODE (9)	THIS	REPORT IS SUBMITT	ED PURSUANT T	THE REQUIR	EMENTS OF 1	0 CFR §: /(Check one or more	of the following) (11)			
POWER		20.402(b)		20.406(c)		A	50.73(a)(2)(iv)		73.71(b) 73.71(c)			
LEVEL 0 10 10		20.405(a)(1)(ii)	50.36(c)(2)		50.73(a)(2)(vii)			OTHER (Specify in Abstract				
		20.405(a)(1)(iii)		50.73(s)(2)(i) 50.73(s)(2)(ii)		50,73(a)(2)(viii)(A) 50,73(a)(2)(viii)(B)		A)	below end in Text, NRC Form 366A)			
		20.406(a)(1)(lv)	X									
		20.406(s)(1)(v)		50.73(a)(2)(iii)		1 60 (10)	50.73(a)(2)(x)					
NAME				ICENSEE CONT	CT FOR THIS	LEM (12)		1	TELEPHONE NUM	BER		
								AREA CODE				
Jimmy	B. Walk	er		1.				2 0 5	7 2 9 -	12151316		
		COMPLETE	ONE LINE FOR	EACH COMPON	ENT FAILURE	DESCRIBE	D IN THIS REPOR	T (13)	1 1			
CAUSE SYSTEN	COMPONEN	T MANUFAC-	REPORTABLE TO NPROS		CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPRDS	•		
								111				
	1111	1111					111	1				
		SUPPLEN	ENTAL REPORT	EXPECTED (14)					MONTH	DAY YEAR		
	amalata EVAEA							SUBMISSIC	DN II			
ABSTRACT (Limit	to 1400 spaces, i	e. approximately fiftee	e ingle-spece type	A No	0							
During allowed accorda The lea valve 1 In addi repaire No safe event.	normal : by Tech nce with k was in ocated : tion to ed. ty limi The pe	startup of hnical Spec h Technical dentified t inside the the hose 1 ts were exc rtinent pro	unit 1, ificatio Specifi o be cau drywell. .eak, a s eeeded. ocedures	an unidens was n cation a used by a small we Procedua have be	entifie noted. require a tempo ld crac re inad en revi	d dryw An or ments. rary l k insi equacy sed to	well leak rderly sh hose whic ide the d y was the p prevent	age rate utdown wa h was use rywell wa root cau further	in excess s initiat d to test s identif se for th occurrence	a of that ted in a check fied and he first bes.		
BP	5040805 DR ADO	89 85032 CK 05000 PI	7 259 DR							14/1		

NRC Form 308 (9-83)

.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO 3150-0104

10.00	100.00	1000	100.0	54.1	0.0	
* *	1 C 1 P	18.20	- 25.7	3127	26.75	

FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6)	PAGE (3)			
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Browns Ferry - Unit 1	0 15 10 0 0 2 5	8 5	- 0 0 1	-0 11	0 2	OFO	2

Unit 1 was in startup, unit 2 was in a refueling outage, and unit 3 was at 100 percent power. This event affected unit 1 only.

During startup of unit 1 on January 21, 1985, after a short outage, at 1710 it was noted that drywell (BD) leakage had exceeded the technical specification limit of 5 gallons per minute (gpm). The measured leakage rate was approximately 32 gpm as detected by drywell sump flow. An orderly shutdown was initiated in accordance with Technical Specification 3.6.C.3 which required cold shutdown within 24 hours. Unit shutdown was started at 1820 on January 21, 1985, and the unit was in cold shutdown at 1030 on January 22, 1985.

Upon drywell entry, the leakage was identified to be caused by a temporary hose (TBG) which was used to test core spray (BM) testable check valve (FCV-75-26) (FCV) located in the drywell between the inboard and outboard isclation valves. The hose was positioned across the check valve for testing purposes but was not removed prior to unit startup. A pressure of approximately 800 psig was achieved during startup and with the associated drain valves left open, the temporary rubber hose slipped off its Chicago fitting. This resulted in leakage into the drywell.

Inadequate procedures were cited as the root cause of this incident. The surveillance instruction did not reference the applicable maintenance instruction, and the maintenance instruction did not have a second part verification that all temporary equipment had been removed and drain valves returned to normal. The net result was that workers failed to remove the hose upon completion of testing. The applicable surveillance and maintenance instructions have been revised to provide continuity of the instructions and to prevent further occurrences.

The misplaced hose partially compromised the isolation function of FCV 75-26, core spray inboard check valve, in that a small bypass route was created. Had this event occurred at full pressure, we expect that it would have been detected by very similar symptoms to those described above.

During a drywell inspection on January 22, 1985, a .50 inch long crack in a socket weld was discovered on "A" recirculation (AD) discharge bonnet vent valve 68-509 on principal recirculation valve FCV-68-3 (FCV). The bonnet vent valves and associated pipe were removed. The socket opening was plugged and seal welded. The cause for the weld to crack was fatigue failure due to vibration.

Both of these events are isolated cases, and no further actions are required.

Responsible Plant Section - MM

Previous Events - BFR0-50-259/82-020 (for cracked welds)

NRC Form 366A

TENNESSEE VALLEY AUTHORITY Browns Ferry Nuclear Plant P. O. Box 2000 Decatur, Alabama 35602

March 29, 1985

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D. C. 20555

Dear Sir:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT (BFN) UNIT 1 -DOCKET NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE REPORT BFR0-50-259/85001 R1

The enclosed report provides additional details concerning unidentified leakage in the drywell. This report is submitted in accordance with 10 CFR 50.73 (a)(2)(11) and (iv).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

G. T. Jones Plant Manager Browns Ferry Nuclear Plant

Enclosures cc (Enclosures): Regional Administrator U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marieita Street, Suite 2900 Atlanta, Georgia 30303

NRC Resident Inspector, BFN

INPO Records Center Suite 1500 1100 Circle 75 Parkway Atlanta, Georgia 30339

IE22

