NRC Forr (9-83)	n 386				LIC	ENSE	E EVE	NT RE	PORT	(LER)				0 OMB N	ORY COM 0. 3150-01					
FACILITY NAME (1) Callaway Plant Unit 1 015101																				
TITLE (4		C	allaw	ay Plant	Unit I					al Barris	0	5 0 0	1014	18 1	3 1 01	F 012				
		I	nadve	rtent Eng	ineered	Saf	ety Fe	ature	s Act	uation										
EVI	ENT DATE	(5)	T		(6)	R	PORT DAT	E (7)		OTHE	R FACI	LITIES INVO	LVED (8	0						
MONTH DAY YEAR YEAR SEQUENTIAL REVISIO							DAY	YEAR		FACILITYN	AMES		DOCKET NUMBER(S)							
								-					0 15	1010	101	11				
10	30	8 4	84	- 01518	- 010	111	20	84					0 15	1010						
	RATING	-		PORT IS SUBMITTE	1 1010	TO THE P	REQUIREME	NTE OF 10	CFR §: (	Check one or mor	e of the	following) (1	Concession of Second	1-1-	1-1					
	DDE (9)	1	20.	402(b)		20.406	i(c)		X	50.73(s)(2)(iv)			Ц,	73.71(b)						
POWER 20.405(a)(1)(i)   LEVEL 0   3   0 20.405(a)(1)(ii)   100 0   3   0 20.405(a)(1)(iii)   20.405(a)(1)(iii) 20.405(a)(1)(iii)						50.38			-	50.73(a)(2)(v) 50.73(a)(2)(vii)			73.71(c) OTHER (Specify in Abstract							
							a)(2)(I)			50.73(a)(2)(viii			below and in Text, NRC Form 366A)							
	20.405(a)(1)(iv)					60.736	a)(2)(ii)			50.73(a)(2)(viii	(8)									
20,405(a)(1)(v)							a)(2)(iii)			60.73(a)(2)(x)	x)									
NAME						LICENSE	CONTACT	FOR THIS	LER (12)				TELEPH	IONE NUM	ABER					
Charles D. Naslund - S							intend	ent.	I&C			AREA CODE								
		10 19					1000					311 1 4	617	16 1 -	-1815	1010				
				COMPLETE	1	1	OMPONENT	FAILURE	DESCRIBE	D IN THIS REP	ORT (1	3)								
CAUSE	SYSTEM	COMP	ONENT	MANUFAC- TURER	TO NPRDS			CAUSE	SYSTEM	COMPONENT		TURER		NPRDS						
											-									
	1	1	11	LLL		ļ		-	1	111		111	-							
			6.6	1.1.1																
				SUPPLEM	ENTAL REPORT	EXPECT	ED (14)	-			+			MONT	H DAY	YEAR				
_												EXPECT SUBMISS DATE (	ION							
1				SUBMISSION DATI			X NO				1									
		I G I t v t t a r T a (S	solat enera evel ransi ibrat o the he S/ tmosp eache he st tmosp Mode GBIS	30/84 at ion (FWIS tor Blowd on steam ent initi ion signa condense G atmosph herics an d the hig eam dumps herics to 2). the reset at	b), Auxi lown Iso generat ated wh at at 11 ar faile deric re d the c h level were s close. FWIS wa 1245.	liar; lati or ( en t 50. d to lief set; witcl Res s res	y Feed on (SC S/G) ' he mai Follo opera s to o nser d point hed to actor set at	water BIS) B.' n tur wing te pr open. lumps on S/ the power 1200	Actu signa The h bine the t operl The cause G 'B. steam was b, the	ation (A als were high leve tripped turbine of y in the oscillant d S/G 10 reduced a AFAS re	AFAS ini el r on trip e Ta tior evel re m and eset	b) and tiated esulte a spur b, the two mode s betw l oscil mode, a l stabt t at 12	Stea by ed fr fious stea le, c veen llati	a hig om a high m dur causin the ons w ving f ed at	gh nps ng which the 3%					
				8 P S	0412100 DR ADO	520 CK (	8411 5000	29 483 PDR					I	622						

LICENSEE EVENT REPORT (LER) TEXT CONTINUATIO

U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104

SVALARE 3/11/95

ACILITY NAME (1)			OOCKET NUMBER (2)							. LER NUMBER (6)								PAGE (3)			
							YEAR SEQUENTIA								NUMBER		T	TT			
Callaway Plant Unit 1								Г											1.		
	0	5	0	0	0	4	813	8	14	-	10	15	8	-	0 0	0 1	21	OF	01		

On 10/30/84 at 1150 CST, with plant in Mode 1 at 30% Reactor power and main generator output at 250 MW, the main turbine tripped on a spurious high vibration signal. Following the turbine trip, the steam dumps to the condenser failed to operate properly in the Tave (automatic) mode, causing the steam generator (S/G) atmospheric reliefs to open. The oscillations between the atmospherics and the condenser dumps caused S/G level oscillations which reached the high level setpoint on S/G 'B' at 1152, causing Feedwater Isolation (FWIS), Auxiliary Feedwater Actuation (AFAS) and S/G Blowdown Isolation (SGBIS).

Operators placed the steam dumps in the steam pressure mode and opened the dumps, allowing the atmospherics to close. Reactor power was reduced and stabilized at 3% (Mode 2). The FWIS was reset at 1200, the AFAS reset at 1220 and the SGBIS reset at 1245.

Investigation of the vibration on the main turbine revealed nothing abnormal and was therefore determined to be a spurious trip. The operation of the steam dumps was investigated and the problem was determined to be improper wiring termination from the turbine impulse chamber which disabled steam dump permissive C-7 and prevented the automatic operation of the dumps when the turbine tripped. This problem had not been identified by previous testing.

The steam dump wiring termination problem was corrected and the dumps verified to be operating properly.

This event posed no threat to the public health or safety.

Previous occurrences: none

IRC Form 366A

UNION ELECTRIC COMPANY CALLAWAY PLANT

> MAILING ADDRESS: P.O. BOX 620 FULTON, MO. 65251

November 29, 1984

U. S. Nuclear Regulatory Commission Dorument Control Desk Washington, DC 20555

ULNRC-987

DOCKET NUMBER 50-483 CALLAWAY PLANT UNIT 1 FACILITY OPERATING LICENSE NPF-30 LICENSEE EVENT REPORT 84-058-00 INADVERTENT ENGINEERED SAFETY FEATURES ACTUATION

Gentlemen:

The enclosed Licensee Event Report is submitted pursuant to 10 CFR 50.73(a)(2)(iv) concerning inadvertent Engineered Safety Features actuation.

Undrew S. Denhalfen

S. E. Miltenberger Manager, Callaway Plant

CDN/WRR/DRM/drs Enclosure

cc: Distribution attached

1E22 11

## cc distribution for ULNRC-987

Mr. James G. Keppler Regional Administrator Office of Inspection & Enforcement U.S. Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

American Nuclear Insurers c/o Dottie Sherman, Library The Exchange Suite 245 270 Farmington Aveune Farmington, CT 06032

Records Center Institute of Nuclear Power Operations Suite 1500 1100 Circle 75 Parkway Atlanta, GA 30339

NRC Resident Inspector Missouri Public Service Commission D. F. Schnell J. F. McLaughlin J. E. Davis (Z40LER) D. W. Capone/R. P. Wendling F. D. Field R. L. Powers A. C. Passwater/D. E. Shafer/D. J. Walker G. A. Hughes W. R. Robinson (QA Record) C. D. Naslund J. M. Price R. A. McAleenan L. K. Robertson (470) (NSRB) Merlin Williams, Wolf Creek SEM Chrono 3456-0021.6 3456-0260 Z40ULNRC G56.37 N. Date