ICENSEE EVENT REPORT (LER)							U.S. NUCLEAR REQULATORY COMMINSION APPROVED OWE NO. 3180-0104 EXPIRES: 8/31/86						
ACILITY	-	1)							0	OCKET NUMBER	(2)	PAGE 13	
R.E	. Gir	na N	uclea	r Power F	lant -	Unit #1				0 15 10 10	0 2 4 4	1 OF 0 1	
The	mrat	lo F	iro D	ntaction	Suston								
EVI	INT DATE	(6)	IIG D	LER NUMBER (System N	REPORT DA	TE (7)		OTHER	ACILITIES INVO	LVED (B)		
MONTH	NTH DAY YEAR YEAR SEQUENTIAL REVENON MONTH DAY YEAR				FACILITY NAM		DOCKET NUMBER(S)						
	10										0 19 0 10		
0 3	09	8 5	85	003	00	0405	85				0 15 0 10	101 1 1	
POWE LEVE (10)			20.4 20.4 20.4 20.4 20.4 20.4 20.4 20.4	004118 00041111 005(a)(1)(1) 005(a)(1)(1) 005(a)(1)(1) 005(a)(1)(1) 005(a)(1)(1) 005(a)(1)(1)		20.405(a) 50.36(a)(1) 50.36(a)(2) 50.73(a)(2)(1) 50.73(a)(2)(1) 50.73(a)(2)(11) 50.73(a)(2)(11)	IENTE OF 10		50,73(a) (2)(v) 50,73(a) (2)(v) 50,73(a) (2)(v) 50,73(a) (2)(vii) (4 50,73(a) (2)(viii) (4 50,73(a) (2)(viii) (1 50,73(a) (2)(viii) (1 50,73(a) (2)(vii) (1)(vii) (1 50,73(a) (2)(vii) (1)(vii) (1)(vii	n me rollowing) (1 5) 5)	73.71(b) 73.71(c) 73.71(c) OTHER (52 before and i 366.4)	acity in Abstract n Text, NRC Form	
NAME						LICENSEE CONTAC	T FOR THIS	LER (12)			TELEPHONE NUL		
										AREA CODE	I		
G.	F. I	ariz	za, 0	perations	Manage	I FACH COMPONE	T FAILURS	0100010	D IN THIS	3115	51214 F	14 14 1416	
CAUSE	SYSTEM	COMP	ONENT	MANUFAC-	REPORTABLE TO NPRDS		CAUSE	SYSTEM	COMPONENT	MANUFAC	REPORTABLE TO NPRDS	•	
A	KIP	- 1D	ET	G101110	S N				111				
	1		i i l	111	1.1				111		1. 1. 1. 1.		
				BUPPLEM	ENTAL REPORT	EXPECT ID (14)				EXPECT	ED MONT	H DAY YEAR	
TYE	\$ //f ym, c	ompiete E	XPECTED	SUBMISSION DAT	e)	V NO				DATE (ION 15)		
Or Su Ca hc di De re Th wh	n Man appre able burs scovetect emove nis nich one v	rch essi Tra of vere tion ed f resu req vith	9, 1 on S ys" that d th Sys rom lted uire the	985 at 6 ystem 8 was req same da at S-15 tem Aut service. in a v s withi inopera	0655 ho s-15 " uested ay, dur was i to Del riolati n an h able in	ours Fir Interme I to be ring Per n servio uge" in our a f nour a f	e Det diat remov iodic ce an istea echni irewa ts at	ecti e Bu ved f Sur d S-4 d ha cal tch lea	on and ilding from ser veillan 05 "Cab d been Specific patrol st once	Auto Pr Baseme rvice. ce Test le Tunn inadve cation to insp per ho	e-action At 1430 , it was el Smoke ertantly 3.14.1. pect the ur.	n 5 9 7 1 9	
			850 PDR S	⁴¹⁶⁰⁰⁷³ АДОСК	85040s 050002	44						22 .	

NRC Form 366A 19-831	LICENSEE EVENT REPORT (LER) TEXT CONTIN	UATION	US NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES 8/31/85				
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUM	8ER (6)	PAGE (3)			

YEAR

NUMBER

-0 0 3 -

NUMBER

010 012 OF 012

P E Ginna Nuclear Down Plant	1								YE.	AR
Unit #1	0	5	0	0	0	12	14	14	8 1	5

TEXT // more spece is required, use additional NRC Form 386A's) (17)

On March 9, 1985 at Ø655 hours Fire Detection and Auto Pre-action Suppression System S-15 "Intermediate Building Basement East Cable Trays" was requested to be removed from service for grinding and welding work activities in that area.

At 1430 hours of the same day, during Periodic Surveillance Test, it was discovered that S-15 was in service and S-05 "Cable Tunnel Smoke Detection System Auto Deluge" instead had been inadvertantly removed from service.

This resulted in S-15 area being left in service while grinding and welding was going on (no alarm or auto pre-action conditions) with a firewatch present while S-05 area was defeated and no firewatch patrol was established to inspect the zone with the inoperable instrument at least once per hour. This violated Technical Specification 3.14.1.1 which requires, within an hour, a firewatch patrol to inspect the zone with the inoperable instruments at least once per hour.

This condition was created by personnel error. The individual assigned this responsibility misread the zone to be deactivated, S-Ø5 rather than S-15. It should be noted that for the defeated zone, "Cable Tunnel" Heat Detection System Z-05 was still operable, and that the spray and/or sprinkler S-Ø5 could still be operated manually upon receipt of Z-05 heat detector alarm in the Control Room. Thus the potential consequences of this event were minimal.

Procedure SC-3.16.2.4 will be reviewed to identify means to preclude re-occurrence. In the interim, when disconnecting the Fire Signaling System, personnel will perform a double verification, similar to the double verification presently required after reactivating the systems.

Modifications to the existing system are being investigated which will provide visual indication of these systems when in or out of service on the Control Room Panel. At present the only indication existing in the Control Room is when a system alarms. Activation and deactivation is performed in a satellite station in the Relay Room.



2

CHESTER GAS AND ELECTRIC CORPORATION . 89 EAST AVENUE, ROCHESTER, N.Y. 14649-0001

ROGER W. KOBER VICE PRESIDENT CLECTRIC & STEAM PRODUCTION

TELEPHONE AREA CODE TIS 546-2700 WEW YORK

April 5, 1985

U.S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

Subject: LER 85-003, Inoperable Fire Detection System R.E. Ginna Nuclear Power Plant, Unit No. 1 Docket No. 50-244

In accordance with 10 CFR 50.73, Licensee Event Report System, item (a)(2)(i)(B) which requests a report of, "any operation or conditions prohibited by the plant Technical Specification", the attached Licensee Event Report LER 85-003 is hereby submitted.

Very truly yours,

Roger W. Kober

RWK/eeg

xc: U.S. Nuclear Regulatory Commission Region I 631 Park Avenue King of Prussia, PA 19406

LEZZ