

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P. O. BOX 126 SAN OLEMENTE "ALIFORNIA 92674-0128

March 17, 1992

R. W. KRIEGER STATION MANAGER

生物的,影中和新的石榴。 生化成于白褐色 电空行标

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Subject: Docket No. 50-361 Supplemental Report Licensee Event Report No. 89-010, Revision 2 San Onofre Nuclear Generating Station, Units 2 and 3

Reference: Letter, H. E. Morgan (SCE) to USNRC Document Control Desk, dated March 16, 1990

The referenced letter provided Licensee Event Report (LER) No. 89-010, (Revision 1), for a condition involving the Units 2 and 3 Main Steam Safety Valve (MSSV) capacity. The enclosed supplemental LER provides additional corrected information concerning Unit 3 operation with a gagged MSSV. The previous revision had failed to address periods when Unit 3 had operated with one MSSV gagged. Since this occurrence involves similar systems, cause, and corrective actions applicable to Units 2 and 3, a single revised report for Unit 2 is being submitted in accordance with NUREG-1022. Neither the health nor the safety of plant personnel or the public was affected by this condition.

If you require any ad itional information, please so advise.

Sincerely,

Enclosure: LER No. 89-010, Rev. 2

9203230276 9 PDR ADOCK 0

cc: C. W. Caldwell (USNRC Senior Resident Inspector, Units 1, 2 and 3)
J. B. Martin (Regional Administrator, USNRC Region V)
Institute of Nuclear Power Operations (INPO)

				LICH	INSEE EVEN	REPORT	(LER)					
active,	v Name ())						Docket No	mber (2)	Fg	KH 10	2
SAN ONCE	FRE NUCLI	CAR GENERA	TING ETATION.	UNIT 2				1 31 51 01	0 0 0 0 6	5 3	20	0 1
fitle ()			VALVE (MSSV	NUM PARA	THU ADDADI	rent i dani						
	PRAD D.	(1996) 1997 D.1	a valet coost	/ Fisher Gerten	GII BEEBN	carra res	10 10A8 1	WEBFLATE AAI	1007			
EVENT	DATE (5		LER NUMBER (6	and the second second		REPORT D	TE (7)		FACILITIES I	NVOLVED	(8)	
Month	Day Y	ar Year	1// Sequentin		Mon Not	nh Day	Year	Facility N	ames boc	het Num	per (1)
		A REAL PROPERTY AND AND			N. F. A.			SONOS, 101	2. 2. 01.3	0 0 0	01.0	1 61
015	210 1	19 819	+ 0111	0 1 0			. 412			1.01.01		1.1
OF	BRASING		THIS REPORT (IS SUBMITTEI	FUREUANT		EQUIREM	ONTS OF 10CFR				(terrorite
	DE (9)	4. 5	20.402(b		20.4050	1)		73(a)(2)(1v)		.71(b)		(incare)
POWER LEVEL			20.405(s 20.405(s		- 50.36(c 50.36(c			73(a)(2)(v) 73(a)(2)(v)1	73	.71(c) her (Sp		
(10)	0	010	20.405(8)	(1)(1111)	50.73(a	(2)(1)	50	73(4)(2)/711	4A (A)(1	stract		
			20.405(A			(2)(11)		73(a)(2)(vii 73(a)(2)(vi	1)(8) 48	test)		
	hinth			CLATER Jam	-lastratu	12672243	(anti-1999)	CC @ 5. 19 3 5. 16 2 5. 16 2		LUNTARY		
<u>anna</u>	ununo	20111111	and the second s								-	
	-		international distances and states	LICENSER	CONTACT I	OR THIS	LER (12))				
R data sea								AREA	CODE		N	-
R. 1	L. Kriegs	r. Statio	m Manager					171	1 4 3 6	181-1	112	1 5
		COMP	LETE ONE LINE	FOR EACH CO	MPONENT F	ULURE DI	SCRIBED	18 THIS REPO	RT (13)			
CAUE	SYSTEM	COMPONE	NT NANUFAC- TURER	KEPORTABL TO NPRDS	E 17/3777	CAUSE	SYSTEM	COMPONENT	MANUFAC-	REPORT TO NP	ABLE	
Б	8.1.8	1] 8	V C 7 1									
					mun				1.1.1	1		HIL
SUPPLEMENTAL REFORT EXPECTED (14)						Expected	Month		Yea			
	na en							The second secon		(Second second		
an a					(1964)				Submission Date (15)			

ARSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16) This revision to voluntary LER 89-010 provides corrected information concerning Unit 3 operation with a gagged main steam safety valve (MSSV).

On 5/20/89, with Unit 2 in Mode 5 (cold shutdown) and Unit 3 at 100% power, during an ongoing evaluation of Information Notice (IN) 36-05, "Main Steam Safety Valve Test Failures and Ring Setting Adjustments," it was concluded that the MSSV flow capacities were most likely less than nameplate rating. This conclusion was based upon best available findings of the Westinghouse Owners Group (WOG) Subcommittee on MSSVs, and upon the factory-set ring settings of the Units 2 and 3 MSSVs.

Analyses performed indicated that overpressure protection with all MSSVs operable at the reduced capacity was adequate and would not alter the results of the safety analyses; these conclusions were supported by actual performance data taken following two actual loss of heat removal events (LER 86-022 [Docket No. 50-361] and LER 90-002 [Docket No. 50-362]). However, a review of operating history for Units 2 and 3 later identified that Unit 3 had operated at power from 8/27/86 to 9/30/86 with one MSSV gagged. During this time, Unit 3 reactor power did not exceed 94%. Unit 2 had not operated at power with a gagged MSSV. An additional analysis concluded that there was minimal safety significance associated with operations at reduced MSSV capacity and with one MSSV gagged.

As reported in IN 86-05, MSSVs with initial factory-set ring settings obtain a disc lift that is less than rated lift. The MSSV ring settings were initially set based upon valve operational tests conducted at limited volume test facilities on valves typically smaller than the MSSVs. Test facilities for full flow testing of MSSVs were not available at the time the valves were manufactured.

The ring settings for the Units 2 and 3 MSSVs were changed such that full flow capacity of the MSSV: was achieved.

SAN ONOFRE UNIT 2	NUCLEAR GENERATION STATION	DOCKET NUMBER 05000361	LER NUMBER 89-010-02	PAGE 2 OF 5
	Plant: San Onofre Nuclear Gener Units: 2 and 3 Reactor Vendor: Combustion Eng Event Date: 05-20-89			
Α.	CONDITIONS AT TIME OF THE EVENT	n		
	Unit 2: Mode 5, Cold Shutdown Unit 3: Mode 1, Power Operatio	on		
Β.	BACKGROUND INFORMATION:			
	The purpose of this revision is plant operation with gagged ma			regard to
	1. Main Steam Safety Valves	(MSSVs)		
	Nine (° MSSVs [RV] are (one line per steam gene overpressurization. The approximately 233 pounds (i.e., at 3% accumulatio obtaining rated lift. R upon the ring settings o in part, the blowdown an	rator [SG]) to prote MSSVs each have a mass per second at n). This rating is ated lift of the va f the valve. The r	ect the MS system nameplate rating o 103% of setpoint dependent upon th lve is dependent, ing settings also	[SB] from f pressure e valve in part, determine,
	2. Technical Specification	(TS) Requirements		
	TS 3.7.1.1, "Turbine Cyc requirements of the MSSV system [JC] linear power one or more MSSVs are in is to ensure that the se	s and the maximum a level-high reactor operable. The purp	llowable reactor p trip (LPLHT) setp ose of these TS re	protectic.) point when equirements

3. Westinghouse Owners Group (WOG) Subcommittee on MSSVs:

operational transient.

Information Notice (IN) 86-05, "Main Steam Safety Valve Test Failures and Ring Setting Adjustments", and Supplement 1 were issued in 1986. This IN was provided to alert recipients of the potential for MSSVs to possess less than full-rated flow capacity due to initial factory-set ring settings. The WOG Subcommittee on MSSVs was formed to address the ring setting problem and to establish recommended MSSV generic ring settings such that full capacity of the MSSVs is achieved. These generic ring settings and their relationship with other MSSV design parameters have been established.

110% of its design pressure during the most severe anticipated system

SAN ONOFRE NUCLEAR GENERATION STATION	DOCKET NUMBER	LER NUMBER	PACE
UNIT 2	05000361	89-010-02	3 OF 5

C. DESCRIPTION OF THE EVENT:

1. Event:

On 5/20/89, with Unit 2 in Mode 5 (cold shutdown) and Unit 3 at 100% power, during an ongoing evaluation of IN 86-05, it was concluded that the MSSV flow capacities were most likely less than nameplate rating. This conclusion was based upon best available findings of the WOG Subcommittee on MSSVs and upon the factory-set ring settings of the Units 2 and 3 MSSVs. The MSSV ring settings had not been subsequently changed by SCE.

An evaluation was performed to determine the capability of the Units 2 and 3 MSSVs to meet design requirements with factory-set ring settings. This analysis indicated that overpressure protection with all MSSVs operable was adequate. However, the power reduction required by the LPLHT setpoint with one MSSV removed from service specified by TS 3.7.1.1 did not provide sufficient margin to preclude exceeding the secondary design pressure limit of 110% if the plant were operated just below the LPLHT setpoint. In practice, a reduction in operating power level would have occurred to preserve a sufficient operating margin.

A review of operating history for Units 2 and 3 later identified that Unit 3 had operated at power from 8/27/86 to 9/30/86 with one MSSV gagged. During this time, the LPLHT was reduced to 98.6% as required by TS 3.7.1.1 for operation with one MSSV gagged. Reactor power did not exceed 94% between 8/27/86 and 9/30/86. Unit 2 had not operated at power with a gagged MSSV.

 Inoperable Structures, Systems or Components that Contributed to the Event:

Not applicable.

3. Sequence of Events:

Not applicable.

4. Method of Discovery:

As discussed in section C.1, "Event", above.

5. Personnel Actions and Analysis of Actions:

Not applicable.

Safety System Responses;

Not applicable.

SAN ONOFRE NUCLEAR GENERATION STATION	DOCKET NUMBER	LER NUMBER	PAGE
UNIT 2	05000361	89-010-02	4 OF 5

D. CAUSE OF THE EVENT:

As reported in IN 86-05, MSSVs with initial factory-set ring settings obtain a disc lift that is less than rated lift. The MSSV ring settings were initially set based upon value operational tests conducted at limited volume test facilities on values typically smaller than the MSSVs. Test facilities for full flow testing of MSSVs were not available at the time the values were manufactured.

E. CORRECTIVE ACTIONS:

Corrective Actions Taken:

The ring settings for the Units 2 and 3 MSSVs were changed to be consistent with the new recommended generic settings during the Cycle 5 refueling outages, thus achieving full flow capacity of the MSSVs.

F. SAFETY SIGNIFICANCE OF THE EVENT:

Conservative evaluation techniques indicated that with all MSSVs available, the reduced MSSV capacities were sufficient to meet design bases and would not have altered the results of the safety analyses. The MSSV analytical model utilized to arrive at this conclusion estimated 75% of full nameplate flow. In addition, these conclusions were supported by actual performance data taken following two actual loss of heat removal events (LER 86-022 [Docket No. 50-361] and LER 90-002 [Docket No. 50-362]).

The loss of condenser vacuum (LOCV) event was re-analyzed using the RETRAN Transient Analysis Code (best estimate) from EPRI. The LOCV is the most limiting design bases event while operating with one gagged MSSV. The results of this analysis indicate that the calculated peak secondary pressure would have been less than the design basis value of 1210 psis at 94% power and 75% MSSV capacity. Therefore, there was minimal safety significance associated with operations at reduced MSSV capacity and with one Unit 3 MSSV gagged.

- G. ADDITIONAL INFORMATION:
 - 1. Component Failure Information:

The MSSVs are manufactured by Crosby Valve and Gage Co. (Model No. 6R10 HA75FN).

2. Previous LERs for Similar Events:

None.

Results of NPRDS Search:

Not applicable. The WOG Subcommittee on MSSVs evaluated reduced MSSV capacities reported at other facilities and in IN 86-05.

SAN ONOFRE NUCLEAR GENERATION STATION	DOCKET NUMBER	LER NUMBER	PAGE
UNIT 2	05000361	89-010-02	5 OF 5

4. Additional Information:

The MSSVs satisfy TS 3.7.1.1, which requires the MSSVs to be operable with specific relief setpoints. Also, they satisfy the basis for this TS by limiting steam pressure to 110% of design during certain severe transients. However, an evaluation revealed that the MSSVs' total flow rate stated in the TS Basis and in FSAR Appendix 5.2A, Over Pressure Protection, was a preliminary value used prior to manufacture rather than the flow needed to limit steam pressure. The UFSAR has been updated to reflect the appropriate design basis. A TS amendment application to revise the basis to TS 3.7.1.1 has been submitted by letter from SCE to the NRC dated November 8, 1990.