## NOTICE OF VIOLATION

Sundberg, Carlson and Associates, Inc. Marquette, Michigan

License No. 21-20397-01 Docket No. 030-18344

During an NRC inspection conducted on March 9, 1992, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1991), the violation is listed below:

Condition 17 of License No. 21-20397-01 requires that licensed material be possessed and used in accordance with statements, representations and procedures contained in an application dated April 14, 1988, and a letter dated December 2, 1986.

Item 7 of the application lists John C. Batchelder as the Radiation Protection Officer.

Contrary to the above, as of August 1990, an individual other than John C. Batchelder has assumed the position of the Radiation Protection Officer.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, Sundberg, Carlson and Associates, Inc. is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, Region III, 799 Roosevelt Road, Glen Ellyn, Illinois, 60137, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. If an adequate reply is not received within the time specified in this Notice, an order may be issued to show cause why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

MAR 23 1992

Dated

Gary L. Shear, Chief Nuclear Materials Inspection

Section 2