

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) EDWIN I. HATCH, UNIT I										DOCKET NUMBER (2) 0 5 0 0 0 3 2 1 1				PAGE (3) 1 OF 0 2										
TITLE (4) Unplanned Actuation of an Engineered Safety Feature																								
EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)															
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES				DOCKET NUMBER(S)											
1	1	1	2	8	4	8	4	0	0	1	2	0	7	8	4	0	5	0	0	0				
OPERATING MODE (9) 5			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)																					
POWER LEVEL (10) 0 0 0			20.402(b)			20.406(c)			<input checked="" type="checkbox"/> 50.73(a)(2)(iv)			73.71(b)												
			20.406(a)(1)(i)			50.36(c)(1)			<input type="checkbox"/> 50.73(a)(2)(v)			73.71(c)												
			20.406(a)(1)(ii)			50.36(c)(2)			<input type="checkbox"/> 50.73(a)(2)(vii)			OTHER (Specify in Abstract below and in Text, NRC Form 366A)												
			20.406(a)(1)(iii)			50.73(a)(2)(i)			<input type="checkbox"/> 50.73(a)(2)(viii)(A)															
			20.406(a)(1)(iv)			50.73(a)(2)(ii)			<input type="checkbox"/> 50.73(a)(2)(viii)(B)															
			20.406(a)(1)(v)			50.73(a)(2)(iii)			<input type="checkbox"/> 50.73(a)(2)(ix)															
LICENSEE CONTACT FOR THIS LER (12)																								
NAME T. L. Elton, Acting Superintendent of Regulatory Compliance										TELEPHONE NUMBER 9 1 1 2 3 1 6 1 7 1 7 1 8 1 5 1 1														
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																								
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC														
SUPPLEMENTAL REPORT EXPECTED (14)										EXPECTED SUBMISSION DATE (15)			MONTH	DAY	YEAR									
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)										<input checked="" type="checkbox"/> NO														

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 11/12/84, at approximately 1350 CST, with Unit 1 in cold shutdown for a refueling outage, during the installation of an upgraded type coil for HFA relays, contract personnel accidentally shorted to ground the wires for contacts 5 and 6 of the "Initial fuel load trip relay" (C71-K13B), thus causing fuses C71-F15A & B (C71-F15A is for Channel A3 Reactor Manual Scram, and C71-F15B is for Channel B3 Reactor Manual Scram) to open. When these fuses opened, manual scram relays for both channels dropped out resulting in an unplanned logic actuation of RPS. The cause of this event was personnel error.

No actual or potential safety consequences or implications resulted from this event. This event had no impact on any other Unit 1 system or on Unit 2. The health and safety of the public were not affected by this repetitive event as last reported on LER 1-84-023.

8412190352 841207  
PDR ADOCK 05000321  
S PDRIE22  
11

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
EDWIN I. HATCH, UNIT I	0500032184	—	022	—	00	2 OF 02

TEXT (If more space is required, use additional NRC Form 366A's) (17)

This LER is required by 10CFR50.73(a)(2)(iv).

On 11/12/84, at approximately 1350 CST, with Unit 1 in cold shutdown for a refueling outage, during the installation of an upgraded type coil for HFA relays, contract personnel accidentally shorted to ground the wires for contacts 5 and 6 of the "Initial fuel load trip relay" (C71-K13B), thus causing fuses C71-F15A & B (C71-F15A is for Channel A3 Reactor Manual Scram, and C71-F15B is for Channel B3 Reactor Manual Scram) to open. When these fuses opened, manual scram relays for both channels dropped out resulting in an unplanned logic actuation of RPS. The cause of this event was personnel error.

No actual or potential safety consequences or implications resulted from this event. This event had no impact on any other Unit 1 system or on Unit 2. The health and safety of the public were not affected by this repetitive event as last reported on LER 1-84-023.

The involved personnel were counseled as to the importance of being cautious when working in panels that are critical to plant operation. Additionally, supervision of contract personnel was increased. The installation of all HFA relays' coils for Unit 1's Reactor Protection system were successfully completed on 11/26/84.

Georgia Power Company  
Post Office Box 439  
Baxley, Georgia 31513  
Telephone 912 367-7781  
912 537-9444



Georgia Power


Edwin I. Hatch Nuclear Plant

December 7, 1984  
GM-84-1097

PLANT E. I. HATCH  
Licensee Event Report  
Docket No. 50-321

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, D. C. 20555

Attached is Licensee Event Report No. 50-321/1984-022. This report is required by 10CFR 50.73(a)(2)(iv).

  
H. C. Nix  
General Manager

*HC*  
HCN/TLE/vlz

xc: R. J. Kelly  
R. E. Conway  
J. T. Beckham, Jr.  
P. D. Rice  
K. M. Gillespie  
Superintendent of Regulatory Compliance  
R. D. Baker  
Control Room  
Document Control

*1222*  
*11*