

ENCLOSURE 1

NOTICE OF VIOLATION

Carolina Power and Light Company
Brunswick Site

Docket Nos. 50-325 and 50-324
License Nos. DPR-72 and DPR-62

During an NRC inspection conducted from April 1 - May 1, 1992, violations of NRC requirements were identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1992), the violations are listed below:

1. Technical Specification 3.7.2 requires that two independent control room emergency filtration systems shall be operable and allows one control room emergency filtration system to be inoperable no more than seven days or shut both units down.

Contrary to the above, on April 13, 1992, the 2A control building emergency air filter was found not to be fastened on one side, which rendered it seismically inoperable. This condition had existed since initial installation. Due to this condition, train 2A of the control room emergency filtration system has been inoperable (but available) since initial plant operation. The licensee had three opportunities to identify this condition; initial testing and during the 1987 and 1992 inspections and evaluations for seismic qualification.

This is a Severity Level IV violation (Supplement I).

2. Technical Specification 6.5.4.7 requires that Nuclear Assessment Department (NAD) personnel who perform independent safety reviews not be directly involved in the activities which they review. CP&L Corporate Quality Assurance Manual section 13.3 requires that personnel performing assessments not have direct responsibility in the areas they are assessing.

Contrary to the above, five NAD personnel were assigned to assist plant personnel in an inspection of plant systems and equipment not accessible during power operation, to develop a deficiency list. This line function inspection started on April 27, 1992, during a dual unit outage and the NAD assistance continued until April 29, 1992.

This is a Severity Level IV violation (Supplement I).

Carolina Power and Light Company 2
Brunswick Site

Docket Nos. 50-325 and 50-324
License Nos. DPR-72 and DPR-62

Pursuant to the provisions of 10 CRF 2.201, Carolina Power and Light Company is hereby required to submit a written statement or explanation to the U. S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, DC 20555, with a copy to the Regional Administrator, Region II, and a copy to the NRC Resident Inspector at the facility that is the subject of this Notice, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. If an adequate reply is not received within the time specified in this Notice, an order or demand for information may be issued as to why the license should not be modified, suspended or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

THE NUCLEAR REGULATORY COMMISSION

Dated at Atlanta, Georgia
this 20th day of May 1992