



ENTERGY

Entergy Operations, Inc.
P.O. Box 756
Port Gibson, MS 39150
Tel 601-437-6408

W. T. Cottle
Vice President
Operations
Grand Gulf Nuclear Station

July 10, 1992

U.S. Nuclear Regulatory Commission
Mail Station P1-177
Washington, D.C. 20555

Attention: Document Control Desk

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-29
Entry Into TS 3.0.3. Statement Due to Standby Gas
Inoperability
LER 92-012-00

GNRO-92/00088

Gentlemen:

Attached is Licensee Event Report (LER) 92-012 which is an interim report.

Yours truly,

W. T. Cottle

WTC/GAZ/
attachment

cc: Mr. D. C. Hintz (w/a)
Mr. J. L. Mathis (w/a)
Mr. R. B. McGehee (w/a)
Mr. N. S. Reynolds (w/a)
Mr. H. L. Thomas (w/o)

Mr. Stewart D. Ebnetter (w/a)
Regional Administrator
U.S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 2900
Atlanta, Georgia 30323

Mr. P. W. O'Connor
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Mail Stop 13H3
Washington, D.C. 20555

LER92012.DOC

146988
9207140175 920710
PDR ADOCK 05000416
S PDR

JEZ 1/1

NRC Form 366 (9-83)										U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3160-0104 EXPIRES 8/31/88									
LICENSEE EVENT REPORT (LER)																			
FACILITY NAME (1) Grand Gulf Nuclear Station										DOCKET NUMBER (2) 0 5 0 0 0 4 1 6 1					PAGE (3) 1 OF 0 4				
TITLE (4) Entry Into TS 3.0.3 Statement Due to Standby Gass Inoperability																			
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)									
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES					DOCKET NUMBER(S)					
0 6	1 0	9 2	9 2	0 1 2	0 0	0 7	1 0	9 2						0 5 0 0 0					
OPERATING MODE (9)			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)																
POWER LEVEL (10) 0 3 7			20.402(b)				20.405(e)				50.73(a)(2)(iv)				73.71(b)				
			20.405(a)(1)(ii)				50.73(a)(1)				50.73(a)(2)(v)				73.71(e)				
			20.405(a)(1)(iii)				50.73(a)(2)				50.73(a)(7)(vii)				OTHER (Specify in Abstract below and in Text, NRC Form 366A)				
			20.405(a)(1)(iii)				50.73(a)(2)(i)				50.73(a)(2)(viii)(A)								
			20.405(a)(1)(iv)				50.73(a)(2)(ii)				50.73(a)(2)(viii)(B)								
			20.405(a)(1)(v)				50.73(a)(2)(iii)				50.73(a)(2)(ix)								
			20.405(a)(1)(vi)				50.73(a)(2)(iv)				50.73(a)(2)(x)								
LICENSEE CONTACT FOR THIS LER (12)																			
NAME G. A. Zinke/Manager, Nuclear Safety & Assessment										TELEPHONE NUMBER 6 0 1 4 3 7 - 2 4 5 9									
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																			
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRRDS					
SUPPLEMENTAL REPORT EXPECTED (14)										EXPECTED SUBMISSION DATE (15)									
<input checked="" type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)										MONTH DAY YEAR 0 8 1 0 9 2									
ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)																			
<p>During Refueling Outage 5 it was determined that a previously identified deficiency concerning potential secondary containment bypass leakage affected the operability of the Standby Gas Treatment System (SBGT). The details of this deficiency were reported in LER 92-011-00 on 7/5/92 as a condition outside the design basis of the plant. A minor modification package (MCP 92/1605) was prepared and issued to repair the condition. The work packages were signed off complete. A post-modification smoke test was performed and signed off as acceptable. On 6/10/92 during a walkdown by plant personnel, it was discovered that the repairs had not been completed. Both SGTS trains were declared inoperable which required a plant shutdown. The deficiencies were promptly corrected, and SGTS was declared operable. This is an interim report. An update will be provided by 8/10/92.</p>																			
LER92012.DOC																			

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
Grand Gulf Nuclear Station	0 5 0 0 0 4 1 6	9 2	0 1 2	0 0	0 2	OF 0 4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

A. Reportable Occurrence

A minor modification package was issued for work during Refueling Outage 5 (RFO5) to correct discrepancies on the Standby Gas Treatment System (SGTS) [BH] identified in Material Nonconformance Report (MNCR) 0148-91. On 6/10/92 after restart from RFO5 a walkdown revealed that not all the required work had been performed. SGTS A and B subsystems were therefore declared inoperable. The actions of Technical Specification 3.0.3 were entered since the action statement for the Limiting Condition for Operation: (LCO) of Technical Specification 3.6.6.3 could not be met. This condition is reportable pursuant to 10CFR50.73(a)(2)(i)(B).

B. Initial Conditions

The plant was operating in Operational Condition 1 at approximately 37 percent power.

C. Description of Occurrence

On 5/2/92 during Refueling Outage 5 it was determined that a previously identified deficiency concerning potential secondary containment bypass leakage affected the operability of the Standby Gas Treatment System for Operational Conditions 1, 2, and 3. The details of this deficiency were reported in LER 92-011-00 on 7/6/92 as a condition outside the design basis of the plant.

A minor modification package (MCP 92/1065) was prepared and issued on 5/22/92 in order to repair potential secondary containment bypass leakage paths in the Standby Gas Treatment System.

The scope of the work packages required installation of fan shaft seals, application of sealant to all seams and joints in the pocket or shroud around the flow control vane assembly control arm, and application of sealant around the outside circumference of the seam between the fan inlet flange and the fan housing.

LER92012.DOC

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
Grand Gulf Nuclear Station	0 5 0 0 0 4 1 6 9 2	0	1	2	0	3
					OF	0 4

TEXT (If more space is required, use additional NRC Form 388A's) (17)

The work packages were signed off complete on 6/3/92 by the contractor supervisor. A post-modification smoke test was performed on 6/3/92 and signed off as acceptable by a plant system engineer. The acceptance criteria for the smoke test was minimal or no visible leakage.

On 6/10/92 during a walkdown of the Standby Gas Treatment System by plant personnel, it was discovered that no sealant had been applied around the outside circumference of the seam inlet flange and the fan housing, and that no sealant had been applied to the shroud around the flow control vane assembly control arm. However, the shaft seals had been installed.

SGTS A and B were declared inoperable following this discovery. Since Technical Specification 3.6.6.3 actions do not allow more than one subsystem to be inoperable during Operational Condition 1, the actions of Technical Specification 3.0.3 were entered. Upon commencement of the required shutdown (Emergency Plan Emergency Action Level), an Unusual Event was declared.

The deficiencies were promptly corrected, SGTS A and B subsystems were declared operable, and Technical Specification 3.0.3 was exited 2 hours 4 minutes after its entry.

D. Apparent Cause

A thorough investigation is being conducted. The pertinent GGNS procedure assigns responsibility for the in-process control of work to the contractor supervisor. The contractor supervisor signed the work package based on verbal communication indicating that the work was done and had been acceptably retested. Although many aspects of this investigation have been completed (e.g. personnel interviews, work document reviews, walkdowns of other work), the root causes have not been conclusively determined. No evidence of willful falsification of records has been identified.

E. Corrective Actions

The SGTS leakage paths were repaired on 6/10/92.

LER92012.DOC

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
Grand Gulf Nuclear Station	0 5 0 0 0 4 1 6	9 2	0 1 2	0 0	0 4	OF 0 4

TEXT (if more space is required, use additional NRC Form 366A's) (17)

The involved workers were removed from all direct plant work pending the root cause investigation.

All PFO5 design change work packages performed by the contractor were reviewed to identify work items signed by the contractor supervisor involved in the event. It was verified that no additional sign-offs had been performed by the subject contract supervisor which had not also been verified by a second person.

Additionally a sample of work packages performed by other supervisors of the contractor were selected to be walked down in order to determine whether the situation was an isolated case. Results of these walkdowns indicated that no additional work was signed off as complete by the job supervisors without actually being performed.

Additional corrective actions will be dependent upon completion of the root cause determination.

F. Safety Assessment

An assessment of the potential dose consequences for secondary containment bypass leakage paths was performed and discussed in LER 92-11-00. Although the calculated doses from the design basis assessment of a postulated accident were outside 10 CFR limits, the doses from the "realistic" assessment were well within the 10 CFR limits. The partially repaired condition described in this LER involved even less potential for bypass leakage than the condition reported in LER 92-11-00. The successful smoke tests confirmed that the potential bypass leakage was much less than the 250 CFM maximum condition evaluated in the "realistic" assessment. Therefore the health and safety of the public were not compromised due to this event.

G. Additional Information

Energy Industry Identification System (EIIS) codes are identified in the text within brackets [].

This is an interim report. An update will be provided by 8/10/92.

LER92012.DOC