U.S. Nuclear Regulatory Commission Approved OMB No. 3150-0104 Expires: 8/31/85

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Arkansas Nuclear One - Unit 2			DOCKET NUMBER (2) PAGE (3) 0 5 0 0 0 3 6 8 1 0F 0 1			
TITLE (4) Fire Door Se	If Closing Mechanis	m out of Adju	stment	Inipinini	01 31 91 811	UF U 1
EVENT DATE (5) LER NUMBER (6)		T DATE (7)	OTHER FACILITIES INVOLVED (8)			
Month Day Year Year Sequential	Revision Number Month	Day Year	Facilit	y Names	Docket Numb	er(s)
1 1 2 9 8 4 8 4 0 2 9 OPERATING THIS REPORT IS SUBMITTE	0 1 0 1 11 21	21 01 81 41	0E 10 CED 8		0 5 0 0 0	士士
MODE (9) 1 (Check one or more of POWER 20.402(b)	the following) (1	1)	73(a)(2)(iv		71763	
LEVEL	50.36(c)(1) 50.36(c)(2) X 50.73(a)(2)(i) 50.73(a)(2)(ii)	50. 50. 50. 50.	73(a)(2)(v) 73(a)(2)(vi 73(a)(2)(vi 73(a)(2)(vi	i) 73 0t	.71(b) .71(c) her (Specify stract below Text, NRC Fo	and
1 20.405(a)(1)(v) 1	LICENSEE CONTACT) 50.	73(a)(2)(x)	1 36	6A)	
	ogers, Plant Licens			I Are		
COMPLETE ONE LINE F	OR EACH COMPONENT	FAILURE DESCR	IBED IN THI	S REPORT (13)		121212
Cause System Component Manufacturer	Reportable to NPRDS	Cause System	Component	Manufacturer	Reportable to NPRDS	
			111	111		
SUPPLEMENT RE	ORT EXPECTED (14)		111	EXPECTED	Month! Day	Tyear
Yes (If yes, complete Expected Submission Date) X No ABSTRACT (Limit to 1400 spaces i.e. approximately fifteen single-space typewn)				SUBMISSION DATE (15)		I I

On 11/29/84 at 1535 hours, it was discovered that the self closing mechanism for Fire Door 284 lacked sufficient force to completely close the door. This door separates ANO-1 and ANO-2 at the 386' elevation, but is only required by ANO-2 Technical Specifications (T.S.). A fire watch was posted within one hour as required by TS 3.7.11. Due to the high usage of this door, the hydraulic oil cylinders and seals on the self closing mechanism deteriorated to the point where the door would not automatically close and latch. The self closing mechanism for Fire Door 284 was replaced, and the door was checked for proper operation. The frequency of fire door inspections for high use doors is being re-evaluated to improve identification of repair requirements before failures occur. Another occurrence relating to a faulty door closing mechanism was reported in LER (50-368) 83-045.

1/1



ARKANSAS POWER & LIGHT COMPANY

POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000 December 20, 1984

2CAN1284Ø8

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Subject: Arkansas Nuclear One - Unit 2

Docket No. 50-368 License No. NPF-6 Licensee Event Report

No. 84-029

Gentlemen:

In accordance with 10CFR50.73(a)(2)(i), attached is the subject report concerning the discovery that the self closing mechanism for Fire Door 284 lacked sufficient force to completely close the door.

Very truly yours,

J. Ted Enos

Manager, Licensing

JTE: RJS: ds

Attachment

cc: Mr. Richard C. DeYoung Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission Washington, DC 20555

> Mr. Norman M. Haller, Director Office of Management & Program Analysis U. S. Nuclear Regulatory Commission Washington, DC 20555

> > IEZZ