NAC FW 19-431	n 264							LIC	ENSE	E EVE	NT RE	PORT	(LER)		U.S. MUG	APPROV		NO. 3160-		
ACILITY	-	11													OCKET MARER			PAO	Contraction of the local division of the loc	
Pea	ich I	Bott	om	Ato	omic	P	owe	er s	Stat	ion	- Un	it		0	1510101	021	7 18	1 OF	03	
HP		Turb	ine	E>	chau	st	Li	ine	Inn	er R	uptui	re Di	sc	(PSD	3-23-6)	Fa	ilu	re		
LVI	NT DATE	())	1	L			11		AL	PORT DA	re in 1			THER P	ACILITIES INVOL					
HONTH	ONTH DAY YEAR		YEAR	TLAR SELUCIATION		12	ALVEN A	MONTH DAY		YEAR	FACILITY NA					DOCKET NUMBERIS				
																0 151	010	101		
1 2	214	8 14	8 4			6		0 10	0 1	2 3	the second se					0 151	0 1 0	101		
641	AATING		-	PORT		-	PUR	SUANT 1	O THE P	COURCE	ENTS OF 10	CPR 1: 10	iners and a	i mais al	the fairemanai (11					
	-001 (#) N					29.404	(e)		_	60.73401			73,71601							
Pont		20.404141110			-	60.36(a)(1) 60.73(a)(2)(4)					R. S. A. S. A	TETIN								
(10)	1101 0 18 10 20.400 (a) (11) (a)		60.73(c)(2)						mand bal	~~~~	and in Test, NRC form									
29.666(s)(1)(90) 29.406 (s)(1)(91)			60,73(a)(3)(V) 80,73(a)(3)(V(A)(B)					Voluntary Repo												
	1.74		_		115 1601	1.5		-	10.174	11211143			60.73ial	21(+)	in since of			1		
						100			ICENSEE	CONTAC	FOA THIS	LER (12)								
NAME							199						AREA COOL	TELEPHO	HE NUM	ILA				
J	. c.	Nag	gle,	E			*	* *			y Spe			-	2 45	8,4	11 -	1 5	1814	
			-		cow	-	ONEL	INE FOR	LACH C	OMPONEN	TFAILURE	DESCRIBE	D IN THIS	REPORT	1131			- MA 100.075		
CAUSE		cour	ONENT		TURER			ATALLE			CAUSE	EVETEM	COUPO	NENT	TUALA	TO N				
в	BJ	, R	PID	C	5 18	3,5		Y	200	71. (s)				1			50 Your			
				T						1996	8			1						
		_			L_L_												MONTH	CAY	YEAR	
	SUPPLEMENTAL REPORT ED												EXPECTE	ION			-			
								-							DATE IT				1	

Abstract: 3-84-16

8502060143 8501 PDR ADOCK 05000

While at power during surveillance testing, the HPCI turbine exhaust rupture diaphragm alarm annunciated during operation of the Unit 3 HPCI Turbine. Inspection revealed that the inner rupture disc, PSD3-23-6, had failed. The HPCI turbine was intentionally removed from service to replace the inner rupture disc. Immediately after removing the turbine from service, the systems required by Technical Specification 4.5.C.2 (RCIC, ADS, LPCI, and Core Spray) were verified to be operable. The rupture disc was replaced and HPCI was declared operable following surveillance test verification.

JX 11

A-1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104

EXPIRES B/31/86

ACILITY NAME III	DOCKET NUMBER (2)		LER NUMBER (6)							PAGE (3)		
Peach Bottom Atomic			YEAR SEQUENTIAL REVISION									
Power Station - Unit	0 15 10 10 10 1	1	8 4	_	011	6	_	010	0	12	OF (13

EX1 fit more space is required, use additional NRC Form 366A's) (17)

NRC Form 366A

Description of the Event:

On December 24, 1984, Peach Bottom Atomic Power Station Unit 3 was operating under normal conditions at 85% power. At approximately 3:00 a.m., while conducting a surveillance test (ST-6.5, HPCI Pump, Valve Flow and Cooler Test) on the Unit 3 HPCI system, the turbine exhaust rupture diaphragm alarm annunciated after the HPCI turbine had been running for about ten minutes. This alarm senses a pressure of greater than 10 psig between the inner and outer rupture discs located in series in a 16" line which taps off the turbine exhaust line and exhausts to the torus room. Investigation revealed that the inner rupture disc, PSD3-23-6 (manufactured by Continental Disc Corporation), had failed. The nominal setpoint of the rupture disc is 175 psig. The HPCI system was intentionally removed from service and declared inoperable at 7:30 a.m. to replace the inner rupture disc. The HPCI turbine was declared operable and returned to service at 11:05 a.m. the same day, following surveillance test (ST-6.5) verification.

Consequences of the Event:

The outer rupture disc, PSD3-23-7, was not affected; therefore, the HPCI system could have remained operable if HPCI operation was required. As a result of the inner rupture disc failure, a small amount of steam was passed to the torus compartment through the one-eigth inch orifice between the inner and outer rupture disc. After intentionally removing the HPCI system from service to replace the inner rupture disc, the Reactor Core Isolation Cooling System, Automatic Depressurization System, Low Pressure Coolant Injection System, and Core Spray systems were verified as operable as required by Technical Specification 4.5.C.2.

Cause of the Event:

Inspection of the inner rupture disc, following this event, revealed a one-quarter inch puncture which allowed the pressure between the inner and outer rupture discs to slowly increase to the alarm setpoint while the HPCI turbine was operating.

LICENSEE EVENT RE	PORT (LER) TEXT CONTIN	UATION		APPROVED C EXPIRES: 8/3	MB NO. 31		ON
FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6)	PAGE (3)			
Peach Bottom Atomic		YEAR	SEQUENTIAL	REVISION NUMBER			
Power Station - Unit	0 5 0 0 0	814 -	0116	-00	0 3	OF O I	3

TEXT III more space is required, use additional NRC Form 366A's) [17]

Corrective Actions:

ST 6.5 HPCI Pump, Valve, Flow, Cooler Test verified the operability of the HPCI system following replacement of the inner rupture disc. Turbine exhaust pressure indication was normal during the test and the system was returned to service.

The Philadelphia Electric Company Metallurgical Laboratory is performing an analysis of the failed rupture disc in an attempt to determine the failure mechanism exhibited by the one-quarter inch puncture.

Previous Similar Occurrences:

LER's: 3-83-15/3L-0, 3-82-23/3L-0, 3-84-001-00, 3-84-013-00, 3-84-015-00.

PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

P.O. BOX 8699

PHILADELPHIA, PA. 19101

(215) 841-4000

January 23, 1985

Docket No. 50-278

Document Control Desk U.S. Nuclear Regulatory Commission Washington, DC 20555

> SUBJECT: Licensee Event Report Peach Bottom Atomic Power Station - Unit 3

This LER deals with the failure of the Unit No. 3 HPCI turbine exhaust inner rupture disc, PSD3-23-6, while performing surveillance testing on the HPCI system.

Reference: Report Number:	Docket No. 50-278 3-84-16
Revision Number:	00
Event Date:	December 24, 1984
Report Date:	January 23, 1985
Facility:	Peach Bottom Atomic Power Station RD #1, Box 208, Delta, PA 17314

Since the HPCI turbine could have remained operable following failure of the inner rupture disc, this LER is submitted as a voluntary report.

Very truly yours, W. T. Ullrich /

W. T. Ullrich / Superintendent Nuclear Generation Division

cc: Dr. Thomas E. Murley, Administrator Region I, USNRC

Mr. T. P. Johnson, Resident Inspector

I.E.2.2 1/1