

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Joseph M. Farley - Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 3 6 4	PAGE (3) 1 OF 0 1
--	--------------------------------------	----------------------

TITLE (4)
Steam Generator Tube Plugging

EVENT DATE (6)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0 1	1 9	8 5	8 5	0 0 1	0 0	0 1	2 8	8 5			0 5 0 0 0
OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)									

POWER LEVEL (10) 0	20.402(b)	20.406(c)	50.73(a)(2)(iv)	73.71(b)
	20.406(a)(1)(ii)	50.36(c)(1)	50.73(a)(2)(v)	73.71(c)
	20.406(a)(1)(iii)	50.36(c)(2)	50.73(a)(2)(vii)	<input checked="" type="checkbox"/> OTHER (Specify in Abstract below and in Text, NRC Form 366A)
	20.406(a)(1)(iii)	50.73(a)(2)(i)	50.73(a)(2)(viii)(A)	
	20.406(a)(1)(iv)	50.73(a)(2)(iii)	50.73(a)(2)(viii)(B)	
	20.406(a)(1)(iv)	50.73(a)(2)(iii)	50.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME J. D. Woodard	TELEPHONE NUMBER 2 0 5 8 9 9 7 5 1 5 6
-----------------------	---

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE) NO

EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

The following steam generator tube plugging report is submitted in accordance with Technical Specification 4.4.6.5.a.

During the Unit 2 Cycle III-IV refueling outage, a total of nine tubes were plugged in the 2A steam generator based on eddy current testing results. Of these nine tubes, three exceeded the pluggable limit. The remaining six tubes were plugged as a precautionary measure because there was evidence of tube wall degradation. Additionally, one tube was plugged in the 2B steam generator because an eddy current probe was stuck in the tube. Tube plugging was completed 1-19-85.

The complete results of the steam generator tube inservice inspection will be reported in accordance with Technical Specification 4.4.6.5.b.

8502060321 850128
PDR ADOCK 05000364
S PDR

IE22
44

Mailing Address

Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Alabama 35291
Telephone 205 783-6090

R. P. McDonald
Senior Vice President
Flintridge Building



Alabama Power
the southern electric system

January 28, 1985

Docket No. 364


Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Sir:

Joseph M. Farley Nuclear Plant, Unit 2, Licensee Event Report
No. LER 85-001-00 is forwarded in accordance with Technical Specification
4.4.6.5.a.

If you have any questions, please advise.

Yours very truly,



R. P. McDonald

RPM:sam

Enclosure

xc: IE, Region II

IE22
//