U.S. NUCLEAR RECULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES 8/31/85 LICENSEE EVENT REPORT (LER) DOCKET NUMBER (2) FACILITY NAME (1) Callaway Plant Unit 1 1 OF 0 | 5 | 0 | 0 | 0 | 4 | 8 | TITLE (4) Reactor Trip Due to Feedwater Isolation Valve Failure REPORT DATE (7) OTHER FACILITIES INVOLVED (8) EVENT DATE (6) LER NUMBER (8) DOCKET NUMBER(S) FACILITY NAMES MONTH MONTH DAY DAY YEAR 0 | 5 | 0 | 0 | 0 0 0 0 1 0 1 0 2 8 5 8 5 0 0 1 2 8 8 0 | 5 | 0 | 0 | 0 | THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR & (Check one or more of the following) (11) OPERATING MODE (9) 20.405(c) 50.73(a)(2)(iv) 73.71(b) 50.73(a)(2)(v) 73.71(e) 20.406(a)(1)(i) 50.36(c)(1) OTHER (Specify in Abstract below and in Text, NRC Form 3664) 50 73(a)(2)(vii) 510 20.405(a)(1)(ii) 50.36(c)(2) 20.405(a)(1)(iii) 50.73(a)(2)(i) 50.73(a)(2)(viii)(A) 20.406(a)(1)(iv) 50.73(a)(2)(viii)(8) 50 73(a)(2)(ii) 50.73(a)(2)(x) 20.408(a)(1)(v) 50.73(a)(2)(iii) LICENSEE CONTACT FOR THIS LER (12) TELEPHONE NUMBER NAME AREA CODE William R. Campbell - Superintendent, Engineering 617161-1814 6 19 COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13) MANUFAC REPORTABLE TO NPROS EPORTABLE TO NPROS CAUSE SYSTEM COMPONENT CAUSE SYSTEM COMPONENT SIJISIV A 1 3 9 11 N

ABSTRACT (Limit to 1400 spaces i.e. approximately fifteen single-space typewritten lines) (16)

YES (If yes complete EXPECTED SUBMISSION DATE)

SUPPLEMENTAL REPORT EXPECTED (14)

On 1/2/85 an inadvertent Steam Generator (S/G) Lo-Lo level Reactor Trip occurred.

With the reactor at approximately 50% power, the S/G 'A' Feedwater Isolation Valve (FWIV) fast closed. S/G 'A' level proceeded to drop rapidly until a S/G 'A' Lo-Lo level Reactor Trip was initiated. A Turbine Trip, Feedwater Isolation, Auxiliary Feedwater Actuation and S/G Blowdown Isolation also occurred coincident with the Reactor Trip, as designed. All equipment and personnel responded as expected following the trip.

Subsequent investigation revealed that the FWIV fast closed due to a failed solenoid in the valve control circuit. The solenoid was replaced and the valve returned to service.

8502060506 850128 PDR ADDCK 05000483 PDR PDR IE 22

MONTH

EXPECTED

DAY

YEAR

NRC Form 366A (9-83)	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION			U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-3104 EXPIRES: 8/31/85		
FACILITY NAME (1)		DOCKET NUMBER (2)	. LER NUMBER (6)		PAGE (3)	
			YEAR SEQUE	NTIAL REVISION		
	Callaway Plant Unit 1	0 5 0 0 0 4 8 3	815 - 010	011 - 010	0 1 2 OF	0 2

On 1/2/85 an unplanned Reactor Trip occurred. Prior to the trip, the plant was in Mode 1 at approximately 50% power.

At 0740 CST, Feedwater Isolation Valve (FWIV) AE-FV-39 "fast closed." As the plant was at 50% power, the level in Steam Generator (S/G) 'A' proceeded to drop rapidly. Approximately forty seconds after the FWIV closed, a Reactor Trip occurred due to a S/G 'A' Lo-Lo level. Other actuations that occurred coincident with the Reactor Trip were a Turbine Trip, Feedwater Isolation, Auxiliary Feedwater Actuation and S/G Blowdown Isolation. Operators recovered from the event via plant emergency operating procedures. All equipment and personnel responded as expected following the actuations.

Subsequent investigation identified that a failed solenoid valve in the FWIV hydraulic actuator unit had caused the FWIV closure. (Manufacturer: Anchor, Parling Valve Co. - Model No. S.O. E6181). When the normally energized solenoid failed, the solenoid valve position shifted to the "fast close" configuration. This aligned the high pressure hydraulic accumulators to the hydraulic piston, which is attached to the FWIV valve stem, causing the FWIV to shut.

The solenoid valve was replaced and the FWIV returned to service. No additional corrective actions are planned, as this incident is considered a single random failure event.

Loss of normal feedwater flow from 100% power is an analyzed event in the plant safety analysis report. Results of the analysis show that a loss of normal feedwater does not adversely affect the core, the Reactor Coolant System, or the steam system, since the auxiliary feedwater capacity is such that reactor coolant water is not relieved from the pressurizer relief or safety valves. Therefore, at no time did this event pose a threat to the public health or safety.

Previous occurrences: none

UNION ELECTRIC COMPANY

P.O. BOX 620 FULTON, MO. 65251

January 28, 1985

U. S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

ULNRC-1023

Gentlemen:

DOCKET NUMBER 50-483
CALLAWAY PLANT UNIT 1
FACILITY OPERATING LICENSE NPF-30
LICENSEE EVENT REPORT 85-001-00
REACTOR TRIP DUE TO FEEDWATER ISOLATION VALVE FAILURE

The enclosed Licensee Event Report is submitted pursuant to 10 CFR 50.73(a)(2)(iv) concerning inadvertent Engineered Safety Features actuations caused by a Feedwater Isolation valve failure.

S. E. Miltenberger

Manager, Callaway Plant

andrew P. Neuhalfen

WRC/WRR/JMS/drs Enclosure

cc: Distribution attached

IEZZ

cc distribution for ULNRC-1023

Mr. James G. Keppler
Regional Administrator
Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

American Nuclear Insurers c/o Dottie Sherman, Library The Exchange Suite 245 270 Farmington Avenue Farmington, CT 06032

Records Center
Institute of Nuclear Power Operations
Suite 1500
1100 Circle 75 Parkway
Atlanta, GA 30339

NRC Resident Inspector Missouri Public Service Commission

D. F. Schnell

J. F. McLaughlin

J. E. Davis (Z40LER)

D. W. Capone/R. P. Wendling

F. D. Field

R. L. Powers

A. C. Passwater/D. E. Shafer/D. J. Walker

G. A. Hughes

W. R. Robinson (QA Record)

W. R. Campbell

C. D. Naslund

J. M. Price

R. A. McAleenan

L. K. Robertson (470) (NSRB)

Merlin Williams, Wolf Creek

SEM Chrono

3456-0021.6

3456-0260

Z40ULNRC

G56.37

N. Date