NRC Form 306 (9-83)						ENSEE E	EVENT RE	PORT	(LER)	U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES 8/31/85								
PACILITY NAME (1) DOCKET NUMBER							DOCKET NUMBER	(2)		OE 13								
	167	DIAB	LO CA	ANYON UNIT	1					0 5 0 0	10121715	1 0	012					
TITLE		REAC	TOR C	COOLANT SY	STEM LO	OP LOW	FLOW REA	CTOR	TRIP									
	VENT DATE	(6)		LER NUMBER	(6)	REPORT	T DATE (7)		OTHER	FACILITIES INVO	LVED (8)							
MONTH	DAY	YEAR	YEAR	SEQUENTIAL	L REVISION NUMBER	MONTH D	AY YEAR	FACILITY NAMES		MES	DOCKET NUMBER(S)							
											0 15 10 10 10 1							
0 1	0 2	8 5	8 5	0 0 1	- 00	0 2 0	1 8 5				0 5 0 0	101	11					
	ERATING		THIS RE	EPORT IS BURMITTE	ED PURSUANT	TO THE REQUI	REMENTS OF 1	0 CFR 5: /	Check one or more	of the following) (1	1)	1941						
MODE (8) 1 POWER LEVEL (10) 4 9		20	0.402(b) 0.408(a)(1)(l) 0.408(a)(1)(ll)		20.408(e) 90.38(e)(1) 50.38(e)(2)		X	50.73(a)(2)(iv) 50.73(a)(2)(v) 90.73(a)(2)(vii)	73.71(b) 73.71(c) OTHER (Specify in Abstract below and in Text, NRC Form									
-			20	20.406(a)(1)(iii) 20.406(a)(1)(iv) 20.408(a)(1)(v)			80.73(a)(2)(i) 80.73(a)(2)(ii) 80.73(a)(2)(iii)			60.73(a)(2)(viii)(A) 80.73(a)(2)(viii)(B) 50.73(a)(2)(x)			366A)					
					L	ICENSEE CON	TACT FOR THIS	LER (12)										
NAME		DAVI	D P.	SISK, REG	ULATORY	COMPLIA	ANCE ENG	INEER		AREA CODE	5 9 5 -		5,1					
	THE REAL			COMPLETE	ONE LINE FOR	EACH COMPO	NENT FAILURE	DESCRIBE	D IN THIS REPO	AT (13)		100	1000					
CAUSE	SYSTEM	COMP	ONENT	MANUFAC- TURER	REPORTABLE TO NPRDS		CAUSE	SYSTEM	COMPONENT	MANUFAC TURER	REPORTABLE TO NPROS							
В	TIG	1F	1511	P101710	N				111									
									111	111								
SUPPLEMENTAL REPORT EXPECTS J (14)							EXPECTE	MONTH	DAY	YEAR								
YES (If yes, complete EXPECTED SUBMISSION DATE) ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typen						NO .	SUBMISSI DATE (1			ON								

While in Mode 1 (Power Operation), the reactor tripped on reactor coolant system (RCS) low flow when a solenoid valve failure in the turbine overspeed protection controller (TOPC) system caused the turbine to slow with a corresponding drop in RCS flow. Diesel Generator 1-2 autostarted but did not load. While shifting to startup power, two of five containment fan cooler units, CFCU 1-1 and 1-4 tripped on thermal overload after autostarting on high speed.

The plant was stabilized in Mode 3 (hot standby) in accordance with procedures. All systems and equipment affected by this event were returned to normal operation. SV-41 was replaced with a spare and tested satisfactorily on January 4, 1985.

8502060593 850201 PDR ADDCK 05000275 S PDR I & 22

NRC Form 366A (9-83) LICENSEE EVENT RI	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION							NUCLEAR REGULATORY COMMISSION APPROVED OMB NO 3150-0104 EXPIRES 8/31/85				
FACILITY NAME (1)	DOCKET NUMBER (2)		LE	R NUMBER (6)	6)		PAGE (3)					
		YEAR		SEQUENTIAL NUMBER	REVIS							
DIARLO CANVON LINIT 1	0 15 10 10 10 12 17 15	815	_	01011	- 01		012	OF	0.12			

At 1945 PST, January 2, 1985, with Unit 1 in Mode 1 (Power Operation), low flow in the Reactor Coolant System (AB) initiated a reactor trip during the performance of Start Up Procedure 43.7, "Net Load Trip From 50 Percent Power." A solenoid valve in the Turbine Overspeed Protection Controller (TOPC) System caused the turbine (TA) (TRB) to slow with a corresponding drop in RCS flow. All automatic equipment responded as designed. Diesel Generator 1-2 autostarted but did not load. When shifting to startup power, two of five Containment Fan Cooler Units (BK) (FCU), CFCU 1-1 and 1-4 tripped on thermal overload after autostarting on high speed. They were manually started in low speed. The high speed windings were reset and both CFCUs were successfully started on high speed. Operations personnel blocked the Low Pressure Safety Injection (LPSI) signal to prevent an unnecessary safety injection actuation from post trip conditions, i.e., steam demand from the Auxiliary Steam System and Main Turbine Pilot Trip Valve leakage. The LPSI setpoint was never reached and the block was reset when plant conditions were stabilized.

The trip was caused by a solenoid valve failure in the Turbine Overspeed Protection Controller (TOPC) System. This system causes the turbine governor (TA) (FCV) and intercept (TA) (ISV) valves to close for short periods to prevent turbine overspeed during transients. TOPC Solenoid Valve SV-41 stuck open during the load rejection transient. This prevented the governor (TA) (FCV) and intercept (TA) (ISV) valves from reopening, thus allowing the Turbine (TA) (TRB) to slow, and generator frequency to approach 54 Hertz. The reactor coolant pump's speed dropped as frequency dropped. This lowered flow in the reactor coolant system causing an RCS loop low flow reactor trip.

The plant was stabilized in Mode 3 (Hot Standby) in accordance with procedures. All systems and equipment affected by this event were returned to normal operation. SV-41 was replaced with a spare and tested satisfactorily on January 4, 1985. Start Up Test 43.7 was completed satisfactorily on January 5, 1985.

This event was a previously analyzed Condition II event and had no effect on the health and safety of the public.

PACIFIC GAS AND ELECTRIC COMPANY

TP G = 18 - 77 BEALE STREET . SAN FRANCISCO, CALIFORNIA 94106 . (415) 781-4211 . TWX 910-372-6587

JAMES D. SHIFFER VICE PRESIDENT NUCLEAR POWER GENERATION February 1, 1985

PGandE Letter No.: DCL-85-044

Document Control Desk U. S. Nuclear Regulatory Commission Washington, D.C. 20555

Re: Docket No. 50-275, OL-DPR-80

Diablo Canyon Unit 1

Licensee Event Report 85-001-00 ESF Actuation - Reactor Trip

Gentlemen:

Pursuant to 10 CFR 50.73(a)(2)(iv), PGandE is submitting the enclosed Licensee Event Report concerning the inadvertent actuation of an engineered safety feature, reactor trip.

This event has in no way affected the public's health and safety.

Kindly acknowledge receipt of this material on the enclosed copy of this letter and return it in the enclosed addressed envelop.

for J. D. Shiffer

Enclosure

cc: J. B. Martin

Service List