cc w/encl. sures:

Mr. O. Mark DeMichele, APS Mr. James M. Levine, APS

Mr. R. Stevens, APS Mr. S. Guthrie, APS Mr. E. C. Simpson, APS Mr. Robert W. Page, APS Mr. Thomas R. Bradish, APS

Mr. Arthur C. Gehr, Esq., Snell & Wilmer

Mr. Al Gutterman, Esq., Newman & Holtzinger P. C. Mr. Curtis L. Hoskins, El Paso Electric Company

Mr. Charles R. Kocher, Esq., Assistant Council, Southern California Edison Company

Mr. James A. Beoletto, Esq., Assistant Council, Southern California Edison Company

Mr. John W. Norman, Chief, Arizona Corporation Commission

Mr. Steve M. Olea, Chief Engineer, Arizona Corporation Commission

Mr. Charles B. Brinkman, Combustion Engineering, Inc.

Mr. Roy P. Lessy, Jr., Esq., Akin, Gump, Strauss, Hauer and Feld Mr. Bradley W. Jones, Esq., Akin, Gump, Strauss, Hauer and Feld Ms. Nancy C. Loftin Esq., Corporate Secretary & Counsel, APS

Mr. Jack R. Newman, Esq., Newman & Holtzinger, P.C. Mr. William A. Wright, Acting Director, Arizona Radiation

Regulatory Agency (ARRA)
Chairman, Maricopa County Board of Supervisors
Institute for Nuclear Power Operations (INPO)

bcc w/enclosures: The Chairman Commissioner Rogers Commissioner Curtiss Commissioner Remick Commissioner de Planque J. Taylor, EDO J. Sniezek, EDO T. Murley, NRR J. Partlow, NRR M. Virgilio, NRR B. Boger, NRR P. Ray, NRR S. Shankman, OEDO J. Lieberman, OE C. Trammell, NRR C. Thompson, NRR T. Quay, NRR C. Holden, NRR J. Martin B. Faulkenberry Project Inspector Resident Inspector G. Cook SALP Board Members DCS PDR LPDR Docket File

bcc w/o enclosure:
J. Zollicoffer

M. Smith

400 LMiller BO1sonto HWO! 3 SRichards 7 /8 /92 7/10/92 19/92 7/10/92 REQUEST COPY REQUEST COPY REQUEST COPY REQUEST CORY REQUEST COPY YES) NO NO YES / NO RZimmerman FWenslawsk9 JMartin 7/9/92 7/10/92 7/10/92 REQUEST COPY REQUEST COPY REQUEST CORY NO

NRC CONCLUSIONS

A. Comments Received From The Licensee

Arizona Public Service Company's (APS) July 1, 1992, response to the Palo Verde SALP Report presented no significant objections to the content of the report. The APS response identified three corrections and clarifications to the report. These three comments have been incorporated into the final report and did not affect the conclusions or ratings for the associated functional areas.

B. NRC Conclusions Regarding Acceptability of the Licensee's Planned Corrective Actions

We concluded that your proposed actions to address areas needing improvement were responsive. We will review your progress as part of our future inspection program, as appropriate.

C. Regional Administrator's Conclusions Based on Consideration of the Licensee's Response

I have concluded that the overall ratings in the affected areas have not changed.

SALP BOARD REPORT REVISION SHEET

PAGE LINE 5 51

NOW READS: and the fire brigade;

SHOULD READ: ; training resson plans for the fire department;

Basis: The term "fire brigade" was used in NRC Inspection Report 50-528/529/530/91-21. Since Palo Verde has a fire department rather than a fire brigade, "fire department" should be used. The specific weakness identified in that inspection report was related to training lesson plans.

PAGE LINES 12-13

NOW READS: In 1991, the volume of radioactive waste shipped from the site decreased to approximately one-half of its 1990 value.

SHOULD READ: The total volume of radioactive waste generated in 1991 was almost ten percent lower than the 1990 total.

Basis: The original sentence accurately reflected the amount of waste shipped to a low level radioactive waste disposal facility, but did not include the amount of waste shipped for volume reduction. The new sentence reflects the amount of waste that was generated.

PAGE LINE 15 56 16 1

NOW READS: Reliability problems persist with nitrogen pressure regulators on atmospheric dump valves even after extensive engineering review and modification.

SHOULD READ: Foreign material has been found in a malfunctioning atmospheric dump valve (ADV) nitrogen regulator even after extensive engineering review and the addition of filters. In addition, several problems have occurred in this period where regulators were controlling above the maximum pressure range and where ADV positioners were found out of calibration.

Basis: The first new sentence provides the description of a condition that was documented in NRC Inspection Report 50-528/529/530/91-26. The other sentence describes problems identified with the atmospheric dump valves.

The additional sentence resulted in text being repositioned on pages 16 through 22.