OYSTER CREEK NUCLEAR GENERATING STATION Forked River, NJ 08731

Licensee Event Report Update
Reportable Occurrence No. 50-219/83-09/01X-2

Report Date

January 22, 1985

Previous Report Date

November 2, 1984

Occurrence Date

February 22, 1983

Identification of Occurrence

The results of local leak rate testing identified ten containment isolation valves and one gasket that failed to meet their acceptance criteria. This constitutes operation of the unit or affected systems when any parameter or operation subject to a limiting condition is less conservative than the least conservative aspect of the limiting condition for operation established in Technical Specifications, paragraph 4.5.F.d.

This event is considered to be reportable as defined in Technical Specification, paragraph 6.9.2.a.2.

Conditions Prior to Occurrence

The plant was in cold shutdown with reactor coolant temperature less than $212^{\mathrm{O}}\mathrm{F}$ and the reactor vented at the time the occurrence was identified. The reactor was in various operating modes prior to the occurrence.

Description of Occurrence

Local leak rate testing identified the following ten (10) valves and one (1) gasket with leakage in excess of the acceptance criteria of 12.08 SCFH @20 psig. The results of the leak rate test program for these valves and gasket are as follows:

DESCRIPTION I	PENETRATION	DATE TESTED	LEAKAGE @20 PSIG (SCFH)
Ins rument Air			
and Nitrogen System	V-6-395	3/4/83	30.49
MSIV	NS04A	2/14/83	16.34
MSIV	NS04B	2/14/83	17.21
MSIV Drain Valves	V-1-106, 107	2/14/83	19.44
Drywell Headseal	Gasket	2/16/83	544.68
Drywell Purge	V-27-1	2/18/83	34.08
Drywell Sump Discharge	V-22-28, 29	3/17/83	12.4
Drywell Vent	V-27-3, 4	2/27/83	23.19

8502010692 850122 PDR ADDCK 05000219 S PDR

Apparent Cause of Occurrence

The cause of the leakage is as follows:

- V-6-395, V-1-106, V-1-107, V-22-28, V-22-29, V-27-3, V-27-4, NS04A, and NS04B had deterioration of valve internals.
- II. Drywell Headseal cause unkown, seal appeared to be in good condition.
- III. V-27-1 stem was found to be out of proper alignment.

Analysis of Occurrence

For valves V-27-1, V-6-395, NS04A, NS04B, V-1-106, and V-1-107 at least one redundant valve for each containment penetration met the acceptance criteria.

The purpose of the Containment System is to provide a barrier to limit the release of radioactive material to the environment to less than 10CFR100 limits during design basis accident conditions. The failure of Containment Isolation Valves V-27-3, 4 and the Drywell Head Seal Gasket to meet required acceptance criteria could have resulted in these limits being exceeded. All other individual containment isolation valves which failed leak testing were in series with other redundant isolation valves which did meet the acceptance criteria.

Corrective Action

Valves V-1-106, 107, and V-6-395 have been replaced with new valves. NSO4A and NSO4B had their seats lapped, stems replaced, and packing changed. V-27-1 stem was adjusted. V-22-28 received a new seat, stem, and plug. V-22-29 had its seat lapped. V-27-3, 4 received new seats and the Drywell Head had a new seal installed.

All penetrations passed their subsequent Local Leak Rate Tests.

NRC FORM 384	LICENSEE EVENT REPORT
	IN SASE PRINT OR TYPE ALL REQUIRED INFORMATIONS
OII NIJ	0 CIPI 1 3 010 1 + 0 010 b 101 - 1 d 0 0 4 11 11 11 11 10 1 1 3
CONT NEPOL	TIL 10 0 1 5 10 10 10 12 1 19 10 10 12 12 12 18 13 10 10 11 12 12 18 15 10 10 10 10 10 10 10 10 10 10 10 10 10
[0] Loca	l leak rate testing revealed that ten containment isolation valves
and and	one gasket failed to meet their acceptance criteria. The failure of
AND DESCRIPTION OF PERSONS ASSESSED.	ell Vent Isolation Valves V-27-3 and 4 and Drywell Head gasket to
	required acceptance criteria could have resulted in exceeding 10CFR
Transportation Military and Publishers	limits during design basis accident conditions. All other contain-
011	isolation valves failing leak testing were in series with redundant
ole L valv	es which passed. Reportable per Tech Specs, paragraph 6.9.2.a.2.
<u>`olo</u>	LUDO TIO LINE IN O LEO DIO
① ¥	[813] <u>[101019] [1011] [X] [1011]</u>
TAMER S	TIME LET LOS LOS OF LAST OF LA
Dryw	the state of the s
111 dete	rioration of internals. All valves were either repaired or replaced.
	ough appearing to be in good condition, the Drywell head gasket was
II3 L repl	aced. All penetrations passed their subsequent local leak rate
TTA L test	
TANKE THIS	1 010 D 13 NA OTHER STATUS 3 LOCAL LEAK Rate Test Program
TIS HO	CONTENT 12 13 LOCATION OF RELEASE 36
ंग्ड हिं	IZ SI NA
الما وال	DIO 13 Z 3 NA
115 [0]0	OR CAMAGE TO PAGUTY (3)
الم الم	DL NA
7 1 1 1 10	NAC USE CALY OLICITY NA
7.5	Kenneth Hutko 609-971-4698



GPU Nuclear Corporation

Post Office Box 388 Route 9 South Forked River, New Jersey 08731-0388 609 971-4000 Writer's Direct Dial Number:

January 22, 1985

U.S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

Dear Sir:

Subject: Oyster Creek Nuclear Generating Station

Docket No. 50-219

Licensee Event Report Update

This letter forwards Reportable Occurrence No. 50-219/83-09/01X-2, a Licensee Event Report (LER) revision, in compliance with paragraph 6.9.2.a.2 of the Technical Specifications. The previous revision of this LER contained incorrect leak rates for three (3) valves (V-27-1, 3 and 4). This occurred due to an administrative error resulting from a procedure revision which had changed the leak rate data sheet number for the above valves.

Very truly yours,

Peter B. Fiedler

Vice President and Director

Oyster Creek

PBF:PC:dam Enclosures

cc: Dr. Thomas E. Murley, Administrator Region I U.S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

> NRC Resident Inspector Oyster Creek Nuclear Generating Station Forked River, NJ 08731