

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Dresden Nuclear Power Station Unit 2 DOCKET NUMBER (2) 0 5 0 0 0 2 3 7 1 OF 0 2 PAGE (3)

TITLE (4) Reactor Building/Turbine Building 517' Interlock Door Failure

| EVENT DATE (5) | | | LER NUMBER (6) | | | REPORT DATE (7) | | | OTHER FACILITIES INVOLVED (8) | | | | | | | | | | | | |
|----------------|-----|------|----------------|-------------------|-----------------|-----------------|-----|------|-------------------------------|---|------------------|-------------|---|---|---|---|---|---|---|---|---|
| MONTH | DAY | YEAR | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | MONTH | DAY | YEAR | FACILITY NAMES | | DOCKET NUMBER(S) | | | | | | | | | | |
| 0 | 1 | 0 | 3 | 8 | 5 | 8 | 5 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| N/A | | | | | | | | | | | | 0 5 0 0 0 0 | | | | | | | | | |
| N/A | | | | | | | | | | | | 0 5 0 0 0 0 | | | | | | | | | |

OPERATING MODE (9) N THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 19 CFR 8: (Check one or more of the following) (11)

| | | | |
|-------------------|------------------|---------------------|--|
| 20.402(b) | 20.406(e) | 90.73(a)(2)(iv) | 73.71(b) |
| 20.406(a)(1)(i) | 90.36(a)(1) | 90.73(a)(2)(v) | 73.71(a) |
| 20.406(a)(1)(ii) | 90.36(a)(2) | 90.73(a)(2)(vi) | OTHER (Specify in Abstract below and in Text, NRC Form 386A) |
| 20.406(a)(1)(iii) | X 90.73(a)(2)(i) | 90.73(a)(2)(vii)(A) | |
| 20.406(a)(1)(iv) | 90.73(a)(2)(ii) | 90.73(a)(2)(vii)(B) | |
| 20.406(a)(1)(v) | 90.73(a)(2)(iii) | 90.73(a)(2)(ix) | |

LICENSEE CONTACT FOR THIS LER (12)

NAME Leslie Turnquest (X-489) TELEPHONE NUMBER 8 1 5 9 4 2 2 9 2 0

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

| CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO NPROS | CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO NPROS |
|-------|--------|-----------|--------------|---------------------|-------|--------|-----------|--------------|---------------------|
| X | | | | | | | | | |

SUPPLEMENTAL REPORT EXPECTED (14) YES (If yes, complete EXPECTED SUBMISSION DATE) X NO

EXPECTED SUBMISSION DATE (15) MONTH DAY YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

During a normal refueling outage, the control room received the Reactor/Turbine 517' Interlock alarm, indicating the interlock doors were simultaneously open. Secondary containment was momentarily broken, but was immediately re-established when personnel in the interlock promptly pushed the Turbine Building door closed. The Turbine Building door was closing too quickly and bouncing back open, while the Reactor Building door was permitted to be opened. The closure arms for the interlock doors were adjusted to allow slower closing of the doors. The interlock functioned as designed, and no further problems were noted.

IE 22
1/1

8502070086 850130
PDR ADOCK 05000237
S PDR

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

| | | | | | | | |
|--|--|----------------|-------------------|-----------------|----------|----|-------|
| FACILITY NAME (1) Dresden Nuclear Power Station, Unit 2 | DOCKET NUMBER (2) 0 5 0 0 0 2 3 7 | LER NUMBER (8) | | | PAGE (3) | | |
| | | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | | | |
| | | 8 5 | - 0 0 2 | - 0 0 | 0 2 | OF | 0 2 |

TEXT (If more space is required, use additional NRC Form 386A's) (17)

During a normal refueling outage on 1/3/85, at 1245 hours, the Reactor/Turbine 517' Interlock Doors Inop/Bypass alarm E-19 annunciated in the control room. Coincidentally, plant personnel were exiting the Reactor Building through the interlock doors. As they entered the interlock, they noticed that the Turbine Building door was still open at the same time the Reactor Building door was open. Secondary containment was momentarily broken, but was immediately re-established when personnel quickly pushed the Turbine Building door closed. Safety significance was minimal due to the short duration that secondary containment was lost.

A Foreman, investigating the problem, found the interlock functioning as designed, but also noticed that the doors were closing too quickly and consequently bouncing back. It appears that when the Turbine Building door closes, it makes contact long enough, before bouncing back, to energize the relay mechanism that permits the Reactor Building door to be opened. Provided the Reactor Building door button is depressed during that time, the door will open. The Turbine Building door, as it bounces, will also remain open due to the negative pressure in the Reactor Building with respect to the Turbine Building. The problem was corrected by adjusting the Reactor and Turbine Building door closure arms in order to allow the doors to close more slowly and eliminate bouncing. The door closures are adjusted in conjunction with building pressures to allow for proper closing of the doors but changing conditions with the ventilation systems may require readjustment. Modifications M12-2-85-9 and M12-3-85-9 have also been initiated in order to install time delay relays that will require one door to be closed for approximately 2 seconds before the other door can be opened. This will prevent simultaneous opening of the interlock doors in the event the interlock doors bounce when closed.

Previous occurrence was reported by R.O. 84-024-0 on Docket 50-237.



Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

January 30, 1985

DJS Ltr #85-111

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Licensee Event Report #85-002-0, Docket #050237 is being submitted as required by Technical Specification 6.6, NUREG 1022 and 10 CFR 50.73 (a)(2)(i)(B).

D.J. Scott
Station Superintendent
Dresden Nuclear Power Station

DJS/kjl

Enclosure

cc: J.G. Keppler, Regional Administrator, Region III
File/NRC
File/Numerical

IE22
11