

September 14, 1992

Ltr: BYRON 92-0609

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Dear Sir:

The enclosed Licensee Event Report from Byron Generating Station is being transmitted to you in accordance with the requirements of 10CFR50.73(a)(2)(i)(B).

This report is number 92-005; Docket No. 50-455.

Sincerely,

R. Pleniewicz

Station Manager

Byron Nuclear Power Station

RP/CW/mw

Enclosure: Licensee Event Report No. 92-005

CC: A. Bert Da ', NRC Region III Administrator
W. Kropp, NRC Se. or Resident Inspector
INPO Record Center
CECo Distribution List

(0960R/VS)

(1609.)

LICENSEE EVENT REPORT (LER)	Form Rev 2.0
Facility Name (1)	Docket Number (2)   Page (3)
Byron, Unit 2	01 51 01 01 01 41 51 5 1 0 0 1 3
fitle (4)	
LCOAR Inadvertently Not Entered	
Event Date (5)   LER Number (6)   Report Date (7)	Other facilities Involved (8)
Month Day Year Year /// Sequential /// Revision Month Day Year Number	facility Names   Ducket Number(s)
	Byron, Unit 1 0  5  0  0  0  4  5  4
0 8 1 4 9 2 9 2 0 0 1 5 0 0 0 9 1 4 9 2	0 5 0 0 0 1 1
OPERATING THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIRE	MENTS OF 10CFR 0.73(a)(2)(iv)   73.71(b)
POWER 20.405(a)(1)(i) 50.36(c)(1) 50.36(c)(2) 50.405(a)(1)(ii) X 50.73(a)(2)(i) 50.405(a)(1)(iv) 50.73(a)(2)(ii) 50.73(a)(2)(ii) 50.73(a)(2)(ii) 50.73(a)(2)(ii) 50.73(a)(2)(ii) 50.73(a)(2)(ii)	0.73(a)(2)(v) 73.71(c) 0.73(a)(2)(vii) Other (Specify on the control of the cont
Name J. Penick, Technical Staff Engineer Ext. 2656  R. Hopkins, Operating Engineer Ext. 2614	TELEPHONE NUMBER  DE
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBE CAUSE   SYSTEM   COMPONENT   MANUFAC-   REPORTABLE   3444444   CAUSE   SYSTEM	COMPONENT   MANUFAC-   REPORTABLE   //////
TURER TO NPRDS	TUPER TO NPROS
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
X  Yes (If yes, complete EXPECTED SUBMISSION DATE)   NO	Expected   Month   Day   Year Submission Date (15) 0 1 1 5 9 3

On U8/13/92, at approximately 0742, Mechanical Maintenance initiated repairs to Extraction Steam non-return check val. 2ES002, per Nuclear Work Request (NWR) B93935. Packing was adjusted to stop a steam leak. Work to the valve was completed on 08/13/92. On 08/14/92, while reviewing NWR B93935, the Unit 2 Shift Foreman noted that valve 2ES002 was a Technical Specification valve. The Shift Foreman immediately initiated 2BOS 3.4.2.c-1, "Extraction Steam Non-Return Check Valve Monthly Surveillance". The partial surveillance was successfully completed at 1714 on 08/14/92 and 2ES002 was declared operable.

The cause of this event was cognitive personnel error by the Operating Engineer who approved the NWR and failed to recognize the ZESOO2 valve as Technical Specification related.

Immediate corrective action was successful partial performance of surveillance 2805 3.4.2.c-1 which showed valve operability. Any further corrective actions determined from further investigation will be delineated in a Supplemental Report.

This event is reportable per 10CFR50.73(a)(2)(i)(B), any operation or condition prohibited by the plants Technical Specifications.

	LICENSEE EVENT REPORT (LER) TEX	KT CONTINUATION	Form Rev 2.0
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	Fage (3)
1		Year /// Sequential /// Revision Number /// Number	
Byron, Unit 2		9 2 - 0 1 0 1 5 - 0 1 0 1	01 2 OF 01 3
TEXT France Industry 1	dentification System (E115) codes	are identified in the text as [XX]	

# A. PLANT CONDITIONS PRIOR TO EVENT:

Event Date/Time08/14/92 /1638			
Unit 1 HODE 1 - Power Operation	Rx Power <u>97%</u>	RCS [AB] Temperature/Pressure	NOT / NOP
Unit 2 MODE 1 - Power Operation	Rx Power95%	RCS [AB] Temperature/Pressure	NOT / NOP

### B. DESCRIPTION OF EVENT:

On August 13, 1992, Mechanical Maintenance Department personnel begun work on Extraction Steam Non-Return Check Valve 2ES002. Packing was adjusted to stop a steam leak. Work on the valve was completed that same day. The appropriate Limiting Condition for Operation Action Requirement (LCOAR), 2805 3.4—1a, "LCOAR, Instrumentation, Turbine Overspeed Protection", was never entered. Action Requirement "b" of Technical Specification 3.3.4, Turbine Overspeed Protection, requires that the turbine must be isolated from the affected steam supply within 6 hours. Per Technical Specification Interpretation, this action requirement can be met by closing the associated Motor Operated Valve (MOV), 2ES001 or Manual Isolation Valves, 2ES003A and 2ES003B. No isolation was performed resulting in this action requirement not being met.

On August 14, 1992 at 1638 it was discovered by Operating Department personnel that LCOAR 2BOS 3.4-la had not been entered as required. A partial surveillance of 2BOS 3.4.2.c-l, "Extraction Steam Non-Return Check Valve Monthly Surveillance", was immediately performed to verify operability of the valve. The surveillance was successfully completed.

No plant systems or components were previously inoperable that contributed to this event. This event is reportable per 10CFk50.73(a)(2)(i)(B), any operation or condition prohibited by the plant's Technical Specifications, in that LCOAR 2BOS 3.4-la was not entered and the action requirement was not satisfied.

#### C. CAUSE OF EVENT:

The cause of this event was cognitive personnel error by the acting Operating Engineer who approved the NWR. The NWR did not identify the valve as a Technical Specification related component. Because the NWR was not marked as Technical Specification related, no further Senior Reactor Operator (SRO, licensed) review was required prior to beginning work on the valve. The mechanic who performed the work was only required to sign in with the Shift Engineer Assistant (non-licensed). He was not required to sign in with the Shift Engineer or his designated SRO licensed assistant because the NWR was not stamped as Technical Specification related.

#### D. SAFETY ANALYSIS:

Following the packing adjustment, the valve remained capable of performing its intended function as demonstrated by the partial surveillance of 2BOS 3.4.2.c-1. The safety of the plant and the public was not affected by this event.

	ICENSEE EVENT REPORT (LER) TEX	T CONTINUATION	Fp:m Rev 2.0
FACILTTY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	Page (3)
		Year /// Sequential /// Revision Number /// Number	
Byron, Unit ¿	0   5   0   0   0   4   5   5	912 - 01015 - 010	013 OF 013
TEXT Energy industry Identi	fication System (EI'S) codes a	re identified in the text as [XX]	

#### E. CORRECTIVE ACTIONS:

Immediate corrective action was successful partial performance of surveillance 2BOS 3.4.2.c-1 which showed valve operability.

Any further corrective actions determined from further investigation will be delineated in a Supplemental Report. NTS #4551809200500.

# F. RECURRING EVENTS SEARCH AND ANALYSIS:

EVENT SEARCH (DIR, LER)

LER 50-454-92-002, LCOAR not entered due to Tack of knowledge of equipment status.

b) INDUSTRY SEARCH (OPEX's NPRDS)

None found.

c) NWR

B93935

d) ANALYSIS

No trends currently identified. Although the current LER (455-92-005) and the previous LER (454-92-002) resulted in LCOARs not being entered, the causes were different.

## G. COMPONENT FAILURE DATA:

MANUFACTURER NOMENCLATURE NUMBER NUMBER

None.