RESCRIBERTANISMENT SERVICE SER

Log # TXX-92419 File # 10110

CP-92-015

TUELECTRIC

Ref. # 10CFR50.55(e)

September 17, 1992

William J. Cabill, Jr. Geoup Vice President

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)
DOCKET NOS. 50-445 AND 50-446
GENERAL ELECTRIC CIRCL T BREAKERS MOUNTING HARDWARE
INCORRECTLY SUPPLIED A INSTALLED BY THE FACTORY
SPAR: CP-92-015 (FINE: MEPORT)

Gentlemen:

On August 18, 1992, ... facsimile. TU Electric notified the NRC of a condition where the venior (General Electric) supplied Class 1E nuclear grade 200A circuit breaters with incorrectly sized mounting bolts. The structural integrity of the circuit breaker mounting may have been inadequate during a seismic event. TU Electric has determined that the deviation is reportable pursuant to 10CFR50.55(e).

Attached is a written report which satisfies the reporting requirements of 10CFR50.55(e). The report has been formatted in a manner that corresponds to the specific information requested by subparts (i) through (viii) of paragraph 10CFR50.55(e)(8) of the regulation. This is exclusive of that portion of subpart (viii) regarding advice that has been or will be given to other entities outside TU Electric. Such advice would be dependent on the entities' specific use and operating/maintenance history of the subject components.

Sincerely,

William J. Cahill, Jr.

D. R. Woodlan

Docket Licensing Manager

JMK/RHS/tg Attachment

c - Mr. J. L. Milhoan, Region IV Mr. B. E. Holian, NRR Resident Inspectors, CPSES (2)

9209220450 920917 PDR ADDCK 05000445 PDR

400 N. Olive Street L.B. 81 Dallas, Texas 75201

Sect 1

Attachment to TXX-92419 Page 1 of 2

10CFR50.35(e) REPORTABLE CONDITION INVOLVING G.E. CIRCUIT BREAKERS MOUNTING HARDWARE INCORRECTLY SUPPLIED AND INSTALLED BY THE FACTORY

(i) Information supplied by:

Filliam J. Cahill. -r.

IV Elect :
400 North Olive Street, L. B. 81
Dallas, Texas 75201

- The facility is Comanche Peak Steam Electric Station Units 1 and 2. The basic component is General Electric 200A circuit breaker bucket assembly for use in 480V. 7300 Series motor control centers (MCCs).
- (iii) The circuit preaker backet assemblies were supplied by General Electric
- Twelve circuit breaker bucket assemblies were specified for procurement as Class IE nuclear grade for stock item for possible replacement or new Class IE applications. The I2 circuit breakers purchased in this lot were premounted with 2 out of 4 mounting bolts undersized. These breakers could have been utilized to supply vital Class IE loads associated with any safe shutdown system.

if used to mount as individual breaker, this condition would have been self detecting, while torquing the mounting bolts to the appropriate torque alues recommended by the vendor. However, if the replacement of the entire assembly with the circuit breaker was required, the mechanical and electrical integrity of circuit breakers during and after a seismic event may have been compromised.

- This defect was identified and documented on corrective action document on June 23, 1992.
- (vi) 12 premounted circuit breakers, each with 2 out of 4 incorrectly sized mounting bolts, were received as stock items.
- (vii) This condition, though considered an isolated case, involved 12 premounted circuit breakers, one or more of which could possibly have been used to supply redundant 480V loads from MCCs, potentially causing a loss of safety function during and/or after a seismic event.

. Attachment to TXX-92419 Page 2 of 2

The mounting bolts shall be replaced by proper vendor supplied #1/4-20 screws on all the circuit breakers in this lot assigned for Class 1E applic tions.

Additionally a sample of 200A General E ectric circuit breakers installed in Unit 2 were inspected with no further discrepancies noted.

Corrective actions will be completed by October 18, 1992.

(viii) Unit 1 was not informed of the defect found in Unit 2 since the sample inspections performed in the Unit 2 did not discover any additional occurrences for previously installed 200A circuit breakers. Therefore, it was inferred that the defective population was limited to the 12 circuit breaker bucket assemblies supplied under a specific Unit 2 purchase order. General Electric also stated in a correspondence that the occurrence was considered to be an isolated case to the specific purchase order.