



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064

SEP 23 1992

Docket No. 50-382
License No. NPF-38


Entergy Operations, Inc.
ATTN: Ross P. Barkhurst, Vice President
Operations, Waterford
P.O. Box B
Killona, Louisiana 70066

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 50-382/92-21

Thank you for your letter of September 16, 1992, in response to our letter and inspection report dated August 17, 1992. We have reviewed your reply and find it responsive to the concerns raised in our inspection report. We will review the implementation of your corrective actions during a future inspection.

Sincerely,



A. Bill Beach, Director
Division of Reactor Projects

cc:
Entergy Operations, Inc.
ATTN: Donald C. Hintz, President
& Chief Operating Officer
P.O. Box 31995
Jackson, Mississippi 39286

Entergy Operations, Inc.
ATTN: John R. McGaha, Vice President
Operations Support
P.O. Box 31995
Jackson, Mississippi 39286

9209280037 920923
PDR ADOCK 05000382
G PDR

IE06
1/1

Entergy Operations, Inc.

-2-

Wise, Carter, Child & Caraway
ATTN: Robert McGehee, Esq.
P.O. Box 65
Jackson, Mississippi 39205

Entergy Operations, Inc.
ATTN: D. F. Packer, General
Manager Plant Operations
P.O. Box B
Killona, Louisiana 70066

Entergy Operations, Inc.
ATTN: L. W. Laughlin
Licensing Manager
P.O. Box B
Killona, Louisiana 70066

Chairman
Louisiana Public Service Commission
One American Place, Suite 1630
Baton Rouge, Louisiana 70825-1697

Entergy Operations, Inc.
ATTN: R. F. Burski, Director
Nuclear Safety
P.O. Box B
Killona, Louisiana 70066

Hall Bohlinger, Administrator
Radiation Protection Division
P.O. Box 2135
Baton Rouge, Louisiana 70884-2135

Parish President
St. Charles Parish
P.O. Box 302
Hahnville, Louisiana 70057

Mr. William A. Cross
Bethesda Licensing Office
3 Metro Center
Suite 610
Bethesda, Maryland 20814

Winston & Straw
ATTN: Nicholas S. Reynolds, Esq.
1400 L Street, N.W.
Washington, D.C. 20005-3500

DMB - Original (IE06)

bcc copy of licensee's letter:

- J. L. Milhoan, RA
- L. J. Callan, DRSS
- J. P. Jaudon, DRSS
- B. Murray, FIPS
- A. D. Gaines, FIPS
- Resident Inspector - Waterford-3
- Section Chief, DRP/A, B. Johnson
- Lisa Shea, RM/ALF (MS 4503)
- FIPS File
- RIV File
- DRP
- Project Engineer, DRP/A
- DRS
- MIS System
- RSTS Operator

RIV:FIPS	C:FIPS	D:DRSS	D:DRP	
ADGaines:nh	BMurray	LJCallan	ABBeach	
9/22/92	9/22/92	9/22/92	9/22/92	

250070

IE06
41

DMB - Original (IE06)

bcc copy of licensee's letter:

- J. L. Milhoan, RA
- L. J. Callan, DRSS
- J. P. Jaudon, DRSS
- B. Murray, FIPS
- A. D. Gaines, FIPS
- Resident Inspector - Waterford-3
- Section Chief, DRP/A, B. Johnson
- Lisa Shea, RM/ALF (MS 4503)
- FIPS File
- RIV File
- DRP
- Project Engineer, DRP/A
- DRS
- MIS System
- RSTS Operator

RIV:FIPS	C:FIPS	D:DRSS	D:DRP	
ADGaines:nh	BMurray	LJCallan	ABBeach	
9/24/92	9/24/92	9/24/92	9/24/92	



ENTERGY

Entergy Operations, Inc.

200 South
Main Street
Boston, MA 02108
Tel: 617 552-8777

R. F. Burski

Director
Public Inquiries
September 3

SEP 7

W3F1-92-0412
A4.05
Q4

September 16, 1992

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

Subject: Waterford 3 SES
Docket No. 50-382
License No. NPF-38
NRC Inspection Report 92-21
Reply to Notice of Violation

Gentlemen:

In accordance with 10CFR2.201, Entergy Operations, Inc. hereby submits in Attachment 1 the response to the violation identified in Appendix A of the subject Inspection Report.

If you have any questions concerning this response, please contact C.J. Thomas at (504) 739-6531.

Very truly yours,

RFB/CJT/ssf
Attachment

cc: J.L. Milhoan, NRC Region IV
D.L. Wigginton, NRC-NRR
A.B. McGehee
N.S. Reynolds
NRC Resident Inspectors Office

~~42092114-7~~
218

ATTACHMENT 1

ENTERGY OPERATIONS, INC. RESPONSE TO THE VIOLATION IDENTIFIED IN
APPENDIX A OF INSPECTION REPORT 92-21

VIOLATION NO. 9221-01

Technical Specification 6.8.1 requires, in part, that written procedures be established, implemented, and maintained covering the activities referenced in Appendix A of Regulatory Guide 1.33, Revision 2, February 1978.

Section 7.e.(4) of Appendix A of Regulatory Guide 1.33, Revision 2, February 1978 lists radiation protection procedures for contamination control.

Section 5.2.2.2 of Administrative Procedure HP-001-219, "Radiological Posting Requirements," requires that contamination area postings be clearly demarcated with the appropriate boundary ropes/ribbons, signs, and stanchions as necessary to control the activity.

Contrary to the above, on July 28, 1992, the inspector determined that the boundary ropes for a contaminated area posting in Safeguards Room A had fallen down and, therefore, did not clearly demarcate the contaminated area.

RESPONSE

(1) Reason for Violation

Entergy Operations, Inc. admits this violation and believes that the root cause was inadequate action in that two pieces of rope demarcating a contaminated area posting in Safeguards Room A were not appropriately connected. The two pieces of rope were taped end to end in a butt connection. It is believed that tensional forces caused the ropes to separate and fall to the floor. The exact time of failure could not be determined; however, the area had been inspected and found satisfactory by a Health Physics Technician on July 27, 1992. Because the boundary ropes were on the floor, they did not demarcate clearly the contaminated area.

(2) Corrective Steps That Have Been Taken and the Results Achieved

Immediately upon discovery of this event, the contaminated area boundary ropes were secured and verified to demarcate clearly the correct area. Additionally, Health Physics personnel performed an inspection of other contaminated areas to identify similar conditions that could potentially lead to downed boundaries. During this inspection, similar conditions were identified and corrected. No instances of downed contaminated area boundaries were identified.

(3) Corrective Steps Which Will Be Taken to Avoid Further Violations

This event will be discussed with the staff Health Physics technicians to accentuate lessons learned and the importance of securing contaminated area boundaries. Moreover, Health Physics will promulgate additional guidance regarding the use of tape when establishing contaminated area boundaries.

(4) Date When Full Compliance Will Be Achieved

Full compliance will be achieved by December 4, 1992.