(9-43)	L'CENSEE EVENT REPORT (L				(LER)	U.S. NUCLEAR REQULATORY COMMISSION APPROVED OMS NO. 3150-0104 EXPIRES - 8/31/85									
	Y HANE (_							Ox	DEKET NUMBER	(2)		1 PA	01 (3)
LI		lck	Gen	erating	Stati	0.7 -	· Un:	it 1			15 10 10	1013	1512	1 0	01
		1			- F D		. Dia		77						
	ENT DATE		ISO	lation	THE RESERVE OF THE PERSON NAMED IN		PORT DAT		real	The second second second second				-	
MONTH	DAY	YEAR	YEAR		ALVEON NUMBER		-	YEAR		FACULTY NAME	ACILITIES INVOI	-	NUMBER	141	
		T GALL		NOMBER	NUMBER	- CONTIN	041	TEAN					1010		
					11.							-1-	1010	101	
9 1	0 4	8 5	85	0 0 0 0 2	1-010	02	011	8 5				0 .5	10 10	.0.	
041	RATING		THIS AS	PORT IS SUBMITT	ED PURBUANT	TO THE R	EQUIREM	INTE OF 1	-CFR 4. 10		the fellowings (11			1-1	
POWE LEVE 1101	0	0 4	N. 20.	406 (17) (41 204 404 404 404 404 404 404 404 404 404		50,36 is 50,36 is 50,73 is 50,73 is 50,73 is	(11) (2) (2)(0) (2)(0)			60.73(a)(2)(v) 60.73(a)(2)(v) 60.73(a)(2)(vii)(A) 60.73(a)(2)(viii)(A) 60.73(a)(2)(viii)(B) 60.73(a)(2)(a)				TOOL MA	
						KENSEE	CONTACT	FOR THIS	LER (12)						
Jo	hn (c. N	agle	e, Engi	neer -	Spec	cial	Pro	ject	s	AREA CODE	8,4	1 4-		1 8,4
				COMPLETE	ONE LINE FOR	EACH CO	MPONENT	FAILURE	DESCRIBE	D IN THIS REPORT	(13)				
CAUSE	SYSTEM	COMPO	NENT	MANUFAG TURER	REPORTABLE TO HPROS		5.,43	CAUSE	SYSTEM	COMPONENT	MANUFAC TURER		TABLE		
		11	1	111			(-Ç)			111	111		- Control	e la	4.6
	,	1.1	1	1:1		A-65	4.			TIL	111				
				SUPPLEM	ENTAL REPORT	EXPECTE	D (14)			1	EXPLOTE		MONTH	CAY	YEAR
7466	ist yes, se	mpro EX	PECTIO	SUBMISSION DAT	D	X	- W				BATE IS	M	1	1	1

Abstract: 85-002

On January 4, 1985, at 8:59 p.m., with Unit No. 1 in the startup condition and at 3.5 percent power, a spurious isolation of the Reactor Water Cleanup (RWCU) system occurred as the result of high differential flow between the system inlet and outlet while valving the "B" RWCU filter/demineralizer into service. The isolation was reset and the RWCU system was returned to service by approximately 9:15 p.m.

8502110683 850201 PDR ADOCK 05000352 PDR

IE22 1/1

NR				

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/85

		EXPINES 0/31/0			
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)		
Limerick Generating Station		YEAR SEQUENTIAL REVISION NUMBER			
Unit 1	0 5 0 0 0 3 5 2	8,5 _ 0,0,2 _ 0,0 0	12 OF 0 3		

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Description of the Event:

On January 4, 1985, at 8:59 p.m. with Unit No. 1 in the startup condition and at 3.5 percent power, a spurious isolation of the Reactor Water Cleanup System (RWCU) occurred. Investigation indicates that the isolation was the result of high differential flow between the inlet and outlet of the RWCU system while placing the "B" RWCU filter/demineralizer in service. The isolation was reset and the RWCU system was returned to service.

Consequences of the Event:

Reactor water chemistry, because of the short duration of the isolation, was not adversely affected. There were no adverse effects as a result of the RWCU isolation.

Cause of the Event:

Investigation indicates that a section of piping between the demineralizer's "F" valve and the common return header for all the filter/demineralizers was not properly filled and vented following system maintenance prior to placing the demineralizer in service. While slowly valving the "B" demineralizer into service, the high differential flow condition, as a result of the air in the system piping, was maintained long enough to generate the high differential flow isolation signal and isolate the RWCU system.

NRC Form 366A

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/85

FACILITY NAME (1) DOCKET NUMBER (2) PAGE (3) LER NUMBER (6) Limerick Generating Station YEAR SEQUENTIAL NUMBER Unit 1 0 |5 |0 |0 |0 |3 |5 |2 |8 |5 |- 0 |0 |2 |- 0 | 0 |3 | OF 0 |3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Corrective Actions:

The isolation signal was reset, the "B" filter/demineralizer was placed in service, and the RWCU system was returned to service by 9:15 p.m. on January 4, 1985. Procedure S44.3.A has been revised to allow better venting of the system piping and is being reviewed for PORC approval.

Previous Similar Occurrences:

None.

PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET P.O. BOX 8699 PHILADELPHIA, PA. 19101

(215) 841-4000

February 1, 1985

Docket No. 50-352

Document Control Desk U.S. Nuclear Regulatory Commission Washington, DC 20555

SUBJECT:

Licensee Event Report
Limerick Generating Station - Unit 1

This LER concerns the spurious isolation of the Reactor Water Cleanup system on high differential flow.

Reference:

Docket No. 50-352

Report Number: Revision Number: 00

85-002

Event Date:

January 4, 1985 February 1, 1985

Report Date: Facility:

Limerick Generating Station

P.O. Box A, Sanatoga, PA 19464

This LER is being gubmitted pursuant to the requirements of 10 CFR 50.73(a)(2)(iv).

Very truly yours,

W. T. Ullrich

mallent

Superintendent

Nuclear Generation Division

cc: Dr. Thomas E. Murley, Administrator, Region I, USNRC J. T. Wiggins, Senior Site Inspector See Service List

cc: Judge Helen F. Hoyt Judge Jerry Harbour Judge Richard F. Cole Troy B. Conner, Jr., Esq. Ann P. Hodgdon, Esq. Mr. Frank R. Romano Mr. Robert L. Anthony Ms. Phyllis Zitner Charles W. Elliott, Esq. Zori G. Ferkin, Esq. Mr. Thomas Gerusky Director, Penna. Emergency Management Agency Angus Love, Esq. David Wersan, Esq. Robert J. Sugarman, Esq. Martha W. Bush, Esq. Spence W. Perry, Esq. Jay M. Gutierrez, Esq. Atomic Safety & Licensing Appeal Board Atomic Safety & Licensing Board Panel Docket & Service Section (3 Copies) James Wiggins Timothy R. S. Campbell