

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) EDWIN I. HATCH, UNIT I	DOCKET NUMBER (2) 0 5 0 0 0 3 2 1	PAGE (3) 1 OF 0 2
---	--------------------------------------	----------------------

TITLE (4)
Unplanned ESF Actuation While Shutdown

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0	1	0	8	5	0	0	2	0			0 5 0 0 0
0	1	0	8	5	0	0	4	8			0 5 0 0 0

OPERATING MODE (9) 4	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)						
POWER LEVEL (10) 0 0 0	20.402(b)	<input checked="" type="checkbox"/>	20.406(c)	<input type="checkbox"/>	50.73(a)(2)(iv)	<input type="checkbox"/>	73.71(b)
	20.406(a)(1)(i)	<input type="checkbox"/>	50.36(c)(1)	<input type="checkbox"/>	50.73(a)(2)(v)	<input type="checkbox"/>	73.71(c)
	20.406(a)(1)(ii)	<input type="checkbox"/>	50.36(c)(2)	<input type="checkbox"/>	50.73(a)(2)(vii)	<input type="checkbox"/>	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
	20.406(a)(1)(iii)	<input type="checkbox"/>	50.73(a)(2)(i)	<input type="checkbox"/>	50.73(a)(2)(viii)(A)	<input type="checkbox"/>	
	20.406(a)(1)(iv)	<input type="checkbox"/>	50.73(a)(2)(ii)	<input type="checkbox"/>	50.73(a)(2)(viii)(B)	<input type="checkbox"/>	
20.406(a)(1)(v)	<input type="checkbox"/>	50.73(a)(2)(iii)	<input type="checkbox"/>	50.73(a)(2)(ix)	<input type="checkbox"/>		

LICENSEE CONTACT FOR THIS LER (12)		TELEPHONE NUMBER	
NAME	AREA CODE		
T. L. Elton, Acting Superintendent of Regulatory Compliance	9 1 2	3 6 7 - 7 8 5 1	

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)										
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS	

SUPPLEMENTAL REPORT EXPECTED (14)		EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)	<input checked="" type="checkbox"/> NO				

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 01/06/85 at approximately 1722 CST during completion of maintenance activities on reactor low water level instrument, 1B21-N080A, an RPS logic actuation occurred. Personnel were backfilling 1B21-N080A prior to returning it to service when the backfilling resulted in the logic actuation of an ESF.

The cause of this event was attributed to backfilling of 1B21-N080A prior to returning it to service.

Personnel performing a maintenance activity will discuss with operations personnel the potential for and the significance of possible ESF actuations prior to performing the maintenance activity. This should prevent future "unplanned actuations of ESFs" as the result of maintenance activities.

8502110708 850204
PDR ADOCK 05000321
S PDR

IE 22
/

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) EDWIN I. HATCH, UNIT I	DOCKET NUMBER (2) 0 5 0 0 0 3 2 1	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8 5	- 0 0 3	- 0 0	0 2	OF 0 2

TEXT (If more space is required, use additional NRC Form 366A's) (17)


This 30 day report is required by 10CFR50.73(a)(2)(iv) since this RPS logic actuation was an unplanned actuation of an ESF.

On 01/06/85 at approximately 1722 CST during completion of maintenance activities on reactor low water level instrument, 1B21-N080A, an RPS logic actuation occurred. Personnel were backfilling 1B21-N080A prior to returning it to service when the backfilling resulted in the logic actuation of an ESF.

The cause of this event was attributed to backrilling of 1B21-N080A prior to returning it to service.

Personnel performing a maintenance activity will discuss with operations personnel the potential for and the significance of possible ESF actuations prior to performing the maintenance activity. This should prevent future "unplanned actuations of ESFs" as the result of maintenance activities.

Georgia Power Company
Post Office Box 439
Baxley, Georgia 31513
Telephone 912 367-7781
912 537-9444




Edwin I. Hatch Nuclear Plant

February 4, 1985
GM-85-57

PLANT E. I. HATCH
Licensee Event Report
Docket No. 50-321

United States Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Attached is Licensee Event Report No. 50-321/1985-003. This report is required by 10CFR 50.73(a)(2)(iv).


H. C. Nix
General Manager

^{TKS}
HCN/TLE/vlz

xc: R. J. Kelly
R. E. Conway
J. T. Beckham, Jr.
P. D. Rice
K. M. Gillespie
Superintendent of Regulatory Compliance
R. D. Baker
Control Room
Document Control

IE22
//