
Survey and Evaluation of System Interaction Events and Sources

Appendices C and D

Prepared by G. A. Murphy/NOAC
M. L. Casada, M. D. Muhlheim, M. P. Johnson,
J. J. Rooney, J. H. Turner/JBFA

Nuclear Operations Analysis Center
Oak Ridge National Laboratory

JBF Associates, Inc.

Prepared for
U.S. Nuclear Regulatory
Commission

NOTICE

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, or any of their employees, makes any warranty, expressed or implied, or assumes any legal liability of responsibility for any third party's use, or the results of such use, of any information, apparatus, product or process disclosed in this report, or represents that its use by such third party would not infringe privately owned rights.

NOTICE

Availability of Reference Materials Cited in NRC Publications

Most documents cited in NRC publications will be available from one of the following sources:

1. The NRC Public Document Room, 1717 H Street, N.W.
Washington, DC 20555
2. The NRC/GPO Sales Program, U.S. Nuclear Regulatory Commission,
Washington, DC 20555
3. The National Technical Information Service, Springfield, VA 22161

Although the listing that follows represents the majority of documents cited in NRC publications, it is not intended to be exhaustive.

Referenced documents available for inspection and copying for a fee from the NRC Public Document Room include NRC correspondence and internal NRC memoranda; NRC Office of Inspection and Enforcement bulletins, circulars, information notices, inspection and investigation notices; Licensee Event Reports; vendor reports and correspondence; Commission papers; and applicant and licensee documents and correspondence.

The following documents in the NUREG series are available for purchase from the NRC/GPO Sales Program: formal NRC staff and contractor reports, NRC-sponsored conference proceedings, and NRC booklets and brochures. Also available are Regulatory Guides, NRC regulations in the *Code of Federal Regulations*, and *Nuclear Regulatory Commission Issuances*.

Documents available from the National Technical Information Service include NUREG series reports and technical reports prepared by other federal agencies and reports prepared by the Atomic Energy Commission, forerunner agency to the Nuclear Regulatory Commission.

Documents available from public and special technical libraries include all open literature items, such as books, journal and periodical articles, and transactions. *Federal Register* notices, federal and state legislation, and congressional reports can usually be obtained from these libraries.

Documents such as theses, dissertations, foreign reports and translations, and non-NRC conference proceedings are available for purchase from the organization sponsoring the publication cited.

Single copies of NRC draft reports are available free, to the extent of supply, upon written request to the Division of Technical Information and Document Control, U.S. Nuclear Regulatory Commission, Washington, DC 20555.

Copies of industry codes and standards used in a substantive manner in the NRC regulatory process are maintained at the NRC Library, 7920 Norfolk Avenue, Bethesda, Maryland, and are available there for reference use by the public. Codes and standards are usually copyrighted and may be purchased from the originating organization or, if they are American National Standards, from the American National Standards Institute, 1430 Broadway, New York, NY 10018.

Survey and Evaluation of System Interaction Events and Sources

Appendices C and D

Manuscript Completed: December 1984
Date Published: January 1985

Prepared by
G. A. Murphy, Nuclear Operations Analysis Center
M. L. Casada, M. D. Muhlheim, M. P. Johnson,
J. J. Rooney, J. H. Turner, JBF Associates, Inc.

Nuclear Operations Analysis Center
Oak Ridge National Laboratory
Oak Ridge, TN 37831

Subcontractor:
JBF Associates, Inc.
1000 Technology Park Center
Knoxville, TN 37932

Prepared for
Division of Safety Technology
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555
NRC FIN B0789

This report describes the first phase of an NRC-sponsored project that identified and evaluated system interaction events that have occurred at commercial nuclear power plants in the United States. The project included (1) an assessment of nuclear power plant operating experience data sources, (2) the development of search methods and event selection criteria for identifying system interaction events, (3) a review of possible events, and (4) a final evaluation and categorization of the events. The report, organized in two volumes, outlines each of these steps and presents the results of the project. Volume 1 contains an introduction to the project, describes the process by which the project identified and evaluated the system interaction events, and presents the results and recommendations from that evaluation. Volume 1 also contains appendixes that review the data sources used in identifying events and outlines the information collected for each event. Volume 2 provides a description of each adverse system interaction event and lists the references for the events.

CONTENTS

	<u>Page</u>
APPENDIX C - EVENT LIST	1
- List of Acronyms and Abbreviations	3
APPENDIX D - EVENT REFERENCES	243

Appendix C

EVENT LIST

Appendix C contains the 235 event descriptions sorted alphabetically by plant name and within plant name, by event date.

LIST OF ACRONYMS AND ABBREVIATIONS

AC	alternating current
ADS	automatic depressurization system
AE	Architect Engineer
AFW	auxiliary feedwater (system)
ANO 1	Arkansas Nuclear Unit 1
AUX	auxiliary
B&W	Babcock & Wilcox
BAST	boric acid storage tank
BKR	breaker
BLDG	building
BRG	bearing
BTY	battery
BWR	boiling-water reactor
CCW	component cooling water (system)
CE	Combustion Engineering
CHG	charging
CI	containment isolation
CIRC	circulating
CNMT	containment
CO ₂	carbon dioxide
COMPRES	compressor
CONC	concentration
CONTR	control
CR	control room
CRD	control rod drive
CS	containment spray (system)
CST	condensate storage tank
CVCS	chemical and volume control system
DBA	design basis accident
DC	direct current
DELTA-P	differential pressure
DEMIN	demineralizer
DEPRES	depressurization
DG	diesel generator
DIFF	differential
DISCH	discharge
DIV	division
ECCS	emergency core cooling system
EDG	emergency diesel generator
ELEV	elevation
ELEC	electrical
EMERG	emergency
EQUIP	equipment
ERCW	essential raw cooling water
ERRON	erroneous
ESF	engineered safety features
ESFAS	engineered safety features actuation system
ESS	engineered safeguard system
EXH	exhaust

EXP	expansion
FCU	fan coil unit
FM	frequency modulation
FW	feedwater
GA	General Atomic
GE	General Electric
GEN	generator
GRAD	gradient
H ₂	hydrogen
HDR	header
HELB	high-energy line break
HI	high
HPCI	high-pressure coolant injection (system)
HPSI	high-pressure safety injection (system)
HTGR	high-temperature gas-cooled reactor
HVAC	heating, ventilation, and air conditioning
HX	heat exchanger
I&C	Instrumentation and Controls
I/P	current/pressure
ICS	integrated control system
IE	Inspection & Enforcement
IEB	Inspection & Enforcement Bulletin
IN	inch
INDIC	indication
INIT	initiation
INJ	injection
INPO	Institute for Nuclear Power Operation
INST	instrument
INV	invertor
ISOL	isolation
KV	kilovolt
LER	Licensee Event Report
LNP	loss-of-normal power
LOCA	loss-of-coolant accident
LOP	loss of (electric) power
LOSP	loss of offsite (electric) power
LPCI	low-pressure coolant injection (system)
MCC	motor control center
MG	motor-generator
MFW	main feedwater (system)
MK	Mark
MOD	modification
MOV	motor-operated valve
MSL	main steam line
MSLB	main steam line break
MULT	multiple
N ₂	nitrogen
NaOH	sodium hydroxide
NDT	nondestructive testing
NEG	negative
NNI	nonnuclear instrumentation
NPP	nuclear power plant

NUCL	nuclear
OBE	operating basic earthquake
OS	offsite
PAMS	postaccident monitoring system
PD	positive displacement
PORV	power-operator relief valve
psig	pounds per square inch gauge (pressure)
PRESS	pressure
PWR	pressurized-water reactor
PZR	pressurizer
RAD	radiation
RAS	recirculation actuation signal
RB	reactor building
RBCCW	reactor building closed cooling water (system)
RBEDT	reactor building equipment drain tank
RCIC	reactor core isolation cooling (system)
RCP	reactor coolant pump
RCS	reactor coolant system
RECIRC	recirculation
REF	reference
REL	related
REQD	required
RHR	residual heat removal (system)
RPS	reactor protection system
RWST	refueling/borated water storage tank
RX	reactor
SCSS	Sequence Coding and Search System
SD	shutdown
SDV	scram discharge volume
SEC	secondary
SEP	Systematic Evaluation Program
SG	steam generator
SGTS	standby gas treatment system
SFAS	safety features actuation system
SI	safety injection
SIAS	safety injection actuation system
SIL	Service Information Letter (GE)
SIS	safety injection signal
SOER	significant operating event report
SSE	safe shutdown earthquake
SW	service water (system)
SWS	service water system
SYS	system
T-HOT	RCS hot leg temperature
TBN	turbine
TEMP	temperature
TRN	train
UNQUAL	unqualified
UPS	uninterruptible power supply
UV	undervoltage
VCT	volume control tank
VDC	volts dc

VLVS	valves
W/D	withdraw
WEST	Westinghouse
W/O	without
XFMR	transformer

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ARKANSAS NUCLEAR 1 PLANT TYPE: B&W PWR
 EVENT DATE: 1/18/1973 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

ESSENTIAL RAW COOLING/ SERVICE WATER
 SUBSYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

REACTOR BUILDING HVAC (PWR)
 SUBSYSTEM OCCURRENCE

REACTOR BUILDING HVAC (PWR)
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR BUILDING HVAC (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: UNKNOWN

INITIATING EVENT: LOSS OF ONE TRAIN OF SERVICE WATER SYSTEM

PROPAGATION: BOTH TRAINS OF REACTOR BUILDING (RB) COOLERS WOULD
 FAIL

DEPENDENCY: TWO TRAINS OF RB COOLERS SUPPLIED BY THE SAME
 TRAIN OF SERVICE WATER

UNDESIRABLE RESULT: LOSS OF REACTOR BUILDING COOLING DUE TO A SINGLE
 FAILURE

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY:13

REFERENCES: L0019 EVENT NO 1

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ARKANSAS NUCLEAR 1 PLANT TYPE: B&W PWR
 EVENT DATE: 9/06/1977 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

HIGH VOLTAGE AC (GREATER THAN 35KV)
 TOTAL SYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

REACTOR AUXILIARY BUILDING HVAC
 SUBSYSTEM OCCURRENCE

REACTOR AUXILIARY BUILDING HVAC
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR AUXILIARY BUILDING HVAC
 TOTAL SYSTEM OCCURRENCE

MULTIPLE ESP SYSTEMS
 UNSPECIFIED COMPONENT

TYPE OF COUPLING: SPATIAL PLANT AREA: REACTOR AUXILIARY BUILDING

RESULT TYPE: 1,3 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: LOCA PLUS LOSS OF OFFSITE POWER

PROPAGATION: NORTH AND SOUTH EQUIPMENT ROOMS AND BATTERY ROOMS
 CAN EXCEED DESIGN TEMPERATURES

DEPENDENCY: OPERABILITY OF EQUIPMENT IN REDUNDANT AREAS CANNOT
 BE ASSURED DUE TO HIGH TEMP

UNDESIRABLE RESULT: ACCIDENT CAN CREATE CONDITIONS LEADING TO
 SUBSEQUENT SAFETY EQUIPMENT FAILURES

REMARKS: ADEQUATE QUALIFIED COOLING WAS NOT AVAILABLE. NEW
 COOLERS PURCHASED.

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY:23

REFERENCES: L0103

EVENT NO 2

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ARKANSAS NUCLEAR 2 PLANT TYPE: CE PWR
 EVENT DATE: 3/01/1978 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

PRIMARY COOLANT (PWR)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CONTAINMENT ISOLATION
 VALVES

PRIMARY CONTAINMENT (PWR)
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

CONTAINMENT ISOLATION
 VALVES

PRIMARY CONTAINMENT (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: LOCA OCCURRING DURING CONTAINMENT PURGE OPERATIONS

PROPAGATION: ALL CONTAINMENT ISOLATION VALVES FOR PURGE
 SUBJECTED TO LOCA AND FAIL TO CLOSE

DEPENDENCY: DELTA P FROM LOCA IN CONTAINMENT GREATER THAN
 DESIGN FOR CLOSURE FROM FULL OPEN

UNDESIRABLE RESULT: LOCA DURING PURGING RESULTS IN LOSS OF CONTAINMENT
 ISOLATION CAPABILITY

REMARKS: PURGING WAS RESTRICTED TO LOW PRESSURE CONDITIONS
 FOR RCS

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 9

REFERENCES: L0100 L0094 EVENT NO 3

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ARKANSAS NUCLEAR 2 PLANT TYPE: CE PWR
 EVENT DATE: 9/16/1978 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

HIGH VOLTAGE AC (GREATER THAN 35KV)
 TOTAL SYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

HIGH VOLTAGE AC (GREATER THAN 35KV)
 TOTAL SYSTEM OCCURRENCE

HIGH VOLTAGE AC (GREATER THAN 35KV)
 ELECTRICAL CONDUCTORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

HIGH VOLTAGE AC (GREATER THAN 35KV)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 0 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: WITH UNIT 2 SHUT DOWN, UNIT 1 TRIPPED CAUSING
 DEMAND FOR OFFSITE POWER

PROPAGATION: ALL LOADS TRANSFERRED TO THE BUS TIE
 AUTO-TRANSFORMER, OVERLOADING IT

DEPENDENCY: OFFSITE POWER FOR BOTH UNITS CAME THRU INADEQUATE
 BUS TIE AUTO-TRANSFORMER

UNDESIRABLE RESULT: LOSS OF UNIT 1 SUPPLY CAUSES LOSS OF OFFSITE POWER
 FOR BOTH UNITS

REMARKS: BUS TIE AUTO-TRANSFORMER SETPOINTS WERE NOT
 CHANGED TO SUPPORT TWO UNITS

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 1

REFERENCES: I-291 M1001 L0153 EVENT NO 4

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ARKANSAS NUCLEAR 2 PLANT TYPE: CE PWR
 EVENT DATE: 9/16/1978 EXPERIENCE: ACTUAL
 OPERATING STATUS: PREOPERATIONAL/STARTUP/POWER ASCENSION TESTS

INITIATING SYSTEM AND COMPONENT

HIGH VOLTAGE AC (GREATER THAN 35KV)
 SUBSYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

VITAL INSTRUMENT, CONTROL, AND COMPUTER AC
 SUBSYSTEM OCCURRENCE

VITAL INSTRUMENT, CONTROL, AND COMPUTER AC
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

CVCS/HIGH PRESSURE SAFETY INJECTION
 TOTAL SYSTEM OCCURRENCE

CONTAINMENT SPRAY
 TOTAL SYSTEM OCCURRENCE

RESIDUAL HEAT REMOVAL (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: BOTH ESP BUSES DEENERGIZED DUE TO TRANSFORMER
 FAILURE

PROPAGATION: WHILE DG STARTED, ALL POWER TO VITAL AC INSTRUMENT
 BUSES FAILED DUE TO ERROR

DEPENDENCY: SI OCCURRED AS DESIGNED BUT LOP CAUSED RAS TOO
 SOON, REALIGNED ECCS TO SUMP

UNDESIRABLE RESULT: COULD FAIL ALL ECCS TRAINS. POTENTIAL EXISTS FOR
 DAMAGING ECCS PUMPS

REMARKS: RWSI LOST 50000 GALLONS TO SUMP. ALTERNATE POWER
 SOURCE SWITCHES WERE SET WRONG

CORRECTIVE ACTION: OTHER

CATEGORY: 6

REFERENCES: I-291 M1001 L0132

EVENT NO 5

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ARKANSAS NUCLEAR 2 PLANT TYPE: CE PWR
 EVENT DATE: 9/16/1978 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

HIGH VOLTAGE AC (GREATER THAN 35KV)
 TOTAL SYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

HIGH VOLTAGE AC (GREATER THAN 35KV)
 TOTAL SYSTEM OCCURRENCE

MULTIPLE ESP SYSTEMS
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

MULTIPLE ESP SYSTEMS
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,4 DISCOVERY: OTHER

INITIATING EVENT: LOSS OF NORMAL POWER FROM UNIT GENERATOR WITH
 AUXILIARY AND ESP STARTING LOADS

PROPAGATION: LOADS WOULD TRANSFER TO STARTUP TRANSFORMER
 CAUSING DEGRADED VOLTAGE

DEPENDENCY: LOW VOLTAGE OPERATION WOULD NOT TRANSFER TO DG'S
 AND COULD CAUSE FUSE FAILURES

UNDESIRABLE RESULT: ESP EQUIPMENT COULD BE DISABLED BY LOW VOLTAGE
 OPERATIONS

REMARKS: POTENTIAL EVENT RECOGNIZED IN REVIEWING THE ACTUAL
 EVENT AT ANO ON 09/16/78

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 1

REFERENCES: I-291 M1001 L0153 EVENT NO 6

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ARKANSAS NUCLEAR 2 PLANT TYPE: CE PWR
 EVENT DATE: 4/07/1980 EXPERIENCE: ACTUAL
 OPERATING STATUS: HOT SHUTDOWN

INITIATING SYSTEM AND COMPONENT

STEAM GENERATOR BLOWDOWN (PWR)
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

STEAM GENERATOR BLOWDOWN (PWR)
 SUBSYSTEM OCCURRENCE

AUXILIARY FEEDWATER (PWR)
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

AUXILIARY FEEDWATER (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: PROCEDURE ERROR-SG BLOWDOWN DEMINERALIZER VALVE TO
 AFW PUMP SUCTION LEFT OPEN

PROPAGATION: FW FLASHED FORCING HOT WATER INTO BLOWDOWN TANKS &
 DEMIN-STEAM BOUND AFW PUMPS

DEPENDENCY: AFW PUMP SUCTION WAS PARALLELED TO SG BLOWDOWN
 RETURN AND CST

UNDESIRABLE RESULT: TOTAL LOSS OF AUXILIARY FEEDWATER SYSTEM

REMARKS: LOSS OF OFFSITE POWER TRANSIENT PRIOR TO EVENT
 CAUSED SHUTDOWN

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 2

REFERENCES: L1006 A0010 I-249 EVENT NO 7

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ARKANSAS NUCLEAR 2 PLANT TYPE: CE PWR
 EVENT DATE: 8/03/1983 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

FIRE PROTECTION
 SUBSYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

FIRE PROTECTION
 SUBSYSTEM OCCURRENCE

MULTIPLE SAFETY SYSTEMS
 ELECTRICAL CONDUCTORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

MULTIPLE SAFETY SYSTEMS
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: REACTOR AUXILIARY BUILDING

RESULT TYPE: 2 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: ACTUATION OF FIRE SUPPRESSION SYSTEM IN AUX BLDG
 FIRE ZONE

PROPAGATION: PROLONGED OPERATION OF FIRE SUPPRESSION SYSTEM
 WITHOUT OPER ACTION CAUSES FLOOD

DEPENDENCY: CABLE SPREADING ROOM NOT PROTECTED FROM FLOODING,
 WATER WOULD RUN INTO ROOM

UNDESIRABLE RESULT: LOSS OF SAFETY RELATED EQUIPMENT

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 3

REFERENCES: L2036 EVENT NO 8

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ARNOLD PLANT TYPE: GE BWR
 EVENT DATE: 3/06/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

RECIRCULATING WATER (BWR)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

DRYWELL/ TORUS HVAC AND PURGE (BWR)
 VALVES

REACTOR DRYWELL (BWR)
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

CONTAINMENT ISOLATION
 TOTAL SYSTEM OCCURRENCE

REACTOR DRYWELL (BWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: LOCA OCCURRING DURING DRYWELL PURGE OPERATIONS

PROPAGATION: PRESSURE SURGE CAUSES OVERTRAVEL AND LOSS OF VALVE
 SEATING CAPABILITY

DEPENDENCY: FULLY OPEN PURGE VALVES INADEQUATE FOR LOCA
 CONDITIONS

UNDESIRABLE RESULT: LOSS OF CAPABILITY OF PURGE VALVES TO ISOLATE
 CONTAINMENT IN CASE OF LOCA

REMARKS: DESIGN CHANGED TO LIMIT VALVES TO 30% OPEN

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 9

REFERENCES: L0048 EVENT NO 9

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: BEAVER VALLEY 1 PLANT TYPE: WEST PWR
 EVENT DATE: 6/21/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MAIN STEAM
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

STEAM GENERATOR (PWR)
 PIPES/FITTINGS

REACTOR PROTECTION
 I&C/SENSORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR PROTECTION
 SUBSYSTEM OCCURRENCE

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: HIGH ENERGY LINE BREAK IN CONTAINMENT RESULTING IN
 HIGH AMBIENT TEMPERATURE

PROPAGATION: HEATUP OF REF LEG, SG LEVEL INSTR FAILS HIGH,
 DELAYS RPS TRIP ON SG LO LO LEVEL

DEPENDENCY: STEAM GENERATOR LEVEL REFERENCE LEG SUBJECTED TO
 HIGH AMBIENT TEMP

UNDESIRABLE RESULT: ACCIDENT DEGRADES SYSTEM REQUIRED TO MITIGATE
 ACCIDENT

REMARKS: ALSO PROVIDES HIGH LEVEL INDICATION TO
 OPERATOR-GENERIC W PROBLEM

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 8

REFERENCES: L0083 L1008 EVENT NO 10

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: BEAVER VALLEY 1 PLANT TYPE: WEST PWR
EVENT DATE: 1/17/1980 EXPERIENCE: ACTUAL
OPERATING STATUS: COLD SHUTDOWN

INITIATING SYSTEM AND COMPONENT

REACTOR VESSEL
BLOWERS/COMPRESSORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

REACTOR VESSEL
BLOWERS/COMPRESSORS

RESIDUAL HEAT REMOVAL (PWR)
PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

RESIDUAL HEAT REMOVAL (PWR)
PUMPS

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,2 DISCOVERY: AUDIO/VISUAL ALARM

INITIATING EVENT: REACTOR VESSEL VENT EDUCTOR IN SERVICE FOR
REFUELING

PROPAGATION: EDUCTOR CAUSED HIGH NEG PRESS IN RCS-PULLED WATER
AND ENTRAINED AIR FROM SG'S

DEPENDENCY: RCS LEVEL AND SG LEVEL DEPENDENT ON NEG PRESS FROM
VENT EDUCTOR

UNDESIRABLE RESULT: RHR PUMPS BECAME AIR-BOUND - LOSS OF BOTH RHR
PUMPS FOR A SHORT TIME

REMARKS: OCCURRED DURING PREPERATIONS FOR REFUELING

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 2

REFERENCES: L0135

EVENT NO 11

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: BEAVER VALLEY 1 PLANT TYPE: WEST PWR
EVENT DATE: 4/11/1980 EXPERIENCE: ACTUAL
OPERATING STATUS: REFUELING

INITIATING SYSTEM AND COMPONENT

PRIMARY COOLANT (PWR)
SUBSYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

RESIDUAL HEAT REMOVAL (PWR)
SUBSYSTEM OCCURRENCE

RESIDUAL HEAT REMOVAL (PWR)
SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

RESIDUAL HEAT REMOVAL (PWR)
TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: OPERATION OF RHR SYSTEM DURING REFUELING SHUTDOWN
WITH LOW REACTOR WATER LEVEL

PROPAGATION: TWO RHR PUMPS BECOME AIR BOUND DURING OPERATION

DEPENDENCY: LOW REACTOR WATER LEVEL DOES NOT PROVIDE ADEQUATE
RHR PUMP SUCTION

UNDESIRABLE RESULT: LOSS OF FORCED FLOW DURING REFUELING RHR OPERATION

REMARKS: CONSEQUENCES ARE NOT SEVERE. MODIFICATIONS ARE TO
BE MADE TO CORRECT PROBLEM

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 2

REFERENCES: L0021 EVENT NO 12

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: BEAVER VALLEY 1 PLANT TYPE: WEST PWR
 EVENT DATE: 8/27/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

PRESSURIZER (PWR)
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CVCS/HIGH PRESSURE SAFETY INJECTION
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: PORV CONTROL FAILURE AFTER SECONDARY SYS HELB
 CAUSES SAFETY INJECTION ACTUATION

PROPAGATION: RCS PRESSURE RISES TO HIGHER THAN CHG PUMP DESIGN
 INJ PRESS; PUMPS OVERHEAT

DEPENDENCY: RECIRC VALVES PROTECT CHG PUMPS, BUT SIAS CLOSES
 RECIRC VALVES

UNDESIRABLE RESULT: LOSS OF MULTIPLE CHG PUMPS PRIOR TO SI SHUTOFF
 CONDITIONS BEING MET

REMARKS: GENERIC W PROBLEM. PUMP FAILURES DEPEND ON
 SPECIFIC DESIGN HEAD FOR CHG PUMPS

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 7

REFERENCES: L0053 I-017 EVENT NO 13

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: BEAVER VALLEY 1 PLANT TYPE: WEST PWR
 EVENT DATE: 9/12/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

COMPONENT COOLING WATER
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

COMPONENT COOLING WATER
 PIPES/FITTINGS

RESIDUAL HEAT REMOVAL (PWR)
 HEAT EXCHANGERS

SAFETY SYSTEMS/COMPONENTS AFFECTED

COMPONENT COOLING WATER
 TOTAL SYSTEM OCCURRENCE

RESIDUAL HEAT REMOVAL (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: UNKNOWN

INITIATING EVENT: EARTHQUAKE WOULD STRESS AND BREAK 2-IN BRANCH LINE
 OFF 24-IN RBCCW LINE

PROPAGATION: BREAK WOULD REQUIRE ISOLATION OF WHOLE 24-IN RBCCW
 HEADER

DEPENDENCY: 24 INCH RBCCW HEADER FEEDS RHR HEAT EXCHANGERS

UNDESIRABLE RESULT: LOSS OF RHR

REMARKS: PIPE SUPPORTS WILL BE MODIFIED TO ALLEVIATE
 OVERSTRESS CONDITION

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 20

REFERENCES: L2026

EVENT NO 14

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: BEAVER VALLEY 1 PLANT TYPE: WEST PWR
 EVENT DATE: 10/03/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MAIN STEAM
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

AUXILIARY FEEDWATER (PWR)
 PUMPS

AUXILIARY FEEDWATER (PWR)
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

AUXILIARY FEEDWATER (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: MAIN STEAM LINE BREAK WHICH DEPRESS ALL STEAM
 GENERATORS AND FAILS TO AFW PUMP

PROPAGATION: MOTOR DRIVEN AFW PUMPS WILL FACE LOW PRESSURE AND
 TRIP ON RUNOUT

DEPENDENCY: NO RUNOUT PROTECTION PROVIDED FOR MOTOR-DRIVEN AFW
 PUMPS, DEPEND ON SG PRESSURE

UNDESIRABLE RESULT: LOSS OF AFW DUE TO PUMP RUNOUT & NO STEAM TO
 TURBINE-DRIVEN AFW PUMPS

REMARKS: IE BULLETIN 80-04 ADDRESSED THIS. ORIFICES WILL
 BE INSTALLED IN AFW LINES

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 11

REFERENCES: L0071 I-031 EVENT NO 15

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: BEAVER VALLEY 1 PLANT TYPE: WEST PWR
 EVENT DATE: 5/21/1981 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

CVCS/HIGH PRESSURE SAFETY INJECTION
 IEC/TRANSMITTERS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CVCS/HIGH PRESSURE SAFETY INJECTION
 ACCUMULATORS/RESERVOIRS

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CVCS/HIGH PRESSURE SAFETY INJECTION
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: FAILURE OF VCT LEVEL TRANSMITTER HIGH STOPS
 LETDOWN FLOW CAUSING LOW TANK LEVEL

PROPAGATION: LOSS OF SUCTION DAMAGES MULTIPLE CHG PUMPS SINCE
 FAILURE ALSO STOPS SWITCHOVER

DEPENDENCY: LEVEL TRANSMITTER CONTROLS LEVEL AND SUCTION
 SWITCHOVER TO RWST

UNDESIRABLE RESULT: REDUNDANT CHG PUMPS DAMAGED. THESE PUMPS ARE ALSO
 HI HEAD SAFETY INJECTION

REMARKS: WESTINGHOUSE NOTIFICATION OF POTENTIAL FAILURE

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 5

REFERENCES: L0121 A0020 A0021 EVENT NO 16

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: BELLEFONTE 1 PLANT TYPE: B&W PWR
 EVENT DATE: 11/01/1976 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

PRIMARY COOLANT (PWR)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

PRIMARY CONTAINMENT (PWR)
 TOTAL SYSTEM OCCURRENCE

REACTOR BUILDING HVAC (PWR)
 HEAT EXCHANGERS

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR BUILDING HVAC (PWR)
 HEAT EXCHANGERS

ESSENTIAL RAW COOLING/ SERVICE WATER
 SUBSYSTEM OCCURRENCE

MULTIPLE SAFETY SYSTEMS
 HEAT EXCHANGERS

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 3 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: LOCA WHEN REACTOR BUILDING COOLER TUBES ARE CLEAN

PROPAGATION: HIGH CONTAINMENT TEMPERATURE MAY CAUSE BOILING IN
 REACTOR BLDG HX'S

DEPENDENCY: ERCW SUBJECT TO ADVERSE ENVIRONMENT-CAUSING
 FAILURE

UNDESIRABLE RESULT: LOCA CAN DEGRADE REACTOR BUILDING COOLING AND
 OTHER ERCW SUPPORTED SYSTEMS

REMARKS: ERCW PRESSURE IS TOO LOW FOR ACCIDENT CONDITIONS

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 23

REFERENCES: L0107 EVENT NO 17

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: BELLEFONTE 1 PLANT TYPE: B&W PWR
 EVENT DATE: 11/12/1982 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

CVCS/HIGH PRESSURE SAFETY INJECTION
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CVCS/HIGH PRESSURE SAFETY INJECTION
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 2 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: GAS BUILDUP IN CVCS MAKEUP TANK OUTLET LINE TO
 TRAIN A MAKEUP PUMPS

PROPAGATION: REDUCED SUCTION HEAD TO PUMPS CAUSES PUMP DAMAGE

DEPENDENCY: TRAIN A PUMPS TIED TO MAKEUP TANK THRU A DEFECTIVE
 PIPING DESIGN

UNDESIRABLE RESULT: LOSS OF ALL TRAIN A MAKEUP PUMPS

REMARKS: ALSO AFFECTS DOCKET NO. 439

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 2

REFERENCES: C14

EVENT NO 18

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: BIG ROCK POINT PLANT TYPE: GE BWR
 EVENT DATE: 10/31/1977 EXPERIENCE: ACTUAL
 OPERATING STATUS: ROUTINE STARTUP

INITIATING SYSTEM AND COMPONENT

RECIRCULATING WATER (BWR)
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

RECIRCULATING WATER (BWR)
 VALVES

AUXILIARY STEAM
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

SECONDARY CONTAINMENT (BWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 2 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: IMPROPER PROCEDURE USED DURING VALVE LINEUP FOR
 RCS POWER OPERATION

PROPAGATION: WATER BACK FLOWED FROM RCS INTO PLANT HEATING
 SYSTEM EXTERNAL TO CNMT

DEPENDENCY: CONTAINMENT IS ALWAYS BREACHED WHEN PLANT HEATING
 SYSTEM IS CONNECTED TO RCS

UNDESIRABLE RESULT: FLOW CAUSED WATER HAMMER IN STEAM SUPPLY LINE,
 MINOR RELEASE OF RADIOACTIVITY

REMARKS: PROCEDURES MODIFIED; TWO STEAM SUPPLY VALVES
 LOCKED CLOSED

CORRECTIVE ACTION: OTHER CATEGORY: 22

REFERENCES: E0004 L2007 EVENT NO 19

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: BIG ROCK POINT PLANT TYPE: GE BWR
 EVENT DATE: 8/22/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

RECIRCULATING WATER (BWR)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

RECIRCULATING WATER (BWR)
 PIPES/FITTINGS

ENGINEERED SAFETY FEATURES ACTUATION
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR PROTECTION
 TOTAL SYSTEM OCCURRENCE

ENGINEERED SAFETY FEATURES ACTUATION
 TOTAL SYSTEM OCCURRENCE

CONTAINMENT ISOLATION
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: UNKNOWN

RESULT TYPE: 1,3 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: LOCA COULD RESULT IN FLASHING IN RX VESSEL LEVEL
 SENSOR REFERENCE LEG

PROPAGATION: COULD PREVENT AUTO INIT OF SCRAM, CNMT ISOL, CORE
 SPRAY, AND AUTO DEPRES.

DEPENDENCY: ESPAS AND RPS DEPENDENT ON DEGRADED RX VESSEL
 LEVEL SENSOR.

UNDESIRABLE RESULT: LOCA CAN DEGRADE MULTIPLE SYSTEMS REQUIRED TO
 RESPOND

REMARKS: DESIGN DEFICIENCY GENERIC TO GE. SENSORS AND
 SETPOINTS MODIFIED

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 8

REFERENCES: L2004 E0004 L2005 EVENT NO 20

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: BROWNS FERRY 1 PLANT TYPE: GE BWR
 EVENT DATE: 3/22/1975 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

CONSTRUCTION ACTIVITY
 TEST/CALIBRATION ACTIVITY

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

RESIDUAL HEAT REMOVAL (BWR)
 TOTAL SYSTEM OCCURRENCE

MULTIPLE SYSTEMS
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

RESIDUAL HEAT REMOVAL (BWR)
 TOTAL SYSTEM OCCURRENCE

HIGH PRESSURE COOLANT INJECTION (BWR)
 TOTAL SYSTEM OCCURRENCE

MULTIPLE SYSTEMS
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: SECONDARY CONTAINMENT (BWR)

RESULT TYPE: 1,4 DISCOVERY: AUDIO/VISUAL ALARM

INITIATING EVENT: CABLE PENETRATION LEAK TESTING WITH OPEN FLAME
 RESULTING IN FIRE

PROPAGATION: FIRE SPREAD INTO CABLE SPREADING ROOM AND CABLE
 TRAYS IN RX BLDG

DEPENDENCY: POWER/CONTROL CABLES FOR MULTIPLE SAFETY SYSTEMS
 IN COMMON AREA

UNDESIRABLE RESULT: FIRE CAUSED RX TRIP AND DEGRADED RHR, ECCS AND
 AUXILIARY SYSTEMS

REMARKS: IEB 75-04 & 04A. FIRE BURNED OUT OF CONTROL 7
 HOURS. AFFECTED UNITS 1 & 2

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 15

REFERENCES: L0122 M2001 EVENT NO 21

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: BROWNS FERRY 1 PLANT TYPE: GE BWR
 EVENT DATE: 8/09/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

RECIRCULATING WATER (BWR)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

RECIRCULATING WATER (BWR)
 PIPES/FITTINGS

ENGINEERED SAFETY FEATURES ACTUATION
 I&C/SENSORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

ENGINEERED SAFETY FEATURES ACTUATION
 TOTAL SYSTEM OCCURRENCE

MULTIPLE ECCS SYSTEMS
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: REACTOR DRYWELL (BWR)

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: LOCA CAUSES HIGH AMBIENT TEMP CONDITIONS IN
 DRYWELL

PROPAGATION: HEATUP OF RX VESSEL LEVEL INST REFERENCE LEG
 CAUSES ERROR IN INDICATION

DEPENDENCY: RX VESSEL LEVEL REF LEG SUBJECT TO HIGH TEMP
 DURING LOCA

UNDESIRABLE RESULT: FAILURE OF MULTIPLE LEVEL INSTRUMENTS - SLOW
 RESPONSE OF ESF

REMARKS: GE SIL 299. SPECIFIC SYSTEMS AFFECTED NOT
 PROVIDED

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 8

REFERENCES: L0180 EVENT NO 22

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: BROWNS FERRY 1 PLANT TYPE: GE BWR
 EVENT DATE: 2/01/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

RECIRCULATING WATER (BWR)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

DRYWELL/ TORUS HVAC AND PURGE (BWR)
 MECHANICAL FUNCTION ITEMS

REACTOR DRYWELL (BWR)
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

CONTAINMENT ISOLATION
 TOTAL SYSTEM OCCURRENCE

REACTOR DRYWELL (BWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: LOCA OCCURRING DURING DRYWELL PURGE OPERATIONS

PROPAGATION: DRYWELL PRESSURE SURGE CAUSES FAILURE OF DUCTS OR DAMPERS

DEPENDENCY: INADEQUATE DUCT STRENGTH OR ISOLATION VALVE CAPABILITY FOR PURGE SYSTEM

UNDESIRABLE RESULT: LOSS OF CONTAINMENT INTEGRITY

REMARKS: PURGING WAS RESTRICTED TO LOW PRESSURE CONDITIONS FOR RCS

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 9

REFERENCES: L0031 L0032 EVENT NO 23

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: BROWNS FERRY 1 PLANT TYPE: GE BWR
 EVENT DATE: 2/10/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

RECIRCULATING WATER (BWR)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

RECIRCULATING WATER (BWR)
 PIPES/FITTINGS

COMPONENT COOLING WATER
 PIPES/FITTINGS

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR DRYWELL (BWR)
 TOTAL SYSTEM OCCURRENCE

COMPONENT COOLING WATER
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: REACTOR DRYWELL (BWR)

RESULT TYPE: 1,3 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: LOCA FROM RECIRC LINE BREAK IMPINGES ON RBCCW LINE
 CAUSING IT TO BREAK

PROPAGATION: IF RBCCW ISOLATION VALVE FAILS, DRYWELL ATMOSPHERE
 IS UNISOLATED

DEPENDENCY: RBCCW LINE SUBJECT TO RECIRC LINE BREAK DAMAGE AND
 ONLY ONE ISOL VALVE EXISTS

UNDESIRABLE RESULT: LOCA PLUS SINGLE FAILURE CAUSES LOSS OF
 CONTAINMENT INTEGRITY

CORRECTIVE ACTION: OTHER

CATEGORY: 23

REFERENCES: L0035 L0123

EVENT NO 24

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: BROWNS FERRY 3 PLANT TYPE: GE BWR
 EVENT DATE: 3/04/1976 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

RECIRCULATING WATER (BWR)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

LOW PRESSURE COOLANT INJECTION (BWR)
 I&C/GENERAL

LOW PRESSURE COOLANT INJECTION (BWR)
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

LOW PRESSURE COOLANT INJECTION (BWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: LOCA PLUS LPCI LOOP SELECTION LOGIC FAILURE

PROPAGATION: LPCI FLOWS SENT TO BROKEN LOOP - ALL 4 PUMPS
 EXCEED RUNOUT FLOW

DEPENDENCY: PUMPS DO NOT HAVE RUNOUT PROTECTION AND ARE
 DEPENDENT ON LOOP SELECTION LOGIC

UNDESIRABLE RESULT: LPCI OPERATION COULD DAMAGE RHR PUMPS, DEFEATING
 LONG TERM OPERABILITY

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 22

REFERENCES: L0108 EVENT NO 25

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: BROWNS FERRY 3 PLANT TYPE: GE BWR
 EVENT DATE: 6/28/1980 EXPERIENCE: ACTUAL
 OPERATING STATUS: ROUTINE SHUTDOWN

INITIATING SYSTEM AND COMPONENT

LIQUID RADWASTE
 VESSELS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

LIQUID RADWASTE
 VESSELS

CONTROL ROD DRIVE (BWR)
 PIPES/FITTINGS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CONTROL ROD DRIVE (BWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: RBEDT NOT ALLOWING WATER TO DRAIN FROM SCRAM
 DISCHARGE VOLUME

PROPAGATION: HIGH WATER LEVEL IN EAST SCRAM DISCHARGE VOLUME
 WITH NO AUTO SCRAM SIGNAL GEN

DEPENDENCY: REACTOR BLDG EQUIP DRAIN TANK CAUSES SDV TO NOT
 DRAIN PROPERLY

UNDESIRABLE RESULT: LOSS OF ABILITY TO SCRAM

REMARKS: SUBSEQUENT EVALUATION IDENTIFIED OTHER POTENTIAL
 PROBLEMS

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 18

REFERENCES: A0009 I-018 I-246 I-236 I-225 EVENT NO 26

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: BRUNSWICK 1 PLANT TYPE: GE BWR
 EVENT DATE: 9/21/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

RECIRCULATING WATER (BWR)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

RECIRCULATING WATER (BWR)
 PIPES/FITTINGS

ENGINEERED SAFETY FEATURES ACTUATION
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

ENGINEERED SAFETY FEATURES ACTUATION
 I&C/SENSORS

MULTIPLE ECCS SYSTEMS
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: REACTOR DRYWELL (BWR)

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: LOCA CAUSES HIGH AMBIENT TEMP CONDITIONS IN
 DRYWELL

PROPAGATION: HEATUP OF RX LEVEL INST REFERENCE LEG CAUSES ERROR
 IN INDICATION

DEPENDENCY: RX LEVEL REF LEG SUBJECT TO HIGH TEMP DURING LOCA

UNDESIRABLE RESULT: FAILURE OF MULT LEVEL INSTR-SLOW RESPONSE OF ESF

REMARKS: GE SIL 299. EVENT JUDGED TO NOT SIGNIFICANTLY
 IMPAIR SAFETY SYSTEM RESPONSE

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 8

REFERENCES: L0092 EVENT NO 27

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: BRUNSWICK 1 PLANT TYPE: GE BWR
 EVENT DATE: 11/08/1979 EXPERIENCE: ACTUAL
 OPERATING STATUS: COLD SHUTDOWN

INITIATING SYSTEM AND COMPONENT

CIRCULATING WATER (OPEN CYCLE)
 MOTORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

EMERGENCY GENERATOR I&C
 I&C/SWITCHES

EMERGENCY POWER GENERATION
 CIRCUIT BREAKER/FUSES

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 2 DISCOVERY: ROUTINE TEST/INSPECTION

INITIATING EVENT: WITH DG IN LOCAL MANUAL MODE, CIRC WATER PUMP
 MOTOR FAILS DEGRADING BUS VOLTAGE

PROPAGATION: DG OUTPUT BREAKER TRIPS, THEN GETS SIMUL. OPEN &
 CLOSE SIGNALS CAUSING LOCKOUT

DEPENDENCY: WHEN DG IN LOCAL MANUAL & LOP, CONTROLS GIVE
 ERRONEOUS SIGNALS

UNDESIRABLE RESULT: FAILURE OF BREAKER TO CLOSE AFTER LOAD SHED
 RESULTS IN LOSS OF EMERGENCY BUS

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 1

REFERENCES: L1020 EVENT NO 28

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: BRUNSWICK 2 PLANT TYPE: 3E BWR
 EVENT DATE: 2/27/1975 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

REACTOR OVERPRESSURE PROTECTION (BWR)
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

PLANT MONITORING
 IEC/INDICATORS

REACTOR OVERPRESSURE PROTECTION (BWR)
 VALVES

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR OVERPRESSURE PROTECTION (BWR)
 VALVES

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 2 DISCOVERY: ROUTINE TEST/INSPECTION

INITIATING EVENT: OVERPRESSURE IN REACTOR CAUSES ADS VALVES TO OPEN

PROPAGATION: TRICKLE CURRENT THRU RELAY INDICAT LIGHTS FEED
 SOLENOID COILS-VALVES WON'T CLOSE

DEPENDENCY: RELAY INDICATING LIGHTS & ADS VALVES' SOLENOID
 COILS HAVE SAME POWER SOURCE

UNDESIRABLE RESULT: ONCE OPENED, ADS VALVES CAN'T BE CLOSED CAUSING RX
 PRESSURE TRANSIENT

REMARKS: PROBLEM WAS DISCOVERED DURING PREOP TESTING OF ADS

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 22

REFERENCES: L1010 EVENT NO 29

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: BRUNSWICK 2 PLANT TYPE: GE BWR
 EVENT DATE: 9/17/1975 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

HIGH VOLTAGE AC (GREATER THAN 35KV)
 TOTAL SYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

ENGINEERED SAFETY FEATURES ACTUATION
 TOTAL SYSTEM OCCURRENCE

EMERGENCY POWER GENERATION
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 TOTAL SYSTEM OCCURRENCE

LOW PRESSURE COOLANT INJECTION (BWR)
 TOTAL SYSTEM OCCURRENCE

ALL SYSTEMS REQUIRING EMERGENCY POWER
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 3 DISCOVERY: UNKNOWN

INITIATING EVENT: LOSS OF OFFSITE POWER WITH A SLOW REDUCTION OF
 REACTOR PRESSURE

PROPAGATION: ESF LOGIC INITIATES LPCI AND CORE SPRAY
 SIMULTANEOUSLY

DEPENDENCY: LOP WITH SLOW REDUCTION OF RX PRESS PRODUCE ESF
 ACTUATION LOGIC ERROR

UNDESIRABLE RESULT: FAILURE OF ONE OR MORE DIESEL GEN AFTER LOP

REMARKS: PERMISSIVE LOGIC ERRCR-DETAILS UNCLEAR

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 1

REFERENCES: L0109 EVENT NO 30

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: BRUNSWICK 2 PLANT TYPE: GE BWR
 EVENT DATE: 1/05/1976 EXPERIENCE: ACTUAL
 OPERATING STATUS: COLD SHUTDOWN

INITIATING SYSTEM AND COMPONENT

ENVIRONMENT (EXTERNAL TO ANY STRUCTURE)
 TOTAL SYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

REACTOR AUXILIARY BUILDING HVAC
 SUBSYSTEM OCCURRENCE

LEAK MONITORING
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

HIGH PRESSURE COOLANT INJECTION (BWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: OUTSIDE TEMPERATURE DROPPED 20F THUS VENTILATION
 SYSTEM TEMP DROPPED

PROPAGATION: LEAK DETECTION CIRCUIT RECEIVED HIGH DELTA-TEMP
 SIGNAL, ISOLATED

DEPENDENCY: LEAK DETECTION IS DELTA-TEMP, NOT ABSOLUTE
 TEMPERATURE

UNDESIRABLE RESULT: HPCI UNAVAILABLE-TURBINE STEAM SUPPLY ISOLATED 3
 TIMES

CORRECTIVE ACTION: OTHER CATEGORY: 22

REFERENCES: L2034 EVENT NO 31

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: BRUNSWICK 2 PLANT TYPE: GE BWR
 EVENT DATE: 4/05/1977 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

REACTOR BUILDING HVAC (BWR)
 TOTAL SYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

REACTOR BUILDING HVAC (BWR)
 TOTAL SYSTEM OCCURRENCE

LEAK MONITORING
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

HIGH PRESSURE COOLANT INJECTION (BWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: SECONDARY CONTAINMENT (BWR)

RESULT TYPE: 2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: RX BLDG HEATING OFF, INLET AIR TEMPERATURE TO HPCI
 ROOM LOWER THAN HPCI ROOM AIR

PROPAGATION: HIGH DIFF TEMP SENSED AS STEAM LINE BREAK

DEPENDENCY: LOW RX BLDG AIR TEMP CAN INITIATE HPCI STEAM LINE
 BREAK LOGIC

UNDESIRABLE RESULT: HPCI LOST DUE TO ISOL SIGNAL FROM STEAM LINE BREAK
 LOGIC

REMARKS: LER INDICATED THIS WAS SECOND OCCURRENCE-ALSO ON
 12/21/76, BUT NO HPCI ISOL

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 23

REFERENCES: L0131 EVENT NO 32

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: CALVERT CLIPPS 1 PLANT TYPE: CE PWR
 EVENT DATE: 5/23/1975 EXPERIENCE: ACTUAL
 OPERATING STATUS: LOAD CHANGE DURING POWER OPERATION

INITIATING SYSTEM AND COMPONENT

CONDENSATE AND FEEDWATER
 TOTAL SYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 4 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: LOSS OF FEEDWATER TRIP

PROPAGATION: QUENCHING OF STEAM IN FW PIPING BY APW CAUSED
 WATER HAMMER DAMAGE TO FW HDR VLVS

DEPENDENCY: COMMON FW HDR FOR MAIN AND AUX FW CAN CONTAIN
 STEAM DURING LOSS OF FW TRIP

UNDESIRABLE RESULT: DAMAGE TO APW FLOW PATH WHEN APW DEMANDED

REMARKS: WATER HAMMER EVENTS ALSO AT SURRY 1, TURKEY
 PT. 2&3, GINNA 1, IND PT. 2 (SEE REP 2)

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 12

REFERENCES: L0139 M1001 EVENT NO 33

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: CALVERT CLIFFS 1 PLANT TYPE: CE PWR
 EVENT DATE: 5/20/1980 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

ESSENTIAL COMPRESSED AIR
 HEAT EXCHANGERS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

ESSENTIAL COMPRESSED AIR
 HEAT EXCHANGERS

ESSENTIAL RAW COOLING/ SERVICE WATER
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

ESSENTIAL RAW COOLING/ SERVICE WATER
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: TUBE FAILURE IN INSTRUMENT AIR COMPRESSOR
 AFTERCOOLER ALLOWED AIR INTO SWS

PROPAGATION: AIR ACCUMULATED ON SHELL SIDE OF IDLE SWS HX WHILE
 HX OUT OF SERVICE

DEPENDENCY: TRAPPED AIR SWEEPED INTO COMMON SW HEADER WHEN HX
 BROUGHT BACK ON LINE

UNDESIRABLE RESULT: BOTH TRAINS OF SERVICE WATER DISABLED DUE TO
 COMMON HEADER IN TURBINE BLDG

REMARKS: NUMEROUS HARDWARE AND PROCEDURAL CHANGES RESULTED

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 2

REFERENCES: A0014 L2054 I-127 EVENT NO 34

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: CALVERT CLIFFS 1 PLANT TYPE: CE PWR
 EVENT DATE: 8/12/1980 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

ESSENTIAL COMPRESSED AIR
 HEAT EXCHANGERS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

ESSENTIAL COMPRESSED AIR
 HEAT EXCHANGERS

ESSENTIAL RAW COOLING/ SERVICE WATER
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

ESSENTIAL RAW COOLING/ SERVICE WATER
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,2 DISCOVERY: AUDIO/VISUAL ALARM

INITIATING EVENT: INSTRUMENT AIR AFTER COOLER TUBES FAIL ALLOWING
 AIR INGRESS INTO SERVICE WATER

PROPAGATION: AIR IN BOTH SERVICE WATER TRAINS CAUSED LOW FLOW

DEPENDENCY: INSTRUMENT AIR AND SERVICE WATER INTERFACE AT
 COMPRES COOLER-AIR AT HIGHER PRESS

UNDESIRABLE RESULT: LOSS OF SERVICE WATER & POTENTIAL LOSS OF ALL
 SAFETY-RELATED EQUIPMENT SERVED

REMARKS: COOLER TUBES WERE CRACKED FROM OVER-ROLLING.

CORRECTIVE ACTION: REPAIR/REPLACEMENT CATEGORY: 2

REFERENCES: L1035 EVENT NO 35

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: CALVERT CLIFFS 1 PLANT TYPE: CE PWR
 EVENT DATE: 11/05/1981 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MAIN CONDENSER
 HEAT EXCHANGERS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

EQUIPMENT DRAINAGE (INCLUDING VENTS)
 PIPES/FITTINGS

ESSENTIAL RAW COOLING/ SERVICE WATER
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

ESSENTIAL RAW COOLING/ SERVICE WATER
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: TURBINE BUILDING

RESULT TYPE: 1,2 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: CONDENSER LEAK OR FLOOD OF CONDENSER PIT WITH
 HEAVY FLOW INTO EQUIPMENT DRAINS

PROPAGATION: CONDENSER LEAKS, EQUIP DRAINS BACKFLOW-FLOOD
 SERVICE WATER PUMP ROOM-PUMPS FAIL

DEPENDENCY: SERVICE WATER PUMP ROOM AND CONDENSER PIT ARE
 CONNECTED VIA UNISOLATIBLE DRAINS

UNDESIRABLE RESULT: TOTAL LOSS OF SERVICE WATER DUE TO FLOODING DAMAGE
 TO PUMPS AND OTHER EQUIPMENT

REMARKS: SERVICE WATER PUMP ROOM IS 12 FT. IN ELEV HIGHER
 THAN CONDENSER PIT.

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 4

REFERENCES: L1026 I-148 I-120 A0016

EVENT NO 36

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: CALVERT CLIFFS 2 PLANT TYPE: CE PWR
 EVENT DATE: 10/17/1978 EXPERIENCE: ACTUAL
 OPERATING STATUS: COLD SHUTDOWN

INITIATING SYSTEM AND COMPONENT

CVCS/HIGH PRESSURE SAFETY INJECTION
 UNSPECIFIED COMPONENT

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CVCS/HIGH PRESSURE SAFETY INJECTION
 TOTAL SYSTEM OCCURRENCE

RESIDUAL HEAT REMOVAL (PWR)
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

RESIDUAL HEAT REMOVAL (PWR)
 PUMPS

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: AIR USED TO TRANSFER RESINS GETS IN PURIFICATION
 SYSTEM LINES

PROPAGATION: AIR LEAKS INTO RHR SYSTEM AND BOTH PUMPS BECOME
 AIRBOUND AND CAVITATE

DEPENDENCY: RHR SYSTEM AND PURIFICATION SYSTEM HAVE A
 CROSS-CONNECTION WHICH WAS OPEN

UNDESIRABLE RESULT: LOSS OF RHR COOLING WHILE IN COLD SHUTDOWN

REMARKS: CAN HAPPEN ONLY IN COLD SHUTDOWN AS THAT IS ONLY
 WHEN CROSS-CONNECTION IS OPENED

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 2

REFERENCES: L1041 M2001 EVENT NO 37

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: CALVERT CLIFFS 2 PLANT TYPE: CE PWR
 EVENT DATE: 11/05/1981 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MAIN CONDENSER
 HEAT EXCHANGERS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

EQUIPMENT DRAINAGE (INCLUDING VENTS)
 PIPES/FITTINGS

ESSENTIAL RAW COOLING/ SERVICE WATER
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

ESSENTIAL RAW COOLING/ SERVICE WATER
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: TURBINE BUILDING

RESULT TYPE: 1,2 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: CONDENSER LEAK OR FLOOD OF CONDENSER PIT WITH
 HEAVY FLOW INTO EQUIPMENT DRAINS

PROPAGATION: CONDENSER LEAKS, EQUIP DRAINS BACKFLOW-FLOOD
 SERVICE WATER PUMP ROOM-PUMPS FAIL

DEPENDENCY: SERVICE WATER PUMP ROOM AND CONDENSER PIT ARE
 CONNECTED VIA UNISOLATIBLE DRAINS

UNDESIRABLE RESULT: TOTAL LOSS OF SERVICE WATER DUE TO FLOODING DAMAGE
 TO PUMPS AND OTHER EQUIPMENT

REMARKS: SERVICE WATER PUMP ROOM IS 12 FT. IN ELEV HIGHER
 THAN CONDENSER PIT.

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 4

REFERENCES: L1027 I-148 I-120 EVENT NO 38

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: CALVERT CLIFFS 2 PLANT TYPE: CE PWR
 EVENT DATE: 7/20/1982 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

RAW SERVICE WATER
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

RAW SERVICE WATER
 VALVES

ESSENTIAL RAW COOLING/ SERVICE WATER
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

ESSENTIAL RAW COOLING/ SERVICE WATER
 TOTAL SYSTEM OCCURRENCE

COMPONENT COOLING WATER
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: SERVICE WATER HEAT EXCHANGER DISCHARGE HEADER
 BUTTERFLY VALVE FAILED

PROPAGATION: FLOW OF SALT WATER CAUSED VALVE DISK TO MOVE TO
 THE CLOSED POSITION

DEPENDENCY: COMMON DISCHARGE HEADER FROM SERVICE WATER HX TO
 DISCHARGE CANAL

UNDESIRABLE RESULT: LOSS OF SW AND ONE TRAIN OF COMPONENT COOLING
 WATER

REMARKS: POINT BEACH 1 & 2 AND FT. CALHOUN HAVE SIMILAR
 DESIGNS

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 13

REFERENCES: A0017 L2053 EVENT NO 39

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: CALVERT CLIFFS 2 PLANT TYPE: CE PWR
 EVENT DATE: 10/19/1983 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

POTABLE AND SANITARY WATER
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

POTABLE AND SANITARY WATER
 PIPES/FITTINGS

REACTOR POWER CONTROL (PWR)
 ELECTRICAL/I&C FUNCTION ITEMS

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR POWER CONTROL (PWR)
 ELECTRICAL/I&C FUNCTION ITEMS

CONTROL ROD DRIVE (PWR)
 CONTROL ROD DRIVES

TYPE OF COUPLING: SPATIAL PLANT AREA: CONTROL BUILDING

RESULT TYPE: 2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: CONTROL ROOM TOILET PLUGS & OVERFLOWS. WATER
 SEEPS THRU FLOOR TO SPREADING ROOM

PROPAGATION: WATER DRIPS ON CONTROL ROD CABINETS SHORTING EQUIP
 - ONE CONTROL ROD DROPS

DEPENDENCY: TOILET IS ABOVE SPREADING ROOM AND FIRE BARRIER
 WALLS ARE NOT WATER TIGHT

UNDESIRABLE RESULT: SHORTING OF CONTROL ROD EQUIP-UNDESIREED ROD
 DROP-POTENTIAL FLUX TILT OR SCRAM

REMARKS: CROWBAR LEFT IN TOILET DRAIN CAUSED CLOGGING

CORRECTIVE ACTION: REPAIR/REPLACEMENT CATEGORY: 4

REFERENCES: L2038 A0023 EVENT NO 40

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: CLINTON 1 PLANT TYPE: GE BWR
 EVENT DATE: 6/26/1981 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

CONTROL BUILDING HVAC
 BLOWERS/COMPRESSORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CONTROL BUILDING HVAC
 BLOWERS/COMPRESSORS

MULTIPLE SAFETY SYSTEMS
 ELECTRICAL CONDUCTORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 ELECTRICAL CONDUCTORS

MULTIPLE SAFETY SYSTEMS
 ELECTRICAL CONDUCTORS

TYPE OF COUPLING: SPATIAL PLANT AREA: CONTROL BUILDING

RESULT TYPE: 2 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: HVAC FAN FAILURE CAN PROPEL MISSILE THRU FAN
 HOUSING

PROPAGATION: SAFETY-RELATED EQUIPMENT CAN BE DAMAGED BY MISSILE

DEPENDENCY: SAFETY-RELATED CABLES UNPROTECTED FROM POTENTIAL
 MISSILES

UNDESIRABLE RESULT: DEGRADATION OF ONE OR MORE SAFETY SYSTEMS

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 16

REFERENCES: C07 EVENT NO 41

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: CONNECTICUT YANKEE PLANT TYPE: WEST PWR
 EVENT DATE: 5/08/1978 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

ENGINEERED SAFETY FEATURES ACTUATION
 TOTAL SYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 TOTAL SYSTEM OCCURRENCE

ALL ESP SYSTEMS
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,2,3 DISCOVERY: UNKNOWN

INITIATING EVENT: LOCA WITH LOSS OF OPPOSITE POWER COINCIDENT WITH
 SAFETY INJECTION SIGNAL

PROPAGATION: DIESEL GENERATORS OVERLOAD DUE TO PRESENCE OF
 NON-SAFETY LOADS

DEPENDENCY: NON-SAFETY LOADS NOT SHED UPON SI SIGNAL

UNDESIRABLE RESULT: ESP SYSTEMS COULD FAIL DUE TO LOP

REMARKS: SINCE CHG PUMPS NOT REQD, DESIGN CHANGED TO TRIP
 OR BLOCK OPERATION

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 1

REFERENCES: L0093 L0096

EVENT NO 42

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: CONNECTICUT YANKEE PLANT TYPE: WEST PWR
 EVENT DATE: 8/25/1978 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

OPERATION ACTIVITY
 PERSONNEL

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

REACTOR POWER CONTROL (PWR)
 I&C/SWITCHES

OPERATION ACTIVITY
 PERSONNEL

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR POWER CONTROL (PWR)
 I&C/SWITCHES

TYPE OF COUPLING: SPATIAL PLANT AREA: CONTROL BUILDING

RESULT TYPE: 2,4 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: OPERATOR KEYED PORTABLE FM TRANSCEIVER IN CONTROL
 ROOM NEAR POWER RANGE INSTR

PROPAGATION: STRONG FM RADIO SIGNALS INITIATED TBN LOAD RUNBACK
 AND AUTO ROD W/D STOP SIGNAL

DEPENDENCY: CONTROL ROOM INSTRUMENTATION SUSCEPTIBLE TO STRONG
 FM SIGNALS

UNDESIRABLE RESULT: RX TRANSIENTS MAY RESULT FROM ACTUATION OF
 PORTABLE FM TRANSCEIVERS

REMARKS: RADIOS ARE IN COMMON USE IN NPP'S - NEED PERSONNEL
 DISCIPLINE TO LIMIT USE IN CR

CORRECTIVE ACTION: OTHER CATEGORY: 23

REFERENCES: L0126 EVENT NO 43

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: CONNECTICUT YANKEE PLANT TYPE: WEST PWR
EVENT DATE: 1/29/1980 EXPERIENCE: POTENTIAL
OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

HIGH VOLTAGE AC (GREATER THAN 35KV)
UNSPECIFIED COMPONENT

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

EMERGENCY POWER GENERATION
SUBSYSTEM OCCURRENCE

EMERGENCY POWER GENERATION
SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
TOTAL SYSTEM OCCURRENCE

ALL SYSTEMS REQUIRING EMERGENCY POWER
TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,2,3 DISCOVERY: REVIEW OF PROCEDURE/TEST RESULTS

INITIATING EVENT: LOSS OF POWER FOLLOWED BY AUTOMATIC AND MANUAL DG
LOADING & THEN A LOCA

PROPAGATION: LOCA GENERATED SIAS SIGNAL WOULD PLACE ADDITIONAL
LOADS ON DG CAUSING OVERLOAD

DEPENDENCY: EMERGENCY POWER MAY FAIL DUE TO NON ESSENTIAL
LOADS

UNDESIRABLE RESULT: DEGRADATION OF SYSTEMS DEPENDENT ON EMERGENCY
POWER DUE IN PART TO NONSAFETY EQP

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 1

REFERENCES: L0043

EVENT NO 44

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: COOK 2 PLANT TYPE: WEST PWR
 EVENT DATE: 3/26/1982 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

REACTOR AUXILIARY BUILDING HVAC
 HEAT EXCHANGERS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

REACTOR AUXILIARY BUILDING HVAC
 HEAT EXCHANGERS

CONTAINMENT ICE CONDENSER (PWR)
 HEAT EXCHANGERS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CONTAINMENT ICE CONDENSER (PWR)
 HEAT EXCHANGERS

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 0 DISCOVERY: ROUTINE TEST/INSPECTION

INITIATING EVENT: TEMP GRAD INDUCED AIR CURRENTS CAUSED ICE
 MIGRATION IN BASKETS NEAR CRANE WALL

PROPAGATION: ICE LOSS COULD PREVENT ADEQUATE STEAM CONDENSATION
 ON LOCA THUS RB OVERPRESSURE

DEPENDENCY: CRANE WALL IS NEAR STEAM GENERATORS WHICH HEAT-UP
 WALL

UNDESIRABLE RESULT: POTENTIAL SERVICE ICE LOSS IN ICE CONDENSER
 LEADING TO RB OVERPRESSURE

REMARKS: LOSS OF 17 AIR HANDLING UNITS CAUSED GREATER
 EFFECT THAN ANTICIPATED

CORRECTIVE ACTION: REPAIR/REPLACEMENT CATEGORY: 23

REFERENCES: L1031 EVENT NO 45

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: COOPER PLANT TYPE: GE BWR
 EVENT DATE: 10/16/1978 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MULTIPLE SAFETY SYSTEMS
 ELECTRICAL CONDUCTORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

MULTIPLE SAFETY SYSTEMS
 ELECTRICAL CONDUCTORS

MULTIPLE SAFETY SYSTEMS
 ELECTRICAL CONDUCTORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

MULTIPLE SAFETY SYSTEMS
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: CONTROL BUILDING

RESULT TYPE: 1 DISCOVERY: UNKNOWN

INITIATING EVENT: ANY EVENT DAMAGING CABLES UNDER PANEL 9-3

PROPAGATION: BOTH DIVISION I AND DIVISION II CABLES ARE ROUTED
 THRU RISER UNDER PANEL

DEPENDENCY: INSTALLATION ERROR ROUTED A SINGLE DIV I CABLE IN
 DIV II RISER

UNDESIRABLE RESULT: VIOLATES REDUNDANCY REQUIREMENT FOR SAFETY SYSTEMS
 (SYSTEMS NOT SPECIFIED)

CORRECTIVE ACTION: REPAIR/REPLACEMENT

CATEGORY: 15

REFERENCES: L0014

EVENT NO 46

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: CRYSTAL RIVER 3 PLANT TYPE: B&W PWR
 EVENT DATE: 2/07/1977 EXPERIENCE: ACTUAL
 OPERATING STATUS: COLD SHUTDOWN

INITIATING SYSTEM AND COMPONENT

CONTAINMENT SPRAY
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CONTAINMENT SPRAY
 VALVES

RESIDUAL HEAT REMOVAL (PWR)
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

PRIMARY COOLANT (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 3 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: CONTAINMENT SPRAY SYSTEM VALVE TESTED WITHOUT
 MANUALLY ISOLATING NAOH TANK

PROPAGATION: NAOH DRAINED INTO DECAY HEAT REMOVAL
 SYSTEM, DILUTING RCS BORON CONCENTRATION

DEPENDENCY: CONTAINMENT SPRAY PUMP SUCTION REMAINED CONNECTED
 TO RHR DURING TEST

UNDESIRABLE RESULT: UNTERMINATED DILUTION COULD RESULT IN INADVERTENT
 CRITICALITY

CORRECTIVE ACTION: OTHER

CATEGORY: 22

REFERENCES: L0101 L0102

EVENT NO 47

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: CRYSTAL RIVER 3 PLANT TYPE: B&W PWR
 EVENT DATE: 2/26/1980 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

DC POWER
 ELECTRICAL/I&C FUNCTION ITEMS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

NON-NUCLEAR INSTRUMENTATION
 TOTAL SYSTEM OCCURRENCE

REACTOR POWER CONTROL (PWR)
 I&C/CONTROLLERS

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR POWER CONTROL (PWR)
 TOTAL SYSTEM OCCURRENCE

FEEDWATER CONTROL
 TOTAL SYSTEM OCCURRENCE

PRESSURIZER (PWR)
 VALVES

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 2,3 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: 24 VDC NNI POWER FAILED-LOST 70% OF NNI
 INSTRUMENTATION

PROPAGATION: POWER FAILURE CAUSED PORV TO LATCH OPEN AND ICS TO
 DEMAND 103% POWER

DEPENDENCY: NON-NUCLEAR INSTRUMENT POWER AFFECTS PORV AND
 INTEGRATED CONTROL SYSTEM

UNDESIRABLE RESULT: LO FW/HI STEAM FLOWS, SG BOILS DRY, PORV LATCHES
 OPEN, RAPID DEPRESS, SIAS

REMARKS: MULT. INSTRUMENTS FAILED-PAMS, PZR LEVEL, RCS FLOW
 T-HOT, SG PRESS, MFW FLOW

CORRECTIVE ACTION: OTHER

CATEGORY: 14

REFERENCES: L1004 I-036 I-270 I-257 I-108

EVENT NO 48

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: DAVIS-BESSE 1 PLANT TYPE: B&W PWR
 EVENT DATE: 12/23/1976 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

EMERGENCY POWER GENERATION
 ENGINES, INTERNAL COMBUSTION

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

ENGINEERED SAFETY FEATURES ACTUATION
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

ENGINEERED SAFETY FEATURES ACTUATION
 TOTAL SYSTEM OCCURRENCE

ALL ESP SYSTEMS
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: UNKNOWN

INITIATING EVENT: LOCA AND A LOSP OCCURRING LATER AFTER DG HAS BEEN
 MANUALLY STOPPED

PROPAGATION: ESPAS SEQUENCER WILL NOT RESTART PUMPS EVEN THOUGH
 DG RESTARTS ON ACTUAL LOSP

DEPENDENCY: STOPPING DG REQUIRES BLOCKING SAFETY ACTUATION
 SIGNAL TO DG - AFFECTS SEQUENCER

UNDESIRABLE RESULT: FOR THIS EVENT, ESPAS SEQUENCER WILL NOT RESTART
 ESSENTIAL PUMPS GIVEN LOSP

REMARKS: DESIGN CHANGE CORRECTED THIS ERROR. SEE EVENT ON
 02/24/77

CORRECTIVE ACTION: DESIGN CHANGE, MODIFICATION CATEGORY: 1

REFERENCES: L0104 EVENT NO 49

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: DAVIS-BESSE 1 PLANT TYPE: B&W PWR
 EVENT DATE: 2/24/1977 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

HIGH VOLTAGE AC (GREATER THAN 35KV)
 TOTAL SYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 TOTAL SYSTEM OCCURRENCE

ALL SYSTEMS REQUIRING EMERGENCY POWER
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: SPECIAL TEST/INSPECTION

INITIATING EVENT: ESPAS MANUAL INITIATION AND A LATER LOSS OF
 OFFSITE POWER

PROPAGATION: ALL EDG LOADS WOULD BE APPLIED AT ONE TIME,
 SEQUENCER WOULD NOT WORK

DEPENDENCY: EDG'S COULD BE OVERLOADED, DUE TO STARTUP SURGES

UNDESIRABLE RESULT: LOSP IN THIS SEQUENCE COULD RESULT IN EDG FAILURES

REMARKS: PROBLEM DUE TO CHANGES TO CORRECT EARLIER
 SEQUENCER DEFECT-12/23/76

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 1

REFERENCES: L0105

EVENT NO 50

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: DAVIS-BESSE 1 PLANT TYPE: B&W PWR
 EVENT DATE: 6/07/1978 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

ENGINEERED SAFETY FEATURES ACTUATION
 TOTAL SYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

MEDIUM VOLTAGE AC (35KV TO 600V)
 SUBSYSTEM OCCURRENCE

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

MULTIPLE SAFETY SYSTEMS
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 2 DISCOVERY: REVIEW OF PROCEDURE/TEST RESULTS

INITIATING EVENT: LOSS OF POWER WHEN OPERATOR BACKFEEDS NONESSENTIAL
 BUS AND THEN SPAS SIGNAL

PROPAGATION: UNLESS LOSS OF POWER ON BUS, SPAS SEQUENCER WILL
 NOT OPERATE

DEPENDENCY: LOADS WILL OCCUR AS INITIATED WITHOUT SEQUENCING,
 THREATENING ESSENTIAL BUS

UNDESIRABLE RESULT: CONNECTION BETWEEN BUSES CAN CAUSE FAILURE OF
 ESSENTIAL BUS DURING LOSP

REMARKS: PROCEDURE CHANGE. A DESIGN CHANGE MAY BE REQUIRED

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 1

REFERENCES: L0095 EVENT NO 51

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: DAVIS-BESSE 1 PLANT TYPE: B&W PWR
 EVENT DATE: 4/19/1980 EXPERIENCE: ACTUAL
 OPERATING STATUS: REFUELING

INITIATING SYSTEM AND COMPONENT

ENGINEERED SAFETY FEATURES ACTUATION
 MISCELLANEOUS EQUIPMENT

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

RESIDUAL HEAT REMOVAL (PWR)
 SUBSYSTEM OCCURRENCE

RESIDUAL HEAT REMOVAL (PWR)
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

RESIDUAL HEAT REMOVAL (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: POWER LOST WHILE 2 ESP CHANNELS PLACED ON ONE
 POWER SUPPLY FOR MAINTENANCE WORK

PROPAGATION: INADVERTENT ACTUATION OF ALL SPAS LEVELS & RHR
 RECIRC SUCTION TO SUMP

DEPENDENCY: INADEQUATE CONTROL OF MAINTENANCE WORK DURING
 OUTAGE

UNDESIRABLE RESULT: DEGRADATION OF RHR, WOULD ALSO HAPPEN TO ECCS AND
 CNMT SPRAY IF OPERATING

REMARKS: OTHER INADVERTENT SWITCHOVERS HAVE OCCURRED
 PREVIOUSLY

CORRECTIVE ACTION: OTHER

CATEGORY: 6

REFERENCES: I-023 I-251 L0151 M0005 M0006

EVENT NO 52

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: DAVIS-BESSE 1 PLANT TYPE: B&W PWR
 EVENT DATE: 7/09/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

ENGINEERED SAFETY FEATURES ACTUATION
 I&C/GENERAL

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

ENGINEERED SAFETY FEATURES ACTUATION
 I&C/GENERAL

EMERGENCY POWER GENERATION
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 TOTAL SYSTEM OCCURRENCE

MULTIPLE SYSTEMS
 MISCELLANEOUS EQUIPMENT

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 4 DISCOVERY: REVIEW OF PROCEDURE/TEST RESULTS
 INITIATING EVENT: SFAS TRIP COINCIDENT WITH LOSS OF OFFSITE POWER
 PROPAGATION: POTENTIAL EXISTS FOR LOADING DG INSTANTEOUSLY (W/O SEQUENCING)
 DEPENDENCY: SPECIFIC COMBINATION AND TIMING DEFEATS SEQUENCER, OVERLOADING DG
 UNDESIRABLE RESULT: LOSP AND SFAS CAN OVERLOAD DG, CAUSING DEGRADATION OF EMERGENCY POWER
 REMARKS: SPECIFIC COMBINATION REQD FOR PROBLEM CONSIDERED EXTREMELY UNLIKELY
 CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 1
 REFERENCES: L0114 L0115 EVENT NO 53

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: DAVIS-BESSE 1 PLANT TYPE: B&W PWR
 EVENT DATE: 7/30/1981 EXPERIENCE: ACTUAL
 OPERATING STATUS: ROUTINE SHUTDOWN

INITIATING SYSTEM AND COMPONENT

SEC CONT RECIRC AND EXHAUST
 BLOWERS/COMPRESSORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

SEC CONT RECIRC AND EXHAUST
 BLOWERS/COMPRESSORS

SECONDARY CONTAINMENT (PWR)
 STRUCTURAL FUNCTION ITEMS

SAFETY SYSTEMS/COMPONENTS AFFECTED

SECONDARY CONTAINMENT (PWR)
 STRUCTURAL FUNCTION ITEMS

SEC CONT RECIRC AND EXHAUST
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: WITH SUPPLY FAN RUNNING, CNMT PURGE EXH FAN
 TRIPPED, OVERPRESS BLEW OUT PANEL

PROPAGATION: WITH BLOW-OUT PANEL OPEN, SHIELD BLDG INTEGRITY IS
 LOST, CAN'T MAINTAIN NEG PRES

DEPENDENCY: OVER-PRESSURIZATION OF AREA AND BLOW OUT PANEL
 OPENS

UNDESIRABLE RESULT: POTENTIAL FAILURE OF SHIELD BLDG TO CONTROL
 LEAKAGE

REMARKS: EXHAUST FAN TRIP ON 13.8 KV TRANSFER AFTER
 CONDENSER FAILURE & SCRAM

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 22

REFERENCES: L1014

EVENT NO 54

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: DIABLO CANYON 1 PLANT TYPE: WEST PWR
 EVENT DATE: 10/06/1978 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

UNKNOWN
 UNSPECIFIED COMPONENT

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

MULTIPLE SAFETY SYSTEMS
 ELECTRICAL CONDUCTORS

MULTIPLE SAFETY SYSTEMS
 ELECTRICAL CONDUCTORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

MULTIPLE SAFETY SYSTEMS
 TOTAL SYSTEM OCCURRENCE

CONTROL ROOM PANELS
 TOTAL SYSTEM OCCURRENCE

MULTIPLE SAFETY SYSTEMS

TYPE OF COUPLING: SPATIAL PLANT AREA: CONTROL BUILDING

RESULT TYPE: 1 DISCOVERY: ROUTINE TEST/INSPECTION

INITIATING EVENT: EVENT CAUSING DAMAGE TO CLASS I CIRCUITS IN
 CONTROL ROOM PANELS

PROPAGATION: MULTIPLE REDUNDANT CLASS I CIRCUITS ARE DAMAGED

DEPENDENCY: REDUNDANT CIRCUITS ARE NOT ADEQUATELY SEPARATED

UNDESIRABLE RESULT: LOSS OF CONTROL OR MONITORING OF SAFETY
 SYSTEMS/PARAMETERS

REMARKS: SPECIFIC SYSTEM NOT IDENTIFIED. ALSO SAME ERROR
 AT UNIT 2

CORRECTIVE ACTION: REPAIR/REPLACEMENT CATEGORY: 15

REFERENCES: L0010 EVENT NO 55

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: DIABLO CANYON 2 PLANT TYPE: WEST PWR
 EVENT DATE: 10/06/1978 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

UNKNOWN
 UNSPECIFIED COMPONENT

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

MULTIPLE SAFETY SYSTEMS
 ELECTRICAL CONDUCTORS

MULTIPLE SAFETY SYSTEMS
 ELECTRICAL CONDUCTORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

MULTIPLE SAFETY SYSTEMS
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: CONTROL BUILDING

RESULT TYPE: 1 DISCOVERY: ROUTINE TEST/INSPECTION

INITIATING EVENT: EVENT CAUSING DAMAGE TO CLASS I CIRCUITS IN
 CONTROL ROOM PANELS

PROPAGATION: MULTIPLE REDUNDANT CLASS I CIRCUITS ARE DAMAGED

DEPENDENCY: REDUNDANT CIRCUITS WERE NOT ADEQUATELY SEPARATED

UNDESIRABLE RESULT: LOSS OF CONTROL OR MONITORING OF SAFETY
 SYSTEMS/PARAMETERS

REMARKS: SPECIFIC SYSTEMS NOT IDENTIFIED. SAME ERROR
 OCCURRED AT UNIT 1.

CORRECTIVE ACTION: REPAIR/REPLACEMENT

CATEGORY: 15

REFERENCES: L0010

EVENT NO 56

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: DRESDEN 2 PLANT TYPE: GE BWR
 EVENT DATE: 2/02/1978 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

DC POWER
 ELECTRICAL CONDUCTORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

DC POWER
 BATTERIES/CHARGERS

DC POWER
 ELECTRICAL CONDUCTORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

DC POWER
 SUBSYSTEM OCCURRENCE

MULTIPLE SAFETY SYSTEMS
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: MISCELLANEOUS/ UNKNOWN STRUCTURE:

RESULT TYPE: 1 DISCOVERY: SPECIAL TEST/INSPECTION

INITIATING EVENT: ANY EVENT CAUSING DAMAGE TO DC CABLE FROM CHARGER
 TO BATTERY

PROPAGATION: CABLE CONNECTING MAIN DC BUS TO RESERVE BUS COULD
 ALSO BE DAMAGED

DEPENDENCY: INSTALLATION ERROR ALLOWED REDUNDANT SOURCES OF DC
 POWER TOO CLOSE TOGETHER

UNDESIRABLE RESULT: POTENTIAL FAILURE OF DC POWER SUPPORTING SAFETY
 SYSTEMS

REMARKS: ERROR FOUND DURING NRC REQUESTED REVIEW OF DC
 BUSES

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 15

REFERENCES: L0013 EVENT NO 57

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: DRESDEN 2 PLANT TYPE: GE BWR
EVENT DATE: 12/23/1981 EXPERIENCE: ACTUAL
OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

FIRE DETECTION
I&C/SENSORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

HIGH PRESSURE COOLANT INJECTION (BWR)
TOTAL SYSTEM OCCURRENCE

FIRE DETECTION
I&C/SENSORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

HIGH PRESSURE COOLANT INJECTION (BWR)
TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: SECONDARY CONTAINMENT (BWR)

RESULT TYPE: 2 DISCOVERY: AUDIO/VISUAL ALARM

INITIATING EVENT: HPCI ROOM FIRE PROTECTION SYSTEM ACTUATED DUE TO
HIGH HUMIDITY AND STEAM

PROPAGATION: WATER ENTERED HPCI OIL SYSTEM

DEPENDENCY: HPCI CAN FAIL DUE TO FIRE SYSTEM ACTUATION

UNDESIRABLE RESULT: HPCI NOT OPERABLE

REMARKS: SIMILAR TO EVENT AT DRESDEN 3

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 3

REFERENCES: I-151 L0060 A0024 EVENT NO 58

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: DRESDEN 3 PLANT TYPE: GE BWR
 EVENT DATE: 7/19/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

LIQUID RADWASTE
 VESSELS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

LIQUID RADWASTE
 VESSELS

CONTROL ROD DRIVE (BWR)
 PIPES/FITTINGS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CONTROL ROD DRIVE (BWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 2 DISCOVERY: SPECIAL TEST/INSPECTION

INITIATING EVENT: RBEDT NOT ALLOWING WATER TO DRAIN FROM SCRAM
 DISCHARGE VOLUME

PROPAGATION: HIGH WATER LEVEL IN WEST SCRAM DISCHARGE VOLUME
 WITH NO AUTO SCRAM SIGNAL GEN

DEPENDENCY: REACTOR BLDG EQUIP DRAIN TANK CAUSES SDV TO NOT
 DRAIN PROPEELY

UNDESIRABLE RESULT: LOSS OF ABILITY TO SCRAM ASSOCIATED CONTROL RODS

REMARKS: FOUND DURING TEST REQUIRED BY IEB 80-17. VENT
 LINES MODIFIED.

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 18

REFERENCES: A0009 I-018 I-236 L0152 EVENT NO 59

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: DRESDEN 3 PLANT TYPE: GE BWR
 EVENT DATE: 11/30/1981 EXPERIENCE: ACTUAL
 OPERATING STATUS: ROUTINE STARTUP

INITIATING SYSTEM AND COMPONENT

FIRE DETECTION
 IEC/SENSORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

HIGH PRESSURE COOLANT INJECTION (BWR)
 TOTAL SYSTEM OCCURRENCE

FIRE PROTECTION
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

HIGH PRESSURE COOLANT INJECTION (BWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: SECONDARY CONTAINMENT (BWR)

RESULT TYPE: 2 DISCOVERY: AUDIO/VISUAL ALARM

INITIATING EVENT: HPCI ROOM FIRE PROTECTION SYSTEM ACTUATED DUE TO
 HIGH HUMIDITY AND STEAM

PROPAGATION: FIRE SUPPRESSION SYSTEM FLOODED HPCI ROOM

DEPENDENCY: HPCI CAN FAIL DUE TO FIRE SYSTEM ACTUATION

UNDESIRABLE RESULT: HPCI NOT OPERABLE

REMARKS: HPCI ROOM HAS HISTORY OF HI HUMIDITY-ALSO TEMP
 VENTILATION WAS NOT OPERATING

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 3

REFERENCES: I-151 L0059 EVENT NO 60

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: FARLEY 1 PLANT TYPE: WEST PWR
 EVENT DATE: 11/21/1978 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

COMPONENT COOLING WATER
 SUBSYSTEM OCCURRENCE

COMPONENT COOLING WATER
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

COMPONENT COOLING WATER
 TOTAL SYSTEM OCCURRENCE

MULTIPLE SAFETY SYSTEMS
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: REVIEW OF PROCEDURE/TEST RESULTS
 INITIATING EVENT: RUPTURE OF COMPONENT COOLING WATER AT CHARGING
 PUMP 1B
 PROPAGATION: BOTH COMPONENT COOLING WATER TRAINS WOULD LOSE
 INVENTORY
 DEPENDENCY: BOTH CCW TRAINS WERE CONNECTED TO SAME CHARGING
 PUMP
 UNDESIRABLE RESULT: LOSS OF BOTH CCW TRAINS WOULD FAIL MULTIPLE SAFETY
 SYSTEMS
 REMARKS: PROCEDURE DID NOT SPECIFY THAT ONLY ONE TRAIN
 SHOULD SUPPORT A PUMP AT ONE TIME
 CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 13
 REFERENCES: L0037 EVENT NO 61

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: FARLEY 1 PLANT TYPE: WEST PWR
 EVENT DATE: 6/22/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MAIN STEAM
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

STEAM GENERATOR (PWR)
 PIPES/FITTINGS

REACTOR PROTECTION
 I&C/SENSORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR PROTECTION
 SUBSYSTEM OCCURRENCE

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: HIGH ENERGY LINE BREAK IN CONTAINMENT RESULTING IN
 HIGH AMBIENT TEMP

PROPAGATION: HEATUP OF REF LEG, SG LEVEL INSTR FAILS HIGH,
 DELAYS RPS TRIP ON SG LO LO LEVEL

DEPENDENCY: STEAM GENERATOR LEVEL REFERENCE LEG SUBJECTED TO
 HIGH AMBIENT TEMP

UNDESIRABLE RESULT: ACCIDENT DEGRADES SYSTEM REQUIRED TO MITIGATE
 ACCIDENT

REMARKS: ALSO PROVIDES HIGH LEVEL INDICATION TO
 OPERATOR-GENERIC W PROBLEM

CORRECTIVE ACTION: OTHER

CATEGORY: 8

REFERENCES: L0077

EVENT NO 62

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: FARLEY 1 PLANT TYPE: WEST PWR
 EVENT DATE: 6/13/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

PRESSURIZER (PWR)
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CVCS/HIGH PRESSURE SAFETY INJECTION
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: SECONDARY SYS HELB CAUSING SI ACTUATION AND PORV
 CONTROL FAILURE

PROPAGATION: RCS PRESSURE HIGHER THAN CHG PUMP DESIGN INJ
 PRESS;PUMPS OVERHEAT

DEPENDENCY: RECIRC VALVES PROTECT CHG PUMPS, BUT SIAS CLOSES
 RECIRC VALVES

UNDESIRABLE RESULT: LOSS OF MULTIPLE CHG PUMPS PRIOR TO SI SHUTOFF
 CONDITIONS MET

REMARKS: GENERIC W PROBLEM. PUMP FAILURES DEPENDS ON
 SPECIFIC DESIGN HEAD

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 7

REFERENCES: L0055 I-017 EVENT NO 63

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: FARLEY 1 PLANT TYPE: WEST PWR
 EVENT DATE: 11/12/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

ESSENTIAL RAW COOLING/ SERVICE WATER
 UNSPECIFIED COMPONENT

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

ESSENTIAL RAW COOLING/ SERVICE WATER
 SUBSYSTEM OCCURRENCE

ESSENTIAL RAW COOLING/ SERVICE WATER
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

ESSENTIAL RAW COOLING/ SERVICE WATER
 TOTAL SYSTEM OCCURRENCE

MULTIPLE SAFETY SYSTEMS
 UNSPECIFIED COMPONENT

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: MAINTENANCE/MODIFICATION

INITIATING EVENT: ANY FAILURE CAUSING LOSS OF 1 TRAIN OF SERVICE
 WATER

PROPAGATION: ONE TRAIN OF SW FAILS AND REDUNDANT TRAIN PUMPS
 OVERHEAT AND FAIL

DEPENDENCY: TRAIN A SERVICE WATER COOLS TRAIN B PUMPS & LUBE
 OIL COOLERS-AND VICE VERSA

UNDESIRABLE RESULT: POTENTIAL TOTAL LOSS OF SERVICE WATER & LOSS OF
 SAFETY-RELATED EQUIPMENT SERVED

REMARKS: IDENTICAL DESIGN PROBLEM ON UNIT 2 - LER
 364/80-001

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 13

REFERENCES: L1038

EVENT NO 64

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: FARLEY 1 PLANT TYPE: WEST PWR
 EVENT DATE: 12/09/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MISCELLANEOUS/ UNKNOWN STRUCTURES
 STRUCTURAL FUNCTION ITEMS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

MISCELLANEOUS/ UNKNOWN STRUCTURES
 STRUCTURAL FUNCTION ITEMS

MULTIPLE SAFETY SYSTEMS
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

MULTIPLE SAFETY SYSTEMS
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: MISCELLANEOUS/ UNKNOWN STRUCTURES

RESULT TYPE: 1,4 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: SEISMIC EVENT

PROPAGATION: SAFETY RELATED PIPING, CONDUIT OR EQMT ATTACHED TO
 38 INADEQUATELY BUILT WALLS

DEPENDENCY: CONSTRUCTION INADEQUACIES ALLOWED DEVIATION FROM
 APPROVED DESIGNS

UNDESIRABLE RESULT: DAMAGE TO MULTIPLE SAFETY SYSTEMS DUE TO
 EARTHQUAKE

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 21

REFERENCES: L0172 EVENT NO 65

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: FARLEY 1 PLANT TYPE: WEST PWR
 EVENT DATE: 5/22/1981 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

NON-NUCLEAR INSTRUMENTATION
 I&C/TRANSMITTERS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CVCS/HIGH PRESSURE SAFETY INJECTION
 ACCUMULATORS/RESERVOIRS

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CVCS/HIGH PRESSURE SAFETY INJECTION
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: VCT LEVEL TRANSMITTER FAILS HIGH STOPPING LETDOWN
 FLOW

PROPAGATION: NO LETDOWN, VCT LOW LEVEL, NO SWITCH TO RWST, LOSS
 OF SUCTION DAMAGES CHG PUMPS

DEPENDENCY: LEVEL TRANSMITTER CONTROLS LEVEL AND SUCTION
 SWITCHOVER TO RWST

UNDESIRABLE RESULT: REDUNDANT CHG PUMPS DAMAGED. THESE PUMPS ARE ALSO
 HI HEAD SAFETY INJECTION

REMARKS: WESTINGHOUSE NOTIFICATION OF POTENTIAL FAULIRE

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 5

REFERENCES: L0120 A0020 A0021 EVENT NO 66

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: PARLEY 2 PLANT TYPE: WEST PWR
 EVENT DATE: 11/12/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

ESSENTIAL RAW COOLING/ SERVICE WATER
 UNSPECIFIED COMPONENT

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

ESSENTIAL RAW COOLING/ SERVICE WATER
 SUBSYSTEM OCCURRENCE

ESSENTIAL RAW COOLING/ SERVICE WATER
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

ESSENTIAL RAW COOLING/ SERVICE WATER
 TOTAL SYSTEM OCCURRENCE

MULTIPLE SAFETY SYSTEMS
 UNSPECIFIED COMPONENT

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: MAINTENANCE/MODIFICATION

INITIATING EVENT: ANY FAILURE CAUSING LOSS OF 1 TRAIN OF SERVICE
 WATER

PROPAGATION: ONE TRAIN OF SW FAILS AND REDUNDANT TRAIN PUMPS
 OVERHEAT AND FAIL

DEPENDENCY: TRAIN A SERVICE WATER COOLS TRAIN B PUMPS & LUBE
 OIL COOLERS-AND VICE VERSA

UNDESIRABLE RESULT: POTENTIAL TOTAL LOSS OF SERVICE WATER & LOSS OF
 SAFETY-RELATED EQUIPMENT SERVED

REMARKS: IDENTICAL DESIGN PROBLEM ON UNIT 1

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 13

REFERENCES: L1044 EVENT NO 67

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: PARLEY 2 PLANT TYPE: WEST PWR
 EVENT DATE: 12/09/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MISCELLANEOUS/ UNKNOWN STRUCTURES
 STRUCTURAL FUNCTION ITEMS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

MISCELLANEOUS/ UNKNOWN STRUCTURES
 STRUCTURAL FUNCTION ITEMS

MULTIPLE SAFETY SYSTEMS
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

MULTIPLE SAFETY SYSTEMS
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: MISCELLANEOUS/ UNKNOWN STRUCTURE:

RESULT TYPE: 1,4 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: SEISMIC EVENT

PROPAGATION: SAFETY RELATED PIPING, CONDUIT OR EQMT ATTACHED TO
 27 INADEQUATELY BUILT WALLS

DEPENDENCY: CONSTRUCTION INADEQUACIES ALLOWED DEVIATION FROM
 APPROVED DESIGNS

UNDESIRABLE RESULT: DAMAGE TO MULTIPLE SAFETY SYSTEMS DUE TO
 EARTHQUAKE

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 21

REFERENCES: L0171 EVENT NO 68

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: PERMI 2 PLANT TYPE: GE BWR
 EVENT DATE: 3/10/1982 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

REACTOR BUILDING HVAC (BWR)
 MECHANICAL FUNCTION ITEMS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

REACTOR BUILDING HVAC (BWR)
 MECHANICAL FUNCTION ITEMS

MULTIPLE SAFETY SYSTEMS
 UNSPECIFIED COMPONENT

SAFETY SYSTEMS/COMPONENTS AFFECTED

MULTIPLE SAFETY SYSTEMS
 UNSPECIFIED COMPONENT

TYPE OF COUPLING: SPATIAL PLANT AREA: SECONDARY CONTAINMENT (BWR)

RESULT TYPE: 2 DISCOVERY: UNKNOWN

INITIATING EVENT: SEISMIC EVENT 4

PROPAGATION: NON-SEISMIC HVAC DUCT FALLS ON SAFETY-RELATED
 EQUIPMENT DURING SEISMIC EVENT

DEPENDENCY: NON-SEISMIC HVAC DUCT ERECTED OVER SAFETY-RELATED
 EQUIPMENT

UNDESIRABLE RESULT: LOSS OF SAFETY-RELATED EQUIPMENT

REMARKS: AFFECTS EQUIPMENT IN REACTOR AND AUXILIARY
 BUILDINGS. NOTED DURING CONSTRUCTION

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 21

REFERENCES: C21 EVENT NO 69

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: FT. CALHOUN 1 PLANT TYPE: CE PWR
 EVENT DATE: 5/19/1982 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

AUXILIARY FEEDWATER (PWR)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

AUXILIARY FEEDWATER (PWR)
 PUMPS

AUXILIARY FEEDWATER (PWR)
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

AUXILIARY FEEDWATER (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: REACTOR AUXILIARY BUILDING

RESULT TYPE: 1 DISCOVERY: SPECIAL TEST/INSPECTION

INITIATING EVENT: LOSS PLUS A BREAK IN THE STEAM SUPPLY LINE TO
 TURBINE-DRIVEN APW PUMP

PROPAGATION: STEAM WOULD CAUSE FAILURE OF REDUNDANT ELECTRIC
 APW PUMP

DEPENDENCY: TURBINE-DRIVEN AND MOTOR-DRIVEN APW PUMPS LOCATED
 IN SAME AREA

UNDESIRABLE RESULT: LOSS OF AUX FEEDWATER DURING LOSS OF OFFSITE POWER

REMARKS: FOUND DURING REVIEW OF INPO SOER 81-17

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY:23

REFERENCES: L0029 EVENT NO 70

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: FT. ST. VRAIN PLANT TYPE: GA HTGR
 EVENT DATE: 5/17/1983 EXPERIENCE: ACTUAL
 OPERATING STATUS: COLD SHUTDOWN

INITIATING SYSTEM AND COMPONENT

HIGH VOLTAGE AC (GREATER THAN 35KV)
 TOTAL SYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

HIGH VOLTAGE AC (GREATER THAN 35KV)
 TOTAL SYSTEM OCCURRENCE

EMERGENCY POWER GENERATION
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 2,4 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: LOSP WITH ONE DG OUT OF SERVICE AND ONE RUNNING
 TIED TO BUS

PROPAGATION: LOSP OVERLOAD RUNNING DG DUE TO ALL PLANT LOADS
 SHIFTING TO THAT DG

DEPENDENCY: DG PARALLELED WITH OFFSITE POWER AND CONNECTED TO
 ALL PLANT LOADS

UNDESIRABLE RESULT: OVERLOAD OF RUNNING DG, TRIPS OFF, LEAVING PLANT
 WITH NO AC POWER

REMARKS: RECOMMENDED RUN DG UNLOADED OR ONLY CONNECTED TO
 EMERGENCY LOADS

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 1

REFERENCES: L0148 A0022 EVENT NO 71

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: GINNA PLANT TYPE: WEST PWR
 EVENT DATE: 4/22/1971 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

VITAL INSTRUMENT, CONTROL, AND COMPUTER AC
 TOTAL SYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

VITAL INSTRUMENT, CONTROL, AND COMPUTER AC
 TOTAL SYSTEM OCCURRENCE

CVCS/HIGH PRESSURE SAFETY INJECTION
 I&C/INDICATORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CVCS/HIGH PRESSURE SAFETY INJECTION
 I&C/INDICATORS

INTERMEDIATE PRESSURE INJECTION (PWR)
 VALVES

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 4 DISCOVERY: SPECIAL TEST/INSPECTION

INITIATING EVENT: VOLTAGE LOST ON ALL 480 V SAFEGUARD BUSES DURING
 STATION BLACKOUT TESTING

PROPAGATION: NO POWER TO INSTRUMENT BUS THEREFORE ALL BAST
 LEVEL CHANNELS INOPERABLE

DEPENDENCY: INTERLOCK PREVENTED 4 VALVES IN SI SUCTION TO BAST
 FROM OPENING

UNDESIRABLE RESULT: LOSS OF ALL 480 V BUSES AND LOSS OF SI PUMP
 SUCTION

REMARKS: POWER SUPPLY FOR LEVEL CHANNELS CHANGED TO BATTERY
 SUPPLY (UPS)

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 14

REFERENCES: E0005 L2014 EVENT NO 72

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: GINNA PLANT TYPE: WEST PWR
 EVENT DATE: 10/21/1973 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

HIGH VOLTAGE AC (GREATER THAN 35KV)
 ELECTRICAL CONDUCTORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

VITAL INSTRUMENT, CONTROL, AND COMPUTER AC
 ELECTRICAL CONDUCTORS

CVCS/HIGH PRESSURE SAFETY INJECTION
 ELECTRICAL/I&C FUNCTION ITEMS

SAFETY SYSTEMS/COMPONENTS AFFECTED

VITAL INSTRUMENT, CONTROL, AND COMPUTER AC
 ELECTRICAL CONDUCTORS

PRIMARY COOLANT (PWR)
 PIPES/FITTINGS

INTERMEDIATE PRESSURE INJECTION (PWR)
 PUMPS

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 4 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: POWER LOST ON INSTRUMENT BUS (SUPPOSEDLY UPS)
 DURING LOSP

PROPAGATION: BUS FAILURE CAUSED LOSS OF BORIC ACID STORAGE TANK
 LEVEL INDICATION

DEPENDENCY: BAST LEVEL CONTROLS SI PUMP SUCTION SWITCH TO
 RWST, TRANSFERRED EARLY

UNDESIRABLE RESULT: PREMATURE TRANSFER OF SUCTION DUE TO POWER LOSS

REMARKS: REASON POWER LOST IS UNKNOWN. MAYBE RELATED TO
 LOSP

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 14

REFERENCES: L2011 L2012 L2013 E0005 EVENT NO 73

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: GINNA PLANT TYPE: WEST PWR
 EVENT DATE: 11/14/1981 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

FIRE PROTECTION
 TOTAL SYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

FIRE PROTECTION
 TOTAL SYSTEM OCCURRENCE

CONTROL ROD DRIVE (PWR)
 CIRCUIT BREAKER/FUSES

SAFETY SYSTEMS/COMPONENTS AFFECTED

CONTROL ROD DRIVE (PWR)
 CIRCUIT BREAKER/FUSES

REACTOR PROTECTION
 GENERATORS

TYPE OF COUPLING: SPATIAL PLANT AREA: MISCELLANEOUS/ UNKNOWN STRUCTURE:

RESULT TYPE: 2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: INADVERTENT ACTUATION OF FIRE SPRINKLER SYSTEM

PROPAGATION: WATER REACHED RPS MG SET SWITCHGEAR AND CRD POWER SUPPLY

DEPENDENCY: SPRINKLER SYSTEM CAN WET SAFETY-RELATED COMPONENTS

UNDESIRABLE RESULT: DEGRADATION OF SAFETY SYSTEMS

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 3

REFERENCES: I-151 L0063 A0024 EVENT NO 74

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: GRAND GULF 1 PLANT TYPE: GE BWR
 EVENT DATE: 7/14/1982 EXPERIENCE: ACTUAL
 OPERATING STATUS: CONSTRUCTION

INITIATING SYSTEM AND COMPONENT

FIRE PROTECTION
 SUBSYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

REACTOR AUXILIARY BUILDING
 STRUCTURAL FUNCTION ITEMS

FIRE PROTECTION
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR AUXILIARY BUILDING
 PENETRATIONS

TYPE OF COUPLING: SPATIAL PLANT AREA: REACTOR AUXILIARY BUILDING

RESULT TYPE: 2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: INADVERTENT REPEATED ACTUATION OF ECCS PENETRATION
 ROOM CO2 SYSTEM

PROPAGATION: BUILDUP OF CO2 PRESSURE BLEW OFF LOCKED DOOR TO
 AUX BUILDING

DEPENDENCY: DESIGN OF ECCS ROOM INADEQUATE TO VENT EXCESS CO2
 PRESSURE

UNDESIRABLE RESULT: DAMAGE TO SAFETY-RELATED STRUCTURE BY FIRE
 PROTECTION ACTUATION

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 3

REFERENCES: I-151 L0128 EVENT NO 75

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: GRAND GULF 1 PLANT TYPE: GE BWR
 EVENT DATE: 8/04/1983 EXPERIENCE: ACTUAL
 OPERATING STATUS: COLD SHUTDOWN

INITIATING SYSTEM AND COMPONENT

VITAL INSTRUMENT, CONTROL, AND COMPUTER AC
 ELECTRICAL CONDUCTORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

VITAL INSTRUMENT, CONTROL, AND COMPUTER AC
 ELECTRICAL CONDUCTORS

DC POWER
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

RESIDUAL HEAT REMOVAL (BWR)
 PUMPS

LOW VOLTAGE AC (LESS THAN 600V)
 CIRCUIT BREAKER/FUSES

PLANT MONITORING
 I&C/INDICATORS

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,2 DISCOVERY: ROUTINE TEST/INSPECTION

INITIATING EVENT: COMPUTER CABLE IMPROPERLY CONNECTED (INSTAL.
 ERROR) 120VAC TO DIV 1 125VDC BUS

PROPAGATION: RHR PUMP FAILED TO START; SW BKR TRIPPED; ERRON
 TRIP INDIC FOR DIV1 BUSES

DEPENDENCY: MISCONNECTION OF CABLE PROVIDED CONNECTION BETWEEN
 120VAC POWER AND 125VDC

UNDESIRABLE RESULT: DAMAGE & FAILURE OF NUMEROUS INSTS-POTENTIAL
 UNDESIRED EQUIP & HUMAN ACTIONS

REMARKS: INCORRECT ALARMS ON CR PANELS FOR DIV 1 BUSES
 COULD MISLEAD OPERATOR

CORRECTIVE ACTION: REPAIR/REPLACEMENT

CATEGORY:22

REFERENCES: L1032

EVENT NO 76

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: HATCH 1 PLANT TYPE: GE BWR
 EVENT DATE: 3/30/1978 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

DC POWER
 BATTERIES/CHARGERS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

DC POWER
 BATTERIES/CHARGERS

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: DESIGN CALCULATION/VERIFICATION
 INITIATING EVENT: LOCA AND LOSP WITH FAILURE OF DG A OR C BATTERY
 PROPAGATION: BATTERY LOSS CAUSES LOSS OF DC POWER REQD TO TRIP
 NON-ESP LOADS OFF DG B BUSES
 DEPENDENCY: BTY LOSS FAILS DG FOR ITS TRAIN (A OR C) AND
 CAUSES OVERLOAD OF DG B
 UNDESIRABLE RESULT: LOCA AND LOSP WITH SINGLE BTY FAILURE CAUSES LOSS
 OF TWO EDG
 REMARKS: MOD WILL TRIP BKRS ON LOSS OF DC POWER. SAME
 DESIGN ERROR APPLIES TO UNIT 2.
 CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 1
 REFERENCES: L0097 EVENT NO 77

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: HATCH 1 PLANT TYPE: GE BWR
 EVENT DATE: 9/10/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

RECIRCULATING WATER (BWR)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

DRYWELL/ TORUS HVAC AND PURGE (BWR)
 MECHANICAL FUNCTION ITEMS

REACTOR DRYWELL (BWR)
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

CONTAINMENT ISCLATION
 TOTAL SYSTEM OCCURRENCE

REACTOR DRYWELL (BWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: LOCA OCCURRING DURING DRYWELL PURGE OPERATIONS

PROPAGATION: PRESSURE SURGE CAUSES PURGE VALVES TO OVERTRAVEL
 AND LOSS OF SEATING CAPABILITY

DEPENDENCY: PURGE VALVES INADEQUATE FOR LOCA CONDITIONS

UNDESIRABLE RESULT: LOSS OF CAPABILITY OF PURGE VALVES TO ISOLATE
 CONTAINMENT IN CASE OF LOCA

CORRECTIVE ACTION: OTHER

CATEGORY: 9

REFERENCES: L0045

EVENT NO 78

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: HATCH 1 PLANT TYPE: GE BWR
 EVENT DATE: 1/29/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

VITAL INSTRUMENT, CONTROL, AND COMPUTER AC
 SUBSYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

VITAL INSTRUMENT, CONTROL, AND COMPUTER AC
 SUBSYSTEM OCCURRENCE

EMERGENCY GENERATOR COOLING
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 GENERATORS

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,2 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: LOCA/LOSP ON ONE UNIT CAUSES TRANSFER OF SUPPLY
 BKR POWER TO OPPOSITE UNIT

PROPAGATION: SUPPLY BREAKERS WILL NOT TRANSFER - NO AC POWER
 AVAILABLE

DEPENDENCY: BREAKERS DESIGNED FOR AC CONTROL POWER, BUT NO AC
 AVAILABLE ON LOSP

UNDESIRABLE RESULT: POWER LOST TO STANDBY SERVICE WATER FOR DG,
 CAUSING DG TO BE INOPERABLE

REMARKS: FOUND DURING IEB79-27 INVESTIGATION. DESIGN
 CHANGE MADE TO DC CONTROL POWER

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 1

REFERENCES: L0175 I-036 EVENT NO 79

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: HATCH 1 PLANT TYPE: GE BWR
 EVENT DATE: 5/24/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

RECIRCULATING WATER (BWR)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

RESIDUAL HEAT REMOVAL (BWR)
 TOTAL SYSTEM OCCURRENCE

LOW PRESSURE CORE SPRAY (BWR)
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

RESIDUAL HEAT REMOVAL (BWR)
 TOTAL SYSTEM OCCURRENCE

LOW PRESSURE CORE SPRAY (BWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: RECIRC LINE BREAK PLUS MCC FAILURE WHEN OPERATING
 WITH LEAKY RHR ISOL VALVE

PROPAGATION: LEAKY VALVE WILL ALLOW RHR HX TO PRESSURIZE

DEPENDENCY: EVENT DISABLES 2 RHR TRAINS AND 1 TRAIN OF CORE
 SPRAY DUE TO LEAKY VALVE

UNDESIRABLE RESULT: DBA WOULD RESULT IN FAILURE OF REDUNDANT EQUIPMENT
 REQUIRED TO RESPOND

REMARKS: OPERATION WITH LEAKY VALVE VIOLATED THE SINGLE
 FAILURE CRITERIA

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 13

REFERENCES: L0020

EVENT NO 80

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: HATCH 1 PLANT TYPE: GE BWR
 EVENT DATE: 7/11/1980 EXPERIENCE: ACTUAL
 OPERATING STATUS: ROUTINE STARTUP

INITIATING SYSTEM AND COMPONENT

REACTOR BUILDING HVAC (BWR)
 HEAT EXCHANGERS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

REACTOR BUILDING HVAC (BWR)
 HEAT EXCHANGERS

VITAL INSTRUMENT, CONTROL, AND COMPUTER AC
 GENERATORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

VITAL INSTRUMENT, CONTROL, AND COMPUTER AC
 GENERATORS

LOW PRESSURE COOLANT INJECTION (BWR)
 VALVE OPERATORS

TYPE OF COUPLING: SPATIAL PLANT AREA: SECONDARY CONTAINMENT (BWR)

RESULT TYPE: 0 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: COOLING WATER TO LPCI INVERTER ROOM COOLER
 ISOLATED-RESULT HIGH AMBIENT TEMP

PROPAGATION: HIGH AMBIENT TEMP TRIPS TRAIN B LPCI INVERTER
 CAUSING FAILURE OF TRAIN B VALVES

DEPENDENCY: LPCI INVERTERS ARE IN SAME ROOM AND COOLED BY SAME
 HVAC SYSTEM

UNDESIRABLE RESULT: POTENTIAL FAILURE OF LPCI/RHR FUNCTION

REMARKS: LER SAYS UNIT 1 AND 2 INVERTERS ARE IN THE SAME
 ROOM.

CORRECTIVE ACTION: OTHER CATEGORY: 13

REFERENCES: L1017 EVENT NO 81

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: HATCH 1 PLANT TYPE: GE BWR
 EVENT DATE: 11/05/1981 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MAIN STEAM
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

SECONDARY CONTAINMENT (BWR)
 TOTAL SYSTEM OCCURRENCE

LEAK MONITORING
 I&C/SWITCHES

SAFETY SYSTEMS/COMPONENTS AFFECTED

HIGH PRESSURE COOLANT INJECTION (BWR)
 TOTAL SYSTEM OCCURRENCE

REACTOR CORE ISOLATION COOLING (BWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: SECONDARY CONTAINMENT (BWR)

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: MSL OR SCRAM DISCHARGE BREAK IN PIPE CHASE & STEAM
 IS VENTED INTO TORUS ROOM

PROPAGATION: LEAK DETECT SYS SENSES HIGH ROOM TEMP-GIVES
 ISOLATION SIGNAL TO HPCI & RCIC

DEPENDENCY: TORUS ROOM & PIPE CHASE ARE CONNECTED FOR VENTING
 OF PIPE CHASE

UNDESIRABLE RESULT: ERRONEOUS ISOLATION OF HPCI & RCIC ON MAIN STEAM
 LINE OR SCRAM DISCHARGE BREAK

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY:23

REFERENCES: L1034

EVENT NO 82

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: HATCH 2 PLANT TYPE: GE BWR
 EVENT DATE: 3/30/1978 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

DC POWER
 BATTERIES/CHARGERS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

DC POWER
 BATTERIES/CHARGERS

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: DESIGN CALCULATION/VERIFICATION
 INITIATING EVENT: LOCA AND LOSP WITH FAILURE OF DG A OR DG C BATTERY
 PROPAGATION: BATTERY LOSS CAUSES LOSS OF DC POWER REQD TO TRIP
 NON-ESF LOADS OFF DG B BUSES
 DEPENDENCY: BTY LOSS FAILS DG FOR ITS TRAIN (A OR C) AND
 CAUSES OVERLOAD OF DG B
 UNDESIRABLE RESULT: LOCA AND LOSP WITH SINGLE BTY FAILURE CAUSES LOSS
 OF TWO EDG
 REMARKS: MOD WILL TRIP BKRS ON LOSS OF DC POWER. SAME
 DESIGN ERROR APPLIES TO UNIT 1.
 CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 1
 REFERENCES: L0097 EVENT NO 83

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: HATCH 2 PLANT TYPE: GE BWR
 EVENT DATE: 1/28/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

CONTAINMENT ISOLATION
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

TORUS/ SUPPRESSION POOL (BWR)
 STRUCTURAL FUNCTION ITEMS

MULTIPLE ECCS SYSTEMS
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

TORUS/ SUPPRESSION POOL (BWR)
 STRUCTURAL FUNCTION ITEMS

MULTIPLE ECCS SYSTEMS
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: LOCA PLUS TORUS GRAVITY FILL ISOLATION VALVE
 FAILURE

PROPAGATION: FLOW PATH EXISTS TO ALLOW TORUS WATER VIA CORE
 SPRAY SUCTION PIPING TO CST

DEPENDENCY: INVENTORY LOSS DURING A LOCA COULD AFFECT MULTIPLE
 COOLING SYSTEMS

UNDESIRABLE RESULT: SINGLE FAILURE HAS POTENTIAL TO DEGRADE MULTIPLE
 SAFETY SYSTEMS DURING LOCA

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY:22

REFERENCES: L0041

EVENT NO 84

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: HATCH 2 PLANT TYPE: GE BWR
 EVENT DATE: 8/25/1982 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

CONTROL ROD DRIVE (BWR)
 VESSELS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

EQUIPMENT DRAINAGE (INCLUDING VENTS)
 TOTAL SYSTEM OCCURRENCE

REACTOR CORE ISOLATION COOLING (BWR)
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR CORE ISOLATION COOLING (BWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: SECONDARY CONTAINMENT (BWR)

RESULT TYPE: 2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: SCRAM DISCHARGE VOLUME VALVE LEAKED

PROPAGATION: COOLANT RELEASED TO RCIC ROOM AND TO OPEN AREAS OF
 REACTOR BUILDING

DEPENDENCY: FLOOR DRAINAGE SYSTEM DID NOT STOP STEAM FLOW

UNDESIRABLE RESULT: LOSS OF RCIC AND AMBIENT TEMP ABOVE LIMITS FOR
 ELEC EQUIP LOCATED NEAR RCIC

REMARKS: FIRE PROTECTION ACTUATED IN RCIC ROOM

CORRECTIVE ACTION: OTHER CATEGORY: 4

REFERENCES: A0001 EVENT NO 85

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: HATCH 2 PLANT TYPE: GE BWR
EVENT DATE: 8/25/1982 EXPERIENCE: ACTUAL
OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

LOW VOLTAGE AC (LESS THAN 600V)
MISCELLANEOUS EQUIPMENT

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

LOW VOLTAGE AC (LESS THAN 600V)
MISCELLANEOUS EQUIPMENT

REACTOR DRYWELL (BWR)
I&C/SENSORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR DRYWELL (BWR)
I&C/SENSORS

TYPE OF COUPLING: SPATIAL PLANT AREA: UNKNOWN

RESULT TYPE: 4 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: LOAD SHEDDING OF DRYWELL CHILLERS ON HIGH DRYWELL
PRESSURE

PROPAGATION: INABILITY TO USE CHILLERS TO REDUCE PRESSURE IN
DRYWELL

DEPENDENCY: SHEDDING OF CHILLER LOADS PREVENTED CLEARING HIGH
DRYWELL PRESS SCRAM SIGNAL

UNDESIRABLE RESULT: SCRAM SIGNAL PREVENTED ISOLATION OF SDV LEAK.
ALLOWED UNCONTROLLED SDV LEAK.

CORRECTIVE ACTION: OTHER

CATEGORY: 23

REFERENCES: A0001

EVENT NO 86

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: HATCH 2 PLANT TYPE: GE BWR
 EVENT DATE: 2/03/1984 EXPERIENCE: ACTUAL
 OPERATING STATUS: UNKNOWN

INITIATING SYSTEM AND COMPONENT

CONTAINMENT COMBUSTIBLE GAS CONTROL
 HEAT EXCHANGERS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

TORUS/ SUPPRESSION POOL (BWR)
 PIPES/FITTINGS

CONTAINMENT COMBUSTIBLE GAS CONTROL
 PIPES/FITTINGS

SAFETY SYSTEMS/COMPONENTS AFFECTED

TORUS/ SUPPRESSION POOL (BWR)
 PIPES/FITTINGS

CONTAINMENT COMBUSTIBLE GAS CONTROL
 PIPES/FITTINGS

TYPE OF COUPLING: SPATIAL PLANT AREA: TORUS/ SUPPRESSION POOL (BWR)

RESULT TYPE: 1,2 DISCOVERY: ROUTINE TEST/INSPECTION

INITIATING EVENT: FAILURE OF N2 VAPORIZER IN TORUS/DRYWELL INERTING
 SYSTEM

PROPAGATION: COLD LIQUID N2 ENTERED PURGE LINE AND IMPINGED ON
 TORUS VENT HEADER

DEPENDENCY: PURGE LINE OUTLET LOCATED DIRECTLY ABOVE TORUS
 VENT HEADER

UNDESIRABLE RESULT: VENT HEADER DAMAGED (CRACKED) BY DRYWELL INERTING
 SYSTEM

REMARKS: CRACKING DUE TO COOLING HEADER BELOW NDT POINT

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 23

REFERENCES: I-297 I-296 EVENT NO 87

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: INDIAN POINT 2 PLANT TYPE: WEST PWR
EVENT DATE: 10/19/1977 EXPERIENCE: POTENTIAL
OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

LOW VOLTAGE AC (LESS THAN 600V)
ELECTRICAL CONDUCTORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CONTAINMENT ISOLATION
VALVES

CONTAINMENT ISOLATION
VALVES

SAFETY SYSTEMS/COMPONENTS AFFECTED

CONTAINMENT ISOLATION
VALVES

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: SHORT CIRCUIT OR FOREIGN VOLTAGE TO AIR EJECTOR
 DIVERSION LINE CNMT ISOL VALVE

PROPAGATION: BOTH CONTAINMENT ISOLATION VALVES FAIL TO CLOSE

DEPENDENCY: BOTH VALVES SUPPLIED BY SINGLE POWER CIRCUIT

UNDESIRABLE RESULT: LOSS OF CONTAINMENT ISOLATION FUNCTION FOR THIS
 LINE

CORRECTIVE ACTION: OTHER

CATEGORY:13

REFERENCES: L0012

EVENT NO 88

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: INDIAN POINT 2 PLANT TYPE: WEST PWR
 EVENT DATE: 6/26/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MAIN STEAM
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

STEAM GENERATOR (PWR)
 PIPES/FITTINGS

REACTOR PROTECTION
 I&C/SENSORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR PROTECTION
 SUBSYSTEM OCCURRENCE

AUXILIARY FEEDWATER (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: HIGH ENERGY LINE BREAK IN CONTAINMENT RESULTING IN
 HIGH AMBIENT TEMP

PROPAGATION: HEATUP OF REF LEG, SG LEVEL INSTR FAILS HIGH,
 DELAYS RPS TRIP ON SG LO LO LEVEL

DEPENDENCY: STEAM GENERATOR LEVEL REFERENCE LEG SUBJECTED TO
 HIGH AMBIENT TEMP

UNDESIRABLE RESULT: ACCIDENT DEGRADES SYSTEM REQUIRED TO MITIGATE
 ACCIDENT

REMARKS: ALSO PROVIDES HIGH LEVEL INDICATION TO
 OPERATOR-GENERIC W PROBLEM

CORRECTIVE ACTION: OTHER

CATEGORY: 8

REFERENCES: L0085

EVENT NO 89

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: INDIAN POINT 2 PLANT TYPE: WEST PWR
 EVENT DATE: 10/17/1980 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

ESSENTIAL RAW COOLING/ SERVICE WATER
 HEAT EXCHANGERS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

PRIMARY CONTAINMENT (PWR)
 STRUCTURAL FUNCTION ITEMS

EQUIPMENT DRAINAGE (INCLUDING VENTS)
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

PRIMARY CONTAINMENT (PWR)
 STRUCTURAL FUNCTION ITEMS

REACTOR VESSEL
 VESSELS

TYPE OF COUPLING: SPATIAL PLANT AREA: UNKNOWN

RESULT TYPE: 2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: SERVICE WATER LEAKS FROM CONTAINMENT FAN COOLERS
 AND PIPES

PROPAGATION: INOPERATIVE CONTAINMENT SUMP PUMPS, NO HIGH WATER
 ALARMS

DEPENDENCY: IN-CONTAINMENT LEAKAGE UNDETECTED-SUBMERGE LOWER
 PART OF VESSEL

UNDESIRABLE RESULT: FLOOD WETTED LOWER 9 FEET OF REACTOR VESSEL WHILE
 AT OPERATING TEMPERATURE

REMARKS: POSSIBLE THERMAL SHOCK TO RX VESSEL

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY:23

REFERENCES: I-012 I-242 EVENT NO 90

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: INDIAN POINT 3 PLANT TYPE: WEST PWR
 EVENT DATE: 6/21/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MAIN STEAM
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

STEAM GENERATOR (PWR)
 PIPES/FITTINGS

REACTOR PROTECTION
 I&C/SENSORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR PROTECTION
 SUBSYSTEM OCCURRENCE

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: HIGH ENERGY LINE BREAK IN CONTAINMENT RESULTING IN
 HIGH AMBIENT TEMP

PROPAGATION: HEATUP OF REF LEG, SG LEVEL INSTR FAILS HIGH,
 DELAYS RPS TRIP ON SG LO LO LEVEL

DEPENDENCY: STEAM GENERATOR LEVEL REFERENCE LEG SUBJECTED TO
 HIGH AMBIENT TEMP

UNDESIRABLE RESULT: ACCIDENT DEGRADES SYSTEM REQUIRED TO MITIGATE
 ACCIDENT

REMARKS: ALSO PROVIDES HIGH LEVEL INDICATION TO
 OPERATOR-GENERIC W PROBLEM

CORRECTIVE ACTION: OTHER

CATEGORY: 8

REFERENCES: L0084

EVENT NO 91

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: KEWAUNEE PLANT TYPE: WEST PWR
 EVENT DATE: 11/05/1975 EXPERIENCE: ACTUAL
 OPERATING STATUS: ROUTINE STARTUP

INITIATING SYSTEM AND COMPONENT

DEMINERALIZED WATER
 CHEMICAL FUNCTION ITEMS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

DEMINERALIZED WATER
 CHEMICAL FUNCTION ITEMS

CONDENSATE STORAGE
 ACCUMULATORS/RESERVOIRS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CONDENSATE STORAGE
 ACCUMULATORS/RESERVOIRS

AUXILIARY FEEDWATER (PWR)
 FILTERS, NON-I&C

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: MAKE-UP WATER DEMINERALIZERS LEAK RESIN BEADS

PROPAGATION: RESINS ACCUMULATE IN CONDENSATE STORAGE
 TANKS-FILTERS ON APW PUMP SUCTION PLUG

DEPENDENCY: MAKE-UP SUPPLIES CS TANKS. CS TANKS ARE PREFERRED
 WATER SOURCE FOR APW PUMPS

UNDESIRABLE RESULT: LOSS OF APW (PUMP SUCTION FILTERS INSTALLED TO
 PREVENT DAMAGE FROM TRASH IN SW)

REMARKS: THERMAL DECOMP OF RESIN COULD HAVE AFFECTED FW
 VALVES OR OTHER COMPONENTS

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY:22

REFERENCES: L1040 M2001 EVENT NO 92

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: KEWAUNEE PLANT TYPE: WEST PWR
 EVENT DATE: 6/26/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MAIN STEAM
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

STEAM GENERATOR (PWR)
 PIPES/FITTINGS

REACTOR PROTECTION
 I&C/SENSORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR PROTECTION
 SUBSYSTEM OCCURRENCE

PLANT MONITORING
 I&C/INDICATORS

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: HIGH ENERGY LINE BREAK IN CONTAINMENT RESULTING IN
 HIGH AMBIENT TEMP

PROPAGATION: HEATS UP SG LEVEL REFERENCE CAUSING INACCURATE SG
 LEVEL SIGNALS (HIGH)

DEPENDENCY: STEAM GENERATOR LEVEL REFERENCE LEG SUBJECT TO
 HIGH AMBIENT TEMP

UNDESIRABLE RESULT: ACCIDENT DEGRADES SYSTEM RESPONSES REQUIRED TO
 MITIGATE ACCIDENT

REMARKS: GENERIC W PROBLEM. ALSO PROVIDES HIGH INDICATION
 TO OPERATOR

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 8

REFERENCES: L0081 EVENT NO 93

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: MAINE YANKEE PLANT TYPE: CE PWR
 EVENT DATE: 1/25/1983 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

CONDENSATE AND FEEDWATER
 TOTAL SYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

AUXILIARY FEEDWATER (PWR)
 TOTAL SYSTEM OCCURRENCE

CONDENSATE AND FEEDWATER
 PIPES/FITTINGS

SAFETY SYSTEMS/COMPONENTS AFFECTED

AUXILIARY FEEDWATER (PWR)
 TOTAL SYSTEM OCCURRENCE

CONDENSATE AND FEEDWATER
 PIPES/FITTINGS

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 4 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: REACTOR TRIP, LOSS OF MAIN FEEDWATER AND AUTO
 INITIATION OF APW SYSTEM

PROPAGATION: COLD APW CAUSED HIGH THERMAL STRESS AND CONDENSED
 STEAM IN FW LINES

DEPENDENCY: AUXILIARY FEEDWATER SYSTEM CAN PUMP COLD WATER TO
 SG

UNDESIRABLE RESULT: HIGH THERMAL STRESS AND WATER HAMMER DAMAGED APW
 PIPING

REMARKS: MODIFICATIONS TO MPW & APW DID NOT CONSIDER
 PREVIOUS GENERIC SAFETY CONCERNS

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 12

REFERENCES: M1009 EVENT NO 94

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: MCGUIRE 1 PLANT TYPE: WEST PWR
 EVENT DATE: 6/22/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MAIN STEAM
 PIPES/PITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

MAIN STEAM
 PIPES/PITTINGS

REACTOR PROTECTION
 I&C/SENSORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR PROTECTION
 SUBSYSTEM OCCURRENCE

AUXILIARY FEEDWATER (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: HIGH ENERGY LINE BREAK IN CONTAINMENT RESULTING IN
 HIGH AMBIENT TEMP

PROPAGATION: HEATS UP SG LEVEL REFERENCE CAUSING INACCURATE SG
 LEVEL SIGNALS (HIGH)

DEPENDENCY: STEAM GENERATOR LEVEL REFERENCE LEG SUBJECT TO
 HIGH AMBIENT TEMP

UNDESIRABLE RESULT: ACCIDENT DEGRADES SYSTEM RESPONSES REQUIRED TO
 MITIGATE ACCIDENT

REMARKS: GENERIC W PROBLEM. ALSO PROVIDES HIGH LEVEL
 INDICATION TO OPERATOR

CORRECTIVE ACTION: OTHER CATEGORY: 8

REFERENCES: L0073 EVENT NO 95

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: MCGUIRE 1 PLANT TYPE: WEST PWR
 EVENT DATE: 2/12/1982 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CVCS/HIGH PRESSURE SAFETY INJECTION
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: HYDROGEN CONTROL SYSTEM FOR PD CHARGING PUMP
 PULSATION DAMPER FAILED

PROPAGATION: HYDROGEN FROM PULSATION DAMPENER ENTERED SUCTION
 OF BOTH CENTRIFUGAL PUMPS

DEPENDENCY: COMMON SUCTION OF CHARGING PUMPS CAN CAUSE GAS
 BINDING OF ALL THREE PUMPS

UNDESIRABLE RESULT: ALL CAPABILITY FOR CHARGING FLOW LOST. ALSO
 CAUSES LOSS OF HPSI.

CORRECTIVE ACTION: OTHER

CATEGORY: 2

REFERENCES: L0002 L1029 I-197 A0021

EVENT NO 96

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: MIDLAND 1 PLANT TYPE: B&W PWR
 EVENT DATE: 7/11/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

PRIMARY COOLANT (PWR)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

PRIMARY CONTAINMENT (PWR)
 TOTAL SYSTEM OCCURRENCE

ESSENTIAL RAW COOLING/ SERVICE WATER
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR BUILDING HVAC (PWR)
 HEAT EXCHANGERS

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 1,3 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: LOCA OR MSLB WHICH RAISES CONTAINMENT TEMPERATURE

PROPAGATION: HI AMBIENT TEMP CAUSES BOILING OF SERVICE WATER
 SUPPLY TO CNMT AIR COOLERS

DEPENDENCY: SERVICE WATER LINES IN CNMT SUSCEPTIBLE TO HI
 AMBIENT TEMP

UNDESIRABLE RESULT: REDUCED COOLING COULD AFFECT LONG TERM OPERATION
 OF MULT SAFETY SYSTEMS

REMARKS: EXTRA PUMP ADDED TO INCREASE SW PRESSURE

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 23

REFERENCES: L0144 EVENT NO 97

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: MIDLAND 1 PLANT TYPE: B&W PWR
 EVENT DATE: 7/22/1983 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

HIGH VOLTAGE AC (GREATER THAN 35KV)
 ELECTRICAL CONDUCTORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

HIGH VOLTAGE AC (GREATER THAN 35KV)
 ELECTRICAL CONDUCTORS

AUXILIARY FEEDWATER (PWR)
 VALVES

SAFETY SYSTEMS/COMPONENTS AFFECTED

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 2,4 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: LOSS OF OFFSITE POWER

PROPAGATION: TWO STEAM SUPPLY VALVES TO THE APW TURBINE CLOSE
 ON LOSS OF OFFSITE POWER

DEPENDENCY: NO DC POWER SUPPLY TO APW TURBINE VALVES

UNDESIRABLE RESULT: LOSS OF APW TURBINE-DRIVEN PUMP WHEN OFFSITE POWER
 IS LOST

REMARKS: SAME DESIGN DEFICIENCY APPLIES TO MIDLAND 2

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 13

REFERENCES: C12 EVENT NO 98

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: MIDLAND 2 PLANT TYPE: B&W PWR
 EVENT DATE: 7/22/1983 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

HIGH VOLTAGE AC (GREATER THAN 35KV)
 ELECTRICAL CONDUCTORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

HIGH VOLTAGE AC (GREATER THAN 35KV)
 ELECTRICAL CONDUCTORS

AUXILIARY FEEDWATER (PWR)
 VALVES

SAFETY SYSTEMS/COMPONENTS AFFECTED

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 2,4 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: LOSS OF OFFSITE POWER

PROPAGATION: TWO STEAM SUPPLY VALVES TO THE APW TURBINE CLOSE
 ON LOSS OF OFFSITE POWER

DEPENDENCY: NO DC POWER SUPPLY TO APW TURBINE VALVES

UNDESIRABLE RESULT: LOSS OF APW TURBINE-DRIVEN PUMP WHEN OFFSITE POWER
 IS LOST

REMARKS: SAME DESIGN DEFICIENCY APPLIES TO MIDLAND 1

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 13

REFERENCES: C12 EVENT NO 99

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: MILLSTONE 1 PLANT TYPE: GE BWR
 EVENT DATE: 5/01/1971 EXPERIENCE: ACTUAL
 OPERATING STATUS: UNKNOWN

INITIATING SYSTEM AND COMPONENT

ESSENTIAL RAW COOLING/ SERVICE WATER
 HEAT EXCHANGERS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

ESSENTIAL RAW COOLING/ SERVICE WATER
 HEAT EXCHANGERS

DC POWER
 ELECTRICAL CONDUCTORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

DC POWER
 ELECTRICAL CONDUCTORS

RESIDUAL HEAT REMOVAL (BWR)
 VALVES

MAIN STEAM
 VALVES

TYPE OF COUPLING: SPATIAL PLANT AREA: REACTOR AUXILIARY BUILDING

RESULT TYPE: 1 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: SERVICE WATER HEAT EXCHANGER LEAKED

PROPAGATION: LEAK FLOODED AREA, SHORTING DC MOTOR CONTROL
 CENTER

DEPENDENCY: MCC IS LOCATED NEAR HX BUT NOT PROTECTED AGAINST
 FLOODING

UNDESIRABLE RESULT: NUMEROUS VALVE MOTOR BURNOUTS IN RWCU, RHR AND
 MAIN STEAM SYSTEMS

CORRECTIVE ACTION: OTHER CATEGORY:23

REFERENCES: L2027 EVENT NO 100

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: MILLSTONE 1 PLANT TYPE: GE BWR
 EVENT DATE: 9/14/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MEDIUM VOLTAGE AC (35KV TO 600V)
 TOTAL SYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

MEDIUM VOLTAGE AC (35KV TO 600V)
 TOTAL SYSTEM OCCURRENCE

REACTOR PROTECTION
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

ALL ECCS SYSTEMS
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: STATION POWERED FROM RESERVE STATION SERVICE
 TRANSFORMER

PROPAGATION: BUS TIE BREAKER OPENED, LOSS OF POWER TO ECCS
 LOADS

DEPENDENCY: LOSS OF NORMAL POWER LOGIC WILL NOT SENSE LOP FOR
 CERTAIN BKR SETUPS

UNDESIRABLE RESULT: LOSS OF ECCS

REMARKS: LOGIC CHANGED TO ELIMINATE THIS POSSIBILITY

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 1

REFERENCES: E0003 L2009 EVENT NO 101

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: MILLSTONE 1 PLANT TYPE: GE BWR
 EVENT DATE: 4/03/1981 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

ENGINEERED SAFETY FEATURES ACTUATION
 I&C/RELAYS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

ENGINEERED SAFETY FEATURES ACTUATION
 I&C/RELAYS

EMERGENCY POWER GENERATION
 CIRCUIT BREAKER/FUSES

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 CIRCUIT BREAKER/FUSES

ALL SYSTEMS REQUIRING EMERGENCY POWER
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: AFTER LOSS OF NORMAL POWER, TIME RELAY TRIPS LOADS
 AND FAILS TO REOPEN

PROPAGATION: A RELAY FAILURE PREVENTS ALL 4160V & SOME 480V
 BREAKER RECLOSURE TO EMERG BUSES

DEPENDENCY: TIME DELAY RELAY GIVES TRIP SIGNAL TO BREAKERS

UNDESIRABLE RESULT: POTENTIAL LOSS OF POWER AND NO EMERGENCY POWER TO
 SAFETY SYSTEMS

REMARKS: SINGLE RELAY FAILURES FAILS ALL 4160V BRKRS-2ND
 RELAY INSTALLED IN LNP CIRCUITS

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 1

REFERENCES: L1028 E0003 EVENT NO 102

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: MILLSTONE 2 PLANT TYPE: CE PWR
 EVENT DATE: 7/05/1976 EXPERIENCE: ACTUAL
 OPERATING STATUS: COLD SHUTDOWN

INITIATING SYSTEM AND COMPONENT

HIGH VOLTAGE AC (GREATER THAN 35KV)
 TOTAL SYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

HIGH VOLTAGE AC (GREATER THAN 35KV)
 TOTAL SYSTEM OCCURRENCE

LOW VOLTAGE AC (LESS THAN 600V)
 ELECTRICAL/I&C FUNCTION ITEMS

SAFETY SYSTEMS/COMPONENTS AFFECTED

MULTIPLE ESF SYSTEMS
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: DEGRADED GRID VOLTAGE DUE TO LIGHT LOAD WITH UNIT
 IN SD & IMPROPER XFMR SETTINGS

PROPAGATION: 480V MCC VOLTAGES INSUFFICIENT TO PULL IN MOTOR
 CONTACTORS-CONTR PWR FUSES BLOW

DEPENDENCY: ESFAS UV RELAYS SET TOO LOW TO ASSURE TRANSFER TO
 EMERG POWER

UNDESIRABLE RESULT: OPERABILITY OF ESFAS EQUIPMENT NOT ASSURED UNDER
 SIMILAR LOW VOLTAGE CONDITIONS

REMARKS: ESFAS UV RELAY SETPOINTS RAISED-PARTIAL CAUSE OF
 7-21-76 EVENT

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 1

REFERENCES: M1010

EVENT NO 103

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: MILLSTONE 2 PLANT TYPE: CE PWR
 EVENT DATE: 7/21/1976 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

EMERGENCY POWER GENERATION
 I&C/RELAYS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

EMERGENCY POWER GENERATION
 I&C/RELAYS

MEDIUM VOLTAGE AC (35KV TO 600V)
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 I&C/RELAYS

MULTIPLE ESP SYSTEMS
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 4 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: START OF LARGE LOAD CAUSED EMERG BUS VOLTAGE TO
 DROP BELOW NEW UV RELAY SETTINGS

PROPAGATION: HI INRUSH CURRENT OF ESPAS LOADS CAUSED UV TRIP TO
 ACTUATE-SHEDDING SAME LOAD

DEPENDENCY: LOAD SHED FROM EMERG BUSES ON TRANSIENT UV AFTER
 EMERG BUSES ENERGIZED FROM DG'S

UNDESIRABLE RESULT: DG ON LINE & EMERG BUSES ENERGIZED, BUT ESPAS EQUIP
 TRIPPED FROM UNDERVOLTAGE

REMARKS: UV RELAY CHANGED DUE TO 7-5-76 EVENT

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 1

REFERENCES: M1010

EVENT NO 104

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: MILLSTONE 2 PLANT TYPE: CE PWR
 EVENT DATE: 1/02/1981 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

DC POWER
 PERSONNEL

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

DC POWER
 ELECTRICAL CONDUCTORS

TURBINE GENERATOR I&C
 ELECTRICAL CONDUCTORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

TURBINE GENERATOR I&C
 SUBSYSTEM OCCURRENCE

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

CONTAINMENT ISOLATION
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,4 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: OPERATOR MISTAKENLY USED 125 VDC CONTROL SWITCH

PROPAGATION: THIS DEENERGIZED 125 VDC BUS CAUSING 4 REACTOR
 TRIP BREAKERS TO OPEN

DEPENDENCY: TURBINE TRIP AND AUX LOAD TRANSFER REQUIRE DC
 POWER

UNDESIRABLE RESULT: FAILURE OF TURBINE TRIP AND LOP TO AUXILIARY LOADS

REMARKS: NUMEROUS ADDITIONAL PROBLEMS DESCRIBED IN REPORT

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 1

REFERENCES: A0015 EVENT NO 105

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: MILLSTONE 2 PLANT TYPE: CE PWR
 EVENT DATE: 1/08/1981 EXPERIENCE: ACTUAL
 OPERATING STATUS: HOT SHUTDOWN

INITIATING SYSTEM AND COMPONENT

COMPRESSED GAS
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

PRESSURIZER (PWR)
 VESSELS

CORE FLOODING ACCUMULATOR (PWR)
 ACCUMULATORS/RESERVOIRS

SAFETY SYSTEMS/COMPONENTS AFFECTED

PRESSURIZER (PWR)
 VESSELS

CORE FLOODING ACCUMULATOR (PWR)
 ACCUMULATORS/RESERVOIRS

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,2 DISCOVERY: AUDIO/VISUAL ALARM

INITIATING EVENT: PERSONNEL LEFT 2 NITROGEN ISOL VALVES TO
 PRESSURIZER OPEN FOLLOWING COOLDOWN

PROPAGATION: STEAM FROM PRESSURIZER LEAKED TO SAFETY INJ TANK
 OVER-PRESSURIZING TANK

DEPENDENCY: LEAK PATH FROM PRESSURIZER TO SI TANKS VIA HIGH
 PRESS NITROGEN SYSTEM

UNDESIRABLE RESULT: POTENTIAL DILUTION OR DAMAGE TO SI TANKS FROM HIGH
 PRESS STEAM FROM PRESSURIZER

REMARKS: SI TANKS AND NITROGEN LINE MAY NOT WITHSTAND RCS
 OVER PRESS-POSSIBLE SMALL LOCA

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 2

REFERENCES: L1022

EVENT NO 106

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: MILLSTONE 2 PLANT TYPE: CE PWR
 EVENT DATE: 12/05/1983 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

FUEL BUILDING
 STRUCTURAL FUNCTION ITEMS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

FUEL BUILDING
 STRUCTURAL FUNCTION ITEMS

FUEL BUILDING HVAC
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

FUEL BUILDING HVAC
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: FUEL BUILDING

RESULT TYPE: 2 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: SEISMIC EVENT DURING FUEL MOVEMENT IN FUEL
 BUILDING

PROPAGATION: TEMPORARY SHIELD WALL COLLAPSE CAUSES DAMAGE TO
 FUEL BLDG HVAC SYSTEM

DEPENDENCY: NON SEISMIC WALL INSTALLED NEAR SAFETY EQUIPMENT

UNDESIRABLE RESULT: POTENTIAL FOR FUEL DAMAGE RELEASE WITHOUT OPERABLE
 FUEL BLDG HVAC

CORRECTIVE ACTION: OTHER

CATEGORY: 21

REFERENCES: L0170

EVENT NO 107

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: MONTICELLO PLANT TYPE: GE BWR
 EVENT DATE: 3/01/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

RECIRCULATING WATER (BWR)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

DRYWELL/ TORUS HVAC AND PURGE (BWR)
 MECHANICAL FUNCTION ITEMS

REACTOR DRYWELL (BWR)
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

CONTAINMENT ISOLATION
 TOTAL SYSTEM OCCURRENCE

REACTOR DRYWELL (BWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: NRC NOTIFICATION

INITIATING EVENT: LOCA OCCURRING DURING DRYWELL PURGE OPERATIONS

PROPAGATION: DRYWELL PRESSURE SURGE CAUSES FAILURE OF DUCTS OR DAMPERS

DEPENDENCY: INADEQUATE DUCT STRENGTH OR ISOLATION VALVE CAPABILITY FOR PURGE SYSTEM

UNDESIRABLE RESULT: LOSS OF CONTAINMENT INTEGRITY

REMARKS: DESIGN DID NOT CONSIDER LOCA FORCES IN VALVE CLOSURE DESIGN

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 9

REFERENCES: L0051

EVENT NO 108

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: MONTICELLO PLANT TYPE: GE BWR
 EVENT DATE: 3/03/1981 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

ESSENTIAL RAW COOLING/ SERVICE WATER
 PUMPS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

ESSENTIAL RAW COOLING/ SERVICE WATER
 PUMPS

ESSENTIAL RAW COOLING/ SERVICE WATER
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

ESSENTIAL RAW COOLING/ SERVICE WATER
 TOTAL SYSTEM OCCURRENCE

RESIDUAL HEAT REMOVAL (BWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: ROUTINE TEST/INSPECTION

INITIATING EVENT: RHR SERVICE WATER PUMP SHAFT PACKING FAILED,
 PRESSURING SEAL WATER SUPPLY

PROPAGATION: CHECK VALVE IN SEAL WATER SUPPLY SYSTEM FAILED
 ALLOWING PRESSURE TO OTHER RHR SW

DEPENDENCY: RHR SERVICE WATER PUMPS SHARE SEAL WATER SUPPLY

UNDESIRABLE RESULT: LOSS OF BOTH RHR SW PUMPS CAUSES LOSS OF HEAT
 REMOVAL FROM TWO RHR TRAINS

REMARKS: ONE RHR SW LOOP WAS ISOLATED AND MADE OPERABLE

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 13

REFERENCES: L0004 EVENT NO 109

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: NINE MILE POINT 1 PLANT TYPE: GE BWR
EVENT DATE: 10/14/1976 EXPERIENCE: POTENTIAL
OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

CONTAINMENT SPRAY
I&C/SWITCHES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CONTAINMENT SPRAY
PUMPS

CONTAINMENT SPRAY
PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CONTAINMENT SPRAY
SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 0 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: PLACEMENT OF CONTAINMENT SPRAY PUMP CONTROL SWITCH
IN LOCKOUT

PROPAGATION: ADDITIONAL CONTAINMENT SPRAY PUMP WOULD NOT AUTO
START

DEPENDENCY: LOCKOUT SWITCH ACTUATION AFFECTS BOTH PUMPS

UNDESIRABLE RESULT: BOTH CONTAINMENT SPRAY PUMPS IN THAT TRAIN FAIL TO
AUTO START

REMARKS: TWO OTHER CS PUMPS EXIST IN OTHER TRAIN

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 13

REFERENCES: L0015 EVENT NO 110

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: NINE MILE POINT 1 PLANT TYPE: GE BWR
 EVENT DATE: 1/07/1981 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

EMERGENCY GENERATOR BUILDING
 STRUCTURAL FUNCTION ITEMS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

EMERGENCY GENERATOR BUILDING
 STRUCTURAL FUNCTION ITEMS

EMERGENCY POWER GENERATION
 I&C/CONTROLLERS

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 I&C/CONTROLLERS

TYPE OF COUPLING: SPATIAL PLANT AREA: EMERGENCY GENERATOR BUILDING

RESULT TYPE: 2 DISCOVERY: ROUTINE TEST/INSPECTION

INITIATING EVENT: PIECE OF BAILING WIRE FELL INTO CONTROL CABINET,
 SHORTING DG VOLTAGE REGULATOR

PROPAGATION: SHORTED V-REGULATOR BLOWS FUSE, DIESEL GENERATOR
 OUTPUT BREAKER TRIPS

DEPENDENCY: WIRE USED TO SECURE FIRE PROOFING FRAMES DIRECTLY
 ABOVE DG CONTROL CABINET

UNDESIRABLE RESULT: POTENTIAL LOSS OF DIESEL GENERATOR

REMARKS: WIRE AND FRAMES MAY NOT BE SEISMIC QUALIFIED-ALSO
 POTENTIAL FOR SIMILAR EVENTS

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY:23

REFERENCES: L1015 EVENT NO 111

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: NINE MILE POINT 1 PLANT TYPE: GE BWR
 EVENT DATE: 1/29/1982 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

RECIRCULATING WATER (BWR)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

SECONDARY CONTAINMENT (BWR)
 STRUCTURAL FUNCTION ITEMS

DRYWELL/ TORUS HVAC AND PURGE (BWR)
 MISCELLANEOUS EQUIPMENT

SAFETY SYSTEMS/COMPONENTS AFFECTED

DRYWELL/ TORUS HVAC AND PURGE (BWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: HUMAN

RESULT TYPE: 5 DISCOVERY: NRC NOTIFICATION

INITIATING EVENT: LOSS OF COOLANT ACCIDENT PROCEDURES CALL FOR
 VENTING CONTAINMENT

PROPAGATION: VENTING PROCEDURE REQUIRES ACCESS TO REACTOR
 BUILDING

DEPENDENCY: REACTOR BLDG WILL NOT BE ACCESSIBLE DUE TO LOCA

UNDESIRABLE RESULT: LOCA REQUIRES VENTING AND PREVENTS VENTING UNDER
 CURRENT PROCEDURE

REMARKS: FOUND IN PROCEDURE REVIEW BY RESIDENT INSPECTOR.
 PROCEDURE/DESIGN CHANGES MADE

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 19

REFERENCES: L0030

EVENT NO 112

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: NORTH ANNA 1 PLANT TYPE: WEST PWR
 EVENT DATE: 10/05/1978 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

VITAL INSTRUMENT, CONTROL, AND COMPUTER AC
 CIRCUIT BREAKER/FUSES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

LEAK MONITORING
 PUMPS

LEAK MONITORING
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

LEAK MONITORING
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: MAINTENANCE/MODIFICATION

INITIATING EVENT: PERSONNEL OPENED BREAKER TO REMOVE POWER FROM A
 CNMT AIR AND PARTICULATE PUMP

PROPAGATION: LOSS OF POWER OCCURRED TO BOTH TRAINS OF
 CONTAINMENT AIR & PARTICULATE MONITORS

DEPENDENCY: THE TRAINS SHARED A COMMON POWER SUPPLY

UNDESIRABLE RESULT: ANY LOSS OF POWER CAUSES LOSS OF CONTAINMENT
 ATMOSPHERE MONITORING

REMARKS: SYSTEM-CONTAINMENT ATMOSPHERE PARTICULATE AND GAS
 MONITORING

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 13

REFERENCES: L0011 EVENT NO 113

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: NORTH ANNA 1 PLANT TYPE: WEST PWR
 EVENT DATE: 6/21/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MAIN STEAM
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

STEAM GENERATOR (PWR)
 PIPES/FITTINGS

REACTOR PROTECTION
 I&C/SENSORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR PROTECTION
 SUBSYSTEM OCCURRENCE

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: HIGH ENERGY LINE BREAK IN CONTAINMENT RESULTING IN
 HIGH AMBIENT TEMP

PROPAGATION: HEATUP OF REP LEG, SG LEVEL INSTR FAILS HIGH,
 DELAYS RPS TRIP ON SG LO LO LEVEL

DEPENDENCY: STEAM GENERATOR LEVEL REFERENCE LEG SUBJECTED TO
 HIGH AMBIENT TEMP

UNDESIRABLE RESULT: ACCIDENT DEGRADES SYSTEM REQUIRED TO MITIGATE
 ACCIDENT

REMARKS: ALSO PROVIDES HIGH LEVEL INDICATION TO
 OPERATOR-GENERIC W PROBLEM

CORRECTIVE ACTION: OTHER

CATEGORY: 8

REFERENCES: L0159

EVENT NO 114

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: NORTH ANNA 1 PLANT TYPE: WEST PWR
 EVENT DATE: 9/17/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

CONDENSATE AND FEEDWATER
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CONDENSATE AND FEEDWATER
 PIPES/FITTINGS

STEAM GENERATOR PRESSURE RELIEF (PWR)
 I&C/CONTROLLERS

SAFETY SYSTEMS/COMPONENTS AFFECTED

STEAM GENERATOR PRESSURE RELIEF (PWR)
 SUBSYSTEM OCCURRENCE

PRESSURIZER (PWR)
 SUBSYSTEM OCCURRENCE

REACTOR POWER CONTROL (PWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: UNKNOWN

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: HIGH ENERGY LINE BREAK (FW OR MS) IN CERTAIN PLANT
 LOCATIONS

PROPAGATION: ADVERSE ENVIRONMENT FROM BREAK CAN CAUSE CONTROL
 SYSTEM FAILURES

DEPENDENCY: CONTROL SYSTEMS SUSCEPTIBLE TO HELB CONDITIONS
 LOCATED SUBJECT TO HELB IMPACT

UNDESIRABLE RESULT: POTENTIAL FOR SG PORV, PZR PORV, AUTO ROD CONTROL,
 AND FW CONTROL FAILURES

REMARKS: PLANT SPECIFIC EVALUATION NECESSARY TO DETERMINE
 SAFETY EFFECT. NOT GIVEN.

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 10

REFERENCES: L0088 L0089 I-277 EVENT NO 115

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: NORTH ANNA 1 PLANT TYPE: WEST PWR
 EVENT DATE: 5/09/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

PRESSURIZER (PWR)
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CVCS/HIGH PRESSURE SAFETY INJECTION
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: SECONDARY SYS HELB CAUSING SI ACTUATION AND PORV
 CONTROL FAILURE

PROPAGATION: RCS PRESSURE HIGHER THAN CHG PUMP DESIGN INJECTION
 PRESS; PUMPS OVERHEAT

DEPENDENCY: RECIRC VALVES PROTECT CHG PUMPS, BUT SIAS CLOSES
 RECIRC VALVES

UNDESIRABLE RESULT: LOSS OF MULTIPLE CHG PUMPS PRIOR TO SI SHUTOFF
 CONDITIONS MET

REMARKS: GENERIC W PROBLEM. PUMP FAILURES DEPENDS ON
 SPECIFIC DESIGN HEAD

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 7

REFERENCES: L0056 I-017

EVENT NO 116

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: NORTH ANNA 1 PLANT TYPE: WEST PWR
 EVENT DATE: 11/14/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

HIGH VOLTAGE AC (GREATER THAN 35KV)
 TOTAL SYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

ENGINEERED SAFETY FEATURES ACTUATION
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

ALL SYSTEMS REQUIRING EMERGENCY POWER
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,4 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: SI ACTUATION FOLLOWED BY LOSS OF OFFSITE POWER

PROPAGATION: OUT OF PHASE TRANSFER OF DG'S TO BUSES DAMAGES
 SAFETY EQUIPMENT

DEPENDENCY: NO LOGIC TO PREVENT DG TRANSFER BEFORE RESIDUAL
 VOLTAGE COLLAPSES

UNDESIRABLE RESULT: DAMAGE TO SAFETY EQUIPMENT FOLLOWING LOSSP

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 1

REFERENCES: L0116 EVENT NO 117

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: NORTH ANNA 1 PLANT TYPE: WEST PWR
 EVENT DATE: 5/22/1981 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

NON-NUCLEAR INSTRUMENTATION
 I&C/TRANSMITTERS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CVCS/HIGH PRESSURE SAFETY INJECTION
 ACCUMULATORS/RESERVOIRS

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CVCS/HIGH PRESSURE SAFETY INJECTION
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: VCT LEVEL TRANSMITTER FAILS HIGH STOPPING LETDOWN
 FLOW

PROPAGATION: NO LETDOWN, VCT LOW LEVEL, NO SWITCH TO RWST, LOSS
 OF SUCTION DAMAGES CHG PUMPS

DEPENDENCY: LEVEL TRANSMITTER CONTROLS LEVEL AND SUCTION
 SWITCHOVER TO RWST

UNDESIRABLE RESULT: REDUNDANT CHG PUMPS DAMAGED. THESE PUMPS ARE ALSO
 HI HEAD SAFETY INJECTION

REMARKS: WESTINGHOUSE NOTIFICATION OF POTENTIAL FAULIRE

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 5

REFERENCES: L0119 A0020 A0021 EVENT NO 118

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: NORTH ANNA 2 PLANT TYPE: WEST PWR
 EVENT DATE: 6/27/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MAIN STEAM
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

STEAM GENERATOR (PWR)
 PIPES/FITTINGS

REACTOR PROTECTION
 I&C/SENSORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR PROTECTION
 SUBSYSTEM OCCURRENCE

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: HIGH ENERGY LINE BREAK IN CONTAINMENT RESULTING IN
 HIGH AMBIENT TEMP

PROPAGATION: HEATUP OF REF LEG, SG LEVEL INSTR FAILS HIGH,
 DELAYS RPS TRIP ON SG LO LO LEVEL

DEPENDENCY: STEAM GENERATOR LEVEL REFERENCE LEG SUBJECTED TO
 HIGH AMBIENT TEMP

UNDESIRABLE RESULT: ACCIDENT DEGRADES SYSTEM REQUIRED TO MITIGATE
 ACCIDENT

REMARKS: ALSO PROVIDES HIGH LEVEL INDICATION TO
 OPERATOR-GENERIC W PROBLEM

CORRECTIVE ACTION: OTHER

CATEGORY: 8

REFERENCES: L0075

EVENT NO 119

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: NORTH ANNA 2 PLANT TYPE: WEST PWR
EVENT DATE: 7/03/1981 EXPERIENCE: ACTUAL
OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

HIGH VOLTAGE AC (GREATER THAN 35KV)
TRANSFORMERS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

FIRE PROTECTION
SUBSYSTEM OCCURRENCE

PLANT DRAINAGE
SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: SWITCHYARD

RESULT TYPE: 2,4,5 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: FIRE IN B PHASE MAIN TRANSFORMER ACTUATED DELUGE
SYSTEM

PROPAGATION: TRANSFORMER RUPTURED, SPILLING OIL INTO
SURROUNDING PIT

DEPENDENCY: XFMR PIT DRAIN TOO SMALL TO REMOVE FLAMING OIL AND
DELUGE WATER QUICKLY

UNDESIRABLE RESULT: PIT OVERFLOWED, SPILLING FLAMING OIL TO
SURROUNDINGS-HAMPERED FIRE FIGHTING

REMARKS: POSSIBLE GENERIC PROBLEM-DRAINS TOO SMALL TO
REMOVE FIRE DELUGE, CAUSING FLOODING

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 4

REFERENCES: I-151 L0129 EVENT NO 120

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: NORTH ANNA 3 PLANT TYPE: B&W PWR
 EVENT DATE: 2/08/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MAIN STEAM
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

AUXILIARY FEEDWATER (PWR)
 TOTAL SYSTEM OCCURRENCE

PRIMARY CONTAINMENT (PWR)
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

PRIMARY CONTAINMENT (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: MSLB PLUS AUX FEEDWATER FLOW TO AFFECTED SG UNDER
 RUNOUT CONDITIONS

PROPAGATION: CONTAINMENT PRESSURE INCREASES TO DESIGN PRESSURE

DEPENDENCY: AFW INJECTION AFTER MSLB CAN CAUSE LONG TERM
 BLOWDOWN

UNDESIRABLE RESULT: LONG TERM BLOWDOWN CAN CAUSE CONTAINMENT DESIGN
 PRESSURE TO BE EXCEEDED

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY:22

REFERENCES: I-031 I-275

EVENT NO 121

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: OCONEE 3 PLANT TYPE: B&W PWR
 EVENT DATE: 12/07/1978 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

CONDENSATE AND FEEDWATER
 MISCELLANEOUS EQUIPMENT

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

REACTOR BUILDING HVAC (PWR)
 FILTERS, NON-IEC

REACTOR BUILDING HVAC (PWR)
 FILTERS, NON-IEC

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR BUILDING HVAC (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: REACTOR AUXILIARY BUILDING

RESULT TYPE: 1,2 DISCOVERY: UNKNOWN

INITIATING EVENT: FEEDWATER SYSTEM LEAK IN PENETRATION ROOM

PROPAGATION: WATER ENTERED BOTH TRAINS OF REACTOR BUILDING
 VENTILATION SYSTEM FILTERS

DEPENDENCY: BOTH TRAINS OF RB FILTERS LOCATED IN SAME AREA AND
 SUBJECT TO LEAKS

UNDESIRABLE RESULT: REDUNDANT RB FILTER TRAINS FAILED

REMARKS: LEAK HAD BEEN REPAIRED A MONTH PRIOR TO DISCOVERY
 OF FILTER FAILURES

CORRECTIVE ACTION: REPAIR/REPLACEMENT CATEGORY: 23

REFERENCES: L0009 EVENT NO 122

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: OCONEE 3 PLANT TYPE: B&W PWR
 EVENT DATE: 11/10/1979 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

VITAL INSTRUMENT, CONTROL, AND COMPUTER AC
 ELECTRICAL/IEC FUNCTION ITEMS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

VITAL INSTRUMENT, CONTROL, AND COMPUTER AC
 ELECTRICAL/IEC FUNCTION ITEMS

NON-NUCLEAR INSTRUMENTATION
 I&C/INDICATORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

PRIMARY COOLANT (PWR)
 I&C/INDICATORS

RESIDUAL HEAT REMOVAL (PWR)
 I&C/INDICATORS

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 2,4 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: NON-CLASS IE INV TRIPPED DUE TO BLOWN FUSE &
 FAILED TO TRANSFER LOAD

PROPAGATION: RCS INSTRUMENTATION FED FROM NNI INVERTER

DEPENDENCY: CONTROL ROOM RCS AND DECAY HEAT INSTR FED FROM
 NON-CLASS IE SOURCE

UNDESIRABLE RESULT: LOSS OF INDICATION FOR SYSTEMS REQD FOR SHUTDOWN

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 14

REFERENCES: I-036 I-270 I-108 I-257 EVENT NO 123

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: OCONEE 3 PLANT TYPE: B&W PWR
 EVENT DATE: 3/03/1981 EXPERIENCE: ACTUAL
 OPERATING STATUS: COLD SHUTDOWN

INITIATING SYSTEM AND COMPONENT

CONDENSATE AND FEEDWATER
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CONDENSATE AND FEEDWATER
 VALVES

EMERGENCY POWER GENERATION
 ELECTRICAL CONDUCTORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 ELECTRICAL CONDUCTORS

TYPE OF COUPLING: SPATIAL PLANT AREA: MISCELLANEOUS/ UNKNOWN STRUCTURE:

RESULT TYPE: 2 DISCOVERY: UNKNOWN

INITIATING EVENT: FEEDWATER VALVE LEAKS

PROPAGATION: HEAT AND MOISTURE DAMAGE TO EMERGENCY POWER
 SWITCHING LOGIC CABLES FROM VALVE

DEPENDENCY: CLOSE PROXIMITY OF EMERGENCY POWER SWITCHING LOGIC
 CABLES TO FEEDWATER VALVE

UNDESIRABLE RESULT: POTENTIAL FOR LOGIC FAILURE & SAFETY EQUIP W/O
 EMERGENCY ELECTRIC POWER

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 23

REFERENCES: L1001

EVENT NO 124

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: OYSTER CREEK PLANT TYPE: GE BWR
 EVENT DATE: 9/18/1973 EXPERIENCE: ACTUAL
 OPERATING STATUS: ROUTINE SHUTDOWN

INITIATING SYSTEM AND COMPONENT

HIGH VOLTAGE AC (GREATER THAN 35KV)
 TRANSFORMERS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

HIGH VOLTAGE AC (GREATER THAN 35KV)
 TRANSFORMERS

EMERGENCY POWER GENERATION
 ENGINES, INTERNAL COMBUSTION

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 4 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: ATTEMPT TO TRANSFER POWER FROM AUX TRANS TO
 STARTUP TRANS. 4160V BUS LOST POWER.

PROPAGATION: DG STARTED, RX TRIPPED. OS POWER RESTORED AND LOST
 AGAIN. DG FAILED TO RESTART.

DEPENDENCY: DG LOCKED OUT AFTER A PAST START DUE TO A DESIGN
 DEFICIENCY

UNDESIRABLE RESULT: LOSS OF POWER TO STATION LOADS

REMARKS: DG LOGIC CIRCUITS MODIFIED. STARTUP TRANS CURRENT
 RATIO SETTINGS CHANGED.

CORRECTIVE ACTION: OTHER

CATEGORY: 1

REFERENCES: E0007 L2017

EVENT NO 125

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: OYSTER CREEK PLANT TYPE: GE BWR
 EVENT DATE: 12/20/1976 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

REACTOR OVERPRESSURE PROTECTION (BWR)
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

REACTOR OVERPRESSURE PROTECTION (BWR)
 VALVES

TORUS/ SUPPRESSION POOL (BWR)
 STRUCTURAL FUNCTION ITEMS

SAFETY SYSTEMS/COMPONENTS AFFECTED

TORUS/ SUPPRESSION POOL (BWR)
 STRUCTURAL FUNCTION ITEMS

MULTIPLE ESP SYSTEMS
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: SPECIAL TEST/INSPECTION

INITIATING EVENT: PRESSURE RELIEF TO MARK I CONTAINMENT TORUS IN
 CERTAIN RELIEF VALVE SEQUENCES

PROPAGATION: STRESSES CREATED ON TORUS COULD EXCEED ACCEPTABLE
 LEVELS

DEPENDENCY: TORUS CAN BE DAMAGED FROM SPECIFIC RELIEF VALVE
 SEQUENCES

UNDESIRABLE RESULT: DAMAGE TO TORUS COULD DEGRADE MULTIPLE SAFETY
 SYSTEMS

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 17

REFERENCES: LO106

EVENT NO 126

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: OYSTER CREEK PLANT TYPE: GE BWR
 EVENT DATE: 5/02/1979 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

RECIRCULATING WATER (BWR)
 TOTAL SYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

RECIRCULATING WATER (BWR)
 TOTAL SYSTEM OCCURRENCE

ISOLATION CONDENSER (BWR)
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR VESSEL
 I&C/INDICATORS

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 4 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: RX SCRAM AND CLOSURE OF ALL RECIRC LOOP DISCH
 VALVES PER PROCEDURES

PROPAGATION: INADEQUATE FLOW FROM ISOL COND TO ANNULUS VIA
 RECIRC DISCH VALVE BYPASS LINE

DEPENDENCY: REACTOR VESSEL WATER LEVEL INDICATION MEASURES
 ANNULUS WATER LEVEL

UNDESIRABLE RESULT: ANOMOLOUS RV LEVEL INDICATIONS TO OPER-ANNULUS VS
 CORE SHROUD LEVEL DIFFERENT

REMARKS: CORE LEVEL NEVER LOW. APPLIES ONLY TO NON-JET
 PUMP BWR PLANTS.

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY:22

REFERENCES: I-283 L0125 M1003

EVENT NO 127

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: OYSTER CREEK PLANT TYPE: GE BWR
 EVENT DATE: 9/30/1980 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

FIRE PROTECTION
 SUBSYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

FIRE PROTECTION
 SUBSYSTEM OCCURRENCE

LOW PRESSURE CORE SPRAY (BWR)
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

LOW PRESSURE CORE SPRAY (BWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: SECONDARY CONTAINMENT (BWR)

RESULT TYPE: 2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: INADVERTENT ACTUATION OF FIRE PROTECTION SYSTEM
 (DUE TO MAINT ERROR)

PROPAGATION: CORE SPRAY SYSTEM DECLARED INOPERABLE DUE TO WATER
 INTRUSION TO SPRAY PUMPS

DEPENDENCY: CORE SPRAY SYSTEM WAS THOUGHT TO BE PROTECTED FROM
 WATER INTRUSION. IT WAS NOT.

UNDESIRABLE RESULT: ACTUATION OF FIRE PROTECTION SYSTEM DISABLES
 EQUIPMENT REQD FOR SAFETY

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 3

REFERENCES: L0176 EVENT NO 128

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: OYSTER CREEK PLANT TYPE: GE BWR
 EVENT DATE: 2/18/1982 EXPERIENCE: ACTUAL
 OPERATING STATUS: COLD SHUTDOWN

INITIATING SYSTEM AND COMPONENT

FIRE PROTECTION
 I&C/SENSORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

HIGH PRESSURE CORE SPRAY (BWR)
 I&C/SWITCHES

REACTOR PROTECTION
 I&C/SWITCHES

SAFETY SYSTEMS/COMPONENTS AFFECTED

HIGH PRESSURE CORE SPRAY (BWR)
 TOTAL SYSTEM OCCURRENCE

REACTOR PROTECTION
 VALVE OPERATORS

TYPE OF COUPLING: SPATIAL PLANT AREA: SECONDARY CONTAINMENT (BWR)

RESULT TYPE: 2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: FIRE PROTECTION DELUGE ACTUATED DUE TO HIGH
 AMBIENT FROM HOT MOTOR BRG

PROPAGATION: WATER ENTERED SEVERAL SWITCHES IN CS AND RPS

DEPENDENCY: SAFETY-RELATED SWITCHES SUBJECT TO FIRE DELUGE
 SPRAY

UNDESIRABLE RESULT: GROUNDED I&C COMPONENTS IN CORE SPRAY AND REACTOR
 PROTECTION SYSTEMS

REMARKS: PLANT MODIFICATION INITIATED

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 3

REFERENCES: I-151 L0058

EVENT NO 129

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: OYSTER CREEK PLANT TYPE: GE BWR
 EVENT DATE: 1/18/1983 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

CONTROL ROD DRIVE (BWR)
 PUMPS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CONTROL ROD DRIVE (BWR)
 PUMPS

LOW PRESSURE CORE SPRAY (BWR)
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

LOW PRESSURE CORE SPRAY (BWR)
 PUMPS

TYPE OF COUPLING: SPATIAL PLANT AREA: SECONDARY CONTAINMENT (BWR)

RESULT TYPE: 2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: A VENT LINE ON CRD PUMP A BROKE OFF DURING
 MAINTENANCE

PROPAGATION: WATER SPRAYED ON CORE SPRAY PUMP A BELOW THE VENT
 LINE

DEPENDENCY: CORE SPRAY PUMPS ARE LOCATED BELOW THE CRD PUMPS
 AND CAN BE AFFECTED BY LEAKAGE

UNDESIRABLE RESULT: SAFETY SYSTEM (CORE SPRAY) AFFECTED BY NONSAFETY
 SYSTEM (CRD PUMP)

REMARKS: B CRD PUMP TRIPPED OFFLINE ALSO

CORRECTIVE ACTION: OTHER CATEGORY: 23

REFERENCES: L0001 EVENT NO 130

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: OYSTER CREEK PLANT TYPE: GE BWR
 EVENT DATE: 3/06/1983 EXPERIENCE: ACTUAL
 OPERATING STATUS: REFUELING

INITIATING SYSTEM AND COMPONENT

ELECTRICAL HEAT TRACING
 HEATERS, ELECTRIC

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

ELECTRICAL HEAT TRACING
 HEATERS, ELECTRIC

REACTOR BUILDING HVAC (BWR)
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR BUILDING HVAC (BWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: WASTE MANAGEMENT BUILDING

RESULT TYPE: 1,2 DISCOVERY: ROUTINE TEST/INSPECTION

INITIATING EVENT: PLASTIC SENSING LINE ON SGTS FAN FLOW SWITCH
 DAMAGED BY EXCESSIVE HEAT

PROPAGATION: LOW FLOW SIGNAL CAUSED FAN INLET & OUTLET VALVES
 TO CLOSE-LOSS OF ONE SGTS TRN

DEPENDENCY: PLASTIC FLOW SWITCH SENSING LINE ROUTED TOO CLOSE
 TO CABINET SPACE HEATER

UNDESIRABLE RESULT: LOSS OF ONE TRAIN OF SGTS-ALTERNATE TRAIN OPERABLE

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 23

REFERENCES: L0145 EVENT NO 131

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: OYSTER CREEK PLANT TYPE: GE BWR
 EVENT DATE: 3/07/1983 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

LOW VOLTAGE AC (LESS THAN 600V)
 CIRCUIT BREAKER/FUSES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

REACTOR BUILDING HVAC (BWR)
 SUBSYSTEM OCCURRENCE

REACTOR BUILDING HVAC (BWR)
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR BUILDING HVAC (BWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: MAINTENANCE/MODIFICATION

INITIATING EVENT: CIRCUIT BKR RACKED OUT ON ONE TRAIN OF SGTS WITH
 ALTERNATE TRAIN OPERATING

PROPAGATION: CTRL PWR LOST TO SOLENOIDS ON AIR-OPERATED INLET &
 OUTLET VALVES-VALVES OPENED

DEPENDENCY: DISCHARGE OF OPERATING SGTS MAY RECIRCULATE THRU
 OTHER TRAIN

UNDESIRABLE RESULT: DEGRADATION OF ONE SGTS TRAIN BY ALTERNATE TRAIN

REMARKS: RACKING OUT CIRCUIT BKR DISCONNECTS CONTROL POWER
 XFMR-COMMON DESIGN

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 13

REFERENCES: L0146 EVENT NO 132

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: OYSTER CREEK PLANT TYPE: GE BWR
 EVENT DATE: 4/06/1983 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

REACTOR BUILDING HVAC (BWR)
 HEATERS, ELECTRIC

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR BUILDING HVAC (BWR)
 HEATERS, ELECTRIC

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: LOSS OF DG #1 DURING LOSS OF OFFSITE POWER

PROPAGATION: POWER LOST TO MCC SUPPLYING CONTROL POWER TO
 HEATING COILS TO BOTH SGTS TRAINS

DEPENDENCY: SINGLE POWER SOURCE TO REDUNDANT SGTS TRAINS

UNDESIRABLE RESULT: SGTS CHARCOAL FILTER EFFICIENCY COULD BE REDUCED
 IF HEATERS OFF

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 13

REFERENCES: L0147 EVENT NO 133

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: PALISADES PLANT TYPE: CE PWR
 EVENT DATE: 9/08/1971 EXPERIENCE: ACTUAL
 OPERATING STATUS: UNKNOWN

INITIATING SYSTEM AND COMPONENT

VITAL INSTRUMENT, CONTROL, AND COMPUTER AC
 ELECTRICAL CONDUCTORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

VITAL INSTRUMENT, CONTROL, AND COMPUTER AC
 ELECTRICAL CONDUCTORS

VITAL INSTRUMENT, CONTROL, AND COMPUTER AC
 ELECTRICAL CONDUCTORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

PRESSURIZER (PWR)
 VALVES

TYPE OF COUPLING: HUMAN

RESULT TYPE: 3 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: TECHNICIAN DEENERGIZED BREAKER TO RPS

PROPAGATION: POWER LOST TO ELECTROMAGNETIC RELIEF VALVE PILOT
 VALVE SOLENOID CONTROL CIRCUIT

DEPENDENCY: NONSTANDARD DESIGNATION OF CONTACTS. TECHNICIAN
 MISLED BY DRAWINGS

UNDESIRABLE RESULT: RELIEF VALVE OPENED. RCS PRESSURE DROPPED TO 1280
 PSIA IN 2-3 MIN FROM BLOWDOWN

REMARKS: MOV USED TO ISOLATE RELIEF VALVE. RPS BREAKER
 CLOSED.

CORRECTIVE ACTION: OTHER

CATEGORY: 19

REFERENCES: E0001 L2002

EVENT NO 134

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: PALISADES PLANT TYPE: CE PWR
 EVENT DATE: 3/12/1972 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

TURBINE GENERATOR
 ELECTRICAL CONDUCTORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

REACTOR PROTECTION
 I&C/RELAYS

HIGH VOLTAGE AC (GREATER THAN 35KV)
 I&C/RELAYS

SAFETY SYSTEMS/COMPONENTS AFFECTED

MEDIUM VOLTAGE AC (35KV TO 600V)
 SUBSYSTEM OCCURRENCE

ALL ESP SYSTEMS
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,4 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: PILOT WIRE TRIP OPENED BOTH GENERATOR OUTPUT
 BREAKERS. RX SCRAMMED MANUALLY

PROPAGATION: MANUAL SCRAM DID NOT TRANSFER PLANT POWER FROM
 GENERATOR TO STARTUP TRANSFORMER

DEPENDENCY: ESP BUS TRANSFER TO STARTUP TRANS DOESNT OCCUR FOR
 MANUAL SCRAM

UNDESIRABLE RESULT: ONE HALF OF ENGR SAFEGUARDS SYSTEM WAS
 UNAVAILABLE.

REMARKS: POWER WAS MANUALLY TRANSFERRED. UNIT PROTECTION
 SCHEME MODIFIED.

CORRECTIVE ACTION: OTHER

CATEGORY: 1

REFERENCES: E0001 L2001

EVENT NO 135

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: PALISADES PLANT TYPE: CE PWR
 EVENT DATE: 9/16/1977 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

ESSENTIAL COMPRESSED AIR
 MISCELLANEOUS EQUIPMENT

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CONTAINMENT ISOLATION
 VALVES

CONTAINMENT ISOLATION
 VALVES

SAFETY SYSTEMS/COMPONENTS AFFECTED

CONTAINMENT ISOLATION
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,2 DISCOVERY: UNKNOWN

INITIATING EVENT: LOSS OF AIR SUPPLY TO CONTAINMENT PURGE ISOLATION
 VALVE SEALS

PROPAGATION: SEAL RINGS DEPRESSURIZE IN ALL SIX CONTAINMENT
 ISOLATION VALVES

DEPENDENCY: NO REDUNDANT AIR SUPPLY PROVIDED

UNDESIRABLE RESULT: CONTAINMENT ISOLATION FUNCTION FAILS

REMARKS: REDUNDANT AIR SOURCE TO BE PROVIDED

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 13

REFERENCES: L0038 EVENT NO 136

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: PALISADES PLANT TYPE: CE PWR
 EVENT DATE: 8/19/1982 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

HIGH VOLTAGE AC (GREATER THAN 35KV)
 GENERATORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

ESSENTIAL COMPRESSED AIR
 PUMPS

ESSENTIAL RAW COOLING/ SERVICE WATER
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

ESSENTIAL RAW COOLING/ SERVICE WATER
 PUMPS

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: LOCA WITH CONCURRENT LOSS OF OFFSITE POWER PLUS
 ONE DIESEL GENERATOR FAILURE

PROPAGATION: LOSP CAUSES INST AIR LOSS, HX VALVES OPEN FULLY,
 FULL SW FLOW DEMANDED

DEPENDENCY: INCREASED SW FLOW DEMAND CAUSES OPERATING 1H SW
 PUMP(S) TO TRIP DUE TO RUNOUT

UNDESIRABLE RESULT: LOSS OF ALL SERVICE WATER DURING A LOCA

REMARKS: DISCOVERED IN SEP REVIEW

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 22

REFERENCES: L0026 L0027

EVENT NO 137

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: PALISADES PLANT TYPE: CE PWR
 EVENT DATE: 11/30/1982 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

DC POWER
 BATTERIES/CHARGERS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

LOW VOLTAGE AC (LESS THAN 600V)
 SUBSYSTEM OCCURRENCE

DC POWER
 BATTERIES/CHARGERS

SAFETY SYSTEMS/COMPONENTS AFFECTED

MULTIPLE SAFETY SYSTEMS
 UNSPECIFIED COMPONENT

CONTAINMENT COMBUSTIBLE GAS CONTROL
 RECOMBINERS

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: LOCA PLUS HYDROGEN RECOMBINERS ONLINE OR STATION
 BATTERIES DISCHARGED

PROPAGATION: CABLES AND FEEDER BREAKERS TO MCC-1 AND MCC-2
 BECOME OVERLOADED

DEPENDENCY: MCC'S NOT DESIGNED TO TAKE LOADS POSSIBLE UNDER
 THESE CONDITIONS

UNDESIRABLE RESULT: SYSTEMS REQUIRED TO MITIGATE LOCA NOT AVAILABLE

REMARKS: MCC-1 & 2 FEED H2 RECOMBINERS, BATTERY CHARGERS AND
 OTHER SAFETY SYSTEMS

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 22

REFERENCES: L0023

EVENT NO 138

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: PEACH BOTTOM 2 PLANT TYPE: GE BWR
 EVENT DATE: 4/11/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

ESSENTIAL RAW COOLING/ SERVICE WATER
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

ESSENTIAL RAW COOLING/ SERVICE WATER
 VALVES

COMPONENT COOLING WATER
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

ESSENTIAL RAW COOLING/ SERVICE WATER
 TOTAL SYSTEM OCCURRENCE

COMPONENT COOLING WATER
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,2 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: SEISMIC EVENT OCCURS

PROPAGATION: RBCCW HEAT EXCHANGER DAMAGED BY SEISMIC EVENT.
 HEAT EXCHANGER LEAKS

DEPENDENCY: SEISMIC QUALIFIED VALVE IS NORMALLY OPEN, ALLOWING
 FLOW TO UNQUAL RBCCW

UNDESIRABLE RESULT: LOSS OF EMERGENCY SERVICE WATER

REMARKS: VALVES WERE LOCKED CLOSED-OPERATORS TRAINED FOR
 APPROPRIATE RESPONSE DURING LOP

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY:20

REFERENCES: L2025 EVENT NO 139

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: PEACH BOTTOM 2 PLANT TYPE: GE EWR
 EVENT DATE: 4/17/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

HIGH PRESSURE COOLANT INJECTION (BWR)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

SECONDARY CONTAINMENT (BWR)
 STRUCTURAL FUNCTION ITEMS

CONDUIT AND CABLE TRAY
 ELECTRICAL CONDUCTORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

MULTIPLE ESF SYSTEMS
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: SECONDARY CONTAINMENT (BWR)

RESULT TYPE: 1,3 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: HPCI STEAM SUPPLY LINE BREAK IN OUTBOARD ISOLATION
 VALVE ROOM

PROPAGATION: OVERPRESSURES CONCRETE BLOCK WALL. MAY CAUSE WALL
 TO FAIL

DEPENDENCY: BLOCK WALL SUPPORTS CONDUITS CONTAINING ENGINEERED
 SAFEGUARD CABLES

UNDESIRABLE RESULT: PIPEBREAK IN HPCI LINE DEGRADES ENGINEERED
 SAFEGUARD SYSTEMS

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 23

REFERENCES: L0040 EVENT NO 140

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: PILGRIM 1 PLANT TYPE: GE BWR
 EVENT DATE: 8/16/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MEDIUM VOLTAGE AC (35KV TO 600V)
 CIRCUIT BREAKER/FUSES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

MEDIUM VOLTAGE AC (35KV TO 600V)
 SUBSYSTEM OCCURRENCE

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 2,4 DISCOVERY: UNKNOWN

INITIATING EVENT: SEISMIC EVENT CAUSES LOSS AND FAILURE TO TRIP OF
 AUXILIARY TRANSFORMER BREAKERS

PROPAGATION: DIESEL GENERATOR BREAKERS FAIL TO AUTO CLOSE DUE
 TO A.T. BKRS FAILING CLOSED

DEPENDENCY: DG BKRS DEPEND ON SUCCESSFUL TRIP OF NON SEISMIC
 AUX TRANSFORMER BREAKERS

UNDESIRABLE RESULT: SEISMIC EVENT CAN CAUSE LOSS OF OFFSITE AND
 EMERGENCY POWER

REMARKS: SEISMICALLY QUALIFIED TRIP BREAKERS TO BE SUPPLIED

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 20

REFERENCES: L0046 EVENT NO 141

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: PILGRIM 1 PLANT TYPE: GE BWR
 EVENT DATE: 1/21/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

CONDUIT AND CABLE TRAY
 ELECTRICAL CONDUCTORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

MULTIPLE SAFETY SYSTEMS
 ELECTRICAL CONDUCTORS

MULTIPLE SAFETY SYSTEMS
 ELECTRICAL CONDUCTORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

MULTIPLE SAFETY SYSTEMS
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: CONTROL BUILDING

RESULT TYPE: 1 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: FIRES IN CERTAIN AREAS OF THE PLANT (UNSPECIFIED
 LOCATIONS)

PROPAGATION: ADEQUATE SEPARATION WAS NOT PROVIDED FOR REDUNDANT
 ECCS DIVISION CABLING

DEPENDENCY: COMMON LOCATION FOR REDUNDANT ECCS CABLES

UNDESIRABLE RESULT: SINGLE FIRE COULD FAIL REDUNDANT ECCS DIVISIONS

REMARKS: DOESN'T ADDRESS RHR. FIRE WOULDN'T CAUSE LOCA BUT
 MIGHT REQUIRE RHR

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 15

REFERENCES: L0007

EVENT NO 142

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: PILGRIM 1 PLANT TYPE: GE BWR
 EVENT DATE: 10/08/1981 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

TURBINE BUILDING
 STRUCTURAL FUNCTION ITEMS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

TURBINE BUILDING
 STRUCTURAL FUNCTION ITEMS

RESIDUAL HEAT REMOVAL (BWR)
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

RESIDUAL HEAT REMOVAL (BWR)
 TOTAL SYSTEM OCCURRENCE

REACTOR CORE ISOLATION COOLING (BWR)
 TOTAL SYSTEM OCCURRENCE

MULTIPLE SAFETY SYSTEMS
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: TURBINE BUILDING

RESULT TYPE: 1 DISCOVERY: SPECIAL TEST/INSPECTION

INITIATING EVENT: TORNADO, SEISMIC, OR PIPE BREAK OUTSIDE CNMT
 COLLAPSE MASONRY WALLS

PROPAGATION: COLLAPSE OF WALLS DAMAGES OR FAILS SAFETY-RELATED
 COMP, ELECTRIC POWER, CONTROLS

DEPENDENCY: TURBINE & REACTOR BLDG MASONARY WALLS ARE LOCATED
 NEAR SAFETY-RELATED EQUIPMENT

UNDESIRABLE RESULT: FAILURE OF NUMEROUS SAFETY & SAFETY-RELATED
 SYSTEMS

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 21

REFERENCES: L1033 L0167

EVENT NO 143

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: POINT BEACH 1 PLANT TYPE: WEST PWR
 EVENT DATE: 3/27/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

PRIMARY COOLANT (PWR)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CONTAINMENT ISOLATION
 VALVES

PRIMARY CONTAINMENT (PWR)
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

CONTAINMENT ISOLATION
 VALVES

PRIMARY CONTAINMENT (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: LOCA OCCURRING DURING CONTAINMENT PURGE OPERATIONS

PROPAGATION: ALL CONTAINMENT ISOLATION VALVES FOR PURGE
 SUBJECTED TO LOCA AND FAIL TO CLOSE

DEPENDENCY: DELTA P FROM LOCA IN CONTAINMENT GREATER THAN
 DESIGN FOR CLOSURE FROM FULL OPEN

UNDESIRABLE RESULT: LOCA DURING PURGING RESULTS IN LOSS OF CONTAINMENT
 ISOLATION CAPABILITY

REMARKS: PURGING WAS RESTRICTED TO LOW PRESSURE CONDITIONS
 FOR RCS

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 9

REFERENCES: L0157

EVENT NO 144

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: POINT BEACH 1 PLANT TYPE: WEST PWR
 EVENT DATE: 7/14/1981 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

CONTROL BUILDING
 STRUCTURAL FUNCTION ITEMS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CONTROL BUILDING
 STRUCTURAL FUNCTION ITEMS

DC POWER
 BATTERIES/CHARGERS

SAFETY SYSTEMS/COMPONENTS AFFECTED

DC POWER
 BATTERIES/CHARGERS

CONTROL ROOM PANELS
 ELECTRICAL/I&C FUNCTION ITEMS

TYPE OF COUPLING: SPATIAL PLANT AREA: CONTROL BUILDING

RESULT TYPE: 1,3 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: SEISMIC EVENT STRONG ENOUGH TO COLLAPSE SEVERAL
 BLOCK WALLS IN THE CONTROL BLDG

PROPAGATION: WALLS COLLAPSE DAMAGING BATTERIES, ELECTRICAL
 PANELS, AND CONTROL BOARDS

DEPENDENCY: WALLS DO NOT MEET REVISED SEISMIC CRITERIA

UNDESIRABLE RESULT: POTENTIAL LOSS OF SAFETY EQUIPMENT NEEDED FOR A
 SAFE SHUTDOWN

REMARKS: RESULT OF IE BULLETIN 80-11 INVESTIGATION

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 21

REFERENCES: L0169 I-024 EVENT NO 145

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: POINT BEACH 2 PLANT TYPE: WEST PWR
 EVENT DATE: 12/19/1974 EXPERIENCE: ACTUAL
 OPERATING STATUS: REFUELING

INITIATING SYSTEM AND COMPONENT

INTERMEDIATE PRESSURE INJECTION (PWR)
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

RESIDUAL HEAT REMOVAL (PWR)
 TOTAL SYSTEM OCCURRENCE

PRIMARY COOLANT (PWR)
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

RESIDUAL HEAT REMOVAL (PWR)
 TOTAL SYSTEM OCCURRENCE

PRIMARY COOLANT (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: HUMAN

RESULT TYPE: 4 DISCOVERY: ROUTINE TEST/INSPECTION

INITIATING EVENT: PROCEDURES WERE NOT REVIEWED AFTER TWO MANUAL
 VALVES WERE PUT BETWEEN 2 SI BANKS

PROPAGATION: VALVES WERE LEFT OPEN DURING A SI PUMP TEST

DEPENDENCY: FUNCTIONAL DEPENDENCY BETWEEN RCS AND RHR
 INTRODUCED BY HUMAN ERROR

UNDESIRABLE RESULT: RHR AND RCS WERE MOMENTARILY PRESSURIZED TO 1400
 PSIG

CORRECTIVE ACTION: OTHER

CATEGORY: 19

REFERENCES: L2024

EVENT NO 146

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: POINT BEACH 2 PLANT TYPE: WEST PWR
 EVENT DATE: 3/27/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

PRIMARY COOLANT (PWR)
 PIPES/PITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CONTAINMENT ISOLATION
 VALVES

PRIMARY CONTAINMENT (PWR)
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

CONTAINMENT ISOLATION
 VALVES

PRIMARY CONTAINMENT (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: LOCA OCCURRING DURING CONTAINMENT PURGE OPERATIONS

PROPAGATION: ALL CONTAINMENT ISOLATION VALVES FOR PURGE
 SUBJECTED TO LOCA AND FAIL TO CLOSE

DEPENDENCY: DELTA P FROM LOCA IN CONTAINMENT GREATER THAN
 DESIGN FOR CLOSURE FROM FULL OPEN

UNDESIRABLE RESULT: LOCA DURING PURGING RESULTS IN LOSS OF CONTAINMENT
 ISOLATION CAPABILITY

REMARKS: PURGING WAS RESTRICTED TO LOW PRESSURE CONDITIONS
 FOR RCS

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 9

REFERENCES: L0157 EVENT NO 147

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: PRAIRIE ISLAND 1 PLANT TYPE: WEST PWR
 EVENT DATE: 8/30/1975 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

RESIDUAL HEAT REMOVAL (PWR)
 MISCELLANEOUS EQUIPMENT

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

RESIDUAL HEAT REMOVAL (PWR)
 SUBSYSTEM OCCURRENCE

RESIDUAL HEAT REMOVAL (PWR)
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

RESIDUAL HEAT REMOVAL (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: REACTOR AUXILIARY BUILDING

RESULT TYPE: 1 DISCOVERY: SPECIAL TEST/INSPECTION

INITIATING EVENT: LEAKAGE IN RHR PIT

PROPAGATION: FLOODING/LEAKAGE WOULD AFFECT BOTH TRAINS OF RHR

DEPENDENCY: PATHS EXIST FOR FLOW TO LEAK INTO PIT FOR
 REDUNDANT RHR EQUIPMENT

UNDESIRABLE RESULT: DEGRADATION OR LOSS OF RHR DUE TO SINGLE EVENT

REMARKS: JUNCTION BOXES SEALED, PENETRATIONS SHIELDED, VENT
 DUCT RAISED

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 4

REFERENCES: L0016 EVENT NO 148

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: PRAIRIE ISLAND 1 PLANT TYPE: WEST PWR
 EVENT DATE: 4/12/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

PRESSURIZER (PWR)
 I&C/CONTROLLERS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

PRESSURIZER (PWR)
 I&C/CONTROLLERS

ENGINEERED SAFETY FEATURES ACTUATION
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

ENGINEERED SAFETY FEATURES ACTUATION
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: SMALL LOCA CAUSES PRESSURIZER PRESSURE DROP BUT
 PZR LEVEL REMAINS UNCHANGED

PROPAGATION: SMALL LOCA MAY NOT CAUSE PZR LEVEL DECREASE

DEPENDENCY: SAFETY INJECTION ACTUATION REQUIRES COINCIDENT LOW
 PRESSURE AND LEVEL IN PZR

UNDESIRABLE RESULT: AUTO ACTUATION OF REQD SAFETY SYSTEM DOES NOT
 OCCUR

REMARKS: PROCEDURE WAS REVISED TO REQUIRE MANUAL ACTUATION
 ON LOW PRESSURE

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY:22

REFERENCES: L0050 EVENT NO 149

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: QUAD CITIES 1 PLANT TYPE: GE BWR
 EVENT DATE: 6/10/1972 EXPERIENCE: ACTUAL
 OPERATING STATUS: COLD SHUTDOWN

INITIATING SYSTEM AND COMPONENT

CIRCULATING WATER (OPEN CYCLE)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CIRCULATING WATER (OPEN CYCLE)
 PIPES/FITTINGS

ESSENTIAL RAW COOLING/ SERVICE WATER
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

ESSENTIAL RAW COOLING/ SERVICE WATER
 PUMPS

EMERGENCY GENERATOR COOLING
 PUMPS

TYPE OF COUPLING: SPATIAL PLANT AREA: TURBINE BUILDING

RESULT TYPE: 2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: MAINT ERROR SHUT CIRC WATER VALVE-WATER HAMMER
 RUPTURED RUBBER EXP JOINT

PROPAGATION: TURBINE BLDG FLOODED AFFECTING RHR SERVICE WATER &
 DIESEL COOLING WATER PUMPS

DEPENDENCY: SW AND DIESEL COOLING PUMPS ARE LOCATED IN
 CONDENSER PUMP ROOM WITH NONSAFETY EQ

UNDESIRABLE RESULT: LOSS OF SW THUS RHR. LOSS DIESEL COOLING THUS
 DIESELS 1 AND 1/2 (SWING DIESEL)

REMARKS: CHANGES: SAFETY-REL EQ IN WATER-TIGHT VAULTS,
 FLOOD ALARMS WITH CIRC PUMP TRIPS

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 23

REFERENCES: L1043 EVENT NO 150

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: QUAD CITIES 1 PLANT TYPE: GE BWR
 EVENT DATE: 12/30/1976 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

CONTROL AND SERVICE AIR
 SUBSYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

ESSENTIAL RAW COOLING/ SERVICE WATER
 SUBSYSTEM OCCURRENCE

ESSENTIAL RAW COOLING/ SERVICE WATER
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

ESSENTIAL RAW COOLING/ SERVICE WATER
 TOTAL SYSTEM OCCURRENCE

RESIDUAL HEAT REMOVAL (BWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: MAINTENANCE WORK LEFT AIR SYSTEM CONNECTION TO
 SERVICE WATER PUMP SUCTION VALVE

PROPAGATION: AIR LEAKED INTO COMMON HEADER FOR RHR SERVICE
 WATER

DEPENDENCY: AIR BINDING OF ALL SERVICE WATER PUMPS POSSIBLE
 DUE TO COMMON SUCTION

UNDESIRABLE RESULT: MAINTENANCE ERROR RESULTED IN DEGRADATION OF
 REDUNDANT EQUIPMENT

REMARKS: DATE GIVEN IS REPORT DATE

CORRECTIVE ACTION: OTHER

CATEGORY: 2

REFERENCES: L0179

EVENT NO 151

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: QUAD CITIES 1 PLANT TYPE: GE BWR
 EVENT DATE: 6/22/1982 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

HIGH VOLTAGE AC (GREATER THAN 35KV)
 TOTAL SYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

HIGH VOLTAGE AC (GREATER THAN 35KV)
 TOTAL SYSTEM OCCURRENCE

EMERGENCY POWER GENERATION
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 I&C/RELAYS

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,4 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: UNIT 2 LO SP WHILE UNIT 1 DG OOS, LEAVING DG1/2 &
 DG2 FOR EMERGENCY PWR BOTH UNITS

PROPAGATION: DG1/2 TRIPPED UPON RHR SW PMP START DUE TO
 UNBLOCKED PROTECTIVE RELAY SIGNAL

DEPENDENCY: DG PROTECTIVE RELAY NOT BLOCKED DURING AUTO-START
 SEQUENCE

UNDESIRABLE RESULT: UNIT 1 NO DG, (BUT HAD OFFSITE PWR), UNIT 2 ONLY ONE
 DG W/NO OFF-SITE POWER

REMARKS: PRIMARY SOURCE OF OFFSITE POWER DOWN FOR ELECTIVE
 MAINTENANCE

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 1

REFERENCES: M1004 L0133 EVENT NO 152

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: QUAD CITIES 2 PLANT TYPE: GE BWR
EVENT DATE: 5/21/1979 EXPERIENCE: POTENTIAL
OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

CONDUIT AND CABLE TRAY
ELECTRICAL/I&C FUNCTION ITEMS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

MEDIUM VOLTAGE AC (35KV TO 600V)
ELECTRICAL CONDUCTORS

MEDIUM VOLTAGE AC (35KV TO 600V)
ELECTRICAL CONDUCTORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

MEDIUM VOLTAGE AC (35KV TO 600V)
TOTAL SYSTEM OCCURRENCE

ALL ESF SYSTEMS
TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: CONTROL BUILDING

RESULT TYPE: 1 DISCOVERY: SPECIAL TEST/INSPECTION

INITIATING EVENT: DAMAGE TO CABLE TRAYS (FIRE, IMPACT, ETC.)

PROPAGATION: REDUNDANT ESS DIVISIONS FAIL DUE TO LOSS OF POWER

DEPENDENCY: BOTH DIVISIONS OF ENGINEERED SAFEGUARD SYSTEM
POWER CABLES IN SAME TRAY

UNDESIRABLE RESULT: FAILURE OF REDUNDANT PORTIONS OF ESS WILL AFFECT
MULTIPLE SAFETY SYSTEMS

REMARKS: SPECIFIC SAFETY SYSTEMS NOT NAMED

CORRECTIVE ACTION: REPAIR/REPLACEMENT CATEGORY: 15

REFERENCES: L0008 EVENT NO 153

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: RANCHO SECO PLANT TYPE: B&W PWR
 EVENT DATE: 9/20/1974 EXPERIENCE: ACTUAL
 OPERATING STATUS: PREOPERATIONAL/STARTUP/POWER ASCENSION TESTS

INITIATING SYSTEM AND COMPONENT

VITAL INSTRUMENT, CONTROL, AND COMPUTER AC
 ELECTRICAL CONDUCTORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

VITAL INSTRUMENT, CONTROL, AND COMPUTER AC
 SUBSYSTEM OCCURRENCE

NON-NUCLEAR INSTRUMENTATION
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

NON-NUCLEAR INSTRUMENTATION
 SUBSYSTEM OCCURRENCE

PRIMARY COOLANT (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 4 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: DURING MAINTENANCE TO CORRECT A SHORT CIRCUIT AN
 INVERTER WAS DISCONNECTED

PROPAGATION: SEVERAL FLOW CONTROLLERS AND RECORDERS DID NOT
 FUNCTION

DEPENDENCY: MULTIPLE CONTROL DEVICES AND OPERATOR DISPLAYS
 DEPENDED ON SINGLE POWER SOURCE

UNDESIRABLE RESULT: FAILURES CAUSE PRESSURE TRANSIENT TO 2400 PSIG AND
 INHIBITED RECOVERY

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 22

REFERENCES: L0018

EVENT NO 154

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: RANCHO SECO PLANT TYPE: B&W PWR
 EVENT DATE: 3/20/1978 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

DC POWER
 ELECTRICAL/I&C FUNCTION ITEMS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

MULTIPLE SYSTEMS
 I&C/INDICATORS

MULTIPLE SYSTEMS
 I&C/CONTROLLERS

SAFETY SYSTEMS/COMPONENTS AFFECTED

PRIMARY COOLANT (PWR)
 VESSELS

AUXILIARY FEEDWATER (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 4 DISCOVERY: MAINTENANCE/MODIFICATION

INITIATING EVENT: LOSS OF POWER TO 4 DC POWER SUPPLIES FOR NNI DUE
 TO MAINTENANCE ERROR

PROPAGATION: OPERATORS AND ICS RECEIVED FAULTY INFORMATION-MAIN
 PW FLOW WENT TO ZERO

DEPENDENCY: CONTROL ROOM NNI AND ICS SIGNALS LOST UPON LOSS OF
 DC RELAY POWER

UNDESIRABLE RESULT: RX TRANSIENT WITH ERRONEOUS RCS AND PLANT
 INDICATION AND LACK OF CONTROL

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 14

REFERENCES: L0130 M1005 EVENT NO 155

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: RANCHO SECO PLANT TYPE: B&W PWR
 EVENT DATE: 11/01/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

HIGH VOLTAGE AC (GREATER THAN 35KV)
 TOTAL SYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

HIGH VOLTAGE AC (GREATER THAN 35KV)
 TOTAL SYSTEM OCCURRENCE

MEDIUM VOLTAGE AC (35KV TO 600V)
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

MEDIUM VOLTAGE AC (35KV TO 600V)
 TOTAL SYSTEM OCCURRENCE

MULTIPLE SAFETY SYSTEMS
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 2 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: LOW VOLTAGE ON THE OFFSITE POWER GRID

PROPAGATION: CAN CAUSE LOSS OF ONSITE POWER DISTRIBUTION DUE TO
 UNDERVOLTAGE RELAY SETPTS

DEPENDENCY: DESIGN ERROR DID NOT ADDRESS LOW ENOUGH POTENTIAL
 GRID VOLTAGE

UNDESIRABLE RESULT: NONSAFETY OFFSITE POWER SYSTEM CAN DEGRADE ONSITE
 POWER DISTRIBUTION

REMARKS: DISCOVERED IN REVIEW REQUESTED BY NRC

CORRECTIVE ACTION: OTHER CATEGORY: 1

REFERENCES: L0044 EVENT NO 156

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: RANCHO SECO PLANT TYPE: B&W PWR
 EVENT DATE: 2/19/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MATERIAL AND EQUIPMENT HANDLING
 HANDLING EQUIPMENT

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

MATERIAL AND EQUIPMENT HANDLING
 HANDLING EQUIPMENT

REACTOR VESSEL
 VESSELS

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR VESSEL
 VESSELS

MULTIPLE SYSTEMS
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: SLING ON RB POLAR CRANE BROKE-3000 LB LOAD FELL
 INTO FUEL TRANSFER CANAL

PROPAGATION: LOAD STRUCK REACTOR VESSEL SEAL PLATE, SHEARING
 OFF A STUD AND BOLT

DEPENDENCY: CRANE CAN TRANSPORT LOADS DIRECTLY ABOVE MANY
 SAFETY-RELATED ITEMS IN RX BLDG

UNDESIRABLE RESULT: DROPPED LOADS COULD DAMAGE RX VESSEL & INTERNALS,
 CR DRIVES, AND SPENT FUEL RODS

REMARKS: DROPPING LOAD INTO RX VESSEL COULD HAVE LEAD TO
 DAMAGE TO INTERNALS

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY:23

REFERENCES: L1018

EVENT NO 157

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ROBINSON 2 PLANT TYPE: WEST PWR
 EVENT DATE: 5/01/1975 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

PRIMARY COOLANT (PWR)
 MECHANICAL FUNCTION ITEMS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

PRIMARY COOLANT (PWR)
 PUMPS

SEAL WATER
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

PRIMARY COOLANT (PWR)
 PUMPS

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: RCP C SHAFT SEAL FAILED, ASSOCIATED SEAL LEAKOFF
 ISOL VALVE WAS NOT CLOSED

PROPAGATION: SEAL LEAKOFF FLOW BACK-PRESSURED RCP A&B LEAKOFF
 PREVENTING SEAL LEAKOFF FLOW

DEPENDENCY: COMMON SEAL LEAKOFF LINE CAUSED INTERACTION AMONG
 REACTOR COOLANT PUMPS

UNDESIRABLE RESULT: LOSS OF CAPABILITY TO OPERATE UNDAMAGED REACTOR
 COOLANT PUMPS

REMARKS: RCP C WAS RUN TO EQUALIZE RCS CONDITIONS, SEAL
 DEGRADED, CAUSED LOSS

CORRECTIVE ACTION: ADMINISTRATIVE PROCEDURE CHANGE CATEGORY: 22

REFERENCES: M1007

EVENT NO 158

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ROBINSON 2 PLANT TYPE: WEST PWR
 EVENT DATE: 6/13/1977 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

CONTROL AND SERVICE AIR
 SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CVCS/HIGH PRESSURE SAFETY INJECTION
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: RUPTURED DIAPHRAGM IN CHARGING PUMP SUCTION VALVE

PROPAGATION: AIR ENTERED COMMON SUCTION, CAUSING AIR BINDING OF
 TWO CHARGING PUMPS

DEPENDENCY: COMMON SUCTION FOR CHARGING PUMP SUBJECT TO AIR
 INTRUSION

UNDESIRABLE RESULT: FAILURE OF, AND POTENTIAL FOR DAMAGE TO, REDUNDANT
 CHARGING PUMPS

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 2

REFERENCES: L0165 EVENT NO 159

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ROBINSON 2 PLANT TYPE: WEST PWR
 EVENT DATE: 6/25/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MAIN STEAM
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

STEAM GENERATOR (PWR)
 PIPES/FITTINGS

REACTOR PROTECTION
 I&C/SENSORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR PROTECTION
 SUBSYSTEM OCCURRENCE

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: HIGH ENERGY LINE BREAK IN CONTAINMENT RESULTING IN
 HIGH AMBIENT TEMP

PROPAGATION: HEATUP OF REF LEG, SG LEVEL INSTR FAILS HIGH,
 DELAYS RPS TRIP ON SG LO LO LEVEL

DEPENDENCY: STEAM GENERATOR LEVEL REFERENCE LEG SUBJECTED TO
 HIGH AMBIENT TEMP

UNDESIRABLE RESULT: ACCIDENT DEGRADES SYSTEM REQUIRED TO MITIGATE
 ACCIDENT

REMARKS: ALSO PROVIDES HIGH LEVEL INDICATION TO
 OPERATOR-GENERIC W PROBLEM

CORRECTIVE ACTION: OTHER

CATEGORY: 8

REFERENCES: L0082

EVENT NO 160

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ROBINSON 2 PLANT TYPE: WEST PWR
 EVENT DATE: 1/13/1981 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

ESSENTIAL RAW COOLING/ SERVICE WATER
 HEAT EXCHANGERS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

ESSENTIAL RAW COOLING/ SERVICE WATER
 SUBSYSTEM OCCURRENCE

PRIMARY CONTAINMENT (PWR)
 I&C/TRANSMITTERS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CONTAINMENT ISOLATION
 TOTAL SYSTEM OCCURRENCE

PRIMARY CONTAINMENT (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: UNKNOWN

INITIATING EVENT: SERVICE WATER LEAK DURING LOCA - CNMT PRESSURE
 HIGHER THAN SWS PRESSURE

PROPAGATION: RAD CONTAMINATION ENTERS SW SYSTEM AND IS CARRIED
 OUTSIDE CONTAINMENT VIA SW

DEPENDENCY: SWS AT LOWER PRESSURE THAN CNMT, NO RADIATION
 MONITORS ON SWS

UNDESIRABLE RESULT: LOSS OF CNMT INTEGRITY WITH UNMONITORED RELEASE
 PATH DURING LOCA

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 22

REFERENCES: LG033 L0034 EVENT NO 161

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ROBINSON 2 PLANT TYPE: WEST PWR
 EVENT DATE: 1/29/1981 EXPERIENCE: ACTUAL
 OPERATING STATUS: HOT SHUTDOWN

INITIATING SYSTEM AND COMPONENT

CONTAINMENT ISOLATION
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CONTAINMENT ISOLATION
 VALVES

CVCS/HIGH PRESSURE SAFETY INJECTION
 VALVES

SAFETY SYSTEMS/COMPONENTS AFFECTED

CVCS/HIGH PRESSURE SAFETY INJECTION
 SUBSYSTEM OCCURRENCE

PRIMARY COOLANT (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 3 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: AUTOMATIC ISOLATION OF CVCS LETDOWN LINE AFTER
 SPURIOUS SAFETY INJECTION

PROPAGATION: OUTER ISOL VLVS CLOSED FASTER THAN INNER
 VLVS-SURGE BLEW OFF END CAP

DEPENDENCY: OPERATOR HAD NO INDICATION OF LETDOWN FLOW.
 LETDOWN RESTARTED.

UNDESIRABLE RESULT: LOCA-6000 GAL OF REACTOR COOLANT RELEASED TO
 CONTAINMENT

REMARKS: END CAP LOCATED BETWEEN INNER AND OUTER ISOL VLVS

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY:22

REFERENCES: L5003 EVENT NO 162

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ROBINSON 2 PLANT TYPE: WEST PWR
 EVENT DATE: 4/19/1983 EXPERIENCE: ACTUAL
 OPERATING STATUS: ROUTINE SHUTDOWN

INITIATING SYSTEM AND COMPONENT

CONDENSATE AND FEEDWATER
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CONDENSATE AND FEEDWATER
 SUBSYSTEM OCCURRENCE

AUXILIARY FEEDWATER (PWR)
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

AUXILIARY FEEDWATER (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: AFW DISCH CHK VALVES AND MOTOR OPER ISOL VALVE
 LEAKED MAIN FW INTO AFW SYSTEM

PROPAGATION: HI PRESS/TEMP FEEDWATER FLASHED TO STEAM IN AFW
 PUMPS

DEPENDENCY: AFW PUMPS RELY ON ISOL VALVES TO PREVENT STEAM
 INTRUSION

UNDESIRABLE RESULT: LOSS OF AFW WHEN PUMPS TRIPPED ON LOW DISCHARGE
 PRESS DUE TO STEAM BINDING

CORRECTIVE ACTION: REPAIR/REPLACEMENT

CATEGORY: 2

REFERENCES: I-294

EVENT NO 163

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SALEM 1 PLANT TYPE: WEST PWR
 EVENT DATE: 2/06/1975 EXPERIENCE: ACTUAL
 OPERATING STATUS: CONSTRUCTION

INITIATING SYSTEM AND COMPONENT

EQUIPMENT DRAINAGE (INCLUDING VENTS)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

TURBINE BUILDING
 STRUCTURAL FUNCTION ITEMS

REACTOR AUXILIARY BUILDING
 STRUCTURAL FUNCTION ITEMS

SAFETY SYSTEMS/COMPONENTS AFFECTED

VITAL INSTRUMENT, CONTROL, AND COMPUTER AC
 ELECTRICAL CONDUCTORS

TYPE OF COUPLING: SPATIAL PLANT AREA: REACTOR AUXILIARY BUILDING

RESULT TYPE: 4 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: SEVERE STORM CAUSED HIGH WATER CONDITION IN
 DELAWARE RIVER

PROPAGATION: WATER BACKED THROUGH A 24-INCH LINE IN THE
 INCOMPLETE SUMP PUMP SYSTEM

DEPENDENCY: WATER FLOWED INTO TURBINE BLDG AND THRU A
 CONSTRUCTION BLOCKOUT INTO AUX BLDG

UNDESIRABLE RESULT: VITAL BUS AND 2-4KV BREAKERS IN AUX BLDG WERE
 DAMAGED BY ARCING DUE TO WATER

CORRECTIVE ACTION: OTHER

CATEGORY: 4

REFERENCES: L2032

EVENT NO 164

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SALEM 1 PLANT TYPE: WEST PWR
 EVENT DATE: 11/07/1978 EXPERIENCE: ACTUAL
 OPERATING STATUS: COLD SHUTDOWN

INITIATING SYSTEM AND COMPONENT

RESIDUAL HEAT REMOVAL (PWR)
 MISCELLANEOUS EQUIPMENT

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

RESIDUAL HEAT REMOVAL (PWR)
 MISCELLANEOUS EQUIPMENT

RADIATION MONITORING
 I&C/SENSORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

ESSENTIAL RAW COOLING/ SERVICE WATER
 VALVES

REACTOR BUILDING HVAC (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: REACTOR AUXILIARY BUILDING

RESULT TYPE: 1 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: HIGH BACKGROUND RADIATION TRIPS SERVICE WATER
 RADIATION MONITORS

PROPAGATION: SW VALVES ISOLATE COOLING WATER TO CONTAINMENT FAN
 COIL UNITS

DEPENDENCY: SW RAD MONITORS ARE LOCATED NEAR RHR PIPING WHICH
 IS RADIOACTIVE

UNDESIRABLE RESULT: FAN COIL UNITS INOPERABLE

CORRECTIVE ACTION: OTHER CATEGORY: 23

REFERENCES: L1009 EVENT NO 165

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SALEM 1 PLANT TYPE: WEST PWR
 EVENT DATE: 7/10/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MAIN STEAM
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

STEAM GENERATOR (PWR)
 PIPES/FITTINGS

REACTOR PROTECTION
 I&C/SENSORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR PROTECTION
 SUBSYSTEM OCCURRENCE

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: HIGH ENERGY LINE BREAK IN CONTAINMENT RESULTING IN
 HIGH AMBIENT TEMP

PROPAGATION: HEATUP OF REF LEG, SG LEVEL INSTR FAILS HIGH,
 DELAYS RPS TRIP ON SG LO LO LEVEL

DEPENDENCY: STEAM GENERATOR LEVEL REFERENCE LEG SUBJECTED TO
 HIGH AMBIENT TEMP

UNDESIRABLE RESULT: ACCIDENT DEGRADES SYSTEM REQUIRED TO MITIAGE
 ACCIDENT

REMARKS: ALSO PROVIDES HIGH LEVEL INDICATION TO
 OPERATOR-GENERIC W PROBLEM

CORRECTIVE ACTION: OTHER

CATEGORY: 8

REFERENCES: L0076

EVENT NO 166

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SALEM 1 PLANT TYPE: WEST PWR
 EVENT DATE: 9/07/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

CONDENSATE AND FEEDWATER
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CONDENSATE AND FEEDWATER
 PIPES/FITTINGS

STEAM GENERATOR PRESSURE RELIEF (PWR)
 I&C/CONTROLLERS

SAFETY SYSTEMS/COMPONENTS AFFECTED

STEAM GENERATOR PRESSURE RELIEF (PWR)
 SUBSYSTEM OCCURRENCE

AUXILIARY FEEDWATER (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: HIGH ENERGY LINE BREAK (FEEDWATER) NEAR SG PORV
 CONTROL SYSTEM

PROPAGATION: ADVERSE ENVIRONMENT CAUSES SG PORV FAILURE

DEPENDENCY: SG PORV CONTROLS SUSCEPTIBLE TO HELB CONDITIONS
 AND LOCATED IN HELB AREA.

UNDESIRABLE RESULT: OPERATOR ACTIONS ARE REQUIRED TO MITIGATE
 POTENTIAL SG PORV FAILURE AND APW LOSS

REMARKS: OTHER THREE GENERIC W CONCERNS (PZR PORV, MPW, AND
 ROD CONTROL) NOT AT SALEM

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 10

REFERENCES: L0090 I-277

EVENT NO 167

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SALEM 1 PLANT TYPE: WEST PWR
 EVENT DATE: 5/21/1981 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

CVCS/HIGH PRESSURE SAFETY INJECTION
 I&C/TRANSMITTERS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CVCS/HIGH PRESSURE SAFETY INJECTION
 ACCUMULATORS/RESERVOIRS

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CVCS/HIGH PRESSURE SAFETY INJECTION
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: FAILURE OF VCT LEVEL TRANSMITTER HIGH STOPS
 LETDOWN FLOW CAUSING LOW TANK LEVEL

PROPAGATION: LOSS OF SUCTION DAMAGES MULTIPLE CHG PUMPS SINCE
 FAILURE ALSO STOPS SWITCHOVER

DEPENDENCY: LEVEL TRANSMITTER CONTROLS LEVEL AND SUCTION
 SWITCHOVER TO RWST

UNDESIRABLE RESULT: REDUNDANT CHG PUMPS DAMAGED. THESE PUMPS ARE ALSO
 HI HEAD SAFETY INJECTION.

REMARKS: WESTINGHOUSE NOTIFICATION OF POTENTIAL FAILURE

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 5

REFERENCES: L0150 EVENT NO 168

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SALEM 1 PLANT TYPE: WEST PWR
 EVENT DATE: 11/06/1981 EXPERIENCE: ACTUAL
 OPERATING STATUS: ROUTINE SHUTDOWN

INITIATING SYSTEM AND COMPONENT

LOW VOLTAGE AC (LESS THAN 600V)
 ELECTRICAL CONDUCTORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

LOW VOLTAGE AC (LESS THAN 600V)
 ELECTRICAL CONDUCTORS

VITAL INSTRUMENT, CONTROL, AND COMPUTER AC
 GENERATORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

VITAL INSTRUMENT, CONTROL, AND COMPUTER AC
 GENERATORS

ENGINEERED SAFETY FEATURES ACTUATION
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: MISCELLANEOUS/ UNKNOWN STRUCTURES

RESULT TYPE: 2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: POWER CABLE FOR CABINET FAN CAUSED ELECTROMAGNETIC
 NOISE WHEN ENERGIZING FAN

PROPAGATION: NOISE TRIPPED VITAL INVERTER-LOSS OF BUS PLUS UNIT
 CONDITIONS (LJ T-AVG) GAVE SI

DEPENDENCY: POWER CABLE FOR CABINET FAN IS LOCATED NEAR
 INVERTER (VITAL INSTRUMENT POWER)

UNDESIRABLE RESULT: SPURIOUS TRIPS OF VITAL INVERTER AND LOSS OF POWER
 TO SAFETY-RELATED INSTRUMENTS

REMARKS: COULD BE GENERIC TO ALL INVERTERS AT SALEM-CNMT
 PCU & BIT INLET VALVES FAILED

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 23

REFERENCES: L1037 EVENT NO 169

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SAN ONOPRE 1 PLANT TYPE: WEST PWR
 EVENT DATE: 3/12/1968 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

PRESSURIZER (PWR)
 ELECTRICAL CONDUCTORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

MEDIUM VOLTAGE AC (35KV TO 600V)
 ELECTRICAL CONDUCTORS

MEDIUM VOLTAGE AC (35KV TO 600V)
 ELECTRICAL CONDUCTORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

MULTIPLE SAFETY SYSTEMS
 SUBSYSTEM OCCURRENCE

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

CVCS/HIGH PRESSURE SAFETY INJECTION
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: SECONDARY CONTAINMENT (PWR)

RESULT TYPE: 1 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: FIRE IN ELECTRICAL PENETRATION CAUSED BY
 OVERLOADED PZR HEATER CABLES

PROPAGATION: FIRE CAUSED GROUND ON A BUS AND REQUIRED ISOLATING
 ENTIRE BUS

DEPENDENCY: UNDAMAGED EQUIPMENT DE-ENERGIZED DUE TO LOCATION
 OF FIRE

UNDESIRABLE RESULT: FIRE AND FIRE FIGHTING DISABLE MULTIPLE EQUIPMENT

REMARKS: PROBLEM DURING SHUTDOWN DUE FAILURE IN BORON
 ADDITION SYSTEM DUE TO FIRE

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 23

REFERENCES: L0177 EVENT NO 170

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SAN ONOPRE 1 PLANT TYPE: WEST PWR
 EVENT DATE: 9/02/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

ENGINEERED SAFETY FEATURES ACTUATION
 MISCELLANEOUS EQUIPMENT

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

ENGINEERED SAFETY FEATURES ACTUATION
 MISCELLANEOUS EQUIPMENT

EMERGENCY POWER GENERATION
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 TOTAL SYSTEM OCCURRENCE

ALL SYSTEMS REQUIRING EMERGENCY POWER
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: SPECIAL TEST/INSPECTION

INITIATING EVENT: SIS FOLLOWED BY USE OF SI BLOCK SWITCH OR RETURN
 TO NORMAL PARAMETERS AND LOSP

PROPAGATION: SIS SEQUENCER WILL NOT RELOAD SAFETY INJECTION
 LOADS

DEPENDENCY: PREVIOUS SHUTOFF OF SIS CAUSES SEQUENCER AND
 EMERGENCY POWER FAILURE

UNDESIRABLE RESULT: SAFETY SYSTEMS FAIL DUE TO LOSS OF POWER

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 1

REFERENCES: L0155

EVENT NO 171

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SAN ONOPRE 1 PLANT TYPE: WEST PWR
 EVENT DATE: 1/16/1981 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

ENGINEERED SAFETY FEATURES ACTUATION
 ELECTRICAL/I&C FUNCTION ITEMS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

MULTIPLE ECCS SYSTEMS
 SUBSYSTEM OCCURRENCE

MULTIPLE ECCS SYSTEMS
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

MULTIPLE ECCS SYSTEMS
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: SAFETY INJECTION ACTUATES AND LOSS OF POWER
 OCCURS. SI PARAMETERS OSCILLATE

PROPAGATION: SEQUENCER WILL RESET IF OSCILLATION OCCURS WITHIN
 21 SECONDS OF LOP

DEPENDENCY: SEQUENCER RESET IS SUSCEPTIBLE TO PARAMETER
 OSCILLATION

UNDESIRABLE RESULT: LOSS OF POWER TO ESF EQUIP- SEQUENCER WILL NOT
 AUTO LOAD EQUIP

REMARKS: THIS DEFECT WAS IDENTIFIED DURING ANALYSIS OF
 EARLIER PROBLEM (9/2/80).

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 1

REFERENCES: L0174

EVENT NO 172

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SAN ONOPRE 1 PLANT TYPE: WEST PWR
 EVENT DATE: 7/17/1981 EXPERIENCE: ACTUAL
 OPERATING STATUS: COLD SHUTDOWN

INITIATING SYSTEM AND COMPONENT

COMPRESSED GAS
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

ESSENTIAL COMPRESSED AIR
 TOTAL SYSTEM OCCURRENCE

COMPRESSED GAS
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

GASEOUS RADWASTE (PWR)
 RECOMBINERS

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 0 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: INST AIR BACK-LEAKAGE (AT APW VALVES) INTO
 NITROGEN SYSTEM

PROPAGATION: HIGH OXYGEN IN WASTE GAS RECOMBINERS-EXPLOSION AND
 TANK DAMAGE PLUS RELEASE

DEPENDENCY: NITROGEN IS BACKUP TO INST AIR FOR SEVERAL
 SAFETY-RELATED VALVES

UNDESIRABLE RESULT: RADIOLOGICAL RELEASE AND DAMAGE TO WASTE GAS EQUIP
 FROM EXPLOSION

REMARKS: NO CHECK VALVES TO SEPARATE NITROGEN AND INST AIR
 WHICH IS AT HIGHER PRESS

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 2

REFERENCES: L2023 I-216

EVENT NO 173

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SAN ONOPRE 2 PLANT TYPE: CE PWR
 EVENT DATE: 1/16/1978 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

PRIMARY COOLANT (PWR)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CONTAINMENT ISOLATION
 VALVES

PRIMARY CONTAINMENT (PWR)
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

CONTAINMENT ISOLATION
 VALVES

PRIMARY CONTAINMENT (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: LOCA OCCURRING DURING CONTAINMENT PURGE OPERATIONS

PROPAGATION: ALL CONTAINMENT ISOLATION VALVES FOR PURGE
 SUBJECTED TO LOCA AND FAIL TO CLOSE

DEPENDENCY: DELTA P FROM LOCA IN CONTAINMENT GREATER THAN
 DESIGN FOR CLJSURE FROM FULL OPEN

UNDESIRABLE RESULT: LOCA DURING PURGING RESULTS IN LOSS OF CONTAINMENT
 ISOLATION CAPABILITY

REMARKS: PRUGING WAS RESTRICTED TO LOW PRESSURE CONDITIONS
 FOR RCS

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 9

REFERENCES: L0158

EVENT NO 174

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SAN ONOPRE 2 PLANT TYPE: CE PWR
 EVENT DATE: 3/14/1982 EXPERIENCE: ACTUAL
 OPERATING STATUS: OTHER

INITIATING SYSTEM AND COMPONENT

CVCS/HIGH PRESSURE SAFETY INJECTION
 PERSONNEL

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CVCS/HIGH PRESSURE SAFETY INJECTION
 PERSONNEL

RESIDUAL HEAT REMOVAL (PWR)
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

RESIDUAL HEAT REMOVAL (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: BACKFLUSHING OF PURIFICATION SYS FILTER WITH N2
 W/O ISOLATING SHUTDOWN COOLING

PROPAGATION: NITROGEN ENTERED RHR SUCTION LINE CAUSING LOSS OF
 SHUTDOWN COOLING

DEPENDENCY: MAINTENANCE OPERATIONS IN NONSAFETY SYSTEM
 CONNECTED TO SAFETY SYSTEM

UNDESIRABLE RESULT: DEGRADATION OF RHR BY ACTIVITIES INVOLVING
 NONSAFETY EQUIPMENT

REMARKS: NO IRRADIATED FUEL WAS IN CORE

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 2

REFERENCES: L0117 I-127 EVENT NO 175

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SAN ONOPRE 3 PLANT TYPE: CE PWR
 EVENT DATE: 1/16/1978 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

PRIMARY COOLANT (PWR)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CONTAINMENT ISOLATION
 VALVES

PRIMARY CONTAINMENT (PWR)
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

CONTAINMENT ISOLATION
 VALVES

PRIMARY CONTAINMENT (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: LOCA OCCURRING DURING CONTAINMENT PURGE OPERATIONS

PROPAGATION: ALL CONTAINMENT ISOLATION VALVES FOR PURGE
 SUBJECTED TO LOCA AND FAIL TO CLOSE

DEPENDENCY: DELTA P FROM LOCA IN CONTAINMENT GREATER THAN
 DESIGN FOR CLJSURE FROM FULL OPEN

UNDESIRABLE RESULT: LOCA DURING PURGING RESULTS IN LOSS OF CONTAINMENT
 ISILATION CAPABILITY

REMARKS: PURGING WAS RESTRICTED TO LOW PRESSURE CONDITIONS
 FOR RCS

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 9

REFERENCES: L0158

EVENT NO 176

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SAN ONOPRE 3 PLANT TYPE: CE PWR
 EVENT DATE: 12/17/1982 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

REACTOR PROTECTION
 ELECTRICAL/I&C FUNCTION ITEMS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

ALL ESP SYSTEMS
 SUBSYSTEM OCCURRENCE

ALL ESP SYSTEMS
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

ALL ESP SYSTEMS
 TOTAL SYSTEM OCCURRENCE

INTERMEDIATE PRESSURE INJECTION (PWR)
 TOTAL SYSTEM OCCURRENCE

CONTAINMENT SPRAY
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: FAILURE OF A SINGLE PIN IN THE PLANT PROTECTION
 SYSTEM

PROPAGATION: DE-ENERGIZES BISTABLE RELAY MATRIX, CAUSING
 ACTUATION OF SIAS AND RAS

DEPENDENCY: SIMULTANEOUS ACTUATION CAUSES ESP SYSTEM TO
 TRANSFER SUCTION TO SUMP PREMATURELY

UNDESIRABLE RESULT: INTERRUPTION OF AND POTENTIAL DAMAGE TO ESP
 COOLING SYSTEMS

REMARKS: IN ACTUAL EVENT, ACTUATION OCCURRED DUE TO
 INDEPENDENT FAILURES-STUDY FOUND PIN

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 6

REFERENCES: L0163 L0156

EVENT NO 177

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SEQUOYAH 1 PLANT TYPE: WEST PWR
 EVENT DATE: 6/29/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MAIN STEAM
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

STEAM GENERATOR (PWR)
 PIPES/FITTINGS

REACTOR PROTECTION
 I&C/SENSORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR PROTECTION
 SUBSYSTEM OCCURRENCE

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: HIGH ENERGY LINE BREAK IN CONTAINMENT RESULTING IN
 HIGH AMBIENT TEMP

PROPAGATION: HEATUP OF REF LEG, SG LEVEL INSTR FAILS HIGH,
 DELAYS RPS TRIP ON SG LO LO LEVEL

DEPENDENCY: STEAM GENERATOR LEVEL REFERENCE LEG SUBJECTED TO
 HIGH AMBIENT TEMP

UNDESIRABLE RESULT: ACCIDENT DEGRADES SYSTEM REQUIRED TO MITIGATE
 ACCIDENT

REMARKS: ALSO PROVIDES HIGH LEVEL INDICATION TO
 OPERATOR-GENERIC W PROBLEM

CORRECTIVE ACTION: OTHER

CATEGORY: 8

REFERENCES: L0072

EVENT NO 178

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SEQUOYAH 1 PLANT TYPE: WEST PWR
 EVENT DATE: 5/25/1980 EXPERIENCE: ACTUAL
 OPERATING STATUS: COLD SHUTDOWN

INITIATING SYSTEM AND COMPONENT

CONDENSATE AND FEEDWATER
 I&C/SWITCHES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CONDENSATE AND FEEDWATER
 I&C/SWITCHES

RESIDUAL HEAT REMOVAL (PWR)
 VALVES

SAFETY SYSTEMS/COMPONENTS AFFECTED

RESIDUAL HEAT REMOVAL (PWR)
 SUBSYSTEM OCCURRENCE

CONTAINMENT SPRAY
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 2 DISCOVERY: ROUTINE TEST/INSPECTION

INITIATING EVENT: LIMIT SWITCH ON FEEDWATER VALVE FAILS TO ACTUATE

PROPAGATION: SWITCH INTERLOCK NOT SATIS, RHR VALVE WON'T
 OPEN, TRAIN OF RHR & CS INOPERABLE

DEPENDENCY: RHR VALVE IS INTERLOCKED (CONTROL LOGIC TO OPEN)
 WITH FEEDWATER VALVE

UNDESIRABLE RESULT: ONE TRAIN (EACH) OF RHR & CONTAINMENT SPRAY
 INOPERABLE

REMARKS: INTERLOCK BETWEEN FEEDWATER AND RHR NOT EXPLAINED

CORRECTIVE ACTION: REPAIR/REPLACEMENT CATEGORY: 22

REFERENCES: L1005 EVENT NO 179

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SEQUOYAH 1 PLANT TYPE: WEST PWR
 EVENT DATE: 6/13/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

PRESSURIZER (PWR)
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CVCS/HIGH PRESSURE SAFETY INJECTION
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: PORV CONTROL FAILURE AFTER SECONDARY SYS HELB
 CAUSES SI ACTUATION

PROPAGATION: RCS PRESSURE HIGHER THAN CHG PUMP DESIGN INJECTION
 PRESS; PUMPS OVERHEAT

DEPENDENCY: RECIRC VALVES PROTECT CHG PUMPS, BUT SIAS CLOSES
 RECIRC VALVES

UNDESIRABLE RESULT: LOSS OF MULTIPLE CHG PUMPS PRIOR TO SI SHUTOFF
 CONDITIONS MET

REMARKS: GENERIC W PROBLEM. PUMP FAILURES DEPENDS ON
 SPECIFIC DESIGN HEAD

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 7

REFERENCES: L0052 I-017

EVENT NO 180

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SEQUOYAH 1 PLANT TYPE: WEST PWR
 EVENT DATE: 11/14/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

REACTOR AUXILIARY BUILDING
 STRUCTURAL FUNCTION ITEMS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

REACTOR AUXILIARY BUILDING
 STRUCTURAL FUNCTION ITEMS

MULTIPLE ECCS SYSTEMS
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

RESIDUAL HEAT REMOVAL (PWR)
 PUMPS

CONTAINMENT SPRAY
 PUMPS

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

TYPE OF COUPLING: SPATIAL PLANT AREA: REACTOR AUXILIARY BUILDING

RESULT TYPE: 1,2 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: SEISMIC EVENT STRONG ENOUGH TO COLLAPSE SEVERAL
 BLOCK WALLS IN THE AUXILIARY BLD

PROPAGATION: WALLS COLLAPSE DAMAGING OR FAILING ALL RHR & CNMT
 SPRAY PUMPS & A CHARGING PUMP

DEPENDENCY: WALLS ARE LOCATED NEAR SAFETY-RELATED EQUIPMENT

UNDESIRABLE RESULT: POTENTIAL LOSS OF SAFETY EQUIPMENT NEEDED FOR A
 SAFE SHUTDOWN

REMARKS: RESULT OF IE BULLETIN 80-11 INVESTIGATION

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 21

REFERENCES: L1039 EVENT NO 181

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SEQUOYAH 1 PLANT TYPE: WEST PWR
 EVENT DATE: 12/12/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

HIGH VOLTAGE AC (GREATER THAN 35KV)
 TOTAL SYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

EMERGENCY GENERATOR I&C
 TOTAL SYSTEM OCCURRENCE

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

ALL SYSTEMS REQUIRING EMERGENCY POWER
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 4 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: LOSS OF OFFSITE POWER WHEN A DIESEL GENERATOR IS
 RUNNING BUT NOT LOADED

PROPAGATION: LOADS NOT STRIPPED FROM BUS; DG BKR CLOSURES TO
 LOADED BUS

DEPENDENCY: WITH DG RUNNING, LOGIC DOES NOT STRIP LOADS PRIOR
 TO CLOSURE OF OUTPUT BREAKER

UNDESIRABLE RESULT: LOSS OF EMERGENCY POWER AFTER LOSS OF OFF SITE
 POWER

REMARKS: LOGIC MODIFIED. PERMISSIVE NOW ASSURES LOAD
 STRIPPING PRIOR TO DG BKR CLOSURE

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 1

REFERENCES: L0112

EVENT NO 182

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SEQUOYAH 1 PLANT TYPE: WEST PWR
 EVENT DATE: 6/18/1982 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

PRIMARY COOLANT (PWR)
 PUMPS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

ENGINEERED SAFETY FEATURES ACTUATION
 I&C/SWITCHES

PRIMARY CONTAINMENT (PWR)
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

CONTAINMENT SPRAY
 TOTAL SYSTEM OCCURRENCE

INTERMEDIATE PRESSURE INJECTION (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 1,3 DISCOVERY: UNKNOWN

INITIATING EVENT: LOSS OF COOLANT ACCIDENT

PROPAGATION: HIGH AMBIENT TEMP, SUMP LEVEL SENSOR BELLOWS-BOIL
 & RUPTURE-FALSE SIGNAL (LOW)

DEPENDENCY: SUMP LEVEL SUSCEPTIBLE TO HI TEMP BUT LOCATED IN
 AREA OF POTENTIAL HI TEMP

UNDESIRABLE RESULT: PREVENTS AUTO SWITCH OF ECCS SUCTION TO SUMP LOCA
 DEGRADES SYS REQ TO RESPOND

REMARKS: FALSE LEVEL SIGNAL WOULD GO TO OPERATOR ALSO,
 POTENTIAL HUMAN RESPONSE ERROR

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 8

REFERENCES: L0028 EVENT NO 183

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SEQUOYAH 1 PLANT TYPE: WEST PWR
 EVENT DATE: 12/01/1983 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

FIRE PROTECTION
 SHOCK SUPPRESSORS AND SUPPORTS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

FIRE PROTECTION
 SHOCK SUPPRESSORS AND SUPPORTS

CONTROL BUILDING HVAC
 HEAT EXCHANGERS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CONTROL BUILDING HVAC
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: CONTROL BUILDING

RESULT TYPE: 1,2 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: SEISMIC EVENT CAUSES PRESSURE BOUNDARY FAILURE IN
 MECH EQMT ROOM FIRE PROTECTION

PROPAGATION: WATER SPRAY COULD DAMAGE ELECTRICAL EQMT,
 DISABLING CONTROL ROOM HVAC CHILLERS

DEPENDENCY: ORIGINAL DESIGN REQUIRED STRUCTURAL, BUT NOT
 PRESSURE BOUNDARY INTEGRITY

UNDESIRABLE RESULT: SEISMIC EVENT WOULD DEGRADE HVAC REQUIRED FOR
 CONTROL ROOM HABITABILITY

REMARKS: PIPING IS NORMALLY DRY, BUT DELUGE VALVE IS
 NONSEISMIC ALSO

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 3

REFERENCES: LO164

EVENT NO 184

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SEQUOYAH 2 PLANT TYPE: WEST PWR
 EVENT DATE: 8/06/1981 EXPERIENCE: ACTUAL
 OPERATING STATUS: COLD SHUTDOWN

INITIATING SYSTEM AND COMPONENT

RESIDUAL HEAT REMOVAL (PWR)
 I&C/RELAYS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

PRIMARY COOLANT (PWR)
 TOTAL SYSTEM OCCURRENCE

RESIDUAL HEAT REMOVAL (PWR)
 VALVES

SAFETY SYSTEMS/COMPONENTS AFFECTED

PRIMARY COOLANT (PWR)
 TOTAL SYSTEM OCCURRENCE

RESIDUAL HEAT REMOVAL (PWR)
 VALVES

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 3 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: RHR-SUMP ISOL VALVE OPENED BECAUSE SOLID STATE
 RELAY CONTACTS WERE REVERSED

PROPAGATION: LEAK PATH EXISTED FROM RCS THRU RHR RECIRCULATION
 PIPING TO CONTAINMENT SUMP

DEPENDENCY: RHR HAS CONNECTION WITH SUMP FOR ECCS
 RECIRCULATION PHASE

UNDESIRABLE RESULT: RCS PRESSURE BOUNDARY BREACHED-8000 GALS. OF
 COOLANT TRANSFERRED TO CNMT SUMP

REMARKS: TEST PROCEDURE INADEQUATE AND SPSS CONTACTS
 REVERSED.

CORRECTIVE ACTION: REPAIR/REPLACEMENT

CATEGORY: 6

REFERENCES: A0011 L0181

EVENT NO 185

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ST. LUCIE 1 PLANT TYPE: CE PWR
 EVENT DATE: 11/25/1975 EXPERIENCE: ACTUAL
 OPERATING STATUS: PREOPERATIONAL/STARTUP/POWER ASCENSION TESTS

INITIATING SYSTEM AND COMPONENT

HIGH VOLTAGE AC (GREATER THAN 35KV)
 TOTAL SYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

LOW VOLTAGE AC (LESS THAN 600V)
 SUBSYSTEM OCCURRENCE

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 2 DISCOVERY: SPECIAL TEST/INSPECTION

INITIATING EVENT: LOSS OF OFF SITE POWER (OCCURRED DELIBERATELY IN
 LOSP TEST)

PROPAGATION: AB BUS FAILED TO LOAD TO ALLOW REPOWERING BY
 EMERGENCY POWER

DEPENDENCY: LOAD SHED RELAY WAS ENERGIZE-TO-ACTUATE AND ONLY
 PROVIDED WITH OFF SITE POWER

UNDESIRABLE RESULT: LOSP PREVENTS BUS LOAD SHEDDING REQUIRED TO
 RE-ENERGIZE BUS

REMARKS: DATE GIVEN IS REPORT DATE

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 1

REFERENCES: L0178

EVENT NO 186

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ST. LUCIE 1 PLANT TYPE: CE PWR
 EVENT DATE: 3/31/1978 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MEDIUM VOLTAGE AC (35KV TO 600V)
 ELECTRICAL/I&C FUNCTION ITEMS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

MEDIUM VOLTAGE AC (35KV TO 600V)
 ELECTRICAL CONDUCTORS

EMERGENCY POWER GENERATION
 ELECTRICAL CONDUCTORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 2 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: SEISMIC EVENT CAUSES FAILURE OF NON CLASS IE
 TRANSFORMER DISCONNECT CONTACTS

PROPAGATION: CONTACTS COULD DISLODGE CAUSING SHORT CIRCUIT ON
 BUS, DEFEATING EMERGENCY POWER

DEPENDENCY: NORMAL AND EMERGENCY POWER SHARE BUS WITH NON
 CLASS IE CONTACTS

UNDESIRABLE RESULT: NONSAFETY SYSTEM CAN CAUSE LOSS OF SAFETY BUS
 DURING SEISMIC EVENT

REMARKS: SAME DESIGN USED AT UNIT 2

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 20

REFERENCES: L0098

EVENT NO 187

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ST. LUCIE 1 PLANT TYPE: CE PWR
 EVENT DATE: 6/11/1980 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

STEAM GENERATOR BLOWDOWN (PWR)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

STEAM GENERATOR BLOWDOWN (PWR)
 PIPES/FITTINGS

COMPONENT COOLING WATER
 ELECTRICAL CONDUCTORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

COMPONENT COOLING WATER
 VALVES

PRIMARY COOLANT (PWR)
 PUMPS

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 4 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: STEAM LEAK FROM FLANGED CONNECTION IN A BLOWDOWN
 LINE

PROPAGATION: STEAM SHORTED TERMINAL BOARD CAUSING CCW VALVE TO
 FAIL CLOSE

DEPENDENCY: TERMINAL BOARD FOR CCW VALVE SUSCEPTIBLE TO
 HUMIDITY LOCATED NEAR A STEAM SOURCE

UNDESIRABLE RESULT: LOSS OF CCW TO REACTOR COOLANT PUMPS & REACTOR
 TRIP

REMARKS: CORRECTIVE ACTION NOT KNOWN

CORRECTIVE ACTION: OTHER

CATEGORY: 23

REFERENCES: A0003

EVENT NO 188

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ST. LUCIE 1 PLANT TYPE: CE PWR
 EVENT DATE: 10/23/1982 EXPERIENCE: ACTUAL
 OPERATING STATUS: ROUTINE SHUTDOWN

INITIATING SYSTEM AND COMPONENT

CVCS/HIGH PRESSURE SAFETY INJECTION
 I&C/CONTROLLERS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CVCS/HIGH PRESSURE SAFETY INJECTION
 PIPES/FITTINGS

CVCS/HIGH PRESSURE SAFETY INJECTION
 VESSELS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CVCS/HIGH PRESSURE SAFETY INJECTION
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 0 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: VOLUME CONTROL TANK LEVEL INSTR REF LEG
 EMPTY, CAUSING LEVEL CONTROL FAILURES

PROPAGATION: DUE TO ERRONEOUS LEVEL INDICATION VCT WAS PUMPED
 DRY AND CHG PUMPS FAILED

DEPENDENCY: VCT FEEDS ALL THREE CHARGING PUMPS AND HAS
 HYDROGEN COVER GAS

UNDESIRABLE RESULT: ALL THREE CHARGING PUMPS BECAME VAPOR BOUND WHEN
 VCT WAS PUMPED DRY

REMARKS: HYDROGEN WAS ADMITTED TO PUMP SUCTIONS

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 5

REFERENCES: L2020 A0021 A0020 I-127 EVENT NO 189

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ST. LUCIE 2 PLANT TYPE: CE PWR
 EVENT DATE: 1/24/1978 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MEDIUM VOLTAGE AC (35KV TO 600V)
 ELECTRICAL/I&C FUNCTION ITEMS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

MEDIUM VOLTAGE AC (35KV TO 600V)
 ELECTRICAL CONDUCTORS

EMERGENCY POWER GENERATION
 ELECTRICAL CONDUCTORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 2,4 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: SEISMIC EVENT CAUSES FAILURE ON NON CLASS IE
 TRANSFORMER DISCONNECT CONTACTS

PROPAGATION: CONTACTS COULD DISLODGE CAUSING SHORT CIRCUIT ON
 BUS, DEFEATING EMERGENCY POWER

DEPENDENCY: NORMAL AND EMERGENCY POWER SHARE BUS WITH NON IE
 CONTACTS

UNDESIRABLE RESULT: NONSAFETY SYSTEM CAN CAUSE LOSS OF SAFETY BUS
 DURING SEISMIC EVENT

REMARKS: SAME DESIGN USED AT UNIT 1

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 20

REFERENCES: L0099

EVENT NO 190

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SURRY 1 PLANT TYPE: WEST PWR
 EVENT DATE: 9/19/1974 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

AUXILIARY FEEDWATER (PWR)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

AUXILIARY FEEDWATER (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: INSTALLATION

INITIATING EVENT: PIPE RUPTURE ON ONE TRAIN OF AUXILIARY FEEDWATER

PROPAGATION: LOSS OF FW FLOW IN ONE TRAIN CAUSES LOSS IN
 REDUNDANT TRAIN

DEPENDENCY: CROSS CONN BETWEEN TRAINS W/O ISOL VALVES ALLOWS
 BREAK TO AFFECT BOTH TRAINS

UNDESIRABLE RESULT: LOSS OF REDUNDANT TRAINS OF APW DUE TO SINGLE
 PIPING FAILURE

REMARKS: ALSO AFFECTS UNIT 2

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 13

REFERENCES: L0017

EVENT NO 191

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SURRY 1 PLANT TYPE: WEST PWR
 EVENT DATE: 1/17/1977 EXPERIENCE: ACTUAL
 OPERATING STATUS: PREOPERATIONAL/STARTUP/POWER ASCENSION TESTS

INITIATING SYSTEM AND COMPONENT

ESSENTIAL RAW COOLING/ SERVICE WATER
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

ESSENTIAL RAW COOLING/ SERVICE WATER
 SUBSYSTEM OCCURRENCE

ESSENTIAL RAW COOLING/ SERVICE WATER
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

ESSENTIAL RAW COOLING/ SERVICE WATER
 TOTAL SYSTEM OCCURRENCE

RESIDUAL HEAT REMOVAL (PWR)
 HEAT EXCHANGERS

TYPE OF COUPLING: SPATIAL PLANT AREA: REACTOR AUXILIARY BUILDING

RESULT TYPE: 1 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: MAINTANENCE LEFT DRAIN VALVES OPEN ON SERVICE
 WATER LINES IN A VALVE PIT

PROPAGATION: WHEN SW ISOL VALVE OPENED, DRAIN VALVES FLOODED
 PIT SUBMERGING VALVE MOTOR OPER

DEPENDENCY: ALL 4 SW VALVES TO RHR HEAT EXCHANGERS LOCATED IN
 SAME PIT-NO LEVEL INSTR IN PIT

UNDESIRABLE RESULT: POTENTIAL LOSS OF SERVICE WATER TO HEAT EXCHANGERS

REMARKS: VALVES OPEN ON ESPAS SIGNAL

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 23

REFERENCES: L1042 M2001

EVENT NO 192

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SURRY 1 PLANT TYPE: WEST PWR
 EVENT DATE: 3/23/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

PRIMARY COOLANT (PWR)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 TOTAL SYSTEM OCCURRENCE

ALL SYSTEMS REQUIRING EMERGENCY POWER
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: LOCA WITH OR WITHOUT LOSS OF OFFSITE POWER

PROPAGATION: POTENTIAL UNDER POWER CONDITION COULD OCCUR ON
 EMERGENCY BUS

DEPENDENCY: DESIGN ERROR ALLOWS BUS FAILURE BY REQUIRING LOAD
 SHEDDING NOT IN PROCEDURES

UNDESIRABLE RESULT: LOCA CAN CAUSE FAILURE OF EMERGENCY BUSES DUE TO
 OVERLOADING

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 1

REFERENCES: L0049

EVENT NO 193

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SURRY 1 PLANT TYPE: WEST PWR
 EVENT DATE: 6/21/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MAIN STEAM
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

STEAM GENERATOR (PWR)
 PIPES/FITTINGS

REACTOR PROTECTION
 I&C/SENSORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR PROTECTION
 SUBSYSTEM OCCURRENCE

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: HIGH ENERGY LINE BREAK IN CONTAINMENT RESULTING IN
 HIGH AMBIENT TEMP

PROPAGATION: HEATUP OF REF LEG, SG LEVEL INSTR FAILS HIGH,
 DELAYS RPS TRIP ON SG LO LO LEVEL

DEPENDENCY: STEAM GENERATOR LEVEL REFERENCE LEG SUBJECTED TO
 HIGH AMBIENT TEMP

UNDESIRABLE RESULT: ACCIDENT DEGRADES SYSTEM REQUIRED TO MITIGATE
 ACCIDENT

REMARKS: ALSO PROVIDES HIGH LEVEL INDICATION TO
 OPERATOR-GENERIC W PROBLEM

CORRECTIVE ACTION: OTHER

CATEGORY: 8

REFERENCES: L0079

EVENT NO 194

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SURRY 1 PLANT TYPE: WEST PWR
 EVENT DATE: 8/29/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MAIN STEAM
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

MAIN STEAM
 PIPES/FITTINGS

STEAM GENERATOR PRESSURE RELIEF (PWR)
 I&C/SENSORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

STEAM GENERATOR PRESSURE RELIEF (PWR)
 SUBSYSTEM OCCURRENCE

PRESSURIZER (PWR)
 SUBSYSTEM OCCURRENCE

REACTOR POWER CONTROL (PWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 0 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: HIGH ENERGY LINE BREAK (FEEDWATER OR STEAM) IN
 SPECIFIC LOCATIONS

PROPAGATION: ADVERSE ENVIRONMENT FROM BREAK CAN CAUSE CONTROL
 SYSTEM FAILURES

DEPENDENCY: SOME CONTROLS(SG PORV,PZR PORV,AUTO ROD CONTROL)
 LOCATED SUBJECT TO BREAK

UNDESIRABLE RESULT: CONTROL FAILURES CONTRIBUTE TO ACCIDENT.
 PROCEDURES CHANGED.

REMARKS: EVENT NOT OUTSIDE EXISTING ANALYSES BUT REPRESENTS
 UNANTICIPATED FAILURE MODES

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY:10

REFERENCES: L0086 L0087 I-277 EVENT NO 195

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SURRY 1 PLANT TYPE: WEST PWR
 EVENT DATE: 5/12/1980 EXPERIENCE: ACTUAL
 OPERATING STATUS: COLD SHUTDOWN

INITIATING SYSTEM AND COMPONENT

ENGINEERED SAFETY FEATURES ACTUATION
 I&C/RELAYS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

BORATED/ REFUELING WATER STORAGE (PWR)
 VALVES

PRIMARY COOLANT (PWR)
 CHEMICAL FUNCTION ITEMS

SAFETY SYSTEMS/COMPONENTS AFFECTED

BORATED/ REFUELING WATER STORAGE (PWR)
 TOTAL SYSTEM OCCURRENCE

PRIMARY COOLANT (PWR)
 CHEMICAL FUNCTION ITEMS

CORE FLOODING ACCUMULATOR (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 4 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: DURING MAINTENANCE A LOCKED-IN SIAS SIGNAL OPENED
 RWST & BIT ISOL VALVES TO RCS

PROPAGATION: RWST GRAVITY FED INTO RCS REDUCING BORON CONC
 WITHOUT CNMT INTEGRITY MAINTD

DEPENDENCY: PROCEDURES DID NOT PRECAUTION AGAINST GRAVITY FLOW
 DURING VALVE CYCLING

UNDESIRABLE RESULT: PRESS IN BOTH SI ACCUMULATORS DEGRADED & RCS BORON
 CONCENTRATION DILUTED

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY:22

REFERENCES: L5005

EVENT NO 196

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SURRY 1 PLANT TYPE: WEST PWR
 EVENT DATE: 6/11/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

PRESSURIZER (PWR)
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CVCS/HIGH PRESSURE SAFETY INJECTION
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: SECONDARY SYS HELB CAUSING SI ACTUATION AND PORV
 CONTROL FAILURE

PROPAGATION: RCS PRESSURE HIGHER THAN CHG PUMP DESIGN INJECTION
 PRESS; PUMPS OVERHEAT

DEPENDENCY: RECIRC VALVES PROTECT CHG PUMPS, BUT SIAS CLOSES
 RECIRC VALVES

UNDESIRABLE RESULT: LOSS OF MULTIPLE CHG PUMPS PRIOR TO SI SHUTOFF
 CONDITIONS MET

REMARKS: GENERIC W PROBLEM. PUMP FAILURES DEPENDS ON
 SPECIFIC DESIGN HEAD

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 7

REFERENCES: L0054 I-017

EVENT NO 197

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SURRY 1 PLANT TYPE: WEST PWR
 EVENT DATE: 10/16/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MAIN STEAM
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

AUXILIARY FEEDWATER (PWR)
 PUMPS

AUXILIARY FEEDWATER (PWR)
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: MAIN STEAM LINE BREAK DEPRESSURES ALL STEAM
 GENERATORS AND FAILS TO APW PUMPS

PROPAGATION: MOTOR DRIVEN APW PUMPS WILL FACE LOW PRESSURE AND
 TRIP ON RUNOUT

DEPENDENCY: NO RUNOUT PROTECTION PROVIDED FOR MOTOR-DRIVEN APW
 PUMPS, DEPEND ON SG PRESSURE

UNDESIRABLE RESULT: LOSS OF APW DUE TO PUMP RUNOUT & NO STEAM TO TD
 APW PUMPS

REMARKS: IE BULLETIN 80-04 ADDRESSED THIS. ORIFICES WILL
 BE INSTALLED IN APW LINES

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 11

REFERENCES: L0070 I-031 EVENT NO 198

APPENDIX C -- SYSTEM INTERACTION EVENTS

PLANT: SURRY 1 PLANT TYPE: WEST PWR
 EVENT DATE: 11/14/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

HIGH VOLTAGE AC (GREATER THAN 35KV)
 TOTAL SYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

HIGH VOLTAGE AC (GREATER THAN 35KV)
 ELECTRICAL CONDUCTORS

EMERGENCY POWER GENERATION
 GENERATORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 TOTAL SYSTEM OCCURRENCE

ALL SYSTEMS REQUIRING EMERGENCY POWER
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,4 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: SAFETY INJECTION SIGNAL CAUSES EDG START, THEN
 OFFSITE POWER LOST

PROPAGATION: EDG WILL ATTEMPT TO CLOSE ON BUS WITH RESIDUAL
 VOLTAGE. OUT OF PHASE TRANSFER

DEPENDENCY: EDG CAN EXPERIENCE DAMAGE FROM CLOSURE. SI MOTORS
 MAY NOT BE ADEQUATELY POWERED

UNDESIRABLE RESULT: LOSEP CAN CAUSE DAMAGE AND POTENTIAL FAILURE OF
 EMERGENCY POWER IN THIS EVENT

REMARKS: TIME DELAY PROVIDED FOR CLOSING OF DG OUTPUT BRKRS
 AFTER OFFSITE BRKRS OPEN

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 1

REFERENCES: L0162

EVENT NO 199

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SURRY 1 PLANT TYPE: WEST PWR
 EVENT DATE: 5/22/1981 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

NON-NUCLEAR INSTRUMENTATION
 I&C/TRANSMITTERS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CVCS/HIGH PRESSURE SAFETY INJECTION
 ACCUMULATORS/RESERVOIRS

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CVCS/HIGH PRESSURE SAFETY INJECTION
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: VCT LEVEL TRANSMITTER FAILS HIGH, STOPPING LETDOWN
 FLOW

PROPAGATION: NO LETDOWN, VCT LOW LEVEL, NO SWITCH TO RWST, LOSS
 OF SUCTION DAMAGES CHG PUMPS

DEPENDENCY: LEVEL TRANSMITTER CONTROLS LEVEL AND SUCTION
 SWITCHOVER TO RWST

UNDESIRABLE RESULT: REDUNDANT CHG PUMPS DAMAGED. THESE PUMPS ARE ALSO
 HI HEAD SAFETY INJECTION

REMARKS: WESTINGHOUSE NOTIFICATION OF POTENTIAL FAILURE

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 5

REFERENCES: L0064

EVENT NO 200

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SURRY 1 PLANT TYPE: WEST PWR
 EVENT DATE: 7/24/1981 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

FUEL BUILDING
 STRUCTURAL FUNCTION ITEMS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

FUEL BUILDING
 STRUCTURAL FUNCTION ITEMS

FUEL POOL COOLING AND CLEANUP
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

FUEL POOL COOLING AND CLEANUP
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: UNKNOWN

RESULT TYPE: 1,2 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: SEISMIC EVENT STRONG ENOUGH TO COLLAPSE SEVERAL
 BLOCK WALLS IN THE FUEL BLDG

PROPAGATION: WALLS COLLAPSE DAMAGING INTEGRITY OF SPENT FUEL
 POOL

DEPENDENCY: WALLS ARE LOCATED NEAR SPENT FUEL POOL

UNDESIRABLE RESULT: POTENTIAL LOSS OF SPENT FUEL POOL INTEGRITY

REMARKS: RESULT OF IE BULLETIN 80-11 INVESTIGATION

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY:21

REFERENCES: L0166 L0168 I-024 EVENT NO 201

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SURRY 2 PLANT TYPE: WEST PWR
 EVENT DATE: 9/19/1974 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

AUXILIARY FEEDWATER (PWR)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

AUXILIARY FEEDWATER (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: INSTALLATION

INITIATING EVENT: RUPTURE OF EITHER TRAIN OF AUXILIARY FEEDWATER
 SYSTEM

PROPAGATION: LOSS OF FW FLOW IN ONE TRAIN CAUSES LOSS IN
 REDUNDANT TRAIN

DEPENDENCY: CROSS CONN BETW TRAINS W/O ISOL VALVES ALLOWS
 BREAK TO AFFECT BOTH TRAINS

UNDESIRABLE RESULT: LOSS OF REDUNDANT TRAINS OF APW DUE TO SINGLE
 PIPING FAILURE

REMARKS: ALSO AFFECTS UNIT 1

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 13

REFERENCES: L0017

EVENT NO 202

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SURRY 2 PLANT TYPE: WEST PWR
 EVENT DATE: 4/29/1981 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

ESSENTIAL RAW COOLING/ SERVICE WATER
 PUMPS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

ESSENTIAL RAW COOLING/ SERVICE WATER
 PUMPS

ESSENTIAL RAW COOLING/ SERVICE WATER
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

TYPE OF COUPLING: SPATIAL PLANT AREA: REACTOR AUXILIARY BUILDING

RESULT TYPE: 1 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: DURING A MODIFICATION OF THE B SERVICE WATER PUMP,
 WATER WAS RELEASED NEARBY

PROPAGATION: THE WATER SPLASHED ON THE A SW TRAIN, CAUSING A
 SHORT AND DISABLING PUMP A

DEPENDENCY: CLOSE LOCATION OF THE TWO SW PUMPS ALLOWED WATER
 RELEASED FROM ONE TO FAIL OTHER

UNDESIRABLE RESULT: LOSS OF SW DISABLED TWO REDUNDANT CHARGING PUMPS

REMARKS: NOTE SAYS "MISSING DRIP SHIELD REPLACED". MAY BE
 MAINTENANCE ERROR

CORRECTIVE ACTION: REPAIR/REPLACEMENT CATEGORY: 23

REFERENCES: L0003 EVENT NO 203

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SURRY 2 PLANT TYPE: WEST PWR
 EVENT DATE: 5/28/1981 EXPERIENCE: ACTUAL
 OPERATING STATUS: UNKNOWN

INITIATING SYSTEM AND COMPONENT

FIRE PROTECTION
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

EMERGENCY GENERATOR FUEL
 VESSELS

FIRE PROTECTION
 VALVES

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY GENERATOR FUEL
 TOTAL SYSTEM OCCURRENCE

EMERGENCY POWER GENERATION
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,2 DISCOVERY: ROUTINE TEST/INSPECTION

INITIATING EVENT: DIESEL FUEL OIL TANK FOAM DISTRIBUTOR CONNECTED TO
 FIRE WATER MAIN

PROPAGATION: CONNECTING VALVE LEFT OPEN

DEPENDENCY: FIRE WATER ENTERED DIESEL FUEL OIL SYSTEM

UNDESIRABLE RESULT: DEGRADATION OF EMERGENCY DG SYSTEM

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 3

REFERENCES: I-151 L0062 A0024

EVENT NO 204

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SURRY 2 PLANT TYPE: WEST PWR
 EVENT DATE: 9/12/1983 EXPERIENCE: ACTUAL
 OPERATING STATUS: ROUTINE SHUTDOWN

INITIATING SYSTEM AND COMPONENT

REACTOR AUXILIARY BUILDING
 STRUCTURAL FUNCTION ITEMS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

REACTOR AUXILIARY BUILDING
 STRUCTURAL FUNCTION ITEMS

AUXILIARY FEEDWATER (PWR)
 MOTORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: REACTOR AUXILIARY BUILDING

RESULT TYPE: 2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: SAFEGUARDS BUILDING ROOF LEAKED

PROPAGATION: WATER LEAKED ONTO AUXILIARY FEEDWATER SYSTEM PUMP
 MOTOR

DEPENDENCY: PUMP SUSCEPTIBLE TO WATER AND NOT PROTECTED FROM
 LEAKAGE

UNDESIRABLE RESULT: AUX FEED PUMP DEGRADED DUE TO WATER INLEAKAGE

CORRECTIVE ACTION: REPAIR/REPLACEMENT CATEGORY: 23

REFERENCES: L2037 EVENT NO 205

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SURRY 2 PLANT TYPE: WEST PWR
 EVENT DATE: 11/18/1983 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

CONDENSATE AND FEEDWATER
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

AUXILIARY FEEDWATER (PWR)
 PUMPS

AUXILIARY FEEDWATER (PWR)
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: AUX FEED WATER HEADER CHECK VALVES LEAK DUE TO
 STEAM CUTS ON THEIR SEATS

PROPAGATION: LEAK OF HOT WATER FROM MAIN FEED HEADER TO APW
 PUMP CASING VAPOR BINDS PUMPS

DEPENDENCY: AUX FEED WATER LINES CONNECT TO MAIN FEED HEADER

UNDESIRABLE RESULT: LOSS OF AUX FEEDWATER DUE TO VAPOR BINDING OF
 PUMPS

REMARKS: TWO OF THREE PUMPS FAILED, POTENTIAL FOR ALL THREE
 TO FAIL

CORRECTIVE ACTION: REPAIR/REPLACEMENT

CATEGORY: 2

REFERENCES: L1023 A0025

EVENT NO 206

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SUSQUEHANNA 1 PLANT TYPE: GE BWR
 EVENT DATE: 3/06/1975 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

REACTOR OVERPRESSURE PROTECTION (BWR)
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

REACTOR OVERPRESSURE PROTECTION (BWR)
 VALVES

TORUS/ SUPPRESSION POOL (BWR)
 STRUCTURAL FUNCTION ITEMS

SAFETY SYSTEMS/COMPONENTS AFFECTED

TORUS/ SUPPRESSION POOL (BWR)
 STRUCTURAL FUNCTION ITEMS

MULTIPLE ESP SYSTEMS
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: LOCA OR ACTUATION OF MAIN STEAM SAFETY/RELIEF
 VALVES-DISCHARGE TO TORUS

PROPAGATION: AIR BUBBLE CLOSURES POOL SWELL-POTENTIAL DAMAGE

DEPENDENCY: TORUS DAMAGE COULD AFFECT MULTIPLE SYSTEMS
 DEPENDENT ON TORUS FOR WATER SUPPLY

UNDESIRABLE RESULT: ACCIDENT CAN DAMAGE REDUNDANT TRAINS OF SYSTEMS
 REQD TO RESPOND

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 17

REFERENCES: L0110

EVENT NO 207

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: SUSQUEHANNA 1 PLANT TYPE: GE BWR
 EVENT DATE: 11/01/1977 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

ENGINEERED SAFETY FEATURES ACTUATION
 ELECTRICAL CONDUCTORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

ENGINEERED SAFETY FEATURES ACTUATION
 ELECTRICAL CONDUCTORS

ENGINEERED SAFETY FEATURES ACTUATION
 ELECTRICAL CONDUCTORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

ENGINEERED SAFETY FEATURES ACTUATION
 TOTAL SYSTEM OCCURRENCE

MULTIPLE ESF SYSTEMS
 UNSPECIFIED COMPONENT

TYPE OF COUPLING: SPATIAL PLANT AREA: MISCELLANEOUS/ UNKNOWN STRUCTURES

RESULT TYPE: 1 DISCOVERY: ROUTINE TEST/INSPECTION

INITIATING EVENT: DAMAGE OCCURS TO SAFETY RELATED CONTROL CABLES

PROPAGATION: DAMAGE CAN ALSO OCCUR TO CONTROL CABLES OF
 REDUNDANT TRAINS

DEPENDENCY: REDUNDANT TRAIN CABLES LOCATED WITHIN SIX INCHES

UNDESIRABLE RESULT: CONTROL CABLES FOR REDUNDANT EQUIPMENT COULD BE
 DAMAGED BY SINGLE EVENT

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 15

REFERENCES: L0039 EVENT NO 208

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: THREE MILE ISLAND 1 PLANT TYPE: B&W PWR
 EVENT DATE: 1/23/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

LOW VOLTAGE AC (LESS THAN 600V)
 ELECTRICAL CONDUCTORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

LOW VOLTAGE AC (LESS THAN 600V)
 SUBSYSTEM OCCURRENCE

LOW VOLTAGE AC (LESS THAN 600V)
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

INTERMEDIATE PRESSURE INJECTION (PWR)
 SUBSYSTEM OCCURRENCE

COMPONENT COOLING WATER
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,4 DISCOVERY: DESIGN CALCULATION/VERIFICATION
 INITIATING EVENT: FAILURE OF ONE 480V BUS WITH ESAS ACTUATION AND
 OPPOSITE POWER AVAILABLE
 PROPAGATION: SECOND 480V BUS COULD OVERLOAD CAUSING LOSS OF
 CLOSED COOLING SUPPORT FOR ECCS
 DEPENDENCY: WITH STATED CONDITIONS, TWO BUSES CAN FAIL DUE TO
 ONE OVERLOAD
 UNDESIRABLE RESULT: DEGRADATION OF ECCS SYSTEMS DURING ESAS ACTUATION
 CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 1
 REFERENCES: L0042 EVENT NO 209

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: THREE MILE ISLAND 1 PLANT TYPE: B&W PWR
 EVENT DATE: 1/17/1981 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

HIGH VOLTAGE AC (GREATER THAN 35KV)
 TOTAL SYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

HIGH VOLTAGE AC (GREATER THAN 35KV)
 TOTAL SYSTEM OCCURRENCE

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

MULTIPLE SAFETY SYSTEMS
 MISCELLANEOUS EQUIPMENT

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 4 DISCOVERY: OTHER

INITIATING EVENT: ESFAS OCCURS STARTING EDG AND SUBSEQUENTLY LOSP
 OCCURS

PROPAGATION: DG BREAKER CLOSURE OCCUR WITH RESIDUAL VOLTAGE AND
 LOAD ON BUS

DEPENDENCY: BKR CLOSURE ONLY REQUIRES DG SPEED AND VOLTAGE
 SIGNALS

UNDESIRABLE RESULT: LOSP AFTER DG START CAN CAUSE DAMAGE TO DG AND
 EXCESSIVE VOLTAGE DIP

REMARKS: FOUND DUE TO INPO SOER REVIEW

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 1

REFERENCES: L0113

EVENT NO 210

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: THREE MILE ISLAND 2 PLANT TYPE: B&W PWR
 EVENT DATE: 8/28/1975 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

CONTROL BUILDING
 STRUCTURAL FUNCTION ITEMS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CONTROL BUILDING
 STRUCTURAL FUNCTION ITEMS

MULTIPLE SAFETY SYSTEMS
 ELECTRICAL CONDUCTORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

MULTIPLE SAFETY SYSTEMS
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: CONTROL BUILDING

RESULT TYPE: 1,4 DISCOVERY: ROUTINE TEST/INSPECTION

INITIATING EVENT: SEISMIC EVENT

PROPAGATION: HOLLOW BLOCK WALLS FALL ON SAFETY RELATED
 ELECTRICAL CIRCUITS

DEPENDENCY: WALLS THAT COULDN'T BE QUALIFIED USED NEAR SAFETY
 CIRCUITS

UNDESIRABLE RESULT: SEISMIC EVENT DAMAGES SEISMICALLY QUALIFIED SAFETY
 SYSTEMS

REMARKS: FOUND DURING ROUTINE INSPECTION OF CONTROL BLDG

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 21

REFERENCES: L0173 EVENT NO 212

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: THREE MILE ISLAND 2 PLANT TYPE: B&W PWR
 EVENT DATE: 3/28/1979 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

PRESSURIZER (PWR)
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

NON-NUCLEAR INSTRUMENTATION
 I&C/SENSORS

OPERATION ACTIVITY
 PERSONNEL

SAFETY SYSTEMS/COMPONENTS AFFECTED

CVCS/HIGH PRESSURE SAFETY INJECTION
 TOTAL SYSTEM OCCURRENCE

PRIMARY COOLANT (PWR)
 MISCELLANEOUS EQUIPMENT

REACTOR CORE
 FUEL ELEMENTS

TYPE OF COUPLING: HUMAN

RESULT TYPE: 1,3 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: DURING RX/TURBINE TRIP SEQUENCE, PORV STUCK OPEN
 CAUSING SMALL LOCA

PROPAGATION: RCS LOSSES CAUSED SIAS, OPERATOR UNAWARE OF PORV
 STATUS DUE TO INADEQUATE INST

DEPENDENCY: OPERATOR ACTED ON INADEQUATE INSTRUMENTS AND SHUT
 DOWN SAFETY INJECTION

UNDESIRABLE RESULT: LOSS OF RCS INVENTORY AND SHUT OFF OF ECCS CAUSED
 FUEL DAMAGE

REMARKS: AFW FAILED ALSO BUT NOT DUE TO SYSTEM INTERACTION

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 19

REFERENCES: I-280 I-048 L0065 M1001 EVENT NO 213

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: TROJAN PLANT TYPE: WEST PWR
 EVENT DATE: 5/21/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

PRIMARY COOLANT (PWR)
 PIPES/PITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CONTAINMENT ISOLATION
 VALVES

PRIMARY CONTAINMENT (PWR)
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

CONTAINMENT ISOLATION
 VALVES

PRIMARY CONTAINMENT (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: LOCA OCCURS DURING CONTAINMENT PURGING OPERATION

PROPAGATION: PURGE DUCTING CAN FAIL, INTERFERING WITH PURGE
 ISOLATION VALVE CLOSURE

DEPENDENCY: DUCT DESIGN DID NOT CONSIDER LOCA CONDITIONS
 DURING PURGE OPERATION

UNDESIRABLE RESULT: LOCA DURING PURGE CAN DEFEAT CONTAINMENT INTEGRITY

REMARKS: PURGE SUPPLY VALVE, EXHAUST VALVE AND H2 VENT VALVE
 AFFECTED

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 9

REFERENCES: L0047 EVENT NO 214

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: TROJAN PLANT TYPE: WEST PWR
 EVENT DATE: 6/21/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MAIN STEAM
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

STEAM GENERATOR (PWR)
 PIPES/FITTINGS

REACTOR PROTECTION
 I&C/SENSORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR PROTECTION
 SUBSYSTEM OCCURRENCE

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: HIGH ENERGY LINE BREAK IN CONTAINMENT RESULTING IN
 HIGH AMBIENT TEMP

PROPAGATION: HEATUP OF REP LEG, SG LEVEL INSTR FAILS HIGH,
 DELAYS RPS TRIP ON SG LO LO LEVEL

DEPENDENCY: STEAM GENERATOR LEVEL REFERENCE LEG SUBJECTED TO
 HIGH AMBIENT TEMP

UNDESIRABLE RESULT: ACCIDENT DEGRADES SYSTEM REQUIRED TO MITIGATE
 ACCIDENT

REMARKS: ALSO PROVIDES HIGH LEVEL INDICATION TO
 OPERATOR-GENERIC W PROBLEM

CORRECTIVE ACTION: OTHER

CATEGORY: 8

REFERENCES: L0080

EVENT NO 215

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: TROJAN PLANT TYPE: WEST PWR
 EVENT DATE: 5/08/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MISCELLANEOUS/ UNKNOWN STRUCTURES
 STRUCTURAL FUNCTION ITEMS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

MISCELLANEOUS/ UNKNOWN STRUCTURES
 STRUCTURAL FUNCTION ITEMS

MULTIPLE SAFETY SYSTEMS
 UNSPECIFIED COMPONENT

SAFETY SYSTEMS/COMPONENTS AFFECTED

MULTIPLE SAFETY SYSTEMS
 UNSPECIFIED COMPONENT

TYPE OF COUPLING: SPATIAL PLANT AREA: REACTOR AUXILIARY BUILDING

RESULT TYPE: 1 DISCOVERY: DESIGN CALCULATION/VERIFICATION

INITIATING EVENT: SEISMIC EVENT (OBE OR SSE)

PROPAGATION: COLLAPSE OR WEAKENING OF MASONRY WALLS

DEPENDENCY: SAFETY-RELATED PIPING OR EQUIPMENT DEPEND ON WALLS
 FOR SUPPORT

UNDESIRABLE RESULT: DAMAGE TO SAFETY-RELATED COMPONENTS IN DESIGN
 BASIS EVENT

REMARKS: DESIGN DEFICIENCY IN MASONRY WALLS

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 21

REFERENCES: I-024 I-051 I-271 EVENT NO 216

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: TROJAN PLANT TYPE: WEST PWR
 EVENT DATE: 4/19/1981 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

PRIMARY CONTAINMENT (PWR)
 STRUCTURAL FUNCTION ITEMS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CONTAINMENT ISOLATION
 VALVE OPERATORS

PRIMARY CONTAINMENT (PWR)
 STRUCTURAL FUNCTION ITEMS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CONTAINMENT ISOLATION
 VALVE OPERATORS

PRIMARY COOLANT (PWR)
 VALVE OPERATORS

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 3 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: FLOODING OF CNMT SUMP SUBMERGED CNMT ISOL VALVE
 OPERATOR FOR RCS DRAIN TANK LINE

PROPAGATION: VALVE OPERATOR WATER DAMAGED & FAILED TO CLOSE
 RCS DRAIN TANK NOT ISOLATED

DEPENDENCY: VALVE AND OPERATOR ARE LOCATED IN THE SUMP SUCH
 THAT FLOODING/SPRAY FAIL OPER

UNDESIRABLE RESULT: POTENTIAL FAILURE TO ISOLATE RCS DRAIN TANK
 FOLLOWING AN ACCIDENT

REMARKS: THERE MAY BE MORE SAFETY-RELATED EQUIP IN CNMT
 THAT CAN BE FLOODED OR SPRAYED

CORRECTIVE ACTION: REPAIR/REPLACEMENT

CATEGORY:23

REFERENCES: L1024

EVENT NO 217

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: TROJAN PLANT TYPE: WEST PWR
 EVENT DATE: 7/28/1981 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

FIRE PROTECTION
 SUBSYSTEM OCCURRENCE

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

FIRE PROTECTION
 SUBSYSTEM OCCURRENCE

CONTAINMENT COMBUSTIBLE GAS CONTROL
 ELECTRICAL/IEC FUNCTION ITEMS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CONTAINMENT COMBUSTIBLE GAS CONTROL
 ELECTRICAL/IEC FUNCTION ITEMS

TYPE OF COUPLING: SPATIAL PLANT AREA: REACTOR AUXILIARY BUILDING

RESULT TYPE: 2 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: FIRE SYSTEM DELUGE ACTUATED BY WELDING SMOKE

PROPAGATION: SHORT-CIRCUITED CONTROL POWER XFMR TO HYDROGEN
 RECOMBINER

DEPENDENCY: HYDROGEN RECOMBINER POWER SUPPLY IN AREA SUBJECT
 TO FIRE DELUGE SPRAY

UNDESIRABLE RESULT: HYDROGEN RECOMBINER INOPERABLE DUE TO FIRE
 PROTECTION SYSTEM

CORRECTIVE ACTION: REPAIR/REPLACEMENT

CATEGORY: 3

REFERENCES: I-151 L0061 A0024

EVENT NO 218

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: TURKEY POINT 3 PLANT TYPE: WEST PWR
 EVENT DATE: 6/26/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MAIN STEAM
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

STEAM GENERATOR (PWR)
 PIPES/FITTINGS

REACTOR PROTECTION
 PIPES/FITTINGS

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR PROTECTION
 SUBSYSTEM OCCURRENCE

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: HIGH ENERGY LINE BREAK IN CONTAINMENT RESULTING IN
 HIGH AMBIENT TEMP

PROPAGATION: HEATUP OF REP LEG, SG LEVEL INSTR FAILS HIGH,
 DELAYS RPS TRIP ON SG LO LO LEVEL

DEPENDENCY: STEAM GENERATOR LEVEL REFERENCE LEG SUBJECTED TO
 HIGH AMBIENT TEMP

UNDESIRABLE RESULT: ACCIDENT DEGRADES SYSTEM REQUIRED TO MITIGATE
 ACCIDENT

REMARKS: ALSO PROVIDES HIGH LEVEL INDICATION TO
 OPERATOR-GENERIC W PROBLEM

CORRECTIVE ACTION: OTHER

CATEGORY: 8

REFERENCES: L0160

EVENT NO 220

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: TURKEY POINT 4 PLANT TYPE: WEST PWR
 EVENT DATE: 6/26/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MAIN STEAM
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

STEAM GENERATOR (PWR)
 PIPES/FITTINGS

REACTOR PROTECTION
 I&C/SENSORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR PROTECTION
 SUBSYSTEM OCCURRENCE

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: HIGH ENERGY LINE BREAK IN CONTAINMENT RESULTING IN
 HIGH AMBIENT TEMP

PROPAGATION: HEATUP OF REF LEG, SG LEVEL INSTR FAILS HIGH,
 DELAYS RPS TRIP ON SG LO LO LEVEL

DEPENDENCY: STEAM GENERATOR LEVEL REFERENCE LEG SUBJECTED TO
 HIGH AMBIENT TEMP

UNDESIRABLE RESULT: ACCIDENT DEGRADES SYSTEM REQUIRED TO MITIGATE
 ACCIDENT

REMARKS: ALSO PROVIDES HIGH LEVEL INDICATION TO
 OPERATOR-GENERIC W PROBLEM

CORRECTIVE ACTION: OTHER

CATEGORY: 8

REFERENCES: L0161

EVENT NO 221

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: TURKEY POINT 4 PLANT TYPE: WEST PWR
 EVENT DATE: 9/06/1982 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

PRESSURIZER (PWR)
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

PRESSURIZER (PWR)
 VALVES

NON-NUCLEAR INSTRUMENTATION
 I&C/COMPUTATION MODULES

SAFETY SYSTEMS/COMPONENTS AFFECTED

PRESSURIZER (PWR)
 SUBSYSTEM OCCURRENCE

PRIMARY COOLANT (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 4 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: PRESSURIZER SPRAY VALVE LEAK CAUSED
 CURRENT/PNEUMATIC CONVERTER TO FAIL

PROPAGATION: I/P CONVERTER FAILURE OPENED PRESSURIZER SPRAY
 VALVE

DEPENDENCY: SPATIAL DEPENDENCY BETWEEN LEAKY VALVE AND I/P
 CONVERTER

UNDESIRABLE RESULT: RCS EXPERIENCED RAPID DECREASE IN PRESSURE

CORRECTIVE ACTION: REPAIR/REPLACEMENT

CATEGORY: 23

REFERENCES: L2021

EVENT NO 222

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: VERMONT YANKEE PLANT TYPE: GE BWR
 EVENT DATE: 1/30/1976 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

RECIRCULATING WATER (BWR)
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

RECIRCULATING WATER (BWR)
 PIPES/FITTINGS

TORUS/ SUPPRESSION POOL (BWR)
 STRUCTURAL FUNCTION ITEMS

SAFETY SYSTEMS/COMPONENTS AFFECTED

TORUS/ SUPPRESSION POOL (BWR)
 STRUCTURAL FUNCTION ITEMS

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: SEVERE LOCA PLUS UNRESTRICTED FLOW FROM BROKEN
 PIPE

PROPAGATION: LOCA FORCES CAUSE SUPPRESSION POOL SWELL

DEPENDENCY: POOL SWELL LOADS MAY DAMAGE CONTAINMENT STRUCTURE

UNDESIRABLE RESULT: POSSIBLE LOSS OF CONTAINMENT INTEGRITY

REMARKS: FOR 19 MARK I CNMTS, 18 PROCEDURE CHANGES, VERMONT
 YANKEE DESIGN CHANGE

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY:17

REFERENCES: M1008 EVENT NO 223

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: WATTS BAR 1 PLANT TYPE: WEST PWR
 EVENT DATE: 6/13/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MAIN STEAM
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

MAIN STEAM
 PIPES/FITTINGS

REACTOR PROTECTION
 I&C/SENSORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR PROTECTION
 SUBSYSTEM OCCURRENCE

AUXILIARY FEEDWATER (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: HIGH ENERGY LINE BREAK IN CONTAINMENT

PROPAGATION: HEATS UP SG LEVEL REFERENCE CAUSING INACCURATE SG
 LEVEL SIGNAL (HIGH)

DEPENDENCY: HIGH SIGNAL DELAYS TRIP BY RPS FOR SG LO LO LEVEL

UNDESIRABLE RESULT: ACCIDENT DEGRADES SYSTEM RESPONSES REQUIRED TO
 MITIGATE ACCIDENT

REMARKS: GENERIC W PROBLEM. ALSO PROVIDES HIGH LEVEL
 INDICATION TO OPERATOR

CORRECTIVE ACTION: OTHER

CATEGORY: 8

REFERENCES: L0074

EVENT NO 224

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: WATTS BAR 1 PLANT TYPE: WEST PWR
 EVENT DATE: 8/08/1983 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

FIRE PROTECTION
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

FIRE PROTECTION
 PIPES/FITTINGS

INTERMEDIATE PRESSURE INJECTION (PWR)
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

INTERMEDIATE PRESSURE INJECTION (PWR)

TYPE OF COUPLING: SPATIAL PLANT AREA: REACTOR AUXILIARY BUILDING

RESULT TYPE: 2 DISCOVERY: UNKNOWN

INITIATING EVENT: FIRE PROTECTION PIPE RUPTURES DURING SEISMIC EVENT
 DUE TO IMPROPER SUPPORTS

PROPAGATION: WATER FROM PIPE RUPTURE SPILLS ON SAFETY INJECTION
 PUMP UNDER PIPE

DEPENDENCY: PIPE THAT IS NOT PROPERLY SUPPORTED IS LOCATED
 DIRECTLY OVER PUMP

UNDESIRABLE RESULT: FAILURE OF SAFETY INJECTION PUMP DUE TO FLOODING
 DURING SEISMIC EVENT

REMARKS: ALSO AFFECTS WATTS BAR 2

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 21

REFERENCES: C10

EVENT NO 225

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: WATTS BAR 2 PLANT TYPE: WEST PWR
 EVENT DATE: 8/08/1983 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

FIRE PROTECTION
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

FIRE PROTECTION
 PIPES/FITTINGS

INTERMEDIATE PRESSURE INJECTION (PWR)
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

INTERMEDIATE PRESSURE INJECTION (PWR)
 PUMPS

TYPE OF COUPLING: SPATIAL PLANT AREA: REACTOR AUXILIARY BUILDING

RESULT TYPE: 2 DISCOVERY: UNKNOWN

INITIATING EVENT: FIRE PROTECTION PIPE RUPTURES DURING SEISMIC EVENT
 DUE TO IMPROPER SUPPORTS

PROPAGATION: WATER FROM PIPE RUPTURE SPILLS ON SAFETY INJECTION
 PUMP UNDER PIPE

DEPENDENCY: PIPE THAT IS NOT PROPERLY SUPPORTED IS LOCATED
 DIRECTLY OVER PUMP

UNDESIRABLE RESULT: FAILURE OF SAFETY INJECTION PUMP DUE TO FLOODING
 DURING SEISMIC EVENT

REMARKS: ALSO AFFECTS WATTS BAR 1

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 21

REFERENCES: C10

EVENT NO 226

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: WPPSS 1 PLANT TYPE: B&W PWR
 EVENT DATE: 6/11/1981 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

CONTROL BUILDING HVAC
 BLOWERS/COMPRESSORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CONTROL BUILDING HVAC
 BLOWERS/COMPRESSORS

MULTIPLE SAFETY SYSTEMS
 ELECTRICAL CONDUCTORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 ELECTRICAL CONDUCTORS

MULTIPLE SAFETY SYSTEMS
 ELECTRICAL CONDUCTORS

TYPE OF COUPLING: SPATIAL PLANT AREA: UNKNOWN

RESULT TYPE: 2 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: HVAC FAN FAILURE CAN PROPEL MISSILE THRU FAN
 HOUSING

PROPAGATION: SAFETY-RELATED EQUIPMENT CAN BE DAMAGED BY MISSILE

DEPENDENCY: SAFETY-RELATED CABLES UNPROTECTED FROM POTENTIAL
 MISSILES

UNDESIRABLE RESULT: DEGRADATION OF ONE OR MORE SAFETY SYSTEMS

REMARKS: ALSO AFFECTS DOCKET NO. 513

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 16

REFERENCES: C11

EVENT NO 227

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: WPPSS 4 PLANT TYPE: B&W PWR
 EVENT DATE: 6/11/1981 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

CONTROL BUILDING HVAC
 BLOWERS/COMPRESSORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CONTROL BUILDING HVAC
 BLOWERS/COMPRESSORS

MULTIPLE SAFETY SYSTEMS
 ELECTRICAL CONDUCTORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 ELECTRICAL CONDUCTORS

MULTIPLE SAFETY SYSTEMS
 ELECTRICAL CONDUCTORS

TYPE OF COUPLING: SPATIAL PLANT AREA: UNKNOWN

RESULT TYPE: 2 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: HVAC FAN FAILURE CAN PROPEL MISSILE THRU FAN HOUSING

PROPAGATION: SAFETY-RELATED EQUIPMENT CAN BE DAMAGED BY MISSILE

DEPENDENCY: SAFETY-RELATED CABLES UNPROTECTED FROM POTENTIAL MISSILES

UNDESIRABLE RESULT: DEGRADATION OF ONE OR MORE SAFETY SYSTEMS

REMARKS: ALSO AFFECTS DOCKET NO. 460

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 16

REFERENCES: C11

EVENT NO 228

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ZION 1 PLANT TYPE: WEST PWR
 EVENT DATE: 7/13/1979 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

MAIN STEAM
 PIPES/FITTINGS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

STEAM GENERATOR (PWR)
 PIPES/FITTINGS

REACTOR PROTECTION
 I&C/SENSORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

REACTOR PROTECTION
 SUBSYSTEM OCCURRENCE

AUXILIARY FEEDWATER (PWR)
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: SPATIAL PLANT AREA: PRIMARY CONTAINMENT (PWR)

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: HIGH ENERGY LINE BREAK IN CONTAINMENT

PROPAGATION: HEATS UP SG LEVEL REFERENCE CAUSING INACCURATE SG
 LEVEL SIGNALS (HIGH)

DEPENDENCY: HIGH SIGNAL DELAYS TRIP BY RPS FOR SG LO LO LEVEL.
 AFW INITIATION DELAYED ALSO

UNDESIRABLE RESULT: ACCIDENT DEGRADES SYSTEM RESPONSES REQUIRED TO
 MITIGATE ACCIDENT

REMARKS: GENEP^oC W PROBLEM. ALSO PROVIDES HIGH INDICATION
 TO OP: ATOR

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 8

REFERENCES: L0078 EVENT NO 229

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ZION 1 PLANT TYPE: WEST PWR
 EVENT DATE: 5/23/1980 EXPERIENCE: POTENTIAL
 OPERATING STATUS: NOT APPLICABLE

INITIATING SYSTEM AND COMPONENT

PRESSURIZER (PWR)
 VALVES

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

CVCS/HIGH PRESSURE SAFETY INJECTION
 PUMPS

SAFETY SYSTEMS/COMPONENTS AFFECTED

CVCS/HIGH PRESSURE SAFETY INJECTION
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1,3 DISCOVERY: AE/VENDOR NOTIFICATION

INITIATING EVENT: SECONDARY SYS HELB CAUSES SI ACTUATION.
 SUBSEQUENTLY PORV CONTROL IS LOST

PROPAGATION: CHG PUMPS INJECT AGAINST HIGHER PRESSURE THAN
 DESIGN. PUMPS OVERHEAT

DEPENDENCY: ACCIDENT CONDITION NOT CONSIDERED. SIAS CLOSES
 RECIRC VALVES FOR CHG PUMPS

UNDESIRABLE RESULT: DAMAGE CAN OCCUR TO MULTIPLE CHG PUMPS PRIOR TO SI
 SHUTOFF CONDITIONS MET

REMARKS: GENERIC W PROBLEM. DEPENDS ON DESIGN HEAD OF
 SPECIFIC CHG PUMPS

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION

CATEGORY: 7

REFERENCES: L0057

EVENT NO 230

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ZION 2 PLANT TYPE: WEST PWR
 EVENT DATE: 5/25/1976 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

CONDENSATE AND FEEDWATER
 HEAT EXCHANGERS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

NON-NUCLEAR INSTRUMENTATION
 I&C/TRANSMITTERS

CONDENSATE AND FEEDWATER
 HEAT EXCHANGERS

SAFETY SYSTEMS/COMPONENTS AFFECTED

AUXILIARY FEEDWATER (PWR)
 PUMPS

INTERMEDIATE PRESSURE INJECTION (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 4 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: HIGH AUXILIARY FEEDWATER FLOW RATE PRODUCED A
 WATER HAMMER

PROPAGATION: WATER HAMMER CAUSED 2 STEAM LINE TRANSMITTERS TO
 SPIKE SIGNALING A HI DELTA-P

DEPENDENCY: HIGH STEAM LINE DELTA-P ON 2 LOOPS CAUSED A
 FEEDWATER PUMP TRIP

UNDESIRABLE RESULT: FEEDWATER PUMP TRIP PRODUCED A SAFETY INJECTION
 ACTUATION

CORRECTIVE ACTION: ADMINISTRATIVE/PROCEDURE CHANGE CATEGORY: 12

REFERENCES: L5004

EVENT NO 231

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ZION 2 PLANT TYPE: WEST PWR
 EVENT DATE: 9/19/1976 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

DC POWER
 ELECTRICAL CONDUCTORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

DC POWER
 CIRCUIT BREAKER/FUSES
 EMERGENCY POWER GENERATION
 GENERATORS

SAFETY SYSTEMS/COMPONENTS AFFECTED

EMERGENCY POWER GENERATION
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 4 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: LOSS OF POWER TO DC BUS WHILE AN EDG IS TIED TO
 GRID

PROPAGATION: NUMEROUS BKRS FAILED TO OPEN, EDG TRIED TO SUPPORT
 ALL LOADS, OVERHEATED

DEPENDENCY: BREAKERS REQUIRE DC POWER TO OPEN

UNDESIRABLE RESULT: LOSS OF DC POWER DAMAGED EMERGENCY PWR SYSTEM

REMARKS: LOP OCCURRED DUE TO HUMAN ERROR

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 1

REFERENCES: L0124 M0004 M0005 EVENT NO 232

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ZION 2 PLANT TYPE: WEST PWR
 EVENT DATE: 9/19/1976 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

DC POWER
 ELECTRICAL CONDUCTORS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

DC POWER
 ELECTRICAL CONDUCTORS

REACTOR PROTECTION
 SUBSYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

PRIMARY COOLANT (PWR)
 VALVES

REACTOR PROTECTION
 SUBSYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 4 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: LOSS OF POWER TO DC BUS

PROPAGATION: TURBINE TRIP OCCURRED BUT GENERATOR REMAINED ON
 GRID DUE TO GEN BKRS NOT OPENING

DEPENDENCY: GEN BKRS REQUIRE DC PWR. MFW PUMPS ONLY TRIP WHEN
 GEN TRIPS. MFW PUMPS CONTINUED

UNDESIRABLE RESULT: SEVERE OVERFEEDING OCCURRED, SI ACTUATED AND
 PRESSURE ROSE TO SV SETTING

REMARKS: SAFETY VALVE RELIEVED TO CONTAINMENT (2500 GAL)

CORRECTIVE ACTION: OTHER CATEGORY: 1

REFERENCES: L0124 M0004 M0005 EVENT NO 233

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ZION 2 PLANT TYPE: WEST PWR
 EVENT DATE: 9/03/1980 EXPERIENCE: ACTUAL
 OPERATING STATUS: HOT SHUTDOWN

INITIATING SYSTEM AND COMPONENT

AUXILIARY FEEDWATER (PWR)
 PUMPS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

STEAM GENERATOR (PWR)
 PIPES/FITTINGS

MAIN STEAM
 IEC/TRANSMITTERS

SAFETY SYSTEMS/COMPONENTS AFFECTED

STEAM GENERATOR (PWR)
 PIPES/FITTINGS

AUXILIARY FEEDWATER (PWR)
 PIPES/FITTINGS

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 4 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: FAILED FEEDWATER PUMP CAUSED APW PUMPS TO START WHICH LEAD TO A WATER HAMMER

PROPAGATION: WATER HAMMER SPIKED 2 STM LINE PRESS TRANSMITTERS INITIATING A SAFETY INJECTION

DEPENDENCY: THROTTLING AUX FD IN 2C & 2D INCREASED FLOW TO 2A & 2B TRAPPING STM BUBBLE IN 2B

UNDESIRABLE RESULT: SIAS CAUSED INJECTION FROM BIT AND DECREASED LIFE OF INJECTION NOZZLES

REMARKS: POTENTIAL EXISTED FOR STRUCTURAL DAMAGE TO STEAM PIPING & SUPPORT STRUCTURES

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY: 12

REFERENCES: L5006 EVENT NO 234

APPENDIX C - SYSTEM INTERACTION EVENTS

PLANT: ZION 2 PLANT TYPE: WEST PWR
 EVENT DATE: 12/11/1981 EXPERIENCE: ACTUAL
 OPERATING STATUS: STEADY STATE OPERATION

INITIATING SYSTEM AND COMPONENT

AUXILIARY FEEDWATER (PWR)
 PUMPS

SYSTEMS/COMPONENTS BETWEEN WHICH THE DEPENDENCY OCCURRED

AUXILIARY FEEDWATER (PWR)
 PUMPS

AUXILIARY FEEDWATER (PWR)
 TOTAL SYSTEM OCCURRENCE

SAFETY SYSTEMS/COMPONENTS AFFECTED

AUXILIARY FEEDWATER (PWR)
 TOTAL SYSTEM OCCURRENCE

TYPE OF COUPLING: FUNCTIONAL

RESULT TYPE: 1 DISCOVERY: OPERATIONAL ABNORMALITY

INITIATING EVENT: RX TRIP DUE TO GENERATOR TRIP (TURBINE-DRIVEN AFW
 PUMP OUT OF SERVICE)

PROPAGATION: MOTOR-DRIVEN AFW PUMPS FAIL TO AUTO START;
 ERRONEOUS LOSS OF SUCTION TRIP

DEPENDENCY: SPLIT HEADER ARRANGEMENT CAUSES TEMPORARY PRESS
 REDUCTION IN SUCTION LINES

UNDESIRABLE RESULT: FAILURE OF MOTOR-DRIVEN AFW PUMPS TO AUTO START

REMARKS: TIME RELAY INSTALLED ON PUMP STARTING CIRCUITRY OF
 MOTOR-DRIVEN PUMPS

CORRECTIVE ACTION: DESIGN CHANGE/MODIFICATION CATEGORY:22

REFERENCES: A0002 L1045 EVENT NO 235

Appendix D

EVENT REFERENCES

This appendix contains the references for the events in Appendix C. The "REFERENCE NO." given here corresponds to the reference field in Appendix C. The format for each reference type is given in Table D.1.

Table D.1. Formats for event references

Document type	First character of reference No.	Report No.	Reference description
AEOD Reports	A	As assigned by AEOD	Report title
Construction Deficiency	C	As assigned by CER pilot program	Contains NRC Document Control Systems (DCS) number and report subject
Systematic Evaluation Program Reports	E	NUREG number	NUREG title
Inspection and Enforcement Bulletins, Circulars, and Information Notices	I	IEB-IE Bulletin IEC-IE Circular IEN-IE Information Notice	Document title
Licensee Event Reports (including LER predecessors)	L	None	Contains plant docket number, LER number (or letter date, if no LER number), and NSIC accession number in the following format: Docket No./LER No. AN: XXXXXX

APPENDIX D - EVENT REFERENCES

REFERENCE NO.	REPORT NO.	REFERENCE DESCRIPTION
A 0001	AEOD/C403	CASE STUDY REPORT FOR THE EDWIN I. HATCH UNIT NO. 2 PLANT SYSTEMS INTERACTION EVENT ON AUGUST 25, 1982
A 0002	AEOD/E213	TRIP OF TWO AUXILIARY FEEDWATER PUMPS FROM LOW SUCTION AT ZION UNIT 2 ON 12/11/81
A 0003	AEOD/C101	REPORT ON SAINT LUCIE 1 NATURAL CIRCULATION COOLDOWN ON 06/11/80
A 0009	AEOD/C001	BROWNS FERRY 3 PARTIAL FAILURE TO SCRAM EVENT ON 06/28/80
A 0010	AEOD/C003	LOSS OF OFFSITE POWER EVENT AT ARKANSAS NUCLEAR ONE UNITS 1 AND 2 ON 04/07/80
A 0011	AEOD/C206	INADVERTENT LOSS OF REACTOR COOLANT AT SEQUOYAH 1 AND 2 ON 02/11/81 AND 08/06/81
A 0014		REPORT ON CALVERT CLIPPS LOSS OF SERVICE WATER ON 05/20/80
A 0015	AEOD/C104	LOSS OF 125V DC BUS AT MILLSTONE 2 ON 01/02/81
A 0016	AEOD/E304	INVESTIGATION OF BACKFLOW PROTECTION IN COMMON EQUIPMENT AND FLOOR DRAIN SYSTEMS TO PREVENT FLOODING OF VITAL EQUIPMENT IN SAFETY-RELATED COMPARTMENTS
A 0017	AEOD/E311	LOSS OF SALT WATER FLOW TO SERVICE WATER HEAT EXCHANGER AT CALVERT CLIPPS 2 ON 06/20/82
A 0020	AEOD/E314	LOSS OF ALL 3 CHARGING PUMPS DUE TO EMPTY COMMON REFERENCE LEG IN THE LIQUID LEVEL TRANSDUCERS FOR THE VOLUME CONTROL TANK
A 0021	AEOD/E317	LOSS OF HIGH PRESSURE INJECTION
A 0022	AEOD/E401	TEMPORARY LOSS OF ALL POWER DUE TO RELAY FAILURES IN DG LOAD SHEDDING CIRCUITRY

APPENDIX D - EVENT REFERENCES

<u>REFERENCE NO.</u>	<u>REPORT NO.</u>	<u>REFERENCE DESCRIPTION</u>
A0023	AEOD/E412	ADVERSE SYSTEM INTERACTION WITH DOMESTIC WATER SYSTEMS AT CALVERT CLIFFS 2 ON 10/19/83
A0024	AEOD/E204	EFFECTS OF FIRE PROTECTION SYSTEM ACTUATION ON SAFETY-RELATED EQUIPMENT"
A0025	AEOD/C404	STEAM BINDING OF AUXILIARY FEEDWATER PUMPS
C07	CDR:49	DCS:8206150150 'INSUFFICIENT FAN HOUSING THICKNESS AT CLINTON 1'
C10	CDR:104	DCS:8308180308 'HIGH PRESSURE FIRE PROTECTION PIPE NOT SEISMICALLY SUPPORTED OVER SAFETY INJECTION SYSTEM PUMP AT WATTS BAR 1 AND 2'
C11	CDR:58	DCS:8307280345 'MISSILE PENETRATION FOR BUFFALO FORGE FANS AT WPPSS 1 AND 2'
C12	CDR:144	DCS:8307289272 'LACK OF DC BACKED POWER FOR FOGG INTERLOCK RELAYS AT MIDLAND 1 AND 2'
C14	CDR:158	DCS:8304010447 'ROUTING OF MAKEUP TANK OUTLET LINES DEFICIENT AT BELLEFONTE 1 AND 2'
C21	CLR:218	DCS:8203230147 'NONSEISMIC EQUIPMENT ERECTED OVER SEISMIC EQUIPMENT AT FERMI 2'
E0001	NUREG-0820	INTEGRATED PLANT SAFETY ASSESSMENT SYSTEMATIC EVALUATION PROGRAM PALISADES PLANT
E0002	NUREG-0824	INTEGRATED PLANT SAFETY ASSESSMENT SYSTEMATIC EVALUATION PROGRAM HILLSTONE 1 PLANT
E0004	NUREG-0828	INTEGRATED PLANT SAFETY ASSESSMENT SYSTEMATIC EVALUATION PROGRAM BIG ROCK POINT PLANT
E0005	NUREG-0821	INTEGRATED PLANT SAFETY ASSESSMENT SYSTEMATIC EVALUATION PROGRAM GINNA

APPENDIX D - EVENT REFERENCES

REFERENCE NO. -----	REPORT NO. -----	REFERENCE DESCRIPTION -----
E 0007	NUREG-0822	INTEGRATED PLANT SAFETY ASSESSMENT SYSTEMATIC EVALUATION PROGRAM OYSTER CREEK PLANT
I-012	IEB 80-24	PREVENTION OF DAMAGE DUE TO LEAKS INSIDE CONTAINMENT (10/17/80 INDIAN POINT 2 EVENT)
I-017	IEB 80-18	MAINTENANCE OF MIN. FLOW THRU CENTRIFUGAL CHARGING PUMPS AFTER SECONDARY SIDE HIGH ENERGY LINE RUPTURE
I-018	IEB 80-17	FAILURE OF CONTROL RODS TO INSERT DURING A SCRAM AT A BWR
I-023	IEB 80-12	DECAY HEAT REMOVAL SYSTEM OPERABILITY
I-024	IEB 80-11	MASONRY WALL DESIGN
I-031	IEB 80-04	ANALYSIS OF PWR MAIN STEAM LINE BREAK WITH CONTINUED FEEDWATER ADDITION
I-036	IEB 79-27	LOSS OF NON-CLASS-1-E I&C POWER SYSTEM BUS DURING OPERATION
I-048	IEB 79-05	NUCLEAR INCIDENT AT THREE MILE ISLAND
I-051	IEB 79-02	PIPE SUPPORT BASE PLATE DESIGNS USING CONCRETE EXPANSION ANCHOR BOLTS
I-108	IEC 79-02	FAILURE OF 120 VOLT VITAL AC POWER SUPPLIES
I-120	IEC 78-06	POTENTIAL COMMON MODE FLOODING OF ECCS EQUIPMENT ROOMS AT BWR'S
I-127	IEN 83-77	AIR/GAS ENTRAINMENT EVENTS RESULTING IN SYSTEM FAILURES
I-148	IEN 83-44	POTENTIAL DAMAGE TO REDUNDANT SAFETY EQUIPMENT FROM BACKFLOW THRU EQUIPMENT AND FLOOR DRAIN SYSTEM
I-151	IEN 83-41	ACTUATION OF FIRE SUPPRESSION SYSTEM CAUSING INOPERABILITY OF SAFETY-RELATED EQUIPMENT

APPENDIX D - EVENT REFERENCES

REFERENCE NO.	REPORT NO.	REFERENCE DESCRIPTION
I-197	IEN 82-19	LOSS OF HIGH HEAD SAFETY INJECTION EMERGENCY BORATION & REACTOR COOLANT MAKEUP CAPABILITY
I-216	IEN 81-27	FLAMMABLE GAS MIXTURES IN WASTE GAS DECAY TANKS IN PWR PLANTS
I-225	IEN 81-12	GUIDANCE ON ORDER ISSUED JANUARY 9, 1981 REGARDING AUTOMATIC CONTROL ROD INSERTION ON LOW CONTROL AIR PRESSURE
I-236	IEN 80-43	FAILURES OF THE CONTINUOUS WATER LEVEL MONITOR FOR THE SCRAM DISCHARGE VOLUME AT DRESDEN UNIT NO. 2
I-242	IEN 80-37	CONTAINMENT COOLER LEAKS & REACTOR CAVITY FLOODING AT INDIAN POINT 2
I-246	IEN 80-30	POTENTIAL FOR UNACCEPTABLE INTERACTION BETWEEN CRD SCRAM FUNCTION & NON-ESSENTIAL CONTROL AIR AT CERTAIN GE BWR'S
I-249	IEN 80-23	LOSS OF SUCTION TO EMERGENCY FEEDWATER PUMPS
I-251	IEN 80-20	LOSS OF DECAY HEAT REMOVAL CAPABILITY AT DAVIS-BESSEE 1 WHILE REPUELING
I-257	IEN 80-10	PARTIAL LOSS OF NON-NUCLEAR INSTRUMENT SYSTEM POWER SUPPLY DURING OPERATION
I-270	IEN 79-29	LOSS OF NON SAFETY-RELATED REACTOR COOLANT SYSTEM INSTRUMENTATION DURING OPERATION
I-271	IEN 79-28	OVERLOADING OF STRUCTURAL ELEMENTS DUE TO PIPE SUPPORT LOADS
I-275	IEN 79-24	OVERPRESSURIZATION OF CONTAINMENT OF PWR AFTER MAIN STEAM LINE BREAK
I-277	IEN 79-22	QUALIFICATION OF CONTROL SYSTEMS
I-280	IEN 79-16	NUCLEAR INCIDENT AT THREE MILE ISLAND

APPENDIX D - EVENT REFERENCES

REFERENCE NO. -----	REPORT NO. -----	REFERENCE DESCRIPTION -----
I-283	IEN 79-13	INDICATION OF LOW WATER LEVEL AT OYSTER CREEK
I-291	IEN 79-04	DEGRADATION OF ENGINEERED SAFETY FEATURES
I-294	IEN 84-06	STEAM BINDING OF AUXILIARY FEEDWATER PUMPS
I-296	IEB 84-01	CRACKS IN BWR MARK I CONTAINMENT VENT HEADERS
I-297	IEN 84-17	PROBLEMS WITH LIQUID NITROGEN COOLING COMPONENTS BELOW NIL DUCTILITY TEMPERATURE
L0001		219/83-003 AN:181646
L0002		369/82-015 AN:172979
L0003		281/81-026 AN:166303
L0004		263/81-002 AN:165456
L0007		293/80-001 AN:154694
L0008		265/79-011 AN:150365
L0009		287/78-019 AN:146523
L0010		275/LETTER TO NRC, 11/02/78 AN:145378 (ALSO APPLIES TO DOCKET 323)
L0011		338/78-107 AN:145365
L0012		247/77-2-24 AN:143277
L0013		237/78-004 AN:142701
L0014		298/78-033 AN:142294
L0015		220/76-028 AN:119514
L0016		282/75-001 AN:107409
L0017		280/74-001 AN:95911 (ALSO APPLIES TO DOCKET NO. 281)

APPENDIX D - EVENT REFERENCES

<u>REFERENCE NO.</u>	<u>REPORT NO.</u>	<u>REFERENCE DESCRIPTION</u>
L0018		312/74-003 AN:95410
L0019		313/LETTER TO AEC, 01/18/83 AN:77971
L0020		321/80-053 AN:158292
L0021		334/80-023 AN:156200
L0023		255/82-044 AN:180005
L0024		289/82-001 AN:173370
L0025		289/82-001-R1 AN:177357
L0026		255/82-024 AN:175994
L0027		255/82-024-R1 AN:176762
L0028		327/82-070 AN:174154
L0029		285/82-012 AN:173957
L0030		220/82-002 AN:172961
L0031		259/80-011R3 AN:169869
L0032		259/80-011 AN:155192
L0033		261/81-002R1 AN:169531
L0034		261/81-002 AN:163487
L0035		259/80-016 AN:155201
L0037		348/78-086 AN:142743
L0038		255/77-045 AN:130027
L0039		387/LETTER TO NRC, 09/05/78 AN:141461
L0040		277/80-008 AN:158286
L0041		366/80-002 AN:154946
L0042		289/80-001 AN:154696
L0043		213/80-003 AN:154452

APPENDIX D - EVENT REFERENCES

<u>REFERENCE NO.</u>	<u>REPORT NO.</u>	<u>REFERENCE DESCRIPTION</u>
L0044		312/79-013 AN:153446
L0045		321/79-081 AN:151755
L0046		293/79-031 AN:151460
L0047		344/79-008 AN:150027
L0048		331/79-002 AN:149241
L0049		280/79-008 AN:148803
L0050		282/79-009 AN:148759
L0051		263/79-003 AN:148741
L0052		327/80-086 AN:159778
L0053		334/80-060 AN:159355
L0054		280/80-036 AN:159198
L0055		348/80-037 AN:159125
L0056		338/80-042 AN:158731
L0057		295/80-023 AN:158254
L0058		219/82-010 AN:173458
L0059		249/81-039 AN:171843
L0060		237/81-079 AN:172255
L0061		344/81-016 AN:168563
L0062		281/81-036 AN:167214
L0063		244/81-019 AN:171940
L0064		280/81-009 AN:166673
L0065		320/79-012 AN:153164
L0070		280/80-059 AN:160908
L0071		334/80-073 AN:160469

APPENDIX D - EVENT REFERENCES

<u>REFERENCE NO.</u>	<u>REPORT NO.</u>	<u>REFERENCE DESCRIPTION</u>
L0072		327/LETTER TO NRC, 07/20/79 AN:154079
L0073		369/LETTER TO NRC, 08/24/79 AN:154076
L0074		390/LETTER TO NRC, 09/21/79 AN:154075
L0075		339/LETTER TO NRC, 07/02/79 AN:153796
L0076		272/79-050 AN:152739
L0077		348/79-023 AN:152168
L0078		295/79-050 AN:150895
L0079		280/79-022 AN:150767
L0080		344/79-011 AN:150700
L0081		305/79-018 AN:150476
L0082		261/79-019 AN:150475
L0083		334/79-015 AN:150424
L0084		286/79-006 AN:150419
L0085		247/79-018 AN:150408
L0086		280/79-026-R1 AN:153317
L0087		280/79-026 AN:151743
L0088		338/79-120 AN:152332
L0089		338/LETTER TO NRC, 11/05/79 AN:155848
L0090		272/79-058 AN:151735
L0092		325/79-058 AN:151936
L0093		213/78-026-R1 AN:142813
L0094		368/LETTER TO NRC, 04/18/78 AN:140152
L0095		346/78-057 AN:139607
L0096		213/78-006 AN:138369

APPENDIX D - EVENT REFERENCES

REFERENCE NO.	REPORT NO.	REFERENCE DESCRIPTION
L0097		321/78-019 AN:13835* (ALSO APPLIES TO DOCKET 366)
L0098		335/LETTER TO NRC, 04/17/78 AN:137352
L0099		389/LETTER TO NRC, 04/17/78 AN:137353
L0100		368/78 LETTER TO NRC, 04/18/78 AN:137048
L0101		302/77-052 SUPPLEMENT AN:131208
L0102		302/77-052 AN:125539
L0103		313/77-019 AN:129789
L0104		346/LETTER TO NRC, 01/21/77 AN:122427
L0105		346/LETTER TO NRC, 03/23/77 AN:123027
L0106		219/76-029 AN:121031
L0107		438/LETTER TO NRC, 11/01/76 AN:119823
L0108		296/LETTER TO NRC, 03/04/76 AN:112145
L0109		324/75-088 AN:106597
L0110		387/LETTER TO NRC, 01/04/75 AN:102145
L0112		327/80-195 AN:163375
L0113		289/81-009 AN:169269
L0114		346/80-053 AN:159115
L0115		346/80-053R1 AN:163512
L0116		338/80-096 AN:161704
L0117		361/82-002 AN:173265
L0119		338/81-042 AN:166508
L0120		348/81-037 AN:166497
L0121		334/81-045 AN:166347
L0122		259/LETTER TO NRC, 06/09/75 AN:111468

APPENDIX D - EVENT REFERENCES

<u>REFERENCE NO.</u>	<u>REPORT NO.</u>	<u>REFERENCE DESCRIPTION</u>
L0123		259/80-016R1 AN:168942
L0124		304/76-038 AN:119480
L0125		219/79-014 AN:149450
L0126		213/78-018 AN:140161
L0128		416/82-014 AN:175135
L0129		339/81-055 AN:169226
L0130		312/78-001 AN:138830
L0131		324/77-024 AN:124913
L0132		368/78-005 AN:141490
L0133		254/82-012 AN:175258 (ALSO APPLIES TO DOCKET 265)
L0135		334/82-002 AN:153725
L0139		317/LETTER TO NRC, 05/23/75 AN:103125
L0144		329/LETTER TO NRC, 08/07/79 AN:153800
L0145		219/83-011 AN:182394
L0146		219/83-010 AN:182443
L0147		219/83-014 AN:183022
L0148		267/83-018 AN:188376
L0150		272/81-054 AN:166595
L0151		346/80-029 AN:158860
L0152		249/80-31 AN:158229
L0153		368/78-004 AN:141487
L0155		206/80-033 AN:160315
L0156		362/82-006R1 AN:184741

APPENDIX D - EVENT REFERENCES

REFERENCE NO.	REPORT NO.	REFERENCE DESCRIPTION
L0157		266/79-004 AN:148775 (ALSO APPLIES TO DOCKET NO. 301)
L0158		361/LETTER TO NRC, 01/16/78 AN:134494 (ALSO APPLIES TO DOCKET NO. 362)
L0159		338/79-083 AN:150373
L0160		250/79-021 AN:150371
L0161		251/79-010 AN:150367
L0162		280/80-070 AN:161615
L0163		362/82-006 AN:181580
L0164		327/83-162 AN:188148
L0165		261/77-009 AN:126011
L0166		280/81-020R1 AN:188527
L0167		293/81-054R3 AN:171899
L0168		280/81-020 AN:168508
L0169		266/81-009 AN:167694
L0170		336/83-030 AN:188149
L0171		364/80-003 AN:162466
L0172		348/80-076 AN:162463
L0173		320/LETTER TO NRC, 8/28/75 AN:106365
L0174		206/81-001 AN:163843
L0175		321/80-016 AN:154884
L0176		219/80-044 AN:160902
L0177		206/LETTER TO AEC, 03/21/68 AN:47801
L0178		335/LETTER TO NRC, 11/25/75 AN:108823
L0179		254/76-036 AN:120762

APPENDIX D - EVENT REFERENCES

<u>REFERENCE NO.</u>	<u>REPORT NO.</u>	<u>REFERENCE DESCRIPTION</u>
L0180		259/79-017 AN:151439
L 10 01		287/LETTER TO NRC, 04/23/81 AN:171562
L 10 04		302/80-010 AN:160846
L 10 05		327/80-077 AN:159793
L 10 06		368/80-018 AN:158279
L 10 08		334/79-015R1 AN:150885
L 10 09		272/78-072 AN:141236
L 10 10		324/76-077 AN:113275
L 10 14		346/81-045 AN:168592
L 10 15		220/81-001 AN:164440
L 10 17		321/80-082 AN:159189
L 10 18		312/80-014 AN:155505
L 10 20		325/79-097 AN:153363
L 10 22		336/81-006 AN:164147
L 10 23		281/83-055 AN:188195
L 10 24		344/81-008 AN:166413
L 10 26		317/81-079 AN:171387
L 10 27		318/81-047 AN:171109
L 10 28		245/81-002 AN:165884
L 10 29		369/82-015 REV 1 AN:183454
L 10 31		316/82-025 AN:184831
L 10 32		416/83-115 AN:185787
L 10 33		293/81-054 AN:169588
L 10 34		321/81-120 AN:171090

APPENDIX D - EVENT REFERENCES

<u>REFERENCE NO.</u>	<u>REPORT NO.</u>	<u>REFERENCE DESCRIPTION</u>
L 1035		317/80-041 AN:159453
L 1037		272/81-110 AN:171528
L 1038		348/80-069 AN:161784
L 1039		327/80-180 AN:161749
L 1040		305/75-020 AN:108078
L 1041		318/78-035 AN:141523
L 1042		280/77-021 AN:130889
L 1043		254/LETTER TO AEC, 06/17/72 AN:075977
L 1044		364/80-001 AN:161769
L 1045		304/81-033 AN:171733
L 2001		255/LETTER TO AEC, 03/02/72 AN:069527
L 2002		255/LETTER TO AEC, 09/16/71 AN:065969
L 2004		155/79-22-R1 AN:153973
L 2005		155/79-22 AN:151825
L 2007		155/77-44 AN:130833
L 2009		245/79-026 AN:151912
L 2011		244/LETTER TO AEC, 10/23/73 AN:087031
L 2012		244/LETTER TO AEC, 10/31/71 AN:085370
L 2013		244/LETTER TO AEC, 10/31/73 AN:085369
L 2014		244/LETTER TO AEC, 04/29/71 AN:066927
L 2017		219/LETTER TO AEC, 09/18/73 AN:083833
L 2020		335/82-050 AN:179450
L 2021		251/82-013 AN:177393
L 2023		206/81-018 AN:168122

APPENDIX D - EVENT REFERENCES

REFERENCE NO.	REPORT NO.	REFERENCE DESCRIPTION
L2024		301/LETTER TO AEC, 12/19/74 AN:099037
L2025		277/79-016 AN:149260
L2026		334/80-067 AN:160142
L2027		245/LETTER TO AEC, 05/12/71 AN:063125
L2030		250/LETTER TO AEC, 11/17/72 AN:076406
L2032		272/LETTER TO AEC, 02/06/75 AN:093620
L2034		324/75-148 AN:109263
L2036		368/83-035 AN:185904
L2037		281/83-040 AN:186451
L2038		318/83-060 AN:187090
L2053		318/82-034 AN:175551
L2054		317/80-027 AN:158650
L5003		261/81-005 AN:164149
L5004		304/76-017 AN:117080
L5005		280/80-026 AN:156952
L5006		304/80-026 AN:161826
M0004	NS18 (4) :549-551	HUMAN ERROR CAUSES DG FIRE AT ZION 2, 09/18/76
M0005	NUREG/CR-1901	REVIEW AND EVALUATION OF SYSTEM INTERACTIONS METHODS
M0006	NS21 (5) :655-656	LOSS OF DECAY-HEAT-REMOVAL CAPABILITY AT DAVIS-BESSE 1, 04/19/80
M1001	NUREG-0090 V2,#1	REPORT TO CONGRESS ON ABNORMAL OCCURRENCES, JANUARY-MARCH, 1979
M1003	NUREG-0090 V2,#2	REPORT TO CONGRESS ON ABNORMAL OCCURRENCES, APRIL-JUNE, 1979

APPENDIX D - EVENT REFERENCES

<u>REFERENCE NO.</u>	<u>REPORT NO.</u>	<u>REFERENCE DESCRIPTION</u>
M1004	NUREG-0090 V5, #3	REPORT TO CONGRESS ON ABNORMAL OCCURRENCES, JULY-SEPTEMBER, 1982
M1005	NS19(6):765-767	COMMON-CAUSE INCIDENT INVOLVING NON-NUCLEAR INSTRUMENTATION AT RANCHO SECO, 03/20/77
M1007	NUREG-75/090	REPORT TO CONGRESS ON ABNORMAL OCCURRENCES, JANUARY-JUNE, 1975
M1008	NUREG-0090-3	REPORT TO CONGRESS ON ABNORMAL OCCURRENCES, JANUARY-MARCH, 1976
M1009	NUREG-0090 V6, #1	REPORT TO CONGRESS ON ABNORMAL OCCURRENCES, JANUARY-MARCH, 1983
M1010	NUREG-0090-5	REPORT TO CONGRESS ON ABNORMAL OCCURRENCES, JULY-SEPTEMBER, 1976
M2001	NUREG/CR-2497	PRECURSORS TO POTENTIAL SEVERE CORE DAMAGE ACCIDENTS: 1969-79. A STATUS REPORT

BIBLIOGRAPHIC DATA SHEET

NUREG/CR-3922
ORNL/NOAC-224
Vol. 2

SEE INSTRUCTIONS ON THE REVERSE

2 TITLE AND SUBTITLE

Survey and Evaluation of System Interaction Events
and Sources
Appendices C and D

3 LEAVE BLANK

4 DATE REPORT COMPLETED

MONTH

YEAR

December

1984

6 DATE REPORT ISSUED

MONTH

YEAR

January

1985

5 AUTHOR(S)

G.A. Murphy/NOAC
M.L. Casada, M.P. Johnson, M.D. Muhlheim, J.J. Rooney,
J.H. Turner/JFBA

7 PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)

Nuclear Oper. Analysis Center Subcontractor:
Oak Ridge National Laboratory JBF Associates, Inc.
P. O. Box Y 1000 Technology Park Ctr
Oak Ridge, TN 37831 Knoxville, TN 37932

8 PROJECT/TASK/WORK UNIT NUMBER

9 FIN OR GRANT NUMBER

B0789

10 SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)

Division of Safety Technology
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, DC 20555

11a TYPE OF REPORT

Technical

b PERIOD COVERED (Inclusive dates)

12 SUPPLEMENTARY NOTES

13 ABSTRACT (200 words or less)

This report describes the first phase of an NRC-sponsored project that identified and evaluated system interaction (SI) events that have occurred at commercial nuclear power plants in the United States. The project included: an assessment of nuclear power plant operating experience data sources; the development of search methods and event selection criteria for identifying SI events; review of possible SI events; and final evaluation and categorization of events. The report outlines each of these steps and presents the results of the project. The results include 235 events identified as adverse system interactions and 23 categories into which those events were assigned. The categories represent groups of similar events and include areas such as: adverse interactions between normal or offsite power and emergency power systems; degradation of safety systems by vapor or gas intrusion; degradation of safety-related equipment by fire protection systems; and flooding of safety-related equipment through plant drain systems. After evaluating each category (and the events contained in them), the project made two major recommendations: the safety significance of each category with emphasis on the potential for continued problems in these areas should be examined; and current system interaction analyses methods should be studied to determine their effectiveness for identifying system interaction events. (Phase II of this project, "Evaluation of System Interaction Methods," will assess the effectiveness of current methods using the events identified in this report).

14 DOCUMENT ANALYSIS - KEYWORDS/DESCRIPTORS

Systems Analysis

15 AVAILABILITY STATEMENT

Unlimited

16 SECURITY CLASSIFICATION

(This page)

Unclassified

(This report)

Unclassified

17 NUMBER OF PAGES

18 PRICE

IDENTIFIERS-OPEN ENDED TERMS

Adverse Systems Interaction
Unresolved Safety Issue A-17

UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D.C. 20555

OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE, \$300

FOURTH CLASS MAIL
POSTAGE & FEES PAID
USNRC
WASH. D.C.
PERMIT No. G-87