

UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

DOCKETE

RELATED CONNESPONDENCE

*84 OCT 25 A10:43

October 22, 1984

DOCKETING & SERVE BRANCH

Peter B. Bloch, Esq., Chairman Administrative Judge Atomic Safety and Licensing Board U.S. Nuclear Regulatory Commission Washington, DC 20555

Dr. Walter H. Jordan Administrative Judge 881 W. Outer Drive Oak Ridge, TN 37830

Herbert Grossman, Alternate Chairman Administrative Judge Atomic Safety and Licensing Board U.S. Nuclear Regulatory Commission Washington, DC 20555

Dr. Kenneth A. McCollom Administrative Judge Dean, Division of Engineering, Architecture & Technology Oklahoma State University Stillwater, OK 74078

50-445-04

In the Matter of Texas Utilities Electric Company, et al. (Comanche Peak Steam Electric Station, Units 1 and 2) Docket Nos. 50-445, 50-446, 50-445/2, and 50-446/2

50-44506-2 50-446 06-2

Dear Administrative Judges:

The NRC Staff ("Staff") has recently issued Inspection Report 84-16 (October 4, 1984). Inspection Report 84-15 discusses the Staff's third walkdown inspection at the Comanche Peak Steam Electric Station ("CPSES"). During this inspection, portions of the CPSES Unit 1 containment building were inspected by the Staff, and two violations of NRC requirements were identified (445/8416-01; 445/8416-02). Copies of this Inspection Report are enclosed for the information of the Board.

The Staff has also transmitted a letter dated October 11, 1984 to the Applicants requesting additional information on Applicants' response to a Notice of Violation (445/8921-02). This Notice of Violation was first identified in Inspection Report 84-21 (July 18, 1984). Since the Board

has previously indicated its interest in Inspection Report 84-21, a copy of the October 11, 1984 Staff letter regarding this Inspection Report is enclosed for the information of the Board.

Sincerely,

Gary S. Mizuno

Counsel for NRC Staff

Enclosures: As stated

cc w/encl.: Anthony Roisman

cc w/o encl.: Remainder of Service List



UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

October 22, 1984

Peter B. Bloch, Esq., Chairman Administrative Judge Atomic Safety and Licensing Board U.S. Nuclear Regulatory Commission Washington, DC 20555

Dr. Walter H. Jordan Administrative Judge 881 W. Outer Drive Oak Ridge, TN 37830 Herbert Grossman, Alternate Chairman Administrative Judge Atomic Safety and Licensing Board U.S. Nuclear Regulatory Commission Washington, DC 20555

Dr. Kenneth A. McCollom Administrative Judge Dean, Division of Engineering, Architecture & Technology Oklahoma State University Stillwater, OK 74078

In the Matter of
Texas Utilities Electric Company, et al.
(Comanche Peak Steam Electric Station, Units 1 and 2)
Docket Nos. 50-445, 50-446, 50-445/2, and 50-446/2

Dear Administrative Judges:

The NRC Staff ("Staff") has recently issued Inspection Report 84-16 (October 4, 1984). Inspection Report 84-16 discusses the Staff's third walkdown inspection at the Comanche Peak Steam Electric Station ("CPSES"). During this inspection, portions of the CPSES Unit 1 containment building were inspected by the Staff, and two violations of NRC requirements were identified (445/8416-01; 445/8416-02). Copies of this Inspection Report are enclosed for the information of the Board.

The Staff has also transmitted a letter dated October 11, 1984 to the Applicants requesting additional information on Applicants' response to a Notice of Violation (445/8921-02). This Notice of Violation was first identified in Inspection Report 84-21 (July 18, 1984). Since the Board

has previously indicated its interest in Inspection Report 84-21, a copy of the October 11, 1984 Staff letter regarding this Inspection Report is enclosed for the information of the Board.

Sincerely,

Geary S. Mizuno

Counsel for NRC Staff

Enclosures: As stated

cc w/encl.: Anthony Roisman

cc w/o encl.: Remainder of Service List

10-11-84

In Reply Refer To: Docket: 50-445/84-21

Texas Utilities Electric Company ATTN: M. D. Spence, President, TUGCO Skyway Tower 400 North Olive Street Lock Box 81 Dallas, Texas 75201

Thank you for your letter of August 17, 1984, in response to our letter and the attached Notice of Violation dated July 18, 1984. As a result of our review, we find that additional information is needed as discussed with your Mr. R. E. Camp on September 24, 1984.

Specifically, the preventive action taken to assure proper indication of installed instrumentation when used for certified test data appears unlikely to provide that assurance. Your letter refers to a change to CP-SAP-7, "Format and Content of Test Instructions/Procedures." Upon reviewing the August 15, 1984, interim change to Section 4.3.3.6.h of CP-SAP-7, we are concerned that the added note does not direct the procedure writer to include a prerequisite or test step which ensures that installed instrumentation (whether previously in service or not) is filled and vented just prior to obtaining preoperational test data. Instead the change suggests that the writer consider such a provision, and then only where the proposed preoperational or acceptance test procedure places the system in service vice the "System Operating Procedure." Whether or not the preoperational test places the system in service is not germaine to the problem. Also, whether the system has been in or out of service before the test has little effect on the presence of air in dead-ended differential pressure detector piping. The interim change to CP-SAP-7 does not appear to provide reasonable assurance that differential pressure detectors will provide reliable data because it does not require the test procedure to contain provisions for filling and venting such detectors before data are obtained. Unless this assurance is provided, Criterion XI and XII of 10 CFR 50, Appendix B would not be satisfied.

In light of the above concern, your response to Notice of Violation 445/8421-02 is inadequate with respect to "preventive action."

Please provide the supplemental information within 30 days of the date of this letter.

Sincerely,

Original Signed by: R. L. BANGART

Richard L. Bangart, Director Region IV Comanche Peak Task Force

cc:
Texas Utilities Electric Company
ATTN: B. R. Clements, Vice
President, Nuclear
Skyway Tower
400 North Olive Street
Lock Box 81
Dallas, Texas 75201

Texas Utilities Electric Company
ATTN: H. C. Schmidt, Manager
Nuclear Services
Skyway Tower
400 North Olive Street
Lock Box 81
Dallas, Texas 75201

TEXAS UTILITIES GENERATING COMPANY

SKYWAY TOWER * 400 NORTH OLIVE STREET, L.B. 81 * DALLAS, TEXAS 75201

BILLY R. CLEMENTS

August 17, 1984 TXX-4253

AUG 17 1984

Mr. Richard L. Bangart, Director Region IV Comenche Peak Task Force U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, TX 76011

Docket Nos.: 50-445

50-446

Comanche Peak Steam Electric Station Response to NRC Notices Of Violations Inspection Report No. 84-21 File No.: 10130

Dear Mr. Bangart:

We have reviewed your letter dated July 18, 1984 on the inspection conducted by the Office of Inspection and Enforcement and by Mr. W. F. Smith regarding Comanche Peak, Unit 1. We have responded to the findings listed in the Appendix of that letter.

To aid in the understanding of our response, we have repeated the requirements and your findings, followed by our corrective actions. We feel the enclosed information to be responsive to the Inspector's findings. If you have any questions, please advise.

Very truly yours,

for Billy R. Clements

BRC:msc

c: NRC Region IV - (0+1)

Director, Inspection & Enforcement (15 copies)
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

NOTICE OF VIOLATION

Texas Utilities Electric Company Comanche Peak Steam Electric Station Docket: 50-445/84-21 Construction Permit: CPPR-126

Based on the results of an NRC inspection conducted during the period of June 14-16, 1984, and in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C), 49 FR-8583, dated March 8, 1984, the following violations were identified:

 Criterion V of Appendix B to 10 CFR 50 states, in part, "Activities affecting quality shall be prescribed by documented instructions, procedures, or drawings, of a type appropriate to the circumstances and shall be accomplished in accordance with these instructions, procedures, or drawings . . ."

Contrary to the above, on June 16, 1984, an operator proceeded to partially open Station Service Water Chlorination Valve XSW-042 in violation of Step 5.4.1.6 of System Operating Procedure SOP-501A (Rev. 0), "Station Service Water System," which requires XSW-036 to be opened. The operation was aborted and the valve restored to the shut position only after the NRC inspector pointed out the procedure violation. Subsequently, it was determined that the procedure was in error, thus was changed accordingly and the operation resumed by opening Valve XSW-042.

This is a Severity Level IV Violation. (Supplement II-D) (445/8421-01)

Discussion

The subject violation occurred during conduct of a preoperational test. The CPSES Final Safety Analysis Report (FSAR) requires trial use of plant operating procedures during the startup test program. The following is an excerpt from the CPSES FSAR, Section 14.2.9:

14.2.9 TRIAL USE OF PLANT OPERATING AND EMERGENCY PROCEDURES

The plant operating emergency and surveillance procedures will be usetested during the test program and will also be used in the development of preoperational and initial startup procedures to the extent practical. The trial use of operating procedures serves to familiarize operating personnel with systems and plant operation during the testing phase and also serves to assure the adequacy of the procedures under actual or simulated operating conditions before plant operation begins.

Prior to fuel load, draft operating procedures may be utilized for equipment operation and may be informally altered to meet special test considerations.

Although the use of draft operating procedures and their informal alteration is allowed by the FSAR, CPSES has chosen to use approved procedures to support testing activities in order to provide a controlled mechanism for documenting procedure deficiencies and changes. That mechanism is the temporar; change process.

The operator involved was using System Operating Procedure SOP-501A, Rev. 0, to chlorinate the Station Service Water inlet. The procedure required the operation of the chlorination inlet valve, XSW-036. The chlorination inlet valve is routinely operated and operators are familiar with its location and use. The operator opened the proper valve. However, the valve was tagged XSW-042 instead of XSW-036 due to renumbering between Revisions CP-1 and CP-2 of the flow diagram. Because the procedure was in trial use as required by the FSAR, it had not yet been revised to reflect the valve number change. Therefore, even though the correct valve was operated, a violation of the procedure occurred in that the valve tagged XSW-042 was operated when the procedure called for the operation of valve XSW-036. It should be noted that the operator consulted with the System Test Engineer prior to operating the valve to ensure that the operation supported the test in progress.

Corrective Action

The on-duty Shift Supervisor initiated Deficiency Report 84-054 which was reviewed by the Operations Quality Assurance Supervisor. The Deficiency Report documented the violation of the procedure. Final disposition of the deficiency was completed on July 5, 1984, and documented appropriate retraining of the operator involved.

Preventive Action

The operator has been reminded of the need to follow approved operating procedures when performing operating evolutions. In addition, he has completed retraining involving procedures STA-205, "Temporary Changes to Procedures", and SOP-501A, "Station Service Water System".

Furthermore, the Operations Supervisor met with each shift operating crew, including Supervisors, Reactor Operators and Auxiliary Operators to review this incident and to emphasize the proper use and adherence to approved procedures.

Also, Special Order 1-50-84-003 specifies that all safety related operating activities will be carried out in accordance with approved procedures. This Special Order is reviewed by the Shift Supervisor at each shift change.

Date of Full Compliance

Corrective and preventive actions have been completed.

- 2. Criterion XI of Appendix B to 10 CFR 50 states in part, "... the test program shall include, as appropriate, proof test prior to installation, preoperational tests, and operational tests during nuclear power plant or fuel reprocessing plant operation of structures, systems, and components. Test procedures shall include provisions for assuring that all prerequisites for the given test have been met, ..."
 - a. Contrary to the above, during the performance of the Diesel Generator Control Circuit Functional and Start Test, 1CP-PT-29-02 RT-1, the NRC inspector noted that there was no prerequisite in the test procedure to provide for station service air so that Step 7.1.6.7 can be performed to operate the barring device, which requires service air to function.

This became apparent to the NRC inspector when he noticed the service air piping was not connected to the barring device. In lieu of service air, the STE utilized temporary air from a portable air compressor, which is not addressed by the procedure.

b. Contrary to the above, the station service water flow balancing test procedure, ICP-PT-04-01, had no prerequisite requirement to ensure the flow gages used during Step 7.8 (Flow Adjustment) were properly filled and vented. Failure to fill and vent these detectors just prior to flow adjustment can cause erroneous flow gage indications. This can place the flow data in question. As a result, during conduct of Step 7.8 of the test, the service water flow gage for containment spray was pegged high with no flow. It was evident that the gage was malfunctioning due to air binding or other mechanical problem.

This is a Severity Level IV Violation. (Supplement II-E) (445/8421-02)

Discussion

- As identified in the finding above, it is acknowledged that one primary 2a. support system (Service Air) was not specified as a prerequisite requirement for conduct of the test. The purpose of the test section noted was to demonstrate barring device operation in the "Maintenance Mode," therefore an air supply was required. As no prerequisite existed requiring a specified air supply, the System Test Engineer noted in the test log that a temporary air compressor would be used to perform the step. At that time, two deficient conditions existed: 1) the service air prerequisite was overlooked during the original procedure review and approval, and 2) the STE failed to properly document the addition of the required air supply in accordance with Startup Administrative Procedure CP-SAP-12. The proposed corrective action below will address these two deficient conditions, since the operability of the barring device was satisfactorily demonstrated as required in 1CP-PT-29-01 RT-1, Step 7.1.6.7.
- 2b. Test Section 7.8 began June 16, 1984 at 0853. After establishing conditions required to perform the flow balance, (Steps 7.8.1 through 7.8.5) the balancing commenced at 1330. At 1500, the test chronological

log notes that all components were aligned and the subject flow indicator would not respond. TUGCo I&C personnel arrived to check the instrument at 1540. After attempting to fill and vent the instrument, it was ascertained that a three-way valve manifold was clogged. At 1615, the test was terminated with no data taken. On June 18, 1984, at 1950, the test section was resumed with a log entry stating that the I&C personnel placed the flow indicator in service after unclogging the three-valve manifold. Test steps 7.8.1 through 7.8.5 were reperformed and the balance was satisfactorily demonstrated at 2150.

Since the Service Water System was in service for a significant length of time prior to conduct of the preoperational test, and the test procedure was not used for initial filling, venting and placing the system into operation, it was not deemed necessary to verify instrument filling and venting as a prerequisite to 1CP-PT-04-01. As indicated above, the erratic instrument was identified and the problem corrected prior to repeating the applicable test steps and recording the required test data. Therefore, the test procedure and results are satisfactory.

Corrective Action

No retests are required to correct the deficiencies described above. The diesel generator cognizant System Test Engineer will be counseled on proper utilization of Startup Administrative Procedure requirements when procedural problems are identified.

Preventive Action

Each organization responsible for review of preoperational test procedures has been instructed to ensure that test prerequisites receive a comprehensive review to ensure system readiness to test and correct component configuration to assure validity of the test results. All Startup personnel responsible for authorizing and performing preoperational tests have been instructed to perform a comprehensive review of test prerequisites prior to authorization of the tests to be performed.

Since preoperational test procedures are not typically used for system filling, venting and initial operation, we do not require that each preoperational test contain prerequisites for verifying proper filling and venting of the system or instrumentation. However, for cases when preoperational test procedures are used to provide instructions for system filling, venting, etc., Startup Administrative Procedure CP-SAP-7 will be revised to ensure that instructions are also provided for instrumentation filling and venting prior to test data acquisition.

Date of Full Compliance

Corrective and Preventive Actions will be completed by August 15, 1984.

10-1-84

In Reply Refer To: Docket: 50-445/84-16

Texas Utilities Electric Company
ATTN: M. D. Spence, President, TUGCO
Skyway Tower
400 North Olive Street
Lock Box 81
Dallas, Texas 75201

Gentlemen:

This refers to the special inspection of the Unit 1 reactor containment building conducted by Mr. L. E. Martin and other members of our staff during the period May 14 through June 20, 1984, of activities authorized by NRC Construction Permit CPPR-126 for the Comanche Peak Facility, Unit 1, and to the discussion of our findings with Messrs. J. T. Merritt and A. Vega and other members of your staff at the conclusion of the inspection.

This inspection is the third in a series of planned construction completion room/area inspections. The primary purpose of this inspection was to evaluate the actual as-built status of the reactor containment building as compared to the design and inspection documentation. This inspection covered certain construction characteristics, such as, workmanship, welding, pipe supports, inspection adequacy, etc., which have been the subject of contentions during the ASLB hearing. As you are aware, the Comanche Peak Technical Review Team has a separate effort ongoing to review technical issues and allegations related to these same characteristics for this and other safety-related areas of the plant. As a consequence, this inspection should not be construed to represent the complete or final findings of the as-built status of the containment building.

Areas examined during the inspection included piping and pipe supports, containment penetrations, HVAC ducts and supports, electrical raceway and supports, safety-related equipment, "as-built" program, QC inspector and welder qualifications, and followup on one unresolved item from the special inspection of the fuel building. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews and discussions with craft and QC personnel, and observations by the inspectors. The findings are documented in the enclosed inspection report.

During this inspection, it was found that certain of your activities were in violation of NRC requirements. Consequently, you are required to respond to these violations, in writing, in accordance with the provisions of Section 2.201 of the NRC's "Rules of Practice." Part 2, Title 10, Code of

Federal Regulations. Your response should be based on the specifics contained in the Notice of Violation enclosed with this letter.

Your response to Item A of the attached Notice of Violation should address the adequacy of inspection of these cable tray hangers (CTHs). It is recognized that the as-built conditions of these hangers are adequate for the intended design function and that the engineering analysis indicates that all of these hangers will be used as they are installed with the exception of CTH 6567 (bevelled washer). Therefore, your response to this violation should address the corrective action and recurrence controls for the inspection of these cable tray hangers.

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosures will be placed in the NRC Public Document Room unless you notify this office, by telephone, within 10 days of the date of this letter, and submit written application to withhold information contained therein within 30 days of the date of this letter. Such application must be consistent with the requirements of 2.790(b)(1).

The response directed by this letter and the accompanying Notice is not subject to the clearance procedures of the Office of Management and Budget as required by the paperwork reduction act of 1980, PL 96-511.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Richard L. Bangart

R. L. Bangart, Director

Region IV Comanche Peak Task Force

Enclosures:

1. Appendix A - Notice of Violation

2. Appendix B - NRC Inspection Report 50-445/84-16

cc w/enclosures:

Texas Utilities Electric Company ATTN: B. R. Clements, Vice

President, Nuclear Skyway Tower

400 North Olive Street Lock Box 81 Dallas, Texas 75201 Texas Utilities Electric Company
ATTN: H. C. Schmidt, Manager
Nuclear Services
Skyway Tower
400 North Olive Street
Lock Box 81

Dallas, Texas 75201

APPENDIX A

NOTICE OF VIOLATION

Texas Utilities Electric Company Comanche Peak Steam Electric Station Docket: 50-445/84-16

Construction Permit: CPPR-126

Based on the results of an NRC inspection conducted during the period of May 14 through June 20, 1984, and in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C), 47 FR 8583, dated March 9, 1984, the following violations were identified:

A. Failure to Properly Inspect Cable Tray Hangers (CTHs)

10 CFR Part 50, Appendix B, Criterion X requires that the inspection program of activities affecting quality shall be established and conducted in a manner to verify conformance with the documented instructions, procedures, and drawings.

Procedure QI-QP-11.10-2, Rev. 27, "Cable Tray Hanger Inspection," specifies the inspection attributes for inspecting assembly, configuration, base plate grouting, welding, etc., for conformance with design drawings and documents.

Contrary to the above:

- The NRC inspectors identified two cases where three supports shared common clip angle attachments to the concrete wall. CTHs 6503, 6504, and 6505 shared a common clip angle that was not called for on Drawing 2323-S-903, Detail D for Case SP4 or on Component Modification Card (CMC) 11097. CTHs 6576, 6577, and 6578 shared common clip angles that were not called for on Drawing 2323-S-903, Detail D for SP4.
- 2. We NRC inspectors identified two hangers where the dimensions did not agree with the drawings. CTHs 6632 and 6638 both have installed dimensions that are more than the ±1/4 inch allowed tolerance from those specified in the appropriate design documents. The dimensional errors are specifically documented on Nonconformance Report M84-01834. The dimensional errors of the members varied from 7/8 of an inch to 1 1/8 of an inch shorter than those shown on the FSE-00159 drawing.
- The NRC inspectors identified two cable tray hangers that did not have the weld configuration specified on the design drawings.

CTH 6642 and CTH 6645 both had horizontal welds at the clip angle to support connection and the design drawings specified vertical welds.

4. The NRC inspectors identified five cable tray hangers that had wall/floor connections that did not conform to those specified by the design drawings. CTH 6657 had a bevelled washer that was improperly installed so that it actually decreased the bearing surface between the nut and the clip angle. CTH 5519 did not have 1 inch of grout under base plate as specified on Drawing 2323-S-913, Detail 6. CTHs 5491, 5498, and 5499 had clip angles that utilized a combination of welding to embed plates and Hilti bolts for the wall or beam attachment for which there was no detail.

The above are examples identified by the NRC inspectors where cable tray hangers were installed by the craft to conditions other than those specified by the identified design documents and the QC inspectors failed to identify and document these conditions.

This is a Severity Level IV Violation. (Supplement II.D) (445/8416-01)

B. Failure to Provide Controlled Issuance of Design Documents and Changes
Thereto

10 CFR Part 50, Appendix B, Criterion VI, "Document Control," requires that documents, such as instructions, procedures, and drawings, including changes thereto, be controlled and properly distributed to the location where activities affecting quality are conducted. ANSI N45.2.11, Section 7 requires that documented procedures be used to control the issuance of design documents and changes thereto and that these procedures shall assure that documents are properly distributed.

Contrary to the above, it was determined that issuance of design documents and changes thereto were not being controlled by Operations Document Control Center (DCC). Specifically, the actual status of design drawings in the control room, file 003, could not be determined. The list of CMCs and design change authorizations identified by Operations DCC to be applicable did not agree with the Construction DCC list. In addition, the effective revision of Drawings 2323-M1-0301 (CP-5), M1-0261 (CP-4), and M1-0262 (CP-4) were not found in the control room file.

This is a Severity Level V Violation. (Supplement II.E) (445/8416-02)

Pursuant to the provisions of 10 CFR Part 2.201, Texas Utilities Electric Company, is hereby required to submit to this office, within 30 days of the date of this Notice, a written statement or explanation in reply, including:

(1) the corrective steps which have been taken and the results achieved;

(2) corrective steps which will be taken to avoid further violations; and

(3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Dated:	October	4,	1984	
	AND RESIDENCE AND PERSONS AND	MUNICIPAL PROPERTY.	STATE OF THE OWNER, WHEN PERSON AND PARTY.	-

APPENDIX B

U. S. NUCLEAR REGULATORY COMMISSION

REGION IV

NRC Inspection Report: 50-445/84-16

Construction Permit: CPPR-126

Docket: 50-445

Category: A2

Licensee: Texas Utilities Electric Company

Skyway Tower

400 North Olive Street

Lock Box 81

Dallas, Texas 75201

Facility Name: Comanche Peak Steam Electric Station (CPSES), Unit 1

Inspection At: CPSES, Unit 1, Glen Rose, Texas

Inspection Conducted: May 14 - June 20, 1984

Inspectors:

(paragraphs 1, 2, 3, 4, 1, 10, 12, and 13)

C. R. Oberg, Reactor Inspector, RIV Task Force (paragraphs 4, 5, 6, 7, 8, 9 and 11)

8/29/84 Date

Other

Accompanying

Personnel:

W. R. Bennett, Reactor Inspector, RIV

M. E. Skow, Reactor Inspector, RIV

Approved:

Hunnicutt, Team Leader, RIV Task Force

Inspection Summary

Inspection Conducted May 14-June 20, 1984 (Report 50-445/84-16)

Areas Inspected: Special inspection of construction completion inside Unit 1 containment building of piping and pipe supports; penetrations; heating, ventilation, and air conditioning ducts and supports; safety-related equipment; electrical raceway and supports; as-built program; QC inspector/welder qualifications; and followup on one unresolved item from the special inspection of the fuel building. The inspection involved 801 inspector-hours onsite by four NRC inspectors.

Results: Within the eight areas inspected, two violations were identified. One violation was identified in the electrical area pertaining to cable tray hanger inspections (445/8416-01, paragraph 7.b) and one violation was identified in the as-built program area pertaining to document control (445/8416-02, paragraph 9.e).

DETAILS

1. Persons Contacted

Principal Licensee Contacts

- J. T. Merritt, Assistant Project General Manager
 *L. F. Fikar, Executive Vice President, Engineering
- *A. Vega, Site QA Manager
- *J. C. Kuykendall, Manager Nuclear Operations
- *B. J. Murray, Building Manager
- J. Kinavy, Assistant Building Manager
- M. McBay, Engineering Manager
- *L. M. Popplewell, Project Engineering Manager
 *L. M. Bielfeldt, Quality Engineering Supervisor
- *W. R. Deatherage, Executive Assistant, Office of Project General Manager
- *C. Killough, Quality Surveillance Supervisor
- *J. Brackney, Records Supervisor
- B. C. Scott, QA Supervisor
- I. Vogelsang, Project Electrical Engineer
- R. Camp, Start Up Supervisor
- M. Hudgins, Electrical Test Group
- R. Calder, Nuclear Engineering Manager
- M. Strange, Supervising Engineer
- R. R. Wistrand, Administrative Superintendent

Other Contractor Contacts

- R. Langston, Brown and Root (B&R) Insulation Superintendent
- T. Chandler, B&R, QC Inspector
- S. Perry, B&R, QC Inspector
- J. Hobbs, B&R, Paper Flow Group
- B. Edwards, Bahnson, Project Manager
- D. O'Brien, Bahnson, Project Manager
- D. Williams, Chicago Bridge and Iron (CBI), QC Supervisor
- R. Moehler, Westinghouse, Site Representative
- J. Foland, Westinghouse, Nuclear Controls Engineer

The NRC inspectors also contacted other plant personnel including members of the construction, technical, quality assurance, and administrative staffs.

^{*}Denotes those attending the exit interview on June 20, 1984.

2. Inspection Objectives and Scope

The objective of this inspection was to evaluate the construction completion of the Unit 1 reactor containment building. This objective was accomplished through examination of installed equipment and hardware to ensure that the installation conforms with FSAR commitments and approved design documents as detailed in the inspection packages.

For each of the areas inspected, prepared inspection data sheets were utilized to define the inspection attributes, acceptance criteria, and results. These inspection data sheets are included as an attachment to this report. Also included in the scope of this inspection were informal discussions with craft and QC personnel and subjective evaluations by the NRC inspectors of their job knowledge.

The areas selected for examination were:

- Piping and piping supports including certain instrumentation for six different piping systems
- Containment penetrations
- HVAC ducts and supports
- · Electrical raceway/supports, terminations, and electrical separation
- Equipment installation and procurement
- · Review of as-built program
- · Review of QC inspector and welder qualifications

This inspection included followup and closure of unresolved item 445/8323-06 from NRC Inspection Report 50-445/83-23 as documented in paragraph 11 of this report.

The major portion of this inspection was done during the period of May 14 through June 20, 1984, and was bounded by the 860' and above elevations of the reactor containment building. However, a portion of this inspection for the main steam, pressurizer relief, and reactor coolant systems occurred in January and February 1984. The inspection of these systems coupled with the inspection of the other systems documented in this report cover most of the elevations in the reactor containment building for Unit 1.

3. Status of Unit 1 Reactor Containment Building

The Unit 1 reactor containment building was essentially complete from the 860' elevation and above. The major construction activities in those areas involved cleaning, touch up painting, and insulation installation.

The following is a summary of the open items as of June 1, 1984, from the master data base (MDB) system (punch list) for the Unit 1 reactor containment building at elevation 860' and above:

Coatings	26
Craft	25
Engineering	18
Quality	17
Start Up/Testing	263
Miscellaneous	35
	384

As seen from above, the majority of the open items were in the startup and testing area, with very few construction items remaining open. At the time of this inspection, access controls for this area were in place.

There was still considerable construction activity in the two lower levels of the reactor containment building. A large clean up and coatings effort was underway. The reactor containment building at all elevations will soon be complete and access controls will be in place.

4. Piping and Pipe Supports

a. Attributes

Predetermined attributes for inspection were identified on the specific inspection data sheet. The following listing gives a detailed description of these attributes:

- (1) Welding The type and size of welds and their location and spacing where detailed as specified by the various design documents.
- (2) Hardware Support members and fasteners were proper type and size with proper orientation.
- (3) Connections Ceiling/wall, etc., connections to attachments per design documents.
- (4) Physical Conditions Dimensions of support members, piping, and their location per design documents.
- (5) Attachments Size of attachment, welding and/or Hilti bolt/Richmond inserts verified for size, type, thread engagement, bearing, spacing, and depth.

- (6) Base Plates Size per design document and sufficient bearing surface contact.
- (7) Grouting Used where specified or appropriate.
- (8) Clearances Sufficient space from interferences to allow for specified thermal expansion and movement.
- (9) Workmanship Conforms to generally accepted craft work practices.
- (10) Documentation Review of installation and inspection records to ensure that these records document the as-installed piping and supports and agree with the current approved design information.

b. Reactor Coolant System (RCS)

(1) General - The construction work on the RCS was found to be essentially complete. The primary system hydrostatic test and the hot functional test (HFT) had been completed. The RCS was open and the reactor pressure vessel head was removed. Work was being done on the system in the areas of instrument calibration and fit up of crossover leg restraint spacers. Reflective insulation had been installed. Grouting of various support base plates was being done. Considerable activity in cleaning up spaces and components and the application of protective coatings was also noted.

(2) Inspection Scope and Inspection Criteria Utilized

Inspection of the RCS included a review of selected portions of the following areas:

- Foundations
- Safety Related Structures
- Safety Related Components
- Instrumentation

Portions of management systems were tested by examination of documents and procedures as they were directly applicable to some of the areas listed above. These included:

- Corrective Actions
- Design Change Control

- Procurement
- Maintenance
- Equipment Qualifications

The FSAR was reviewed to determine system technical requirements and licensee commitments. Applicable drawings and design change authorizations (DCAs) were reviewed. In addition, records of QC inspections, craft installation records, and other applicable documents were reviewed to determine the specific craft construction and QC inspection requirements. A detailed list of documents reviewed is contained in Attachment 1.

(3) Foundations

(a) Foundation for Reactor Coolant Pump (RCP) and Steam Generator (SG) Supports

The documents including applicable drawings relating to the foundations of the RCP and SG supports were reviewed by the NRC inspector. The following information was found to be documented:

- Traveler ME81-2154-5500 identified the need for grouting the columns.
- Grout Card 186 documented that grouting was authorized by B&R engineering and performed on December 23, 1981.
- Comprehensive strength of the three grout cubes averaged 8450 psi (6000 psi required).

The applicable drawings were found to differ in one area. Westinghouse Drawing 1457F29 (Rev. 5) and Traveler ME81-2154-5500 both called for approximately 8 inches of "grout". Drawing 2323-S1-0550, Rev. 4 called for "Class E concrete" to be used under the pedestal bases.

Discussions were held with TUGCO civil engineering. The engineering representative stated that no technical problem existed since the commercial grout strength exceeded the Class E concrete strength. The reason for changing from "Class E concrete" to commercial grout could not be immediately established by the licensee. This matter was then referred to the site QA manager who initiated an inquiry. This matter is considered unresolved. (445/8416-03)

(b) Crossover Leg Horizontal Restraint Anchor Bolts

Two types of anchor bolt assemblies were used on the horizontal restraints of the reactor coolant crossover leg. RAB3 and RAB4 assembly bolts, nuts, and washers were made from material that conformed to ASTM A-540 requirements. The anchor plates were made from material that conformed to ASTM A-558, Grade 50 requirements. The assemblies were fabricated off site, shipped to the site, receipt inspected, and later installed as part of Concrete Placement 101-2812-01 (in blockouts). Subsequently, foundation concrete for the loop 1 crossover restraints was installed (Placements 101-9812-01 and 101-9812-02).

The materials and installation of the 2 ½-inch anchor bolts, RAB-3 (75 inches long) and RAB-4 (57 inches long) were confirmed by a review of records and verification of code marking on top of anchor bolts. The NRC inspector concluded that the anchor bolts were installed in accordance with the applicable drawings.

(c) Foundations for the Steam Generator and Reactor Coolant Pump Cross Over Leg Restraints

The records documenting the placement of foundation concrete for the crossover leg restraints were examined for Unit 1. Concrete Pour Packages 101-9812-002 and -003 were reviewed. Design Mix 129 was used for the placement on June 1, 1978. All 28-day cylinder breaks were verified, by review of compression test reports, to be in excess of 4000 psi as required by Construction Specification 2323-SS-9, Rev. 4. The placements took place on June 1, 1978. Proper curing was performed.

No discrepancies in the documentation were noted. Specific documents reviewed are listed on the inspection data sheets.

(4) Reactor Coolant System Piping Cleanliness (External)

Insulation on the RCS piping and major components is the reflective or mirror stainless steel type manufactured by Diamond Power and installed by B&R. Prior to installation of the insulation sections, swipes were taken of the surface of the stainless steel piping in order to determine the chloride and fluoride contamination levels. FSAR, Section 5.4.3.3.3 stated that prior to application of thermal insulation,

austenitic stainless steel surfaces are cleaned and analyzed to a halogen limit of 0.0015 mg ${\rm Cl}_2/{\rm dm}^2$ and 0.0015 mg ${\rm ri}_2/{\rm dm}^2$.

The NRC inspector reviewed the program for determining surface contamination. The procedures contain adequate controls for ensuring that the surface of stainless steel does not exceed the designated levels. Inspection travelers were reviewed. Specific requirements for cleaning and QC inspection were identified. Inspection item removal notices are required when insulation is removed and reinspection for contamination is repeated. The NRC inspector also observed the cleaning and obtaining swipe samples.

No deviations or violations were identified.

(5) Safety-Related Components

The NRC inspector reviewed Traveler ME-78-004-5505 that documented the installation of the RCP casing and supports. Final adjustment of the column supports was done after HFT. The NRC inspectors noted that the columns were grouted. Readings of pump casings level were recorded as required by the traveler. No discrepancies were noted in documentation. QC inspections had been accomplished.

(6) Instrumentation

RCS flow transmit. rs (1-FT-415, 416, and 414) for loop 1 were selected for inspection. The NRC inspectors examined the runs to determine if identification, routing, slope, supports, and valves were installed in accordance with applicable drawings and specifications.

Instrumentation tubing was classified Safety Class 2, Seismic Category I. Wet process lines generally required a slope of 1 inch per foct. Routing and support locations were specified on the installation drawings. Records reviewed (see Attachment 1) agreed with the actual installation of the instrument runs. QC inspections had been accomplished in accordance with hold points specified on each weld data card. QC hold points included cleanliness, fitup, purge, final visual inspection, and dye penetrant examinations.

The NRC inspector concluded that the flow instrumentation for loop 1 was installed in accordance with approved drawings and specifications.

(7) Nonconformance Reports (NCR)

B&R NCR C706-R1 (7/21/77) identified that 11 RAB-15 anchor bolt assemblies used in crossover leg (vertical) restraints were nonconforming in that jam nuts were welded to the plate washers instead of heavy hex nuts. The assemblies had the jam nuts removed by a lath and grinding from the bolt and the plate washers. The NCR was reviewed and approved by QA on August 8, 1977. On August 1, 1977, TWX-824 requested approval of the repair procedure from Gibbs & Hill (G&H) (New York office). On August 4, 1977, GTT-1420 documented approval of the repair. Design Change/Design Deviation Authorization (DC/DDA)-65 was issued on August 4, 1977, authorizing the repair.

Inspection and acceptance was to be done in accordance with ASTM A-540. A QC inspector observed the machining operation and performed a final inspection.

The NCR package was reviewed by the NRC inspector. An inspection report (8/5/77) documented the results of the machine shop operation. Nondestructive Examination Report (NDER)-1108 documented acceptance of the materials for further use. Verification of corrective action by QC was performed on August 12, 1977.

This NCR was selected for followup due to the special nature of the inspection action requested by the NCR and DC/DDA. All required licensee actions were found to have been completed and appropriately documented.

No deviations or violations were identified.

c. Containment Spray Piping and Piping Supports

The NRC inspectors selected 15 supports, 21 nozzles, and approximately 112 linear feet of containment spray piping for inspection. The specific areas inspected are identified on the support/hanger inspection data sheets of Attachment 1 to this report.

These sections were physically walked down and inspected. The NRC inspectors utilized the current approved design information and the latest QC inspection reports to determine adequacy of installation and accuracy of documentation.

No deviations or violations were identified.

d. Feedwater Piping and Piping Supports

The NRC inspectors selected 24 supports and approximately 210 linear feet of feedwater piping for inspection. The specific sections observed are identified on the support/hanger inspection data sheets of Attachment 1 to this report.

These sections were physically walked down and inspected. The NRC inspectors utilized the current approved design information and the latest QC inspection reports to determine adequacy of installation and accuracy of documentation.

No deviations or violations were identified.

e. Pressurizer and Associated Piping

(1) Pressurizer Piping Systems and Associated Supports

The NRC inspectors inspected 15 pipe supports and approximately 150 feet of piping associated with the pressurizer relief system. All of the supports and piping were installed in accordance with the latest design drawings and the appropriate procedures. This inspection also included a review of the documentation packages including inspection reports, welding documentation, design changes, nonconformance reports and their closure, material certifications, and construction travelers.

(2) Foundations and Foundation Bolts

The NRC inspectors inspected the installation of the pressurizer including rigging, pouring of concrete slab, and bolting. Construction Operational Traveler RI 78-009-5503 covered the rigging lifting and setting of the pressurizer. Drawing 2323-S1-0SS1, Rev. 6 and the documentation for Concrete Pour 101-7853-001 covered the location, size, type, securing, and thread protection of the base hold down bolts for the pressurizer. Purchase Order 35-1195-6812 and Receiving Inspection Report 03749 for the bolts were reviewed and found to be correct.

The NRC inspector verified that the heat number identification (007) was marked on each of the 24 anchor bolts. The bolts were certified to be ASTM A-540, B23, Class 4 material. The anchor bolt assemblies were manufactured by Bostrom-Bergen.

The NRC inspectors concluded that the pressurizer anchor bolt assemblies were of the specified materials and installed in accordance with the drawings and applicable design changes. QC inspections and documentation of these activities were appropriate.

The NRC inspector also reviewed the records for Design Mix 133 and Master Builders Grout 928 utilized in the installation of the anchor bolts and setting the pressurizer. The average

28 day strength was 4550 psi (design 4000 psi). The concrete pour recards for Pour 101-7853-001 were appropriate.

No deviations or violations were identified.

f. Main Steam System Supports and Whip Restraints

The NRC inspectors reviewed four pipe supports and two pipe whip restraints associated with the main steam system. These supports and restraints are located above the 860' elevation of containment. The individual supports and restraints are identified on the data sheets in Attachment 1 of this report.

These items were inspected in detail to assure that the supports and restraints as installed conformed with the vendor certified drawings; FSAR, Section 3.6.B; ASME, Section III, Subsection NF; and the associated specifications and procedures. A partial inspection of these supports and restraints was documented in NRC Inspection Report 50-445/84-05 and specifically related to certain allegations. This inspection was a total inspection of the supports and restraints including a review of the documentation.

The NRC inspectors found that the inspected supports and restraints were constructed and installed in accordance with the design drawings and procedures. The NRC inspectors also found the document packages for these supports and restraints to contain the pertinent documents related to QC inspections, welding, design changes, and procurement.

No violations or deviations were identified in this area of the inspection.

5. Penetrations

The NRC inspectors examined 3 mechanical penetrations and 3 electrical penetrations. Dimensions and locations of all penetrations were found to be in accordance with applicable drawings. Craftsmanship was satisfactory. There was no evidence of insulation cracking on electrical penetration cabling. The NRC inspectors' review of records indicated that installation and maintenance were in accordance with the acceptance criteria and had been accurately documented, and that leak rate testing had been performed in accordance with the applicable procedure.

No violations or deviations were identified in this area of the inspection.

6. Heating, Ventilation, and Air Conditioning

Twenty-five seismic duct supports and associated duct segments of the Unit 1 containment air circulation and cooling system were inspected.

Specific supports are listed in Attachment 1. All but one of the supports were located on or above the 905' level of containment. The 24 supports are approximately 25% of the total HVAC supports on the 905' level. The 25th support was located on the 860' level.

The following attributes were utilized during this portion of this inspection.

Duct Supports	Duct Segments
Location	Orientation
Dimensions	Size
Member Size	General Configuration
Welding	Location

Supports for HVAC were examined in two parts. First, the seismic supports as designed and installed by Bahnson and second, the attachment to the containment liner plate, installed by Chicago Bridge and Iron Company (CBI), that held the support in place.

Three of the supports were found to have dimensional discrepancies as incorrect member sizes. These supports were examined by Bahnson and submitted to Corporate Consulting and Development Company, Ltd. (CCL) for evaluation. Similar problems had been previously identified in the CAT Inspection Report 50-445/83-18 and Region IV Inspection Report 50-445/84-10. CCL's report had not included containment HVAC supports in their evaluation. The weld stresses were recomputed based on the "as-installed" condition. The recomputed stresses were found to be within the allowable limits as shown below.

Support Member	Maximum Emergency Condition Stress	Upset Condition Allowable Stress	
RB-1-905-1D-1G	12,585 psi	21,000 psi	
RB-1-905-1D-4N	16,542 psi	21,000 psi	
RB-1-905-1D-4J	9,137 psi	21,000 psi	

The results of the analysis were contained in CCL's letters to Bahnson dated May 22 and May 25, 1984. The analysis confirmed that the installed HVAC supports were adequate for the expected service requirements.

Bahn on procedures for "Direct Support Design, Fabrication and Installation" (DFP-TUSI-003, Rev. 8, 5/4/83) and "Ductwork Fabrication Procedure" (DFP-TUSI-001, Rev. 10, 7/21/83) were reviewed and were found to be appropriate and contained sufficient detail and criteria.

The second part of the HVAC inspection involved an examination of the attachment assemblies holding the HVAC supports to the containment liner. CBI manufactured and shipped 406 "50-A" attachments to CPSES. The attachment supports were made of ½" SA 537, Class 2 material, and consisted of 2 pieces joined by a full penetration weld. The base plate was approximately 6½"x6". The attachment bracket was 6"x3½", welded at right angles to the base plate. The base plate was welded to the containment liner by a 3/16" fillet weld around the circumference of the plate. Other attachment brackets of similar configuration were made of 3/8" plate and welded to the liner plate in a similar fashion.

The NRC inspector concluded that the materials were as specified on the CBI and G&H drawings. Material traceability was confirmed by a review of receipt inspections, shop releases, and material heat number sheets. Attachment welding was inspected by qualified QA welding supervisors as confirmed by the CBI master checklists. A Bahnsen welding specification (BSC-20) was coordinated with TUGCO to conform to base metal SA 537, Class 2 welded to ASTM A-36 material using E8018 filler metal (group F-4). Discussions were held with CBI and Bahnson personnel. Visual examination was made of approximately 25 HVAC attachments.

No deviations or violations were identified.

7. Electrical

This section of the report contains information regarding the inspection of cables and cable terminations, cable trays, conduit runs, and their associated supports.

a. Attributes

Predetermined attributes for inspection are identified on the specific inspection data sheet. The following paragraphs give a detailed description of these attributes:

- Cable Type The type of cable used was confirmed by comparison of the cable to cable connection sign-off cards and cable pull cards. The number of conductors and color of cables were specifically verified as part of the inspection.
- Type and Size This pertains to the type and size of conduit or cable tray including fittings, splices, pull boxes, covers, offsets, and fasteners.
- Tray covers Installed as required or identified as an open item.

- Grounding Installed as required on all raceways.
 This grounding is primarily for personnel protection.
- Craftsmanship All fasteners properly installed, raceways
 free of sharp edges and burrs, galvinox protection, raceways
 free of damage, overall integrity of raceways, and proper
 bending of conduit. In addition, note was made of correctness
 of craft functions such as appropriate and adequate use of cable
 ties, crimping of connections, correct and clear identification
 of the cables, bend radius of cables, surface condition of cable,
 etc.
- Identification Raceway identification and train or channel identification at each end and at the proper intervals in between as specified in IEEE 384.
- Supports Proper type and spacing of raceway supports, material size and dimensions, welding, structural attachments, raceway attachments, location, bolt size, and spacing.
- Separation (physical/electrical) Proper separation from piping, ducting, etc.; proper separation between voltage level; one foot/three feet separation between redundant trains or barriers; and separation from possible noise sources for nuclear instrumentation system (NIS) cables. Cable termination racks and panels were also inspected for internal separation requirements.

Separation criteria for Class IE circuits for CPSES is contained in IEEE 384-1974 (draft). Typical separation details for cables and raceways are contained in G&H Drawing 2323-EI-1702-02. This drawing was based on the Electrical Erection Specification 2323-ES-100, Section 4.11, "Separation Criteria". Additional criteria for NIS separation is contained on G&H Drawing 2323-EI-0602-03.

 Color Coding - Safety-related trains are indicated by the color of the outer jacket of the cable as indicated below:

"A" train - orange - Ø

Associated "A" train - orange with white stripes

"B" train - green - G

Associated "B" train - green with white stripes

"C" train - black - K - non-Q

Instrument Channel I - Red R

Instrument Channel II - White W

Instrument Channel III - Blue B

Instrument Channel IV - Yellow Y

Cable trays and conduits are marked with unique identification numbers which include a train or color code designation. The use of color code assisted in the determination of acceptable separation achievement. The cables were checked for consistent and correct color (train) designation.

 Documentation - review of installation and inspection records to ensure that these records document the as-installed raceway and supports and agree with the current approved design information.

Documentation of the cables was reviewed to determine if the QC inspection record was (a) clearly identified to the cable involved, (b) legible, (c) corrected, when necessary, by the use of a single line drawn through incorrect entries, and (d) completely filled out, dated, and signed by authorized QC inspector.

 Terminations - Inspection of cable terminations included these items to ensure that the cables were consistent with the installation record. Specifically:

Cable numbering and marking at termination points.

Terminations of conductors were properly crimped, terminals were tight, and conductor color and markings were verified.

Electrical Raceway and Raceway Supports

The NRC inspectors selected 108 sections of cable tray for inspection. The specific raceway sections inspected are identified on the raceway inspection data sheets of Attachment 1 to this report.

The NRC inspectors physically walked down and inspected 108 cable tray sections, 92 cable cable tray supports, and approximately 924 feet of cable tray. All of the cable trays and 77 of the cable tray supports inspected were properly installed, and the documentation was in order. The remaining 15 cable tray supports did not have proper supporting documentation. This reflects inadequate inspection. The deficiencies were subsequently documented by TUGCO on NCRs M84-01834, M84-01835, and M84-01836.

10 CFR Part 50, Appendix B, Criterion X and the FSAR require the organization performing an activity to verify conformance with documented instructions and drawings for accomplishing the activity. QI-QP-11.10-2, Rev. 27 of June 19, 1984, specifies inspection requirements for 1 ceway supports including assembly inspection, attachment inspection, verification of base plates for grouting, and welding inspection.

In two cases, three supports shared a common clip angle attached to the concrete wall. The cable tray hangers of Drawing FSE-00159, Sheets 6503, 6504, and 6505 specifiy hangers per Drawing 2323-E1-0502-S, Detail "F". Detail "F" and Field Sketch Electrical (FSE), Sheets 6576, 6577, and 6578 refer to Drawing 2323-S-0904, Detail "5" for additional specifications, which in turn refers to Drawing 2323-5-0903, "Case SP4". SP4 specifies attachment per "Detail D". Detail D clearly shows a connection for one support to a clip angle and attachment using two bolts. However, to place the hangers with the required 16-inch vertical separation per these FSE sheets and Detail D, there would have been insufficient separation between the Hilti bolts per Table 3 of QI-QP-11.2-3, Rev. 20, dated May 8, 1984. The QC inspectors failed to recognize and document that the supports identified above were not installed in accordance with approved design drawings.

The cable tray hanger of FSE-00159, Sheet 6638 shows that dimension ℓ_2 of Detail "B" of Drawing 2323-E1-0502-01-S should be 3'10 1/8". The allowed tolerance for this specific application is $\frac{1}{2}$ inch. The actual dimension as-built is 3'9". This difference is beyond tolerance specifications and was not recognized by the QC inspectors.

The cable tray hanger of FSE-00159, Sheet 6632 shows that dimensions for detail "E" of Drawing 2323-E1-0502-01-S should be $h_1=9'4$ ¼", $h_2=5'4$ ½", and $h_3=2'8$ ½". The allowed tolerance for these specific applications is ½ inch. The as-built dimensions are $h_1=9'3$ ", $h_2=5'3$ ", and $h_3=2'7$ ". This difference is beyond the tolerance specifications and was not identified by the QC inspectors.

Cable tray hanger of FSE-00159, Sheet 6657 has a Hilti bolt installed at an angle. The bevelled washer that was installed to provide improved bearing contact between the nut and the clip angle was misaligned. The misalignment of the bevel washer exacerbated the nut bearing contact. This was not identified by the QC inspectors.

The cable tray hanger of FSE-00159, Sheet 5519 shows a 1-inch grout to improve the bearing of the angle clips per Drawing 2323-S-0913 Detail "6". Grout was not used and this condition was not recognized by the QC inspectors.

Cable tray hangers of Sheets 5491, 5498, and 5499 of FSE-00159 are to be attached to the concrete per Note 1. Note 1 refers to Drawing FSE-00179 for specific requirements. As-built, these hangers have welded the clip angle at one end to a plate embedded in the concrete. At the other end, a Hilti bolt is used. FSE-00179 does not provide for this option in 2-bolt clips. This substitution was not identified by the QC inspection.

Cable tray hangers FSE-00159, Sheet 6642 refers to Detail "A" of Drawing 2323-E1-0502-01-S and Sheet 6645 refers to detail "G" for assembly details. Both details refer to "Case SP1" of Drawing 2323-S-0903 for additional instructions. In all these drawings, the welds where the support joins the clip angle are shown to be 4-inches long in the vertical direction. As-built, the welds are horizontal and less than the 4-inch length required on the vertical edges. This condition was not identified by the QC inspectors.

The licensee's engineers stated, and the NRC inspectors agreed, that the hangers discussed above are adequate for use as-built. Only the bevel washer will be reworked to correct its misalignment. Changes were being prepared to correct the documentation for these hangers to reflect the as-built condition. The design document or instruction used to install and inspect the hangers could not be identified.

The above are examples of failure of QC inspectors to properly inspect cable tray hangers and to verify conformance with approved drawings.

This is a violation, Severity Level IV. (445/8416-01)

c. Electrical Conduit and Conduit Supports

The NRC inspectors physically walked down and inspected 33 conduit runs, approximately 200 conduit supports, totaling approximately 1500 linear feet of conduit. The NRC inspectors utilized the current approved design information and the latest QC inspection report to determine the adequacy of installation and accuracy of documentation. The conduits inspected, including supports and fixtures, were properly installed and accurately documented.

No deviations or violations were identified.

d. Electrical Separations

The NRC inspectors observed separation requirements during the raceway and conduit inspection. In addition, several hours were spent walking down the 860' and 905' elevations of containment specifically inspecting to the requirements of IEEE 384.

The following list of equipment was opened and inspected for separation, terminations, and cleanliness:

Valves	Junction Boxes	Cabinets
MOV 1 HV-6075	JB1C-566G	RPI Cabinet A
MOV 1 HV-6074	JB1C-3030Ø	RPI Cabinet B
MOV 1 HV-6076	JB1C-3031G	Thermocouple
	JB1C-438Ø	Ref. Junction
	JB1C-442Ø	Box

The NRC also inspected Valve MOV 1RH-8702 and witnessed the change of the torque switch setting required by Traveler MEV 84-0607-5800 and DCA 19537 R-1.

All of the above equipment was properly terminated, exhibited good craftsmanship, and was properly maintained and clean with the exception of the red position indication (RPI) cabinets.

The RPI cabinets were not terminated yet. The cables were in the cabinets with the plugs attached, but the drawers and cards were not installed. The plugs were sealed in plastic bags. The RPI cabinets were dirty inside and required cleaning. These cabinets are non Class 1E cabinets, and due to the status of the cabinets, the lack of cleanliness does not have safety significance.

The NRC inspector reviewed the procurement testing and installation of the separation blanket material utilized at CPSES to meet the barrier requirements of Regulatory Guide 1.75 and the thermal radiation shield requirements of 10 CFR Part 50, Appendix R. See data sheets in Attachment 1 of this report for the details of this inspection and review.

No deviations or violations were identified in this area.

8. Equipment

a. Hydrogen Recombiners

The NRC inspectors examined the maintenance records and installation of the hydrogen recombiners. Installation, foundation, and anchor bolts were found to be in accordance with the installation drawings. Type Class "B" storage was required. Maintenance records indicated that maintenance had been performed properly during storage in the warehouse. In place maintenance is required every 2 years. It had not yet been performed because the equipment had been installed for less than 2 years.

The NRC inspectors' review of the procurement package revealed out-of-specification voltage readings for comparator output voltage. The licensee was informed and obtained a modified quality release from Westinghouse stating that voltages were satisfactory. Discussions with startup and Westinghouse personnel revealed that voltage readings do not affect the operation of the equipment, and that the equipment has successfully completed preoperational testing.

The reason for failing to identify the out-of-specification reading during the Westinghouse and QA review of the data for the quality release could not be immediately determined. The matter was referred to the site QA manager who began an inquiry into the circumstances. This matter is considered unresolved. (445/8416-04)

b. Equipment Procurement Documentation

This portion of the inspection was conducted to review the procurement documentation of three components in containment. The components selected were:

- Hydrogen Recombiners (905' level) (two each)
- Motor Operated Block Valves pressurizer relief system (905' level) (two each)
- Air operated, pressurizer spray valves pressurizer spray line (905' level) (two each)

The inspection concentrated on the procurement specifications, purchase orders, and receiving inspection reports.

ANSI N45.2.13 was used as the acceptance criteria. Specifically, the following attributes were looked for in the documentation.

- Scope of work
- Technical requirements
- QA program requirements
- Right of access
- Documentation requirements
- Nonconformance requirements
- Raview of procurement documents (equipment supplies)

The NRC inspector determined that the documentation was available on site. All documentation reviewed was found to be acceptable in accordance with the acceptance criteria. Purchase specifications will be retained under TUGCO Nuclear Engineering (TNE) for configuration control for future purchase of replacement units, if required, and purchase of repair parts.

No deviations or violations were identified.

9. As-Built Design Documentation Program

a. General - A review of the licensee's program for verification and control of design documents was conducted. Specific drawings and diagrams were selected by the manager, nuclear operation and TNE for updating prior to fuel loading. These drawings and diagrams are listed below. TNE is in the process of assuming responsibility for CPSES drawings and specifications as they are verified by the AE, G&H. After design verification, the drawings are then issued as "CP-" drawings.

The purpose of this portion of the inspection was to determine (1) adequacy of procedures governing the generation and completion of as-built design documents (drawings and specifications) and (2) the schedule for completion of the as-built drawing documentation.

- b. Procedures Procedures governing the generation and completion of as-built design documents, reviewed by the NRC inspector, are listed in Attachment 1. The procedures meet the applicable requirements of ANSI N45.2, N45.2.11, and N45.2.9. It was verified that CMCs and DCAs affecting G&H design documents are being reviewed and, where indicated, included in the revised drawings and specifications. G&H Project Guide 24, "Processing CMCs and DCAs," includes a "Change Verification Checklist". This form is used as engineering control for the review of CMCs and DCAs. G&H engineering determines if the change (CMC or DCA) will be incorporated into the drawing, and documents that decision on line 6 of this form. When all outstanding CMCs and DCAs are reviewed and incorporated into the design documents, TNE plans to issue engineering change notices when system design changes are required.
- c. <u>Schedule</u> The following diagrams and drawings were included in the licensee's schedule:
 - Mechanical Flow Diagrams (M1-200 and 300 series)
 - Electrical One-Line Diagrams, 3-Line Diagrams, Electrical Wiring and Connection Diagrams (El-001 through El-200 series)

- Instrument and Control Diagrams (M1-2200 and 2300 series)
- Instrument Equipment List (MI-2400 series)
- Instrument Location Drawings and Tab Sheets (MI-2500 and MI-2500 series)
- Safety-Related Vendor Drawings

Of the 4537 drawings originated by G&H, 4422 had been reissued by TUGCO as of April 21, 1984.

Drawings that have outstanding design changes at fuel load will be identified in the MDB for updating prior to commercial operation. Additional drawings will be updated after commercial operation. These were identified as follows:

- Electrical Physical Drawings (El-300 through El-800 series)
- Electrical Fire Protection Detection Drawings (E1-2000 series)
- Plant Architectural Drawings (G&H "A" prefix drawings)
- Non-Safety Related Vandor Drawings
- Electrical Lighting Drawings (E1-900 series)
- Electrical Material List (E1-1800 series)
- Computerized Cable and Raceway Schedule (E1-1700) and other miscellaneous (E1-1700) series drawings
- Instrument Rack Wiring Drawings (E1-2800 series)
- Instrument Installation Drawings (M1-2100 series)
- d. Program Conclusions The NRC inspection concluded that the program for updating and providing as-built design drawings and specifications is adequate and meets regulatory requirements and FSAR commitments.
- e. <u>Implementation</u> Seven drawings under control of TNE were selected for review to determine if they were being controlled in accordance with the approved procedures.

When selected controlled drawings in the control room were examined, three of the seven, M1-0301, M1-261 and M1-262, were determined not to be of the correct version.

TUGCO document control center (DCC) (Operations) has the responsibility for maintaining the control room drawing file (003) current. TUGCO DCC had received the aperture cards, date stamped May 22, 1984, for the current revision of the drawings and was in the process of producing copies for distribution. (Note: The inspection was conducted the afternoon of June 6, 1984; drawings had been updated May 15, 1984.)

In addition, the NRC inspector reviewed the design change log sheets (Construction DCC) and DCA log file (TUGCO DCC) for the selected drawings. It was found that these two records do not reflect the same status. Further information regarding this matter was found in Quality Surveillance QSR-84-011. The findings resulted in a Corrective Action Request (CAR) 84-001. This surveillance report stated that ". . . the design charge logs for design drawings and the specification log sheets for design specifications, which are maintained by the Operations Document Control Center, do not reflect the same document status as that of TUSI Nuclear Engineering. Due to this condition, the correct status of design drawings and specifications distributed by Operations DCC is indeterminate."

A permanent solution to the deficiency identified in CAR 84-001 was to have been implemented by June 1, 1984. Implementation was delayed until June 30, 1984 (TIM-840667). The NRC inspector found on June 6, 1984, that the control problem (as stated in the CAR) still existed. A similar problem with a manual system had been identified in a surveillance conducted in October 1983.

Two aspects of document control were thus identified:

- (1) The actual status of design drawings can not be determined. This problem had been identified by the licensee in surveillance reports, and action had been initiated, but had not been completed. Control of documents and changes to these documents are required by 10 CFR 50, Appendix B, Criterion VI as well as corrective action required by Criterion XVI. The commitment for providing controlled documents was established in the FSAR, Section 17.2.6.
- (2) Some design drawings available for use by control room personnel were out of date. The operations procedure (STA-306) governing the control of drawings did not have a specific time limit for issuance of revised drawings after receipt of aperture cards. However, based on the date of drawing revision (5/15/84) and "completion" of aperture cards (5/22/84), updated versions of the drawing could

reasonably be expected to have been provided prior to June 6, 1984, the date of the inspection. Lack of adequate measures to effectively control the issuance of documents affecting quality is a violation of 10 CFR Part 50, Appendix B. Criterion VI.

This is a violation. (445/8416-02)

10. QC Inspector Qualifications

The NRC inspectors selected eight QC inspectors for verification of their inspector qualifications. The names selected were chosen from inspection records used in other areas of this report. The names included two electrical inspectors, three electrical (mechanical) inspectors, and three mechanical inspectors.

The verification included checking that qualifications were made in accordance with current procedures and that the inspector was indeed qualified at the time selected inspections were performed. The NRC review found one inspector who was not qualified to perform inspection in accordance with QI-QP-11.10-2. The selected inspection was performed on September 1, 1983, while the inspector did not become qualified to perform this inspection until December 1983. This situation had already been identified by the licensee in NCR M83-03049 dated November 15, 1983. Appropriate action was being taken by the licensee to resolve the NCR. The licensee has identified all the inspections for which the inspector was not qualified, and a reinspection program is underway. This reinspection is being done on a room-by-room basis.

During this inspection, the NRC inspectors had informal discussions with QC, engineering, electrical test group, and documentation personnel to determine job knowledge and overall familiarity with drawings, procedures, and the day-to-day mechanics of their jobs. In all cases, the people were knowledgeable and professional.

No violations or deviations were identified in this area.

11. Miscellaneous

(Closed) Unresolved Item (8323-06): QA Audits - Formal audits have been conducted by TUGCO regarding the construction turnover completion activities. The NRC inspector reviewed the following audit reports:

TCP-80 Fuel Building, August 15-26, 1983

TCP-88 Auxiliary and Safeguards Building, October 31 - November 15, 1983 TCP-95 No. 1 Diesel Generator Building,

February 20-24 and February 27-March 2, 1984

TCP-103 Auxiliary Building, May 29 and April 24-May 4,

1984

The audit reports indicate satisfactory implementation of the room turnover process. Additional audits have been scheduled. This item is considered closed.

12. Summary of Inspection Results

This special inspection identified two violations. Only violation 445/8416-01 (cable tray hanger inspection) pertains to the construction completion and room/area inspection of the Unit 1 reactor containment building.

13. Unresolved Items

Unresolved items are matters about which more information is required in order to ascertain whether the items are acceptable or not. There were two new unresolved items identified in paragraphs 4.b.(3) (445/8416-03) and 8.a (445/8416-04).

14. Exit Interview

On June 20, 1984, the NRC inspector and other members of the Region IV staff, including the resident inspectors met with the licensee representatives as denoted in paragraph 1 of this report. The NRC inspector discussed the findings of this report including the two violations. The licensee representative acknowledged the violations.

NSPECTION ELEMENT:
GENERAL PROCEDURES AND INSTRUCTIONS UTILIZED
IN THE PIPE SUPPORT APER OF THIS INSPECTION.
CP-QAP-11.1
QI-QAP-11.1.26
QI-QAP-11.1.28
QI-QAP-11.1.28A
QI-QAP-11, 1, 38.
CP-QAP-8.1
QI-QAP-11.2.28
CP-QAP-12.1
CP-QAP-16.1
CP-QAP-17.1
QI-QP-11.14-1
QI-09-11.14-7
CP-QP-16.0
CCP-21
CP-QP-15-5
CEI-20
QI- QP-11, 2-7
INSP. RPT. NO: 84-16 PAGE: ATT1-0 INSPECTOR: MARTIN/ORE

GENERAL INSPECTION DATA SHEET

NYPELITUN ELEMENT.	120/84
Foundations Safety Related Structures;	
Safety Related Components; Instrumentation	
ATTRIBUTES: CONFORMANCE TO APPLICABLE DEALINGS SIE	CIFICHTOWS,
ACCEPTANCE CRITERIA: 75AR (Section 5,1-5.4); DRAWWOS	ND
SPECIFICATIONS	
RESULTS: IN GENERAL, ALL REQUIREMENT WERE MET. E.	CEPTIONS:
NO RECORD WAS FOUND OR PROVIDED FOR THE INSTALLAT	TION OF
THE CROSSOVER LEG RESTRAINT BASES	
RESOLUTION: Notice of Violation WAS ISSUED AS PART O	F
INSP. REPORT 50-445/84-08	
INSP. RPT. NO: 50-445/84-16 PAGE: Art 1-1 INSPECTOR: C	BERG/MART

Purchase O.	Men (P.O)	35-1195-6	2/2	August 1971 and 1971
Concrete Pan	Parhage	No 101 - 78	53-001	
7SAR SA	etim 51-	5.4)		
Drauma o: E	EP- EC-1	-520-00	1 Ren 6	Reactor Cools
×	Loop Xaya	ent and De	toils_	<u> </u>
				Nation 17 a
				era i Win et auto de la como
				1.5
				urain na maill
	A REPLECTION			

INSPECTION ELEMENT: RCS DOCUMENTS REVIEWED	
DRAWINGS:	
2327-51-0550 RB Internal Structure Equipment	Support
and Foundations, Start 1	0
2323-51-0550 RB Internal Structure Equipment	Supporta
and Foundations, Sheet 2	
2327-51-0528 RB INTERNAL STRUCTURE, EL 85/6" + 8:	B'-0"OUTLINE
(SECT 313 Gressuringer anchor batta)
2323-SI-0519 RB INTERNAL STRUCT. EL 808'0	" BOTLINE
SCB-10519 CONST JOINT PLAN - EL 808'-0"	
WDWG 1457F29 RCS EQUIPMENT SUPPORT (SG+	RC P)
WIDGE HEREDS PRESSURIZEE RELIEF TANK.	
FSC-00398 FOUNDATION RESTEEL PROBLEMS (#15.G. + RCA
(SHEET 1.2.3+4)	
AFCO STEEL DWG 76-519/RY)CROSSOVER LEG	RC RESTR
#113,112	
INSP. RPT NO: 50-445/84-16 PAGE: An1-5 INSPECTOR: OBEEG	IMARTW

WSPECTION ELEM	ENT:
DCA 150	6 FOUNDATIONS FOR SG, RCP & CROSS OVER LEG
RESTERINT	BASES
DCA 1960	O SHEAR LUGS ON CROSSOUER LES RESTRAINTS
	J CROSSOURE LEG RESTRAINT - PIPE SUPPORT
	ATTACHMENT
DCA 1280	2 ATTACHMENT TO CROSSONER LEE RESTRAINTS
TRAVELER	ME 81- 2154- 5500 GROUT STEAM GENERATOR BASES
GROUT CAL	ED No 186
INSPECTION	REPORT IR C 5558 GROUT OF EQUIPMENT BASE

NSPECTION ELEMENT: RCS FOUNDATIONS
CONCRETE POUR CARDS - 101-9812-002 + 003 (6/1/78)
STEAM GENERATOR OROSS OVER LEG RESTRAINTS FOUNDATION
RC PUMP CROSSOVER LES KESTRAINTS FOUNDATIONS
(PCB#1, Comp#1)
(Following apply to both plosement)
- QA Concrete Placement Checklist 6/1/18
- QA Reinforcing Steel, Electrical, mechanical and
Embedied Stem Challits 6/1/78
- Concrete accepting Test Report HCP 38266 6/2/18
- Concrete Placement Report (mix 129) 6/1/78
- Batch Plant Report Tichdo: 40506; 42486; 42497
- Concrete Compression Test Report: HCP38383 6/5/78
- " + CP 38552 6/8/18
- " " HCP39278 6/29/78
- Concrete Curing Charlist (7 days) 6/5/18 (Taken and after4
- " Report Tempestine Record 6/8/78
- QC Concrete Curing and Impertion Report HCF 39278 7/11
- Concrete Derig Mix Proportion Report (mix # 129/128)
3/17/77
INSP. RPT. NO: 50-445/84-16 PAGE: ATT-5 INSPECTOR: MARTIN/OBERG

	CTION ELEMENT: RCS CLEANLINESS (HALOGEN)
	EVIEWED THE FOLLOWING DOCUMENTS:
_	CONSTRUCTION TRAVELERS FOR INSTALLATION OF
	RCS INSULATION: MEB2 - 2519 THEU 2522 - 53
	ME81-2534 THEO 2537 -55
_	- QC Limetin Reports AM - 03765; 04704;
	05199:05716
	NCR-M-83-00509
	Procedure:
	CP-CPM 6.12 (RO) 7/22/82
	ep-cpm 10,2 (RZ) 7/11/83
,	2= 22 11/5 (PW 12/1/29 Determination of Surface
_9	05-9P-11.1-65 (R4) 14/1/79 Determination of Lunfor Contamination of Florible and Chloride on Stainles
	stul
	. RPT. NO: 50-445/8416 PAGE: ATTI-6 INSPECTOR: MARTIN/OBERG

MENTS REVI		INSTALLATION DO
TRAVELER A	1E-78-004-5505	(REV1-5)
EQUIPMENT .	SUPPORT MEDIFICA	TION: TBX-4-132;
		UX 710- 797-365-8
DCA 11,3/2-		
	UP GEORGE STEEL	

INSTRUMENTATION INSPECTION DATA SHEET

		DATE 6/20/8	
INSTRUMENTATION NUMBER/SYSTEM			
-FT-414; 1-FT-415; 1-1	ET-416 (5P)	N # TBX -QB	ELDP-OI)
ATTRIBUTES TAGING; ROUTING; SPAN; VENT/ PRAIN VI	PROPER SLOPE ALVES; DOCUME	; SUPPORTS;	SUPPORT
ACCEPTANCE CRITERIA:			
FSAR SECTION: SECTION 7.0			
SPECIFICATION: 2323-MS-6	25 INSTRUMENT (NUCLEAR SA 25 A FIELD INSTR	FETY RECTION	(KE L D
RESULTS: ROOT VALVES	ARE CORRECT	TUBING CO	RRECT
KESULIS. KOOT PHETE			
FOR THE ABOUE ATT	RIBUTES LISTE		
FOR THE ABOVE ATTI	T ROOT VALVE	TAGS WER	
NUMBERS ON INS	RIBUTES LISTED T ROOT VALVE (BRP-PC-1-RB	TAGS WER	E FOUND
FOR THE ABOVE ATTI	RIBUTES LISTED T ROOT VALVE (BRP-PC-1-RB	TAGS WER	¥14/806
FOR THE ABOVE ATTI NUMBERS ON INS TOBE INCORRECT.	T ROOT VALVE (BRP-PC-1-RB 415/8060A	TAGS WER	¥14/806
FOR THE ABOVE ATTI	T ROOT VALVE (BRP-PC-1-RB 415/8060A	TAGS WER -044) 415/8059A	Y14/806
FOR THE ABOVE ATTI NUMBERS ON INS TOBE INCORRECT.	RIBUTES LISTE ! T ROOT VALVE (BRP -PC-1-RB 415/8060A 414/8060A	TAGS WER -044) 415/8059A 415/8059A	414/8061 416/8061
FOR THE ABOVE ATTI NUMBERS ON INS TO BE INCORRECT. IN FIELD: DWGS + DCA REQ: RESOLUTION: DETERMINED	TROOT VALVE (BRP-EC-1-RE 415/8060A 414/8060A THAT INSTRUM	TAGS WER -044) 415/8059A 415/8059A	414/8061 416/8061
FOR THE ABOVE ATTIONS NUMBERS ON INS TO BE INCORRECT. IN FIELD: DWGS + DCA REQ: RESOLUTION: DETERMINED CORRECT FLOW TRANSA	TROOT VALVE (BRP-PC-1-RB 415/8060A 414/8060A THAT INSTEUR	TAGS WER -044) 415/8059A 415/8059A MENT LINES W WAS IN TAK	414/8061 416/8061 DENT TO
FOR THE ABOVE ATTIONS NUMBERS ON INS TO BE INCORRECT. IN FIELD: DWGS + DCA REQ: RESOLUTION: DETERMINED CORRECT FLOW TRANSA NCR 1-84-007045	TROOT VALVE (BRP -PC-1-RB 415/8060A 414/8060A THAT INSTRUM MITTER ERROR HAD INCLUDED	TAGS WERE -044) 415/8059A 415/8059A MENT LINES W WAS IN TAKE THE ABOVE	414/8061 416/8061 DENT TO GMG ONLY,
FOR THE ABOVE ATTION THE NUMBERS ON INSTANTON TO BE INCORRECT. IN FIELD: DWGS + DCA REQ: RESOLUTION: DETERMINED CORRECT FLOW TRANSA	TROOT VALVE TROOT VALVE (BRP-EC-1-RB 415/8060A 414/8060A THAT INSTRUM MITTER ERROR HAD INCLUDED ED/VERIFIED	TAGS WERE -044) 415/8059A 415/8059A 415/8059A WAS INTAGE THE ABOVE DN 6/11/84	414/8061 416/8061 DENT TO GANG BNLY, VALVES.

EUIEWED FOLLOWING DOCUMENTS:	
· RIR 16194; MER CF8982	
· I E 4: IR-I-1812 } FT-415 LP	
IE-I-0482	
IR-I-1806 } FT-414 LP	
IR-I-2986)	
IR-I-1811 - FT-416 HP	
ASSOCIATED WELD DATA CARDS	
DCAS/CMCA:	
. DCA - 13,602 TO MS 625A FOR SEPARATION T	FOR
COMMON TAP OF FT-414, 415, 416 (MP)	
· DCH - 16, 614 ROOT VALUE NUMBER CHANGE	
· CMC 66571, 66572, 66576, 66696, 666	60
66575 RI, 57455 RZ	
· DCA- 12,212	
DEAWINGS: BEP-RCI-RB-044 REU3	
2323-M1-250303;2323-M1-2104-07	
FSI-1-502;-503; 504; 505	

NSPE	CTION ELEMENT: ITE - 4108, 4118,4138 - INSTEUMENTATIO
	ONST OP TRAVELEES - MERZ - 2307 - 5500 - INSTALLATIO
	OF THERMOWELL ITE -4138
	ME 82 - 2306-5500 - ITE - 41173 THERMOWELL
	ME 82 - 2306-5500- ITE - 4108 THERMOWELL
R:	IR 23528 / MER CP1 2391 - ITE 4113 (SPIN # TBX -
	PAELRT-OI FOR RTD
F	SI-1-505 RO (HP SIDE OF FLOW INSTRUMENTS)
	MANUFACTURING RECORD SHEET - 1 FT 415/414/416 (39 WELD
	WELD DATA CARDS FOR; FW-1 Through-39
	MT/PT REPORTS
	OF DEFT VISUAL EXAMCHECKLISTS
	WELD FILLER MATERIAL LOGS
	P. RPT. NO: 50-445/8416 PAGE: And INSPECTOR: MARTIN/OBERG

SUPPORT/HANGER INSPECTION DELT SHEET

ROOM CONTAINMENT	8106 905'+860' LEVEL	DATE	6/20/84
SUPPORT NUMBER/C	LASS/SYSTEM: CON	TAINMENT SPRAY	
		: CT-1-051-404-(728, CT-	1-05/-405- C72K
CT-1-051-405-C	72K, CT-1-051-403-	C72 R, CT-1-051-407-C	72R, CT-1-051-417.672K
CT-1-051-406- C7	ZK, CT-1-051-409.	(72.8	
ATTRIBUTES:			
WELDING	HARDWARE	CONNECTIONS (WALL	/CEILING, ETC)
PHYSICAL CO	ONDITIONS (DIMENSION	S/LOCATIONS) ATTACHMEN	TS BASE PLATES
WORKMANSHIF	,	CLEATANCES	GROUTING
ACCEPTANCE CRITE	RIA .		
FSAR SECTION: 3.	. 6B		
SPECIFICATION(S)	MS-46A (Nuclea	r Safety Class Hanger	& Supports)
	MS-94 (Pipe V	Mhip Restraints)	
ASME SECT III, S	Subsection NF; VCD/	'DRD's; Procedures: QI-	QAP 11.1-28
RESULTS THE MRC	INSPECTORS REVIEWS	TO AND DESERVED 15 SUP	PORTS AND APROXIMATELY
			DRAWING BRP-CT-
		ENT DISCREPANCIES NOTE	
7- KB-030. The	AC WEST TO THE TAIL		
RESOLUTION:			
KESOLOTTON.			
		DACE NO #-1-1	INSPECTOR MARTIN
INSPECTION REPO	RT NO. 89-/6	PAGE NO. ATTE	Cur.

SUPPORT/HANGER INSPECTION DATA SHEET

ROOM		DATE	6/20/84
SUPPORT NUMBER/CLA	SS/SYSTEM: CONTA	THENT SPRAY (CONT	rinuso)
RAWING: BRHL- CT-1-	RB-020 SUPPOR	7: CT-1-057-401-C725	i
DRAWING: BRHL-CT-1	-86-030 suppo	RTS : CT-1-124-408-C	72R, CT . 1- 124 - 417 - C72 R
T-1-124-007-572R.	T-1-124-414- C72	R, C7-1-124-415-C72K	CT-1-124-413-C72K
ATTRIBUTES:			
WELDING	HARDWARE	CONNECTIONS (WALL	/CEILING,ETC)
PHYSICAL COND	ITIONS(DIMENSION	S/LOCATIONS) ATTACHMEN	TS BASE PLATES
WORKMANSHIP		CLEARANCES	GROUTING
ACCEPTANCE CRITERI	A		
FSAR SECTION: 3.6B			
SPECIFICATION(S)	MS-46A (Nuclea	r Safety Class Hanger	& Supports)
	MS-94 (Pipe W	hip Restraints)	
RESULTS	section NF; VCD/	DRD's; Procedures: QI-	QAP 11.1-28
RESOLUTION:			
	•		
INSPECTION REPORT	NO. 84-/6	PAGE NO. Arr1-12	INSPECTOR MARTIN

SUPPORT/HANGER INSPECTION DATA SHEET

ROOM CONTAINMENT	BLD6 860 + 905 LEV	DATE_	6/20/84
SUPPORT NUMBER/CL	ASS/SYSTEM: FEE	D WATER	
DRAWING: BRHL FW-1	-R8-005A SUPPORT	5; FW-1-095-700-C621	K, FW-1-095-009-067 K,
			rs: FW-1-017-708-C72K,
			2K, FW-1-017-710-C7ZA
ATTRIBUTES:			
WELDING	HARDWARE	CONNECTIONS (WALL	/CEILING, ETC)
PHYSICAL COM	NDITIONS (DIMENSION	S/LOCATIONS) ATTACHMEN	ITS BASE PLATES
WORKMANSHIP		CLEARANCES	GROUTING
ACCEPTANCE CRITER	AIS		
FSAR SECTION: 3.6	5B		
SPECIFICATION(S)	MS-46A (Nuclea	r Safety Class Hanger	& Supports)
		hip Restraints)	
ASME SECT III, Su	ubsection NF; VCD/	DRD's; Procedures: QI-	-QAP 11.1-28
		LEWED AND OBSERVED	
		OF PIPING . THERE WERE	
DISCREPANCIES NO			
RESOLUTION:			
INSPECTION REPOR	T NO. 84-16	PAGE NO. Arr1-1	3 INSPECTOR MARTIN
			SKOW

INSPECTION ELEMENT:	CONTAINMENT BUILDING 860 + 905 LEVELS
FEED WATER SYSTE	M SUPPORT NUMBERS (CONTINUED) FW-1-017-7/2-(72K,
FW-1-017-007-C725	FW-1-017-008- C725, FW-1-017-713-C62R.
DRAWING: BRHL - 1- RB-	006B SUPPORTS: FW-1-096-037-C62R, FW-1-096-038-C62
	DRAWING: BRHL-FW-1-RB-DOY SUPPORTS:
FW-1-018-005-C725	, FW-1-018-708- C72K, FW-1-018-007-C725, +W-1 08+
	FW-1-018-711-672K, FW-1-018-709-672K,
EW-1-018-029- C62K, F	FW-1-018-009-C725, FW-1-018-713-C62R.
A. A.	

SUPPORT/HANGER INSPECTION DATA SHEET

DOOM P	CONTRINENT	B. O. DATE	4/20/84
SUPPORT NUMBER/CL	ASS/SYSTEM: Per	SSUPPLE PEUEF -	PC-1-097-005-08
Re-1-097-00	2-086K, EC-	1-097-001-086K,	PC-1-115-005-0762
20-1-115-008	C76K, BC-1-1	15-016E, RC-1-11:	5-014-C76K
RC-1-115-018-	Clack , 20-8-11	15-017-0765, Re-1-	115-019-066K (00000
ATTRIBUTES:			
WELDING	HARDWARE	CONNECTIONS (WALL/	CEILING, ETC)
PHYSICAL CON	DITIONS (DIMENSION	S/LOCATIONS) ATTACHMENT	S BASE PLATES
WORKMANSHIP		CLEARANCES	GROUTING
ACCEPTANCE CRITER	IA		
FSAR SECTION: 3.6	B + 5.2		
SPECIFICATION(S)	MS-46A (Nuclea	r Safety Class Hanger &	Supports)
	MS-94 (Pipe W	hip Restraints)	
ASME SECT III, Su	bsection NF; VCD/	DRD's; Procedures: QI-Q	AP 11.1-28
		ES FOUND ALL OF T	AP-//0/6-1
		ED IN CONFORM	
		PRILINGS PNO TH	
		EXITES. MOS	
		V SUPPORTS, HO	
THE SUPPORT	S WEEE CLA	SS I SUPPORTS,	THE NEC (CONID)
被导展的基本			
INSPECTION REPORT	T NO. 50-445/8	4-16 PAGE NO. ATT 1-15	INSPECTOR MARTIN
	-		OBERG

	-1-146-001-0818, RC-1-000-000-08
	D PC-1-146-004-CBIK.
	S ALSO INSPECTED THE PIPING
BUNS MESSOCHETED NOWN	THESE SHPARETS. THE DOCUME
PTION OF THE SUPPO	ETS AND PIPING KONS
COMPLETELY BEYLEW.	ED AND FOUND TO BE
SUISFACIONY	

ROOM CONTAINMENT	- UNITI	DAT	E 6/23/8	4
SUPPORT NUMBER/CLASS/S	YSTEM: MAIN	STEAM SYSTE	M SUPPORT.	S STRUCTURE
MS1-004-007-072	; MS1-001-	904-679W; MS	1-003-009.	C72 K;
MS1-003-010-C7				
ATTRIBUTES:				
WELDING MA	RDWARE	CONNECTIONS (N	MALL/CEILING, ET	c)
PHYSICAL CONDITIO	NS(DIMENSIONS/L	OCATIONS) ATTACH	MENTS -BA	SE PLATES
WORKMANSHIP		-eLEARANCES	-GROUTIN	G
ACCEPTANCE CRITERIA				
FSAR SECTION: 3.6B				
SPECIFICATION(S) MS	-46A (Nuclear S	afety Class Hang	ger & Supports)	
	-94 (Pipe Whip			
ASME SECT III, Subsect	ion NF; VCD/DRI	's; Procedures:	QI-QAP 11.1-28	
RESULTS Inspection 1				
whip restraints	impected u	were in acco	stone w	ith code,
drawing and a	pecification	requiremen	t	
RESOLUTION: N.A.				
INSPECTION REPORT NO.	50-444/8416	PAGE NO. Ant.	-/7 INSPECTOR	OBERG
INSPECTION REPORT NO.	0011/07/6	TAGE NO. MITE		MARTIN

CCP-22 Structure Steel Exection CP-CPM-9.10 Fabrication of ASME- Related Component Supports DEAWINGS: BRHL-MS-1-RB-001/002/003/009
MSI- 004-003-C725; MSI-004-007-C72K; MSI- 001-901-C77W; MSI-003-009-C72K; MSI-003- 010-C72K (Pachage included QC Checklish; mendon Certified Drawing: Well Data Cale; Well Filler Material Xog; IRa Traneles; CMCa; NPSI Smulber Installation Tra PROCEDURES: CP-CPM-G. 9 General Pripring Provalence CCP-22 Structures Steel Spection CP-CPM-9.10 Fabrication of ASME- Related Compensant Support DRAWINGS: BRHL-MS-1-RB-001/002/003/004
MSI- 004-003-C725; MSI-004-007-C72K; MSI- 001-901-C77W; MSI-003-009-C72K; MSI-003- 010-C72K (Pachage included QC Checklist; mendon Certified Drowing: Well Data Cale; Well Fille. Material Xay; IRa Transles; CMCa; NPSI Smulter Installation Too PROCEDURES: CP-CPM-G. 9 General Pripring Procedure CCP-22 Structure Steel Exection CP-CPM-9.10 Fabrication of ASME- Related Commonant Support DEAWINGS: BRHL-MS-1-RB-001/002/003/004
OID-C7ZK (Gachage included QC Checklist; Newdown Certified Drowing: Well Dota Cole; Well Fille. Material Xay; Ile Traveler; CMC a; NPSI Smulter Installation Too PROCEDURES: CP-CPM-G. 9 General Paping Provalence CCP-22 Structures Steel Expection CP-CPM-9.10 Fabrication of ASME- Related Common ant Supports DRAWINGS: BRHL-MS-1-RB-001/002/003/004
OID-C72K (Pachage included QC Checklist; Newdown Certified Drawing: Well Dota Cola; Well Fille. Material Xoy; Ile Transles; CMCa; NPSI Smuller Installation Too PROCEDURES: CP-CPM-G. 9 General Paping Provadure CCP-22 Structure Steal Expection CP-CPM-9,10 Fahrisation of ASME- Related Commonant Supports DRAWINGS: BRHL-MS-1-RB-001/002/003/004
Certified Braing: Well Data Carla: Well Fills. Material Xay; Ila Traneles: CMCa; NPSI Smulle Installation That PROCEDURES: CP-CPM-G. 9 General Pripring Provaline CCP-23 Structure Steel Exection CP-CPM-9.10 Fabrication of ASME- Related Component Support DRAWINGS: BRHL-MS-1-RB-001/002/003/004
Zag; IR a Translers; CMCa; NPSI Smulbe Installation has PROCEDURES: CP-CPM-G. 9 General Propring Provadure CCP-22 Structure Steel Exection CP-CPM-9.10 Fabrication of ASME- Related Component Support DEAWINGS: BRHL-MS-1-RB-001/002/003/004
PROCEDURES: CP-CPM-G. 9 General Paping Provalure CCP-23 Structure Steel Exection CP-CPM-9.10 Fabrication of ASME- Related Commemont Support DRAWINGS: BRHL-MS-1-RB-001/002/003/009
CCP-22 Structure Steel Exection CP-CPM-9.10 Fabrication of ASME- Related Component Support DRAWINGS: BRHL-MS-1-RB-001/002/003/009
CP-CPM-9,10 Fabrication of ASME- Related Component Support Denwines: BRHL-MS-1-RB-001/002/003/009
Related Component Support Deawines: BRHL-MS-1-RB-001/002/003/004
DEAWINGS: BRHL-MS-1-RB-001/002/003/008
DEAWINGS: BRHL-MS-1-RB-001/002/003/008
BRHL-MS-1-RB-001/002/003/004
200 MC . DR - 00//003/207/204
BRP-MS-1-RB-001/202/003/004
NSP. RPT. NO: 50-445/8416 PAGE: ATT 1-18 INSPECTOR: OBERG MARTIN

Hydrogen Purge Supry	Level DATE 6/20/84 -18/Mechanical
tigatojen soste polit j	
ATTRIBUTES:	
WELDING/NDE	PHYSICAL CONDITIONS (DIMENSIONS & LOCATIONS
CRAFTSMANSHIP	LEAK RATE TEST (!0 = 2 stdCM3/s)
ACCEPTANCE CRITERIA:	
FSAR Sections: 3.8.1.1.6 3.8.2.6 6.2.2.2 (Table SPECIFICATIONS: Electrical E RG: 1.63 (Electrical; IEEE 31	ES-12/12A; Mechanical FiS-74
ASME Section III, NE for Clas	ss MC Components
PROCEDURES N/A	
222- MA-0503 and 2323-M1	cation were found to be in accordance with -0503. Welding and craftsmanship had been the acceptance criteria and had been accurately
clocumented	
RESOLUTION MA	
RESOLUTION_ M/A	

ROOM Reactor Bldg., 860 L PENETRATION NUMBER/TYPE MI	evel DATE 6/20/24 -5 [Mechanical	
Feedwater to Steam Generator #1		
ATTRIBUTES:		
WELDING/NDE	PHYSICAL CONDITIONS (DIMENSIONS & LOCATIONS	
CRAFTSMANSH1P	LEAK RATE TEST (10=2 STUCM3/S)	
ACCEPTANCE CRITERIA:		
FSAR Sections: 3.8.1.1.6 3.8.2.6 6.2.2.2 (Table SPECIFICATIONS: Electrical I RG: 1.63 (Electrical; IEEE 3)	ES-12/12A; Mechanical NS-74	
ASME Section III, NE for Clas	ss MC Components	
PROCEDURES N/A		
RESULTS Dimensions and low	ation were found to be in accordance with oso3. Welding and craftsmanship had been performed	
in accordance with the acc	ceptance criteria and had been accumulately documented	
RESOLUTION N/A		
INSPECTION REPORT NO 50 -445	124-16 PAGE NO Ant-20 NSPECTOR Oberg Bennett	

	14 / Mechanical
Containment Pressure Re	
ATTRIBUTES:	
WELDING/NDE	PHYSICAL CONDITIONS (DIMENSIONS & LOCATIONS
CRAFTSMANSHIP	LEAK-RATE TEST (10=2 stdcM3/s)
ACCEPTANCE CRITERIA:	
FSAR Sections: 3.8.1.1.6 3.8.2.6 6.2.2.2 (Tables SPECIFICATIONS: Electrical ES RG: 1.63 (Electrical; IEEE 317	-12/12A; Nechanical Pi3-74
ASME Section III, NE for Class	
PROCEDURES NA	
RESULTS Dimensions and luca	tion were found to be in accordance with
	nd craftsmanship had been performed in accordance
2323-M1-0502. Welding an	111
with the acceptance criteria	and had been accurately documented.
2323-M1-0502. Welding an with the acceptance criteria	and had been accurately documented.
with the acceptance criteria	and had been accurately documented.
a3a3-M1-050a. Welding an with the acceptance criteria RESOLUTION NA	and had been accurately documented.
with the acceptance criteria	and had been accurately documented.
with the acceptance criteria	and had been accorately documented.
with the acceptance criteria	and had been accorately documented.
with the acceptance criteria	and had been accorately documented.

PENETRATION NUMBER/TYPE IE-	18 / Electrical
ATTRIBUTES:	PHYSICAL CONDITIONS (DIMENSIONS & LOCATION
HELDING/NDE	
CRAFTSMANSHIP	LEAK RATE TEST (!0=2stdCM3/s)
ACCEPTANCE CRITERIA:	
FSAR Sections: 3.8.1.1.6 3.8.2.6 6.2.2.2 (Table SPECIFICATIONS: Electrical RG: 1.63 (Electrical; IEEE 3	ES-12/12A; Mechanical MS-74
ASME Section III. NE for Cla	ss MC Components
PROCEDURES BEI -9 Rev 2 VI	1/83 Leak Rate Testing of Electrical Penetration
A Mander Sus	tem
- O-marians and le	ocation were found to be in accordance will
non moise Maintenance	and leak rate testing had been performen in
the the access	stance criteria and procedures, and has been
accordance with the accept	ere was no evidence of insulation cracking on
penetration calling.	
RESOLUTION N/A	
	15/84-16 PAGE NO ATT1-22 INSPECTOR Obers

ENETRATION NUMBER/TYPE IE-	-17 / Electrical
ATTRIBUTES:	
WELDING/NDE-	PHYSICAL CONDITIONS (DIMENSIONS & LOCATIONS
CRAFTSMANSHIP	LEAK RATE TEST (10=2stdCM3/s)
ACCEPTANCE CRITERIA:	
FSAR Sections: 3.8.1.1.6 3.8.2.6 6.2.2.2 (Tabl SPECIFICATIONS: Electrical RG: 1.63 (Electrical; IEEE 3	ES-12/12A; Mechanical MS-/4
ASME Section III, NE for Cla	ss MC Components
PROCEDURES EET-9 Rev 2 1/17	183 Leak Rate Testing of Electrical Penetration
A Us and Header Sus	ten
Dimensions and	location were found to be in accordance with
res 00182 Maintenance	and leak rate testing had been performed in
Jone with the acces	tunce criteria and procedures, and had been
Lely documented. T	here was no evidence of insulation cracking
on penetration cabling.	
RESOLUTION N/A	
	-/ -14 PAGE NO P-1-23INSPECTOR Oben
INSPECTION REPORT NO 50-44	5/84-16 PAGE NO ATT1-23 INSPECTOR Obey

CRAFISMANSHIP LEAK RATE TEST (10=2stdCM3/s) ACCEPTANCE CRITERIA: FSAR Sections: 3.8.1.1.6 3.8.2.6 6.2.2.2 (Tables 6.2.4-1) SPECIFICATIONS: Electrical ES-12/12A; Mechanical MS-74 RG: 1.63 (Electrical; IEEE 317 ASME Section III, NE for Class MC Components PROCEDURES EEI-9 Rev 2 1/11/83 Leak Rate Testing of Electrical fenethation Assemblies and Header System RESULTS Dimensions and location Dere found to be in accordance with FSE 00182. Maintenance and leak rate testing had been performed in accordance with the acceptance criteria and procedures, and had been accumed occumented. There was no evidence of insulation cracking on penetration cabling. RESOLUTION N/A	PENETRATION NUMBER/TYPE 15-6/Electrical		
CRAFISMANSHIP LEAK RATE TEST (10=2stdCM3/s) ACCEPTANCE CRITERIA: FSAR Sections: 3.8.1.1.6 3.8.2.6 6.2.2.2 (Tables 6.2.4-1) SPECIFICATIONS: Electrical ES-12/12A; Mechanical MS-74 RG: 1.63 (Electrical; IEEE 317 ASME Section III, NE for Class MC Components PROCEDURES EEI-9 Rev 2 1/17/83 Leak Rate Testing of Electrical Penetration Assemblies and Header System RESULTS Dimensions and location Were found to be in accordance with FSE OCI82. Maintenance and leak rate testing had been performed in accordance with the acceptance criteria and procedures, and had been accurate documented. There was no evidence of insulation cracking on penetration cabling. RESOLUTION N/A	ATTRIBUTES:		
FSAR Sections: 3.8.1.1.6 3.8.2.6 6.2.2.2 (Tables 6.2.4-1) SPECIFICATIONS: Electrical ES-12/12A; Mechanical MS-74 RG: 1.63 (Electrical; IEEE 317 ASME Section III, NE for Class MC Components PROCEDURES EEI-9 Rev 2 1/17/13 Leak Rate Testing of Electrical Penetration Assemblies and Header System RESULTS Dimensions and location Were found to be in accordance with FSE 00182. Maintenance and leak rate testing had been performed in accordance with the acceptance criteria and procedures, and had been accordance with There was no evidence of insulation cracking on penetration cabling. RESOLUTION N/A	WELDING/NDE-	PHYSICAL CONDITIONS (DIMENSIONS & LOCATIONS	
FSAR Sections: 3.8.1.1.6 3.8.2.6 6.2.2.2 (Tables 6.2.4-1) SPECIFICATIONS: Electrical ES-12/12A; Mechanical MS-74 RG: 1.63 (Electrical; IEEE 317 ASME Section III, NE for Class MC Components PROCEDURES EET-9 Rev 2 1/17/83 Leak Rate Testing of Electrical Penetration Assemblies and Header System RESULTS Dimensions and location Were found to be in accordance with FSE 00182. Maintenance and leak rate testing had been performed in accordance with the acceptance criteria and procedures, and had been accurate documented. There was no evidence of insulation cracking on penetration cabling. RESOLUTION N/A		LEAK RATE TEST (!0=2stdCM3/s)	
3.8.2.6 6.2.2.2 (Tables 6.2.4-1) SPECIFICATIONS: Electrical ES-12/12A; Mechanical MS-74 RG: 1.63 (Electrical; IEEE 317 ASME Section III, NE for Class MC Components PROCEDURES EEI-9 Rev 2 1/17/73 Leak Rate Testing of Electrical Penetration Assemblies and Header System RESULTS Dimensions and location Were found to be in accordance with FSE 00182. Maintenance and leak rate testing had been performed in accordance with the acceptance criteria and procedures, and had been accordance documented. There was no evidence of insulation cracking on penetration cabling. RESOLUTION N/A	ACCEPTANCE CRITERIA:		
ASME Section III, NE for Class MC Components PROCEDURES EET-9 Rev 2 1/17/83 Leak Rate Testing of Electrical Penetration Assemblies and Header System RESULTS Dimensions and location Were found to be in accordance with FSE 00182. Maintenance and leak rate testing had been performed in accordance with the acceptance criteria and procedures, and had been accuma documented. There was no evidence of insulation cracking on penetration cabling. RESOLUTION N/A	3.8.2.6 6.2.2.2 (Tabl SPECIFICATIONS: Electrical	ES-12/12A; Mechanical MS-74	
PROCEDURES EEI-9 Rev 2 1/17/83 Leak Rate Testing of Electrical Penetration Assemblies and Header System RESULTS Dimensions and location Were found to be in accordance with FSE 00182. Maintenance and leak rate testing had been performed in accordance with the acceptance criteria and procedures, and had been accordance documented. There was no evidence of insulation cracking on penetration cabling. RESOLUTION N/A	ASME Section III. NE for Cla	ss MC Components	
Assemblies and Header System RESULTS Dimensions and location Dere found to be in accordance with FSE 00182. Maintenance and leak rate testing had been performed in accordance with the acceptance criteria and procedures, and had been accum documented. There was no evidence of insulation cracking on penetration cabling. RESOLUTION N/A	DENCEDURES FET-9 Rev 2	117/83 Leak Rate Testing of Electrical Penetration	
RESULTS Dimensions and location Dere found to be in accordance with FSE 00182. Maintenance and leak rate testing had been performed in accordance with the acceptance criteria and procedures, and had been accordance documented. There was no evidence of insulation cracking on penetration cabling. RESOLUTION N/A	Acomplies and Header Sys	ten	
FSE 00182. Maintenance and leak rate testing had been performed in accordance with the acceptance criteria and procedures, and had been accordance documented. There was no evidence of insulation cracking on penetration cabling. RESOLUTION N/A	Duranting and In	ration Dere found to be in accordance with	
accordance with the acceptance criteria and procedures, and had been accordance documented. There was no evidence of insulation cracking on penetration cabling. RESOLUTION N/A	RESULIS Dimensions and to	and leak rate testing had been performed in	
documented. There was no evidence of insulation cracking on penetration cabling. RESOLUTION N/A	The out with the access	stance criteria and procedures, and had been accumtely	
RESOLUTION N/A	Accordance with the conf	eridence of insulation cracking on penetration	
RESOLUTION M/A			
NE SOL OTTON			
TOWN TO THE PROPERTIES OF THE	RESOLUTION N/A		
TOWN TO THE PROPERTIES OF THE			
The state of the s			
- And Was and A and Medicine Ober			
THE PROPERTY OF THE PARTY OF TH		15/84-16 PAGE NO Arr2-24 INSPECTOR Oberg	

HVAC INSPECTION DATA SHEET

ROCM: Reactur Bldg. 905 Level DATE: 6/20/84
AREA(s) EXAMINED: HVAC seismic duct supports and associated duct
segments. The seismic duct supports examined are: 10-4F, 10-4G, 10-4H,
10-45, 10-4K, 10-4L, 10-4BE, 10-4M, 10-4N, 10-4P, 10-4R, 10-4R,
ATTRIBUTES:
Equipment (Ducts, Bampers, Supports) Instrumentation & Controls (Separation & Craftsmanship) Documentation (Installation & Inspection)
ACCEPTANCE CRITERIA;
FSAR Sect 9.4 Specifications MS-85 Procedure
and associated duct segments. This examination consisted of approximately
Vy of the seismic duct supports on the 905 level of the reactor building.
The seismic duct attributes observed by the NRC inspectors are as follows:
1) location, 2) dimensions, 3) member size, and 4) welding. The duct segment
attributes observed are: 1) orientation, 2) segment size, 3) location,
4) general lucation, and 5) associated hardware. Three of the 25
RESOLUTION: N/A
INSP. RPT. NO: 50-445/84-16 PAGE NO: ATT1-25 INSPECTOR: Oberg Bennett, Skow

HVAC INSPECTION DATA SHEET

Room:	Reactor	Bldg , 905 Leve	1	DATE: 6/20	184
			T, 10-40, 10-4V	, 10-486, VIO	- (2,
VIO-	CI,10-44	2,10-10, VIO-	15, 10-16, 10-40	, and 1E-16. 0	uct segments
insp	ected wer	e those associa	ted with seism	ic duct supports	inspected
ATTRIB	UTES:				
Instru	mentation.	, Dempen s, Supp & Controls (Sep nstallation & I	aration & Crafts	manship)	
ACCEPT	ANCE CRITE	RIA;			
Specif	Sect for fications of 1122-MA-01	MS-85 154,2128-MI-4553,24 ts inspected ex	R.G. Procedu	re vensional discrep	incies and
			by the NRC inspe		
-	AND REAL PROPERTY AND ADDRESS OF THE PARTY AND	COLUMN TAXABLE DESCRIPTION DE LA COLUMN DE L	analysis by Corp		
			ports were found		
			s documented in		
-			l during inspection		
		906-1D-16,			
RESOLI	UTION: M/				
	1				
					•
			Part and a second		
INSP.	RPT. NO:	50-445/84-16	PAGE NO: Arr1	-2 INSPECTOR	Bennett skan

Procedures: Bahnson Procedure OF1-TUSE-001,	ler 10 , July 21, 198:
"Ductwork Fabrication Procedure"	
Bahnsun Procedure DFF-TUSI-003, 1	Per 7, May 6, 198
4 Duct Support Fabrication & Installat	ion trocedure"
Bahas on Procedure OFP-TUSI-004,	Res 10, April 17, 19
ue Orilled - In Expansion Bolts Installation	
Bahnson Procedure Off-TUSE-003, Re	er 8, May 4, 148
a Duct support Design Fabrication & Inst	kullation Procedure 4
Letters: CCL letter to Bahnson Service Co. of	May 22, 484
CEL letter to Behason Service Co. al	May 25,1974
REPORT: CCL REPORT A-579-83 E	YALVATION OF
NON-CONFORMING WELDS TUST C	PSES DUCTWO
	Olem
P. RPT. NO: 50-445 /84-16 PAGE: ATT1-27 INSPECTOR:	Bernett
	Skow

NSPE	TION ELEMENT: HVAC - AddITIONAL DOCUMENTS REVIEWED
(CBI Documents / Descrongs related to the second
1	welled to the containment lines plate)
	· Marter Check List - Stem = 1, 3, 19 (Pal = 50.4)
	· Shop Release For Shipment Check test (7/30/76)
	(8/23/26)(12/9/26)
	· Material Heat Number Sheet (12/9/76)(8/23/
	(8/2/26)
	· CBI Telecopy #817-897-4000 5/25/84
	· WPS - E 8018-C1 74-2427/8 (Rev-4-3/15/7)
	· Welde Performance Qualification text No 305
	(10/16/74)
	· CBI OA Menual (ASME SECTION III PRODUCT
	Division 3, Section 8 - Welding
	· CBI Drawing No 50, Ren 5 - 74- 24272
	· Bahnson Welling Procedure Specification
	BSC-20 (Ren 3 7/5/28)
NSP.	RPT. NO: 50-445/8416 PAGE: ATT1-28 INSPECTOR: OBERG

RACEWAY INSPECTION DATA SHEET

RACEWAY NUMBER/TYPE; (Tray,	, Conduit)
THWREB SECTIONS OF THE	13 TIZGREM SECTIONS 27 THRU 47
THYRED SECTIONS 26 THAN	28 ; TIZ GRBM SECTIONS SI THRU 67
TINGRDE SECTIONS 19 THRU	40 ; TIYORDX SECTIONS OF THRU 06
TISGREL SECTIONS 28 THREE	51 ; TIYGROZ SECTIONS OF THRU OF
ATTRIBUTES!	
Type & Size Tray Covers Grounding	Identification Documentation (Installation Fill Factor & Inspection) Supports Connections
Craftsmanship ACCEPTANCE CRITERIA:	Separation (Physical/Electrical)
FSAR Section 8.3 IEEE 384	R.G
Specification	Procedure
THIS IS APPROXIDATELY 924 FOR INSPECTED. ALL CABLE TRAY INSTALLED AND THE DOCUMENTATION TO RESOLUTION: NCR 5 M 8 4	THE SHOW THE AS BUILD CONDITION. THOSE CABLE TO DOCUMENT THE DEFICIENCIES.

RACEWAY INSPECTION DATA SHEET

ROOM: CONTAINMENT BUILDING	(continued)	DATE: 6/20/84
RACEWAY NUMBER/TYPE: (Tray, Cor	nduit)	
TIZORBK SECTIONS 41 7	thru 42	
TIBORCJ SECTIONS 43	thru 44	
TIZORBK SECTION 49		
TIYBREC SECTION 37		
ATTRIBUTES!		
Tray Covers Grounding	fill Factor	Documentation (Installation & Inspection) Connections /Electrical)
ACCEPTANCE CRITERIA;		
FSAR Section 8.3 IEEE 384	R.G	
Specification	Procedure	
RESULTS: (CONTINUED) HANGERS ARE 6567, 6576, 6577, 6578, 544 3 SEPARATE HANGERS SHARED A	91,5498, \$499 AN	5519. IN TWO CASTS,
WALL THE USE OF A CONTON PIEC	E is A DOCUMENTED	ALTERNATIVE TO OTHER
TYPE OF MANGERS, BUT WAS A	OT A BOOM DENTED	SUTERNATIVE IN THESE CASE
RESOLUTION:		
INSP. RPT. NO: 84-/7	PAGE NO: Anti-	INSPECTOR: MARTIN

THOSE HANGER WATER 6502, 6504, 6505, 6576,6577, AND 6578. CARLE TA WATHER 6567 MAP A BEVEL WASHER FOR A HILTI BOLT MISHLENED. STH 6632 AND 6638 MAP DIRENSIONS BETOND AND WED TOLERANCE, CTH 6642 AND B HARD WELD LOCATED IN DIFFERENT PLACES FLOW THOSE SPECIFIED. CTH 54 TYPE AND 5419 HAVE NO ENGINEETHING APPROVAL FOR WELDING TO INDEPED PLATS IN CONSUNCTION WITH HILTI BOLTS. CTH 5519 REQUIRED GROUT PETWEEN THE BASE PLATE MAP THE FLOOR, BROUT WAS NOT USED.	INSP. RPT. NO: 84-17 PAGE: #772-3/INSPECTOR:	Mresin
THOSE HANGERS WERE 6507, 6504, 6505, 6576,6577, AND 6578. CARLE THE MANNER 6567 MAP A BEVER WASHER FOR A HILTI BOLF MISALIGNED. STH 6632 MAD 6638 MAP BINENSIONS BETOND ALLOWED TOLERANCE, CTH 6642 AND GOOD WELD LOCATED IN DIFFERENT PLACES FROM THOSE SPECIFIED. CTH 54 TYPE AND 5498 MAD 5499 HAVE NO ENGINEERING APPROVAL FOR WELDING TO INDEDED PLATER ON CONJUNCTION WITH HILTI BOLTS, CTH 5519 REQUIRED GROUT PETWEEN		
HOSE HANGERS WERE 6503, 6504, 6505, 6576,6577, AND 6578. CARLE THE ANDRE 6567 MAP A BEVEL WASHER FOR A HILTI BOLT MISALIGNED. CTH 6632 NO 6638 MAP DIRENSIONS BEYOND ALLOWED TOLERANCE, CTH 6642 AND 6 THE WELD LOCATED IN DIFFERENT PLACES FROM THOSE SPECIFIED. CTH 54 THEY AND 5419 HAVE NO ENGINEERING APPROVAL FOR WELDING TO INDEDED PLATS IN CONSUNCTION WITH HILTI BOLTS, CTH 5519 REQUIRED GROUT BETWEEN		
HOSE HANGERS WERE 6507, 6504, 6505, 6576,6577, AND 6578. CARLE THE HANGER 6567 MAP A BEVEL WASHER FOR A HILTI BOLT MISALIGNED. CTH 6632 HO 6638 MAP DIRENSIONS BETOND ALLOWED TOLERANCE, CTH 6642 AND 6 HAD WELD LOCATED IN DIFFERENT PLACES FROM THOSE SPECIFIED. CTH 54 HAS AND 5499 HAVE NO ENGINEERING APPROVAL FOR WELDING TO INDEDED PLATE HE CONSUNCTION WITH HILTI BOLTS, CTH 5519 REQUIRED GROUT BETWEEN		
WOSE HANGERS WERE 6500, 6504, 6505, 6576,6577, AND 6578. CARLE THE WORK 6567 MAP A BEVEL WASHER FOR A HILTI BOLT MISALIGNED. CTH 6632 NO 6638 MAP DIRENSIONS BETOND ALLOWED TOLERANCE, CTH 6642 AND 6 NO WELD) LOCATED IN DIFFERENT PLACES FROM THOSE SPECIFIED. CTH 54 NO 848 AND 5499 HAVE NO ENGINEERING APPROVAL FOR WELDING TO INDEDED PLATE OF CONSUNCTION WITH HILTI BOLTS, CTH 5519 REQUIRED GROUT BETWEEN		
HOSE HANGERS WERE 6507, 6504, 6505, 6576,6577, AND 6578. CARLE THE HANGER 6567 MAP A BEVEL WASHER FOR A HILTI BOLT MISALIGNED. CTH 6632 HO 6638 MAP DIRENSIONS BETOND ALLOWED TOLERANCE, CTH 6642 AND 6 HAD WELD LOCATED IN DIFFERENT PLACES FROM THOSE SPECIFIED. CTH 54 HAS AND 5499 HAVE NO ENGINEERING APPROVAL FOR WELDING TO INDEDED PLATE HE CONSUNCTION WITH HILTI BOLTS, CTH 5519 REQUIRED GROUT BETWEEN		
HOSE HANGER WELL 6507, 6504, 6505, 6576,6577, AND 6578. CARLE THE HAVER 6567 HAP A BEVEL WASHER FOR A HILTI BOLT MISALIGNED. CTH 6632 NO 6638 HAP DIRENSIONS BEYOND ALLOWED TOLERANCE, CTH 6642 AND 6 AP WELD LOCATED IN DIFFERENT PLACE FROM THOSE SPECIFIED. CTH 54 198 AND 5499 HAVE NO ENGINEERING APPROVAL FOR WELDING TO INDEDED PLATE NO CONSUNCTION WITH HILTI BOLTS, CTH 5519 REQUIRED GROUT BETWEEN		
HOSE HANGER WERE 6503, 6504, 6505, 6576,6577, AND 6578. CARLE THE ANDER 6567 HAD A BEVEL WASHER FOR A HILTI BOLT MISALIGNED. CTH 6632 NO 6638 HAD DIRENSIONS BEYOND ALLOWED TOLERANCE, CTH 6642 AND 6 AD WELD LOCATED IN DIFFERENT PLACES FROM THOSE SPECIFIED. CTH 54 TYPE AND 5419 HAVE NO ENGINEERING APPROVAL FOR WELDING TO INDEDED PLATE NO CONSUNCTION WITH HILTI BOLTS, CTH 5519 REQUIRED GROUT BETWEEN		
HOSE HANGER WELL 6507, 6504, 6505, 6576,6577, AND 6578. CARLE THE HAVER 6567 HAP A BEVEL WASHER FOR A HILTI BOLT MISALIGNED. CTH 6632 NO 6638 HAP DIRENSIONS BEYOND ALLOWED TOLERANCE, CTH 6642 AND 6 AP WELD LOCATED IN DIFFERENT PLACE FROM THOSE SPECIFIED. CTH 54 198 AND 5499 HAVE NO ENGINEERING APPROVAL FOR WELDING TO INDEDED PLATE NO CONSUNCTION WITH HILTI BOLTS, CTH 5519 REQUIRED GROUT BETWEEN		
HOSE HANGERS WERE 6503, 6504, 6505, 6576,6577, AND 6578. CARLE THE ANDRE 6567 MAP A BEVEL WASHER FOR A HILTI BOLT MISALIGNED. CTH 6632 NO 6638 MAP DIRENSIONS BEYOND ALLOWED TOLERANCE, CTH 6642 AND 6 AD WELD LOCATED IN DIFFERENT PLACES FROM THOSE SPECIFIED. CTH 54 TYPE AND 5419 HAVE NO ENGINEERING APPROVAL FOR WELDING TO INDEDED PLATS NO CONSUNCTION WITH HILTI BOLTS, CTH 5519 REQUIRED GROUT BETWEEN		
HOSE HANGERS WERE 6502, 6504, 6505, 6576,6577, AND 6578. CARLE THE MORE 6567 HAP A BEVER WASHER FOR A HILTI BOLT MISALIGNED. CTH 6632 NO 6638 HAP DIDENSIONS BETOND ALLOWED TOLERANCE, CTH 6642 AND BE THE WELDS LOCATED IN DIFFERENT PLACES FROM THOSE SPECIFIED. CTH 54 198 AND 5499 HAVE NO ENGINEERING APPROVAL FOR WELDING TO INDEDED PLATS		2004 727 2007
THOSE HANGERS WERE 6507, 6504, 6505, 6576,6577, AND 6578. CARLE THE ANDRE 6567 HAP A BEVEL WASHER FOR A HILTI BOLT MISALIGNED. CTH 6632 NO 6638 HAP DIRENSIONS BEYOND ALLOWED TOLERANCE, CTH 6642 AND 6 HAP WELDS LOCATED IN DIFFERENT PLACES FROM THOSE SPECIFIED. CTH 54		
MOSE HANGER WORE 6502, 6504, 6505, 6576, 6577, AND 6578. CABLE TA	HAP WELDS LOCATED IN DIFFERENT PLACE FROM THOSE SPEC	IEIED. CTH 5491
CHOSE HANGEN WERE 6502, 6504, 6505, 6576,6577, AND 6578. CARLE TA		
		6578. CABLE TRA
ACCWAY INSPECTION DATA - RESULTS (CONTINUED)		

CONTRINTENT	BUILDING	616V	860 4	905	(CONTINUED)
£					

THE SABLE TRAT AND ASSOCIAT	TO SUPPORTS:
2323-E1-0502-11	2323-5-0901
2323-E1-0502-12	2323-5-0902
2323-E1-0502-13	2323-5-0903
2323-E1 .0502-14	2323-5-09/3
2323-F1-0502-15	2323-F1-0502-S
2323-61-0502-/6 .	2323- £1-0502-01-5
2323-61-0502	2323-61-0503-S
2323-E1-0502-01	2323-£1-0510-S
2323- <i>E1-0502-17</i>	2323-F1-0510-01-S
2323-61-0510-01	FSE-00220-MAP
2323-E1-1702	FSE-00221
2323-E1-1702-01	FSE-00228 (MAP)
FSE-00159 Series	FSE - 00229 - MAP
FSE-00179 Series	2323-£1-/800
INSP. RPT. NO: 84-17	PAGE: And-32 INSPECTOR: MARTIN

RACEWAY INSPECTION DATA SHEET

ROOM: C	iontainment	Bldg.	860 ¢ 905	Levels	DATE:_	6/20/8	7
RACEWAY N	UMBER/TYPE: (Tray, C	onduit)				
C 13 Ø 11	886, C13Ø1	0134, (13 6 11306	C13 \$ 106	286, CI	3\$ 11956	
C 13 6 30	511, c 13 00	7849, C	13\$ 08750,	C136 10	132, 61	26 11 303	
C 13 G 10	285, C 1261	1497, 0	136 30512,	C 136 029	123, C1	3 6 07405)	
C 136 13	834, C14 W30	537, 0	14Y 30522	, C12 \$ 160	078, (1	26 09120	
ATTRIBUTE	<u>s</u> :						
Type & Si Tray Cove Grounding Craftsman	75 .		Identifica Fill Facto Supports Separation	>	& In Connec	spection) tions	Installation
ACCEPTANC	E CRITERIA;						
	tion ES-I			R.G. 1.	QI-QP	-11.3-23, G	RI-Q1-11.3-40
	All of the						
	were installed te design dra						
RESOLUTIO	N: <u>N/A</u>						
INSP. RPT	. NO: 50-145	184-16	PAGE NO	An1-	35 I	NSPECTOR:	Oberg Gennett

RACEWAY INSPECTION DATA SHEET

ROUM: Contai	nment Bidg.	860 9 405 Le	vels	DATE:_	6/20/8	4
RACEWAY NUMBER	TYPE: (Tray	, Conduit)				
13 630365, 1	48 09362,	14 Y 30536)	14Y 1315	5, 120	08110,	
14 \$ 15162, 1	4R 30556,	14620499,	120 11957	, 13 \$	10113)	
136 07379, 1	26 07924,	14 7 30554,				
ATTRIBUTES!						
Type & Size Tray Covers Grounding Craftsmanship		Fill Fact Supports	ation or (Physica	& Ins	spection)	Installation
ACCEPTANCE CRI	TERIA:					
FSAR Section 8 IEEE 384 Specification			R.G. 1.			17-11.3-40
RESULTS: N/A	1					
RESOLUTION:	N/A					
INSP. RPT. NO:	50-445/84	PAGE NO	: An1-3	s' II	NSPECTOR:	Oberg Bennett

GENERAL INSPECTION DATA SHEET

SPECTION ELEMENT: CABLE SEPRONTION BAPRIEL MATERIAL DATE: 6/19/84
TRIBUTES: QUALFICATION OF MATERIALS, PROCUREMENT,
PABEICATION, INSTALLATION, CERTIMALISMA,
DOLUMENIATION.
CCEPTANCE CRITERIA: G: H SPECIFICATIONS 2323-MS-30 AND
2323-MS-38H; REGULATORY GUIDE 1.75; IDCFRSO, APP. R
TEEE 384; PROCEDURE EET- 25, R3; PROCEDURE QI-QP-11.3-
RIZ, AND REGULATORY GUIDE 1.29.
ESULTS: THE SBM DOES OBNISCEM TO THE SPECIFICALLY
AS EXNIBITED BY DOCUMENTED TEST RESULTS AND
THE INSTALLATION OF THE SAM WAS ASSOMBLISHED
IN MODED MIKE WHING THE REQUIREMENTS, (SEE CON
RESOLUTION:
INSP. RPT. NO: 84-16 PAGE: ATT-1-35 INSPECTOR: MAETIN

INSPECTION ELEMENT: CARLE SEPREDION BAPPIER MOTERIAL (58M) IN ADDITION TO SHEET MEIRL BARRIERS, CPSES IS WILLIAMS A BLANKET MATERIAL SUPPLIED BY BEB INSULATION, INC. THE BLANKETS ARE 1/2 INCH THICK CEPAFIBER MATERIAL COURFED WITH AMETER SILTEMP FABRIC, WITH THE COURSE BEING STITCHED TOGETHER WITH ASTED BURETZ THREAD. THESE BLANKETS ARE USE TO MEET THE REQUIREMENTS OF REGULATOR GUIDE 1.75 PAID THE PADATION ENERSY SNIELD PERMITEMENTS OF LOCFR SO, APPENDIX R, FOR CHEVES, ERCEIDAY, JUNCTION BOXES, AND INSTRUMENTATION, THE SILTEMP FABRE PROVIDES PROTECTION FOR THE FIBER MATERIAL AND INSURES THAT THE FIBER MATERIAL PEMPINS IN PLACE DURING INITIATION OF FIRE SUPPRESSION SYSTEM OR USE OF FIRE HOSE. THE BLANKETS ARE FABRICATED ON SITE IN A SEWING SHOP DREW. THE BURNKETS ARE SEWN IN A MANNEE TO INSHEE THAT THE 1/2 INCH THICKNESS, AND SIZED FOR A 2" OVERIAP DURING INSTRUBTION THE NRC INSPECTOR REVIEWED THE PROCUREMENT, TESTING BND INSTAURTION DOCUMENTATION AND INSPECTED 15 APERS WHERE SEM MATERIAL WAS INSTALLED (SEE CONT. SHT) INSP. RPT. NO: 84-16 PAGE: PAT 1-36 INSPECTOR: MARTIN

HE FOLL	OWING DO	CHMENTATIO	ON WAS EEVIEWED!
; H SX	ECIFICATION	v 2323-m	5-384
HSP	ECIFICATION	2323- M	's -30
DESIGN	CHANGE A	NINDERATI	DUS 17,470, 2.6
,,	•	~	18,569, R.O
^	*	,,	18,627, 8.0
SER A	ומחוזו נפנו	VON EXPORT	FOR INSUCO/HEMYC
	The state of the s	Charles for which	,
,			
PANE D	Wear Sys	TEN	
PARE D	Vens Sys	-25, REV. 3	AND GJ & P41.3-44, R.
PAREDU Vumen	Wear Sys Less EEL OUS TEST	SERT - 25, REV. 3 REPORTS FR	AND GI-GP41.3-44, R. BOM SOMMWESTERN LA
PAREDU Vunce	Wear Sys Less EEL OUS TEST	SERT - 25, REV. 3 REPORTS FR	AND GI-GP41.3-44, R. BOM SOMMWESTERN LA
PAREDU Vunea FOR	Dear Sys vecs EEI ous TEST	SEM - 25, REV. 3 REPORTS FA	AND QI & PH. 3-44, R. SOM SOMMWESTEEN LA
PARLEDU PARLEDU VUMER PARCITA	DEAP SYSTEMS TEST	SERT - 25, REV. 3 REPORTS FR CORL TRISTIA POLLAGE C	AND QI &PH. 3-44, R. BOM SOMMWESTEEN LA G OF THE SBM BY
PARLEDU PARLEDU VALIME B FOR ? PURCHIR PARL	DEAP SYSTEMS TEST OF CHECHTED E.	SERT - 25, REV. 3 REPORTS FOR PRICES OF 123 AND 1	AND QI &PH.3-44, R. BOM SOMMWESTEEN LA G OF THE SBM BY A PF-10194-5 AND ME MEES.
PARCEDU PARCEDU FOR T PURCHA PURCHA	Dear Systems EEL OUS TEST OUE CHEM OU DEPER OURILD E	SEM - 25, REV. 3 REPORTS FO CAL TESTIA PALLAGE O TRS AND I PALLAGE O	AND COLORPHIS - 44, R. BOM SOMMWESTEEN LA BOM SOMMWESTEEN LA BOF THE SBM BY A PF-10794-5 AND THE MEPS.
PARE DE LA PORTE D	Dear Systems EEL OUS TEST OUE CHEM OU DEPER OURILD E	SERT - 25, REV. 3 REPORTS FOR PRICES OF 123 AND 1	AND COLORPHIS - 44, R. BOM SOMMWESTEEN LA BOM SOMMWESTEEN LA BOF THE SBM BY A PF-10794-5 AND THE MEPS.
PARE DE LA PORTE D	Dear Systems EEL OUS TEST OUE CHEM OU DEPER OURILD E	SEM - 25, REV. 3 REPORTS FO CAL TESTIA PALLAGE O TRS AND I PALLAGE O	AND COLORPHIS - 44, R. BOM SOMMWESTEEN LA BOM SOMMWESTEEN LA BOF THE SBM BY A PF-10794-5 AND THE MEPS.
PARLEDU PARLED	Dear Systems EEL OUS TEST OUE CHEM OU DEPER OURILD E	SEM - 25, REV. 3 REPORTS FO CAL TESTIA PALLAGE O TRS AND I PALLAGE O	AND COLORPHIS - 44, R. BOM SOMMWESTEEN LA BOM SOMMWESTEEN LA BOF THE SBM BY A PF-10794-5 AND THE MEPS.
PARLEDU VILIMER FOR T PURCHA PARLAR	Dear Systems EEL OUS TEST OUE CHEM OU DEPER OURILD E	SEM - 25, REV. 3 REPORTS FO CAL TESTIA PALLAGE O TRS AND I PALLAGE O	AND COLORPHIS - 44, R. BOM SOMMWESTEEN LA BOM SOMMWESTEEN LA BOF THE SBM BY A PF-10794-5 AND THE MEPS.

COMPONENT INSPECTION DATA SHEET

ROOM Con	tainment Bldg. 905 Level DATE
	DENTIFICATION: Hydrogen Recombiners; Tex-GHREEL (GHREEE) -01/02; No. 7824914/5
ATTRIBUTES	INSPECTED: Installation, maintenance, anchor bolting, foundation
	CRITERIA: Westinghouse Manual CP-0001-041; 2323-51-0534; 1-0551; DC/00A # 928
with the i	Installation, Foundation, and anchor bolts were found to be in accordance installation drawings. Type Class "B" storage was required. Maintenance had been
performed	properly during storage in the warehouse. Installation of the hydrogen was completed in December, 1982 (Unit #2) and February, 1883 (Unit #1), Maintonan
THE RESIDENCE OF THE PARTY OF T	every dyears and has not yet been performed since equipment has been
production of the latest the late	r less than dyears. Review of procurement package revealed out of spec voltage
the second control of	3v vice 10±2v) for compantor output on pages 15 and 17 (unit #2).
RESOLUTION	: Licensee was informed of out of spec voltage readings. Quality release N-41424
	obtained by licensee from Westinghouse stating that voltages were satisfactory.
Discussions	with Startup and Westinghouse personnel revealed that voltage readings du not
effect the	operation of the equipment, and that equipment has successfully completed
preoperation	nul testing.
INSPECTIO	REPORT NO. 50-445/84-16 PAGE NO And-35 INSPECTOR Oberg /Bennett

PROCUREMENT INSPECTION DATA SHEET

ROOM CONTAINMENT - 2/NIT/ DATE 6/20/84	
ITEM IDENTIFICATION: Pressuringer Spring Values (2)	
air-Operated, V- fall naties	
Serial No 644 8863; 6448864	
Wer Bailey Paritimen, Frisher Entrolo	
Instruction Book: 4 5 710-99-4045 Rano	
CP-0001-009A	
SUPPLIER Westinghouse (Fisher Controls Company)	
PROCUREMENT SPECIFICATION NO/TITLE: E - 678844 CONTROL VALUE ASME SECTION TO CLASSES 1, 2 - 3	S
ATTRIBUTES INSPECTED: SEE DATA SHEET	
ACCEPTANCE CRITERIA: ANSI NUS. 2. /3 - /976	
RESULTS: 2 PO solcified (admin + technical) - all	
items y acceptance criteria mose acceptable.	
	-
RESOLUTION: NA	
INSPECTION REPORT NO 50.440/8416 PAGE NO ATT1-39 INSPECTOR OZE	RG

PROCUREMENT INSPECTION DATA SHEET

ROOM CONTAINA	MENT 985-860' LEVELS	DATE 6/20	184
	TION: ELECTRIC HYDROG		afete Class II
Enclose			
SUPPLIER WES	TINGTOUSE - NUCLEAR EN	eery Systems - Pr	TISEVERN, Pa
ATTRIBUTES INSP	CIFICATION NO/TITLE: Equipment (78) PECTED: Purchase Order;	QA Program; Do	tin 957426
ACCEPTANCE CRIT	TERIA: ANSI NUS, 2.13-1976	<i>its</i> —	
all items s	ops-917-01, Rev O , were specified;	all pants for	d Cambridge
RESOLUTION: N			
	ODDT NO 50-445/8416 PAGE	NO ATTI-YO INSPE	CTOR OBERG

PROCUREMENT INSPECTION DATA SHEET

ROOM CON	NTAINMENT - UNIT DATE 6/20/84
TEM IDENT	TIFICATION: PRESSURIZER RELIEF SYSTEM BLOCK VALUES
(2)	VALVE ID Nos 3GM88 FNH SER: 0012; 0013
met	to appended makes.
	The same of the transfer of Principle
	WELECTRIC CORP (Electro- mechanical Division viel Pa.
PDOCUBENE	ENT SPECIFICATION NO/TITLE: G-678852, Rev. + Interim
Chone	e No 1 (5/20/79); No 2 (11/4/74); No 3 (3/20/75)
ATTRIBUTE	ES INSPECTED: SEE DATA SHEET
ACCEPTANO	CE CRITERIA: ANSI N45, 2.13-1976
RESULTS:	all attributes aperified in provisionent specifical related Pennhaue Order were found to meet tomes criterie
acry	tence anterie
RESOLUTI	ION:_NA
INSPECT	TION REPORT NO 50.445/8416 PAGE NO ATT 1-41 INSPECTOR ORERO

INSPECTION ELEME	INT: CONTRINMENT. Procurement documents Reviewed
	gen Recombiners
	chare Order 546-ALP-2798808E (+CN-001+002)
	exponent Specification 95 3426 Ren- 0 (1/05/28)
· Dra	using (8760) 69 Sheet 5 - REVI
- Blo	ch Values (Pressoningen Relief)
	Drawing 8372025 (Ren 1)
	rigment Specification G - 6788 5- 2 Reve
a	12/15/73 + Interin Change No1: No2: No3
	Quality Release QR- 22585
	e RIR 03860 6/14/27
	D. 546-NRK- 214153 BN (+ CN-01 7km 019)
- Some	y Value
	iment Sperification 6-678844 Rev 2 (3/9/16)
	546-CCF-252003-BN (CN-001,7hm 008)
	6-46-CCF- 178380-XN(CN-001 The 030-
	4) (ADMIN P.O.)
· w	QE N-49052 (Ren 0, 1+2)
. 8+1	R RIR 12/8/
· Fis.	HER DWG 55A1225 (Rem C)
	0445/8416 PAGE: An1-42 INSPECTOR: OBERG

SPECTIO	N ELEMENT:_	PEDCUREMENT	DOCUMENT	REVIEW
(B.	ud m	ANSI N45.2.1:	3-1976)	
.5	cone of	Work		
. 2	chnice	Regisirement		
.0	A Grage	am Regisirem	mto	
100		ances		
. 1	acumen	tation Require	nent.	
		amond .		
. 1	Ceniem	of Procurence	t Documents	- A-1 - 3-8
	Tall 1			
		Contract to the contract of th		
			1-43 INSPECTOR:	

GENERAL INSPECTION DATA SHEET

INSPECTION ELEMENT:	"AS-BUILT 7	PROGRAM	DATE: 6/20/8	<u> </u>
ATTRIBUTES: Proce	dens adequa	t to ensu	re drawing a	he
DRAFTII , ROLI				<u></u> 9
RESULTS: Progra of as-limit asignate. Is	derign docum	ento was of	and to be	
RESOLUTION: N. V.	ing control	for the Cont	to mintain con	ntrol q
TNSP RPT NO: 50-7	10-10416 PAGE	Drs 9 - 44	INSPECTOR: OBERG	

INSPECTION ELEMENT: "AS-BUILT" PROGRAM - DOCUMENTS
REVIEWED:
. N.O. PROCEDURE NOC 102 REVI DEAWING + SPECIFICATION
CONTROL
· STA PROCEDURE STA-306, REUS DRAWING + SPECIFICATI
CONTROL
· MASTER RECORDS INDEX
· OPERATIONS QUALITY SURVEILLANCE REPORTS: QSR-84-008
· TUGCO AUDIT REPORT TUG-45
· TUGCO MONITORING DISCREPANCY REPORTS: 82-19 thm 7.5;
83-14 the 83-21 and 83-2526,27
· DRAWINGS: 2323-MI-0300/301 ; 2323-MI-0261/262 ; 2323-MI 0232 ; 2323-MI-0250/251 (ASSOCIATED DCAS AND CMC
· DESIGN CHANGE LOG AFFECTED DECUMENT UPDATE REPORT -
(FOR DRAWINGS LICTED ABOVE)
INSP. RPT. NO: 50-445/8416 PAGE: ATT 1-45 INSPECTOR: OBERG

SPECTION ELEMENT:	As-BUILT PERSEAM.	- ENGINEER INC DE
	CEDURES REVIEWED	
· THE - AD- 1	Rev 2 12/16/83	Organization
* CP-EP-3.0	Rev 6 9/9/83	Organization
There procedure	es define the engr	neering arganing
responsible for	CPSES engineer	ing work.
TNE is sched	for Kint I on a	Il engineering
Naponeilistices	for Knit I on a	ugust 1, 1984

SPECTION ELE	EMENT: AS-Builts: TNE-DC-1 Daign Control
	Requiremente (Ran 2: 1/20/84) - Contain an
	- the general framework and requirements
	Commence and contral of design activities,
	TUGGO Muclean Engineering (CPSES) (Manage
	nall responsibility for implementation
y the de	sign contral procedures.
	Identified the following a whatel & control
design	activities - (also references to implementing procedures)
	in deput (TNE-DC-3,4,7+11)
Dans	on Documentation (TNE-DC-3,4,5,7,11; 12, 15+16)
	face Control
Desig	m Verification (TNE-DC-8,10)
	ment Contal
	on Change Control
Correc	time Octor (procedenal moneonformeres XTNE A
	20 (TNE-AD-Y)
audit	E (TUED ON DEDT PROCEDUEES)
<u> </u>	
NSP. RPT. NO	: 3:1-16 PAGE: ATTI-47 INSPECTOR: DBEEG

Colors.	INSPECTION DATA CONTINUATION SHEET
NSPECTION ELEMENT:	AS-BUILT PREGRAM
CP-EP-18,0	
Turnoner a	
Establishe	I general control of activities
invalving	turn oner of safety related reco
	ing design procument and constr
phases.	
Can 3.3 - R	Eguired a plan for turnoner includ
0 01100 000	of decements " Von telication land
a summery	of Sociemento; Dentification / int
of specific d	of documents; and antisipated schedule.
of specific d	of Sociements; and antisipated schedule.
of sperific d	of Sociments; and antisipated schedule.
of sperific d	of Sociments; and antisipated schedule.
a summany of specific d	of Sociements; and antisipated schedule.
a summany of specific d	of Sociements; and antisipated schedule.
a summany of specific d	of Sociements; and antisipated schedule.
a summany of specific d	of Sociements; and antisipated schedule.
a summany of specific d	of documents; and antisipated schedule.

INSP. RPT. NO: 50-445/8416 PAGE: Art 1-40 INSPECTOR: OBERG

C P.EP. 4.5	R1	2/18/80	LE DEAWN	Verification
general	do	und t	regarding	of Darin Verification
			17 19 27	
			The Here ?	
		1.34		

	to: TNE-AD-4-Control of Engineering
	a matrix of document contra
retention responsibility	. specifically identifies the
following locuments:	Sperifications
	Vandor Document
	Drewing
	Daign Verification
	Design Engineering parloge
•	Engineering Change Notice
	· · · · · · · · · · · · · · · · · · ·
NSP. RPT. NO: 84-16 P	AGE: Art 1-50 INSPECTOR: OBEEG

INSPECTION ELEMENT: As - Builto: TNE-DC-7 Preparation and
Review of Design Drawings - applies to new
drawing and browings transferred to TNE
oustoby. Final nine drawings (prevoned by
the original designer - G+ H, Westinghame) - effect
the trousfer of drawing contral, Final some
drawings are reviewed as required by TNE
Manager
INSP. RPT. NO: 84-16 PAGE: ATT1-51 INSPECTOR: OBCOC

	POCURE MENT		- VENDOE	SPECIFICATIONS
· Pro	conement ense only	raccifica.	tions (6+	H) to be mad for will be moutten
				ifiction: TNE X
· Som	a prosine			with OPS DCC
(TU	660)			
		DAGE 4	1_1_= THER	ECTOR: DBEEG

INSPECTION ELEMENT: DESIGN VERIFICATION (AS-BUILT PROGRAM)
I. Change Verification Cheshlist for CMC a and DCAL
Ref: G4H Project quibe - Section 24" Processing
CMC's and DCA's" 2/3/83
· CMC and DCA a dealing with paging changes are as-built norified (ag V-71)
· Design review shall performed on CMC's and DCA
for rafety related system & components.
· Reviewing engineer lettermines necessity for including a CMC a DCA in the appropriate 6+H documents on
CVC, line 6.
I CMC a and DCA a may on may not be included
in the applicable drawings, as identified on computer change log.
INSP. RPT. NO: 50-445/8416 PAGE: ATT1-53 INSPECTOR: OBEEG

FOLLOWING D					
DWO NO.	PELLISION	DATE ISSUED	7	TITLE	
M1-0300	CP-5	84 02 25	F.D.	HVAC	
M1-0301	CPS (CPS	1) 84 05 15	,	.,	SHZ
1 M2 - 0261	CPY (CF	3) 8405-17	11 "	SAFET	Y IJECT.
1m1-0262	CP4(CF	3) 840517	и и	,,	"
M1-0232	CPY	840208	.,	CONT. SA	PRAY
M1-0250	CP4	840315		REACTI	A COOLANT
M1-0251	CPS	840308			
"DCC CUER					OM
· Determined t					e for
Leeping ant					
003)					
13 of 7 dra	wing the	hed were o	nt of	date.	

NSPECTION ELEMENT: AS-BUILT PROSEAM
REVIEW OF: STA-306 (Ren 5, 7/19/83) Drawing
and Specification Control
· Precorder controls for reciept, filing, distribution and maintenance of drowings and specification
· Require distribution of drawings IAW distribute Cord after receipt of aperture cards. (no time specified)
cord after recient of appertune cards. (no time
specified)
INSP. RPT. NO: 50-445/8416 PAGE: ATT1-55 INSPECTOR: OBERG

INSPECTION ELEMENT: _ "AS-BUILT" PROGRAM -
· REVIEWED TUGGO DEC CONTOC OF DEAWINGS
DETERMINED THE FOLLOWING:
-TUGGO DCC uses a monnel cont regotom
for determination of applicable CMCs and
DCAA.
- CONSTRUCTION DCC uses aTNE computerage
method for truling CMC a and DCA.
- DCA Log Cardo (in TUGGO DCC) are med
to trash conco and DCA a to a specific
drawing (although a computer terminal is
in Tugco Dec)
. The two methods do not some when applicable
lists of DCAs and CMC's are compared.
Data for M1-0262 and M1-0301 was examined
and found not to agree.
INSP. RPT. NO: 50445/8416 PAGE: Ant-Scinspector: OBERG
INSP. RPT. NO: SOMYS/87/6 PAGE: MIL SCINSPECTOR. CBERG

GENERAL INSPECTION DATA SHEET

A QA Q	EMENT: 2	(.I. 832 - NRC	3-06	in Repor	DATE:_	6/20/84 .445/8323
ATTRIBUTES:	N.A.					
ACCEPTANCE CR	RITERIA:	N.A.				
RESULTS: D	tes for	that to	andit	ince a	lomes	t, 1983
				in page.		
INSP. RPT. NO	D: <u>50-44</u> 5	/84-16 PA	GE: An1 -:	57 INSPE	CTOR:_e	BERG

NSPECTION	ELEMENT: QA AUDITS
TCP-80	CONSTRUCTION/TURNOVER COMPLETION ACTIVITIES - FUEL
	BUILDING (3 ROOMS) CONDUCTED 8/15-26/83
TCP-88	ENGINEERING CONSTRUCTION QC : TURNOVER COMPLETION ACTIV-
101	ITIES (AUX + SAFEGUARDS BUILDINGS - ELEVATIONS 873
	AND AROUE) CONDUCTED 10/31-11/15/83 (ELECTRICAL
	AND MECHANICAL AREAS)
700-95	TURNOVER COMPLETION NO 1 DIESEL GENERATOR
107-10	BUILDING - CONDUCTED 2/20-24/84 and 2/27-3/2/81
	3 AREA COMPLETION/TURNOVER AUSILIARY BUILDING -
TCP-10	CONQUETED 4/24 - 5/4/84
	5 AREA COMPLETION TURNOVER ACTIVITIES - CON.
TCP - 10	DUCTED 5/29 - 6/8/84 (REPART HASNOT BEEN
	RECIEVED)
THISD DOT	T. NO: 50-445/84-16 PAGE: An1-58 INSPECTOR: 08EEG