PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE--PNO-III-84-88

Date October 22, 1984

This preliminary notification constitutes EARLY notice of events of POSSIBLE safety or public interest significance. The information is as initially received without verification or evaluation, and is basically all that is known by the staff on this date.

Facility:

Commonwealth EdisonCompany Dresden Nuclear Power Station

Unit 3

Morris, IL 60450 Docket No. 50-249 Licensee Emergency Classification:
Notification of an Unusual Event

Alert

Site Area Emergency
General Emergency
XX Not Applicable

Subject:

CONTROL ROD FAILS TO INSERT BECAUSE OF FAULTY VALVE

At 3:26 p.m. (CDT), October 20, 1984, while operating at 94 percent power, the unit scrammed on a low reactor water level signal. The licensee determined that the cause of the scram was a faulty master level controller in the feedwater control system. The controller was subsequently replaced.

During the scram, control rod J-07 failed to insert properly, moving only six inches into the core, from position 48 (full out) to position 46. The rod was inserted manually by an operator. Although the one rod failed to automatically insert, the reactor was still made subcritical because of the insertion of the other 176 control rods.

The licensee investigated the incident and determined that a manual valve downstream of the scram outlet valve had failed with the valve disk disengaging from its stem.

The valve was replaced. The licensee sampled 10 percent of the remaining valves, dismantling them to determine if there were any problems similar to the failed valve. There were none. The valves were reassembled, and the licensee is now conducting control rod surveillance to verify that the control rods were not affected by the valve inspections. The surveillance includes friction testing and rod scram timing. The licensee will also conduct a differential pressure test on the rod that did not originally insert to further verify the operability of that drive.

If no other problems are detected, the licensee will return the unit to power. Region III (Chicago) has been monitoring the licensee's activities and has coordinated the information regarding this event with NRR and IE.

The State of Illinois will be notified.

Region III was first notified of this event at 3:45 p.m. (CDT), October 20, 1984. This information is current as of 11:30 a.m. (CDT), October 22, 1984.

CONTACT:

R. Lansdman FTS 388-6587 Shafer FTS 388-5656

Phillips 3,45

DISTRIBUTION: H. St. 3:09

H. St. 3:09
Chairman Palladino
Comm. Roberts
Comm. Asselstine
Comm. Bernthal

MNBB 3:29
ED0
PA
ED0
PA
ELD

Air Rights 4:06

SP

Applicable Resident Site 4:03

E/W 3:07 Willste 3:30 IE NMSS OIA RES

Licensee (Corporate Office) 4:05

AEOD AEOD

INPO 4:17

MAIL: ADM:DMB DOT: Trans Only

SECY

Comm. Zech

ACRS

PDR

Regions 1423, 114.05, 18415, 8410260044 841022

Rev. 07/06/84 *IF34* 011