Cooper Industries
Cooper-Bessemer Reciprocating Products Division
150 Lincoln Avenue
Grove City, PA 16127-1898
412 458-8000

November 2, 1992

CO P.

Our Ref: QCG-9081

Document Control Desk U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Subject: Fuel Nozzle Tip 10 CFR Part 21 Final Report


Dear Sir:

The following is a report of activities and corrective action associated with the subject 10CFR21 which have taken place since our initial report of April 5, 1991. We believe that these have provided sufficient information to warrant closure of this issue.

On April 6, 1991, the NRC was notified in writing of a failure involving a standby diesel generator at Houston Light and Power Company's South Texas Project Electric Generating Station. Subsequent investigation revealed that a cracked fuel nozzle tip purchased from Bendix, (a supplier of Cooper-Bessemer), Lot 150006, caused the failure. Affected utilities were notified and a parts recall was initiated.

Subsequent interim reports to the NRC dated July 23, 1991, September 20, 1991, and October 31, 1991 detail the distribution of fuel nozzle tips to the affected utilities and actions taken during this time period.

Since then, additional testing of fuel nozzle tips performed by the Materials Technology Division (MTD) of Houston Light and Power in conjunction with Cooper-Bessemer, the Cooper- Bessemer Owners Group and MPR Associates has been completed, reviewed and recommendations to prevent further failures made. Samples of production lots from utility inventories were submitted to MTD for examination which included visual examination, wet fluorescent magnetic examination (WFMT), internal ligament thickness, effective nitrided case depth, visual nitrided case depth, thickness of the Fe,N compound layer, and core hardness. Each spray tip sample was visually examined for clogging. Secondly, the sample was transversely cut immediately below the ligament tip for subsequent sectioning by EDM. EDM conical sectioning through the three passage holes allowed WFMT on the fuel hole surfaces. Additional purposes of the EDM sectioning were to ensure precision measurements of the ligament thicknesses between the fuel passage holes and the center bore to make precise metallographic sections through the ligaments. A metallographic section was produced for each lot examined. This section is a radial axial plane that passes through the thinnest part of the ligament between the fuel passage hole and the center bore. The nitrided case depth was determined for each sample by determining the distance from the surface to a depth at which the Knoop hardness equivalent to Rockwell "C" scale 55 was reached.



Page 2 QCG-9081 November 2, 1992

The effective depth of the case was determined for each metallographic sample at the surface of the fuel passage hole and at the surface of the center bore. In addition to measuring the effective case depth of the nitrided case, the metallographic section was also used to determine the visual case depth, the presence and thickness of the white Fe_xN compound layer, and core hardness.

The results of the metallurgical and dimensional examinations can be found on Table 1 (MTD Report MT-3309 dated July 16, 1991) and Table 1 (MTD Report MT-3822 dated May 4, 1992). A brief summary of the results is as follows:

- 1. The inner ligament thickness measurements ranged from a low value of .039 inch on lot 150004 to a high value of .063 inch on lot LC001090. The spray tip from Lot 150004 which had failed the Haynes Go-NoGo gage test contained the smallest ligament dimension, had a deep nitride case, and contained cracks on the surface of two of the three fuel passage holes at the ligament between the fuel passage hole and the center hole.
- The effective nitride case depth in all spray tips examined was lower than the visual nitride case depth.
- Other than the tip submitted from Lot 150004, none of the remaining lots contained any cracking as determined by visual and WFMT examination.
- All samples were visually examined for the presence of clogging of the spray holes.
 The tips of the samples were clean and free of clogging in the as-received condition.

The root cause of this failure of the fuel nozzle tip has been determined to be insufficient ligament thickness (less than 0.048 inch) along with improper nitriding resulting in a too deep case depth (over 45% ratio of case depth to core size).

Revised technical specifications require an effective case depth of .008-.011" and a ratio of visual case depth to core size of 45% maximum measured 1/32" from the ligament tip. This will be verified by destructive examination at the heat treat vendor and again by the Haynes Corporation. Ligament thickness and location of fuel delivery holes will be verified by use of Haynes gauge #44-703039.

Process controls as outlined in our letter to the NRC (our reference QCG-8434 dated 9/20/91) have been revised and are current practice with above stated specifications. Agreement between Cooper-Bessemer and the Cooper-Bessemer Owners Group at the May 1992 meeting and subsequent discussions have resulted in the classification of all fuel nozzle lots as either acceptable or reject.

Acceptable Lots are those with no known failures or found to meet technical requirements. These lots are identified as the early unnumbered or unrecorded lots (most before 1979), 001110, LC001059, LC001090, LC001091, 207 '40, 150001, 150002, 150003, 150005, 150010, 150013, LCH1, LCH19, and all later LCH series which are now confirmed with Quality Assurance efforts at Haynes Corporation and Cooper-Bessemer.

Page 3 QCG-9081 November 2, 1992

Lot 150003 will have dimensional inspections imposed as fuel nozzle assemblies are reconditioned as one sample did not pass inspection with the new Haynes hole angle gauge, but in the direction of greater ligament thickness.

Reject Lots are those with known failures or failing to meet technical criteria of ligament thickness and nitride case depth as a result of destructive examination at MTD. The previously recalled lots in 1988 and 1991 as a result of 10CFR Part 21 notification to the NRC are 1124 (includes 1135), 150006, and 150008. In addition, Cooper-Bessemer is adding to this recall list lots 150004, 150009, and D870001. These fuel nozzle tips should be replaced at the next scheduled plant refueling outage and tips in warehouse stores should not be installed in a diesel engine.

The attached listing shows the serial numbers, lot numbers, quantity and location of all reject lot fuel nozzle tips.

In conclusion, Cooper-Bessemer, in agreement with the Cooper-Bessemer Owners Group, and MPR Associates believe that the corrective actions taken by Haynes Corporation (current manufacturer of nozzle tips), Cooper-Bessemer and the utilities are sufficient to preclude this failure from recurring and that this incident should be closed. If you have any questions, please contact J. R. Schneider, Quality Assurance Manager, or J. M. Home, Manager of Nuclear Engineering at 412-458-8000.

Sincerely,

H. A. LaBrun

Vice President and General Manager

HAL/kll

CC:

D. T. Blizzard - CES/GC

J. M. Home - CES/GC

J. S. Baron - CES/GC

W. O. Ferguson - CES/MV

A. D. Gillette - CES/GC

B. R. Sedelmyer- CES/GC

CC:

Mr. Walter Haass - NRC One White Flint North Mailstop 9D4 Washington, DC 20555

Mr. Arthur G. Killinger MPR Associates, Inc. 1050 Connecticul Evenue, N.W. Washington, DC 20036 Page 4 QCG-9081 November 2, 1992

CC:

Mr. Ted Fryar Houston Lighting and Power South Texas Project Wadsworth, TX 77483

Mr. Matthew Heidom Pennsylvania Power and Light Two North Ninth Street Allentown, PA 18101

Mr. Elmer Hemandez Commonwealth Edison Co. Byron Nuclear Power Station 445 North German Church Rd. Byron, IL 61010

Mr. Michael Kneble EnTergy Associates Louisiana Power and Light Waterford 3 SES Highway 18 Taff LA 70006

Mr. Dwain Lambert Commonwealth Edison Co. Braidwood Nuclear Power Station Route 1, Box 81 Braceville, IL 60407

Mr. Doug Mullen Nebraska Public Power District Cooper Nuclear Station P. O. Box 98 Brownville, Nebraska 68321

Mr. Terry O'Brien Commonwealth Edison Co. 1400 Opus Place Downers Grove, IL 60515

Mr. Lenny Schiavone - SM-3 Niagara Mohawk Power Corp. 301 Plainfield Road North Syracuse, NY 13212 Page 5 QCG-9081 November 2, 1992

cc: Mr. Neil Thibodaux
Arizona Public Service
Palo Verde Nuclear Generating Station
P. O. Box 52034
Phoeniz, AZ 85072-2034

Mr. Terry Vanderport Commonwealth Edison Zion Generating Station 101 Shiloh Blvd. Zion, IL 60099

TABLE 1. SUBBARY OF BLAP EXAMINATIONS OF DIESEL FLEE INJECTOR SPRAY TIPS

						TALLET	ALCOHOL T. M.L. a. C.	FREE Trees	Action for Good Science	-	A 200 A 200 A	The Control of Control
HT #	LOT #	SERVICE HOURS	HOLE	EDDY CURRENT TESTING	WENT	INNER LIGAMENT THICKNESS (INCHES)	NOMINAL LIGAMENT AREA (SQ. IN.)	CASE DEPTE (INCHES)	CASE D'PIH (INCHES)	VISUAL CASE DEPTH	LAYER DEPTH	CORE
						Administration	Annual Land	ARTHURES	Trucital	A85.14	(INCHES)	(HRC)
3259-1	150010	357	2	MD	ACC	0.048	0.224	0.012	0.016	52	NONE	41
			3		REJ	0.052	0.221					
					REJ	0.049	0.212					
3309-1	150006	382	1	REJ	REJ	0.011	0.157	0.015	0.036	100	0.0007	40.5
			2		REJ	0.013	9.159					
			3		REJ	0.012	0.153					
3309-2	150010	357		ACC	ACC	0.056	0.245	0.010	0.000	- 22		
			2		ACC	0.051	0.243	0.018	0.020	54	0.001	42.5
			3		ACC	0.049	0.243					
						0.047	241					
3309-3	LC1091	217	1	ACC	ACC	0.052	0.233	0.013	0.012	32	NONE	48
			2		ACC	0.045	0.233					
			3		ACC	0.040	0.228					
3309-4	150006	324		REJ	REJ	0.012	0.174	ND	MD	MD	ND	
			2		REJ	0.013	0.175		NO.		No.	
			3		ACC	0.013	0.175					
3309-5	150006	432	1	REJ	ACC	0.012	0.477				- 100-5	
	130000		2	we a	REJ	0.012	0.174	0.011	0.017	100	0.0005	45.5
			3		REJ	0.018	0.173					
3309-6	350010	140										
130A-9	150010	ND		ACC	ACC	0.055	0.261	ND	ND	ND	MD	ND
			2		ACC	0.054	0.252					
					ACC	0.054	0.252					
3309-7	150010	357	1	ACC	ACC	0.055	0.244	0.011	0.016	50	0.0005	42.0
			2		ACC	0.055	0.250					
			3		ACC	0.051	0.246					
309-8	LCH19	NEW	1	ACC	ACC	0.05	0.226	0.008	0.006	30	0.601	41.5
			2		ACC	0.05	9.228		0.000	30	0.001	41.3
			3		ACC	0.053	0.228					
309-9	LCH19	NEW	,	ACC	***	0.053	0.074	Sec. 20				
		ML.W	2	NCC	ACC	0.052	0.231	ND	MO	ND	MD	MO
			3		ACC	0.051	0.236					
3309-10	150009	100		400								
1307-10	130009	100	2	ACC	REJ	0.047	0.215	0.012	0.019	63	0.0005	41.0
			3		REJ	0.047	0.215 0.215					
						0.040	0.213					
309-11	150006	324	1	ACC	REJ	0.019	0.173	0.013	0.018	100	0.0005	42.0
			2		REJ	0.021	0.182					
					NEW .	0.021	0.181					
309-12	LCH1	NEW	1	ACC	ACC	0.056	0.238	0.010	0.016	23	NONE	41.5
			2		ACC ACC	0.056	0.238					

TABLE 1. SUMMARY OF HI&P EXAMINATIONS OF DIESEL SUEL INJECTOR SPRAY TIPS

	Sample Desc	ription				D	imensions & Metal	Burgical Evaluation	en .	
Sample Identification Number	Lot #	Utility	Hole #	WFMT Results	Inner Ligament Thickness (inches)	Effective Case Depth (inches)	Visual Case De ₃ sh (inches)	% Visual Case Depth	Core Hardness (HRC)	White Layer Depth (inches)
3822-1	10001059	PP\$1.	; 2 3	ACC ACC ACC	0 056 0 053 0 048	0.007	0.013	46.4	42.7	None
3822-2	LC001090	APS	1 2 3	ACC ACC ACC	0.042 0.044 0.063	0.008	0.012	47.1	45.2	None
3822-3	001110	PP&1.	1 2 3	ACC ACC ACC	0.041 0.041 0.050	0.007	0.011	50.2	43.3	None
3822-4	150004 (Tag 4E1616)	PP&L	1 2 3	ACC ACC ACC	0.045 0.047 0.051	0.008	0.015	64.6	45.2	0.0002
3822.5	150004 (Tag 4E1607	PP&L	1 2 3	REJ REJ ACC	0.040 0.041 0.039	0.010	0.018	77.6	45.5	0.0002
3822-6	150013	APS	1 2 3	ACC ACC ACC	0.055 0.057 0.059	0.008	0.014	45.5	45.8	0.0006
3822-7	200440	L8cd	1 2 3	ACC ACC	0.042 0.043 0.044	0.007	0.610	38.6	45.7	None
3822-9	087001	APS	1 2 3	ACC ACC ACC	0 043 0 041 0 042	0.012	0.016	72.5	44.2	None

	FUEL IN	Z-50F-203-023 FUEL INJECTOR TIP		
DATE	CES S/N	# LO1 #	QTV	CUSTOMER
* 200,000	Q&2401-16	150009	16	
0,000	O ADADA O A			CECO/BYRON
	POLICE STATE			CECO/BRAIDWOOD
	9A2405-08			CECO/BYRON
	9A2409, 11, 14-16			30*
	9A2412, 13			APO
9/26/79	9K2001-02	001124	2	
	96,2002			Ni-MO
1/10/86	681001-29	D37001	29	
	6R1001 02 05 07 09 15 21, 24, 29			HL&P
	AB1003 06 10-13 17-19 23			APS
	ARTION 14 16 20 22 25-28			CECO/BYRON
10/26/86	61.1701-12	150004	12	
		*******	20	
10/31/86	6L1901-29	150004		08 17
	61,1901-06, 08-13, 15, 29			TLOF
	61 1507, 14, 18, 19, 21, 25, 27, 28			PP&L
	6L1920, 23, 26			APS
	6L1916			HL&P
10/28/88	940401-02	150009	2	
20,00				CECO/BRAIDWOOD

October 30, 1992 Page 1

October 30, 1992 Page 2

HLar

APS

7M1828-47

7M1801-27

	REJECT LOTS 2-50F-003-023 FUEL INJECTOR TIP	CES S/N CUSTOMER	0701-14 150006 14	0701-07, 09-14 HL&P	0708 APS	2901-06 6 HL&P	2301-04 4	2304 HL&P	1701-14 14	1701 CECO/BRAIDWOOD	1706, 09 APS	2601-07 APS	
And the second particular and the second par		CES S/N	7H0701-14	7H0701-07, 09-14	7H0708	7G2901-06	9G2301-04	9G2304	9K1701-14	9K1701	9K1706, 09	9F2601-07	
And the commence of the commen		DATE	7/22/87			7/20/87	6/29/79		9/26/79			4/10/89	

	REJECT LOTS KSV-13-2A#4 FUEL INJECTOR ASSEMBLY	LOTS 2A#4 R ASSEMBLY			
DATE	CES S/N	TC1	1k	QTY	CUSTOMER
3/17/88	8D0201-50	150008 (T)	JS0008 (A)	50	
	8D02C1-06, 08-12, 27-29, 31-38				CECO/BYRON
	8D0207, 13, 14, 18-26, 43, 45, 46-48				CECO/BRAIDWOOD
	8D0203				SCARP #03962 5/90
4/22/87	7E1101-64	150004 (T)	JS0005 (A)	4	HL&P
a lot on the re	The second second	100			
1/30/07	101001-03	130004 (1)	JSGOOD (A)	70	
	781801, 03: 04, 06				HL&P
	781832, 05, 09				CECO/BRAIDWOOD
	7B1807, 08				CECO/BYRON
7/31/87	7H0501-36	150006 (T)	JS0006 (A)	36	
	7H0501,02,07,09,10,12,13,14,16,17,18,20,24,28,29				APS
	7H0503, 08, 11, 30, 31-36				HL&P
	7H0504-06				HL&P
	7H0515, 21, 23, 26				CECO/BRAIDWOOD
and a supplement of the second	7H0519, 22, 25, 27				HL&P
7/3/87	7H1801-02	150006 (T)	JS0006 (A)	2	CECO/BRAIDWOOD
d.					
12/15/86	7B0901-30	150004 (T) OR JS0004 (A) OR	R 150005 (T) R JS0005 (A)	30	
	780901				CECO/BRAIDWOOD
	780902-06, 08, 10, 12-15, 26-28, 30, 21				CECO/RYBON

YTD # TO.
150009 (T) JS0009 (A) 40
150009 (T) JS0009 (A) 10
150003 (T) OR 15 15 150004 (T) JS0003 (A)
150004 (T) JS0003 (A) 5
150004 (T) JS0004 (7)(A) 10 150003 (T) JS0003 (3) (A)
150003 (T) JS0004 (A) 5

	REJECT LOTS KSV-13-2A#4 FUEL INJECT OR ASSEMBLY	OTS A#4 ASSEMBLY		
DATE	CES S/N	* 101	∆TTO	CUSTOMER
3/5/86	6C1201-10	D87001 (T) JS0001 (1)(A) JS0002 (9)(A)	(A) 10	
	6C1201-07			LP&L
11/11/85	5L2101-60	D87001 (T) JS0001 (A)	(A) 60	
	5L2123, 42, 48, 50, 58			CECO/BYRON
	5L2145, 46, 47, 49, 57			CECO/BRAIDWOOD
	512724, 43, 44, 56			APS
	512125, 27, 28, 36, 37, 41,			NEBRASKA
	5L2126, 31			LP&L.
	5L2129, 30, 32-35, 38, 39, 52, u.t., 55, 59			CECO/BYRON
	5L2140, 51, 53, 60			NEMO
	5L2101-22			CECO/BYRON
11/11/85	5L2501-56	D87001 (T) JS0001 (A)	(A) 56	
	5L2501-19, 21, 72, 24, 25, 28-36, 38-47, 49, 51, 53-56			PP&L
	512520, 23, 26, 27, 37, 48, 50, 52			CECO/BYRON
11/25/85	5M1101-03	(A) 150001 (T) 150001 (A)	(A) 3	LP&L
11/25/85	51.2601-10	D87001 (T) JS0001 (A)	(A) 10	
	51.2602			CECO/ZION
	5L2101, 03-10			LP&L
12/1/86	6M1101-07	150004 (T) JS0003 (A)	(A) 7	Ni-Mo

	REJECT LOTS KSY-13-2A#4 FUEL INJECTOR ASSEMBLY	TS #4 SSEMBLY		
DATE	CES S/N	LOT#	YTD	CUSTOMER
12/11/86	6M1718-20	150004 (T) JS0004 (A)	8	NI-M0
12/11/86	6M1701-17	150004 (T) JS 0005 (A)	17	
	6M1701-05, 11-14, 16			CECO/BY9ON
	6M1706, 08			APS
	6M1707			LP&L
3/1/88 DHC 967	7H0167, 7J1501-03, 7D2003, 7D2006, 2C3286, 1D1416, 8K0902	150008 (T) JS0008 (A)	0	CECO/ZION
6/3/92 DRO 704	512604, 512608, 6C1201, 6M1707	150004 (1) D87001 (3)	26	LPAL
4/1/92 DRO 717	6M1103, 6M1104, 6M1720	150004 (3)	11	NI-MO
6/13/92 RCM 1492		150009	9	CECO/BRAIDWOC)
6/23/91 RCM 1493		150008		CECO/BRAIDWOOD

107

	REJECT LOTS KSV-13-5A#1 FUEL INJECTION TIP	S 1 N TIP		
DATE	CES S/N	#TCT	YTO	CUSTOMER
8/21/92 DRO 780	9206046	D87001 (1)	40	HLRP
9/15/92 DRO 813	9208020, 21, 26, 27, 30, 42, 43	150004 (7)	50	CECO/BYRON
	9208025, 28	D87001 (2)		
	9208037, 38	150009 (2)		
	9208024, 29, 35, 39, 40	001124 (5)		