| NRC Form 366<br>(9-83)   |  |   | LIC   | ENSEE   | EVENT  | RE  | PORT   | (LER)   |   | UCLEAR REGULAT  | ORY COMMISSION<br>0. 3150-0104        |  |
|--|--|---|---|---|--|---|--|---|---|---|---------------------------------------|--|
| FACILITY NAME  | 1)   |   |   |   |  |   |  | In  |   | (2)   | PAGE (3)                              |  |
| Presses Press Hadt 2   |  |   |   |   |  |   |  | 15   0   0   0   2   9   6   0 F 0  2   |   |   |                                       |  |
| TITLE (4)  |  |   |   |   |  |   |  |   |   |   |                                       |  |
| Inadv  | ertent I   | nitiati   | on of a   | Safet   | y Sys  | tem                                       | s Du   | ring Su   | rveilla   | nce Tes   | ting                                  |  |
| EVENT DAT  | 8 (5)  | LER NUMBER  | the second se | REPO  | RT DATE (7)  | T   |  | OTHER   | ACILITIES INVO  | LVED (8)  |                                       |  |
| MONTH DAY YEAR YEAR BEQUENTIAL REVEION NUMBER NUMBER                                       |  |   |   | MONTH DAY YEAR FACILITY NA                                    |  |   |  | FACILITY NAN  | 183   | DOCKET NUMBE  | CKET NUMBER(S)                        |  |
|  |  |   |   |   |  |   |  |   |   | 0 15 10 10  | 10111                                 |  |
| 010110   |  |   | -   | 110   | 1 0 01   |   |  |   |   |   |                                       |  |
| 0 9 1 3  | 8 4 8 4  | 0 0 9   | 00  | 10  | 1 2 8  | 4   |  |   |   | 0 151010  | 10111                                 |  |
| OPERATING<br>MODE (9)  | NY T   | and the second se | D PURSUANT  | 1   | UIREMENTS  | OF 10                                     | CFR §: /0  | Check one or more o   | f the following) (1   | T   |                                       |  |
| 20.402(0)  |  |   |   |   |  |   | 50.73(e)(2)(iv)                                  |   | 73.71(b)  |   |                                       |  |
|  |  |   |   | 60.36(e)(1)   |  |   |  | 50.73(a)(2)(v)  |   | 73.71(c)<br>OTHER (Specify in Abstract  |                                       |  |
|  |  | 405(a)(1)(iii)  | -   | 50.38(c)(2)<br>50.73(a)(2)(i)                                 |  |   |  | 50.73(a)(2)(vii)<br>50.73(a)(2)(viii)(A)  |   | below and in Text, NRC Form<br>366A)  |                                       |  |
| 20.406(a)(1)(iv)   |  |   | 50.73(a)(2)(ii)   |   |  |   | 50.73(a)(2)(viii)(8)                             |   |   |   |                                       |  |
|  | 20   | 406(a)(1)(v)  |   | 80.73(a)(2  | (141)  |   |  | 60.73(a)(2)(x)  |   | A CALL STREET STREET  |                                       |  |
|  |  |   |   | ICENSEE CO  | NTACT FOR  | THIS                                      | LER (12)   |   |   |   |                                       |  |
| NAME   |  |   |   |   |  |   |  |   |   | TELEPHONE NUP   | HBER                                  |  |
| Dot Fhe  | raala  |   |   |   |  |   |  |   | AREA CODE   |   |                                       |  |
| Pat Ebe  | rsole  |   | ت والمراجعة   | -   |  | _   |  |   | 2 0 5   | 7 2 9 -   | 1317 8 8                              |  |
|  |  | COMPLETE  | ONE LINE FOR  | EACH COM  | PONENT FAI   | LURE                                      | DESCRIBE   | D IN THIS REPOR   | T (13)  |   |                                       |  |
| CAUSE SYSTEM   | COMPONENT  | MANUFAC-<br>TURER   | REPORTABLE<br>TO NPRDS  |   | c  | AUSE                                      | SYSTEM   | COMPONENT   | MANUFAC<br>TURER  | REPORTABLE<br>TO NPADS  |                                       |  |
|  | 111  | 1 1 1   |   |   |  |   |  |   |   |   |                                       |  |
|  | E E I  |   |   |   |  |   |  |   |   |   |                                       |  |
|  |  | SUPPLEM   | INTAL REPORT  | EXPECTED  | (14)   |   |  |   |   | MONT  | H DAY YEAR                            |  |
| YES // VAL   | comple & EXPECTED  |   |   | -   | NO   |   |  |   | EXPECTED<br>SUBMISSION<br>DATE (16)   |   |                                       |  |
| the inst<br>4.7.D.1<br>which re<br>spray pr<br>event re<br>first er<br>affected<br>when an | the unit is<br>trument li<br>.d). Duri<br>esulted in<br>umps, and<br>esulted in<br>vent occur<br>d by the e<br>excess fl<br>ected inst | ine high f<br>ing this t<br>the inac<br>emergency<br>an injec-<br>red when<br>excess flo<br>low check   | low che<br>cest, va<br>lvertent<br>diesel<br>ction to<br>test pe<br>ow check                                    | ck val<br>lving<br>start<br>gener<br>the v<br>rsonne<br>valve | ves wa<br>errors<br>ing of<br>ators<br>vessel<br>el did<br>e being | s p<br>ca<br>th<br>on<br>fro<br>not<br>te | erfor<br>used<br>two s<br>m RHR<br>prop<br>sted. | med (surv<br>an errone<br>idual hea<br>eparate of<br>or core<br>perly isol<br>The sec | veillance<br>eous low<br>at remova<br>occasions<br>spray pu<br>ate all<br>cond even | e instruct<br>vessel si<br>al pumps,<br>s. Neithe<br>imps. The<br>instrument<br>occurre | ignal<br>core<br>er<br>e<br>nts<br>ed |  |
| 841<br>PDF<br>S  | 0300102<br>ADOCK   | 841012<br>05000296<br>PDR   |   |   |  |   |  |   |   | JE22<br>Vi  | 2                                     |  |

| LICENSEE | EVENT | REPORT | (LER) | TEXT | CONTINUATION |
|----------|-------|--------|-------|------|--------------|
|          |       |        |       |      |              |

U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104

EXPIPIES: 8/31/85

| FACILITY NAME (1)     | DOCKET NUMBER (2)     | LE   | IMBER (6)        | PAGE (3)  |  |
|-----------------------|-----------------------|------|------------------|-----------|--|
|                       |                       | YEAR | UENTIAL REVISION |           |  |
| Browns Ferry - Unit 3 | 0  5  0  0  0   2 9 6 | 8 4  | 0 9 9 - 9 d      | 9 20F 0 2 |  |

Unit 1 was operating at 100 percent power, and units 2 and 3 were in scheduled refueling outages. With unit 3 shutdown, during the hydrostatic test of the reactor pressure vessel, a test of the instrument line excess flow check valves was being performed in accordance with technical specification 4.7.D.1.d.

During the performance of this test and subsequently during maintenance on these excess flow check valves, failure to properly isolate affected instrumentation resulted in false low reactor level indication and subsequent initiation of residual heat removal pumps, core spray pumps, and the emergency diesel generators. Inadvertent operation of these devices is not a safety problem since their availability is not affected. There are operational concerns related to maintaining vessel water cleanliness. In these instances, however, the reactor pressure was greater than 500 psig which prevented injection to the vessel from the residual heat removal or the core spray systems.

On 9/13/84 an erroneous low reactor level signal caused an initiation of these engineered safety systems. This initiation occurred as a result of maintenance personnel not isolating all of the instruments that were affected by the valve that was being tested. Involved personnel were counseled as to the importance of strict compliance with written procedures.

On 9/15/84 an excess flow check valve was isolated to inspect and clean its internals. Failure to isolate the level instrumentation associated with this flow check valve again caused an erroneous vessel level to be received and resulted in the auto initiation of these engineered safety systems. The maintenance instruction that was in effect at the time that this repair was being made had no reference as to the importance of isolating the affected instruments while a repair or inspection was being performed on one of these excess flow check valves. This instruction, MMI 123, is been revised to assure that instruments associated with these flow check valves have been isolated when any maintenance is to be performed on these valves.

During this test, eight of the instrument line excess flow check valves exhibited leakage which required maintenance consisting of disassembly and cleaning. These valves are manufactured by the Marotta Valve Corporation and are designed to go closed at a flow in the instrument line of approximately 2 gpm. These valves were then reassembled and successfully passed a leakage test. Unit 3 has been in a refueling outage for over a year which may have contributed to the additional maintenance requirements.

Responsible Plant Section - IM, MM

PNE:BDL October 12, 1984

NRC Form 366A

## R42 841012 886

TENNESSEE VALLEY AUTHORITY Browns Ferry Nuclear Plant P. O. Box 2000 Decatur, Alabama 35602

October 12, 1984

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D. C. 20555

Dear Sir:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT (BFN) UNIT 3 -DOCKET NO. 50-296 - FACILITY OPERATING LICENSE DPR-09 - REPORTABLE OCCURRENCE REPORT BFR0-50-296/84009

The enclosed report provides details that concern the inadvertent initiation of safety systems during surveillance testing. This report is submitted in accordance with 10 CFR 50.73 (a)(2)(iv).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

Jundill

G. T. Jones Plant Manager Browns Ferry Nuclear Plant

Enclosure cc (Enclosure): Regional Administrator U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 2900 Atlanta, Georgia 30303

INPO Records Center Suite 1500 1100 Circle 75 Parkway Atlanta, Georgia 30339

NRC Resident Inspector, BFN

IE22 1/1