

October 15, 1984
(NMP2L 0201)


Mr. R. W. Starostecki, Director
U. S. Nuclear Regulatory Commission
Region I
Division of Project and Resident Programs
631 Park Avenue
King of Prussia, PA 19406

Re: Nine Mile Point - Unit 2
Docket No. 50-410

Dear Mr. Starostecki:

Enclosed is an interim report, in accordance with 10CFR50.55(e), for the problem concerning an ITT Grinnell weld that was accepted on the basis of an incorrect radiograph. This problem was reported via tel-con to P. Russ of your staff on September 13, 1984.

Very truly yours,



C. V. Mangan
Vice President
Nuclear Engineering and Licensing

CVM/GG/pbd

xc: Director of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

R. A. Gramm, NRC Resident Inspector

Project File (2)

8410300176 841015
PDR ADOCK 05000410
S PDR

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
DOCKET NO. 50-410

Interim Report for a Problem
Concerning Incorrect Radiograph
(55(e)-84-39)

Description of the Problem

During a review of ITT Grinnell weld radiographs, it was observed that radiographs for welds CSH 25-7 FW015 and CSH 25-7 FW017 are identical. Radiographic interpretation reports for both welds had been signed off as approved. Apparently, one of the welds had not been radiographed. This weld joint has since been radiographed and found acceptable. The subject weld is located in the high pressure core spray system.

Further investigation and review of additional weld joints will be conducted to determine the extent of this condition.

A final report will be submitted by February 11, 1985.