NRC Form (9-83)	* 366										LIC	EN	SE	E	EVE	IN	r RE	PORT	r (LEF	3)				U.			OVE	0 0	-		COM	4155101 04	
FACILITY	-	13																	-			-	Tpo	CKET	NUR	ABEI	1 (2)				-	PAC	E (3)	-
	JAME		A. 1	FIT	ZPAT	RI	CK	NU	CL	EAI	R PC	WE	R	PL	ANT								1					13	13	13	1	OF	1	2
TITLE (4)		-												-		-			-				1	1	-	1	1	1.	1.	1.	-	1-	101	-
	REAC	TO	R	SCI	RAM	WH	ILI	S	HU	TDO	OWN																							
EVE	INT DATE	(5)		Γ		LE	RNU	MBER	(6)			T	RE	POP	TDA	TE ()	n				(THE	RFA	CILIT	TIES	INVO	LVE	D (8)						-
MONTH	DAY	YE	AR	YE	AR	R SEQUENTIA			AL REV			MON	AONTH		DAY		EAR	FACILITY NAMES				-	DOCKET NUMBER(S)							-				
				1		1			1	-		1		T		1	_										0	15	10	10	10	1	1.1	
		Ľ.,									1			L			. 1										1	-	-	-	-	-		1
0 9	1 8	8	4	8	4		0 1	1 8	3	- (0 0	1	0	1	6	8	4	1.11									0	15	10	10	10	1	1.1	
	RATING		N	THE	S REPO	RT	IS SU	BMITT	TED	PUR	UANT	TO TH	EA	EQU	JIREM	ENT	8 OF 1	O CFR §:	10	heck o		r moi	e of	the fo	linwi	ng) (11)	-				-		
MC	DE (9)				20.40	2(6)						20.	406	(e)				2	K	50.7	3(#)(2)(iv)						7	3.71((b)				
POWER		-	20.40	0.406(s)(1)(i)					50.36(c)(1) 50.73					3(a)(2)(+)	()(v)				1	73.71(e)													
(10)	0	0	10	-	20.40	5(#)((1)(0)					50.	36(c	:)(2)						60.7	3(*){	2)(vii)				L] 0	THE	R (Sp	ecity	in Ab	C Form	
					20.40							50.	73(*)(2)	(i)					60.7	3(#)(2)(vii	(A)(i)					3	66A)				e r grins	
				L	20.40							50.	73(*	(2)	(6)				1	80.7	3(a)(2) (vii	(8)											
				1	20,400	5(.)((1)(v)					50.	73(#)(2)	(111)				1	50.7	3(a)(2)(x)		1		_								
NAME												LICEN	SEE	cor	NTACI	TFO	R THIS	LER (12)	1			_		-		_	_	_				_		
NAME																								-	EAC	0.0.5	TEL	EPHO	ONE	NUM	BER			_
	Will	ia	m	Fer	man	de	2.	Op	or	at	ions	Su	ne	r	int	en	dent							1		220								
						ae			_	_			_	_		_			_		-		_	3	11	15	3	14	12	1-	13	18	41)
						_	COM	PLET	EON	VE LI	NE FOR	REAC	H CO	OMP	ONEN	TFA	ULURE	DESCRIE	BEC	DINT	HIS	REP	DAT	(13)			-							_
CAUSE SYSTEM CON		OMP	ONEN	et	T MANUFAC			REPORTA TO NPRI			E					CAUSE	SYSTEM		COMPONENT			MANUFAC TURER			-		PORTABLE							
	1			1		1	ų,	T														1												
				-				-	+			1				+		+	+	-	-	-	+	-	-	-	+			+			i	
	1		1	1		1	. 1	1										1 m		1	1	1		1		. 1								
			-				SUP	PELEN	AENT	AL	REPORT	TEXP	CT	ED	14)	k			-		-	-	+	-+-	-	-	-	-	TM	ONTH	T	AY	YEAR	-
													Γ						-				-		SUB		ION		-		+			-
YES	\$ 119 yes, c	ompie	ete E	XPEC	TED SU	BM	155101	V DA	TE)				X	5	NO										DA	TEI	15)		1	i í			1	
ABSTRAC	T ILimit	140	90 se	acas.	i.a., appi	0.8.1	mately	tifter	ter girt	19:0-11	Dece typ	ewritte	n lin	141)	(16)	1							-			-				-		-		-

While shutdown for a scheduled maintenance outage, two inadvertent reactor scrams occurred within a period of approximately one hour. At the time of events, one scram channel was in the tripped condition due to maintenance. During this time interval it is believed that craft personnel, accidentally bumped a scram discharge instrument volume level switch while performing modification work in the general area. This provided momentary high level scram signal inputs and caused the scrams.

Initial actions were to reset the scrams and determine the cause of the scrams.

JEZZ

8410310052 841016 PDR ADUCK 05000333

19-831 LICENSEE	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION							
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NU	EXPIRES 8/31/8	PAGE (3)				
JAMES A. FITZPATRICK NUCLEAR POWER PLANT			ENTIAL REVISION MBER NUMBER					

0 5 0 0 0 3 3 3 8 4 - 0 1 8 - 0 0 0 2 OF 0 2

TEXT (If more space is required, use additional NRC Form 366A's) (17)

During a scheduled outage for maintenance, two reactor scrams occurred within an approximate one hour time frame. At the time of events, one scram channel was in a tripped condition due to maintenance being performed on reactor protection system relays. The other scram channel received two short duration trip signals which initiated the scrams. The signals were not of long enough duration to "lock-in" therefore positive identification of the cause is not possible. Due to the shutdown, the sequence-of-events recorder, which would normally record the scram signals, was not in service.

An investigation was held to determine the cause of the scrams. As a result of some spurious alarms and determination of where work was in progress, the results of the investigation revealed that the most probable cause was the accidental bumping of a scram discharge instrument volume level switch by craft personnel performing modification work in the area of the scram discharge instrument volume.

The scrams were reset and at outage meetings supervisors were requested to caution craftsmen concerning work around instrumentation.

James A. FitzPatrick Nuclear Power Plant P.O. Box 41 Lycoming, New York 13093 315 342 3840



Corbin A. McNeill, Jr. Resident Manager

October 16, 1984 JAFP-84-0963

United States Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

REFERENCE: DOCKET NO. 50-333 Licensee Event Report: 84-018-00

Dear Sir:

We have enclosed the referenced Licensee Event Report in accordance with 10CFR50.73

If there are any questions concerning this report, please contact Mr. William Fernandez at (315) 342-3840, Extension 300.

Very truly yours,

by dir. 8 Canen

CORBIN A. McNEILL, JR. RESIDENT MANAGER

CAM:WF:dmh Enclosure

CC: USNRC, Region I (1) INPO Records Center, Atlanta, Georgia (1) Internal Power Authority Distribution American Nuclear Insurers (1) NRC Resident Inspector Document Control Center LER/OR File