NRC For (9-83)	m 366							LIC	ENSE	E EVE	NT RE	PORT	(LER)			U.S.	APF	RO		MB NO	ORY CON	MISSION 104
FACILIT	Y NAME (	1)		-	-		-							DOC	KET	NUMB	ER (2	1)		-	PA	GE (3)
Se	quoya	h . 1	In	-	1									0	15	101	0 1	0 1	312	1.7	10	F 012
TITLE (	1)	113	2112	-	-									1-	1-	1-1	-	-1	-1-		1 1-	1 -1-
Au	xilia	rv	But	1 d	ing	Isolat	ion	1														
_	ENT DATE	man di mananan	T		-	ER NUMBER	-		REI	PORT DAT	TE (7)		ОТН	ER FAC	CILIT	TIES IN	VOLV	/ED	(8)	-		
MONTH	DAY	YEA	RY	EAF	SEQUENTIAL REVISION			MONTH DAY YEAR			FACILITY NAMES				DOCKET			KET N	ET NUMBER(S)			
			+			NUMBER		NUMBER	- Control								-	) 1	510	10	101	1 1
															_	_	+	-	-		1	
0 19	2 1	8	4	8 4	4 -	0 6 0	-	00	1 0	1   8	8 4						1	) 1	510	10	101	1 1
	ERATING	-	-	-	REPORT		1	URSUANT	O THE R	EQUIREM	ENTS OF 10	CFR 8: /6	heck one or mo	ore of th	he fo	llowing		_		1	1-1	
M	- 1	1	-					20.406(				CFR §: (Check one or more of the following) (  XA 50.73(a)(2)(iv)				T	73,71(b)					
POWI	R		+	7	20.4061	0(1)(0			50.38(c)				50.73(a)(2)(v)				1	٦	73.71	(c)		
(10) 11010			0	7	20,405(a)(1)(ii)									50.73(a)(2)(vii)				OTHER (Specify in Abstract				
20.406(a)(1)(iii)						50.73(a)(2)(i)				50,73(a)(2)(viii)(A)				1	below and in Text, NRC Form 366A)							
														0.73(a)(2)(viii)(B)								
				-	20,406(4				50.73(a)				50.73(a)(2)(x				- 1					
-				-			-	-	ICENSEE	CONTACT	FOR THIS	LER (12)					_		-	-		
NAME							-										T	ELE	PHONE	NUM	BER	
															AR	EA CO	E					-
He	yward	R.	Ro	ge	rs,	Compli	and	ce Sec	tion	Engi	neer				6	111	5	81	710	1 -	1611	14 1 6
						COMPLET	E ONE	LINE FOR	EACH CO	MPONEN	T FAILURE	DESCRIBE	D IN THIS REP	PORT	_	-		-			-	-
CAUSE	USE TEM		MPONE	ENT	T MANUFAC		REPORTABLE TO NPROS				CAUSE	SYSTEM	COMPONEN	T	MANUFAC- TURER				PORTA O NPR			
	1		1	1		111	T						1 1	T	-	1	1					
			-				1								-		_					
	1	- 1	1	1		1-1-1	1					1	1.1.1		1	1	1					
	-	_	_	_	_	SUPPLEN	ENTA	AL REPORT	EXPECTE	D (14)					_	-		-	N	ONTH	DAY	YEAR
YES (If yes, complete EXPECTED SUBMISSION DATE)  XX NO										EXPECTED SUBMISSION DATE (15)			4			1	1.					
Se 09	ven a	uxi 4.	lia Th	ry e	bui	ilding	isc	olatio	ons of	ccurr were	caus	ed by	the dat	on	th	e s	per	ıt	fue	1	l l	

found and all systems returned to normal. There was no effect on public health or safety.

8410310090 841018 PDR ADUCK 05000327 S PDR

NRC Form 366A

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION
APPROVED OMB NO. 3150-0104

EXPIRES 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)		L	ER NUMBER (6)	PAGE (3)		
		YEAR		SEQUENTIAL NUMBER	REVISION		T
Sequoyah, Unit 1	0  5  0  0  0   3   2	7 8 14	-	0 6 1 0	_0 10	0 12 0	F 0 12

TEXT (If more space is required, use additional NRC Form 366A's) (17)

This report describes seven inadvertent auxiliary building isolations caused by spikes on the spent fuel pool radiation monitors. For all incidents, the spent fuel pool area was surveyed by Health Physics and no indication of abnormal radiation levels were found. Operations personnel reset the signal, realigned all affected dampers to their normal position, and returned the ventilation systems to normal operation. The event dates included in this report are (1) 1906 CST on 09/21/84 from RM-90-102, (2) 1115 CST on 09/23/84 from RM-90-102, (3) 1730 CST on 09/24/84 from RM-90-102, (4) 0039 CST on 09/28/84 from RM-90-102, (5) 0228 CST on 09/28/84 from RM-90-102, (6) 2205 CST on 09/29/84 from RM-90-103, and (7) 0114 CST on 09/30/84 from RM-90-103.

The two spent fuel pool radiation monitors are Geiger-Mueller tubes manufactured by General Atomic (Models RD-1 and RP-1) mounted above the fuel pool and are designed to monitor the air spaces above the pool area. A high radiation signal initiates auxiliary building isolation and is designed to limit releases to the environment in the event of a fuel handling accident. For all events described, the auxiliary building isolations were caused from noise and/or background spikes reaching the monitor setpoint resulting in the automatic isolation. The range of these monitors is from  $10^{-1}$  to  $10^{4}$ 4 mr/hr and the technical specification allowable setpoint is 15 mr/hr. The spikes causing the isolations peaked at approximately the setpoint value for the events described. The noise was from normal EMF on the monitor signal cable and the background radiation was from contaminated waste material passing near the monitors or fuel pool water radiation levels.

The following corrective actions have been taken to reduce the number of inadvertent auxiliary building isolations:

- A one-second time delay was added to the high radiation isolation circuit to help descriminate between an inadvertent spike and an actual high radiation condition.
- 2) The spent fuel pool water was cleaned through its own filtering system to reduce the background levels to the monitors.
- 3) Contaminated waste material near the spent fuel pool monitors has been moved to reduce background levels and efforts are being made to maintain this area clear of contaminated waste.
- 4) A technical specification change is being pursued to increase the allowable isolation actuation setpoint from the present 15 mr/hr to a higher value.

It is expected that corrective actions one through three will limit the number of ABIs; however, until the technical specification setpoint change is obtained, inadvertent isolations from these monitors are expected to continue. For the events in this report, there was no effect upon public health and safety.

## TENNESSEE VALLEY AUTHORITY

Sequoyah Nuclear Plant Post Office Box 2000 Soddy Daisy, Tennessee 37379

October 18, 1984

U.S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

Gentlemen:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE REPORT SQR0-50-327/84C60

The enclosed licensee event report provides details concerning seven incidents of inadvertent auxiliary building isolation from spent fuel pool radiation monitors. This event is reported in accordance with 10 CFR 50.73, paragraph a.2.iv.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

P. R. Wallace Plant Manager

Enclosure cc (Enclosure):

James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Suite 2900 101 Marietta Street, NW Atlanta, Georgia 30323

Records Center Institute of Nuclear Power Operations Suite 1500 1100 Circle 75 Parkway Atlanta, Georgia 30339

NRC Inspector, NUC PR, Sequoyah

IE27