NRC Form (9-83)	366	4						L	CENS	SEE EV	ENT RE	PORT	(LER)			0 0000 140	0RY COM	
FACILITY	NAME	11												DOCKET NUMBER	(2)		FA	SE (3)
			Nu	cle	ar P	lant	- 1	Unit 2						0 15 10 10	103	9 17	1 OF	0 12
TITLE 14		011				Tune		01110 -						L	1_6	P dia	*****	1
Auto	Sta	rt	of	th	e Co	ntro	I R	oom Em	eraen	cv Fi	Itrati	on Svs	stem on H	ligh Chlor	ine			
the second se	INT DAT	And the second second				ER NUM		And in the local division of the local divis	the second s	REPORT DA		011 011		A FACILITIES INVO				
MONTH	DAY	-	AR	VEA		SEQUE	TIAL	REVISI		TH DAY	YEAR		PACILITY N	AMES	DOCKE	NUMBER	R(S)	
					-+-	NUM		NUMB							0 15	1010	101	11
019	310	8	4	8		1 10	12	-01	011	0 18	8 4				0.5	10 10		
015	210	10	-					1			-		Cherk one or mon	af the following: (1	Anna Anna	1-1-	1-1-	
OPERATING 1			HIS			MITTE	TURBUAN			ALATS OF T	I V	80.73(a)(2)(iv)			3.71(b)			
				20.408(a)(1)(i) 20.408(a)(1)(i) 20.408(a)(1)(ii)				50.3 50.3	20.405(c) X 50.36(c)(1) 50.36(c)(2)			50.73(a)(2)(v) 50.73(a)(2)(vii)			73,71(e) X OTHER (Specify in Abstract below and in Test, NRC Form 3664)			
						a)(7)(v) a)(7)(v)		F	80.7	3(a)(2)(i) 3(a)(2)(ii) 3(a)(2)(iii)		F	50.73(a)(2)(viii 50.73(a)(2)(viii 50.73(a)(2)(u)				)(2)(1	ii)
									LICENS	EE CONTAC	T FOR THIS	LER (12)						
R. L	<u>. Ko</u>	eni	qs	, C	ompl			nginee		COMPONEN	NT FAILURE	DESCRIBE	D IN THIS REPO	and the second	<b>—</b>	And the second second	1 21 5	10.1.1
CAUSE	SYSTEM	0	OMP	DNENT		TURER		REPORTAB TO NPRO			CAUSE	SYSTEM	COMPONENT	MANUFAC		PADS		
D	K] N	D	E	T I	M	10 2	IB	N				1	111	1.1.1	-			
	1		1			1.1	1			1.1			LLL	111				
						\$1.199	LEME	NTAL REPO	AT EXPE	CTED (14)				EXPECT		MONTH	DAY	YEAR
- 65	111 yan c	mpil	era E	XPECT	-	WISSION	JATE	,		X NO				SUBMISSI DAYE II	ON	1	1	1
ABSTRAC	T . c . mit		00 10	eces .		×/~ #78.5	-	ungia space	y permitten	Lings: (16)		and the address from		-		da	de service de se ser	

I&C Technicians found during the calibration of one of the control room chlorine detectors that the electronics module required replacement. After installing a new card the technicians completed the calibration of WOA-SR-15. The electronics module had not come up to operating temperature when the calibration was performed. As the card warmed the settings began to drift and unit alarmed on Hi Chlorine causing WMA-FN-54A, a control room emergency filtration fan to auto start.

IEDD

8410310250 841018 PDR ADOCK 05000397 S PDR

# LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

Mere's			-		 -	-
-			-	6		
EXP	1963	: 873	11/660			

ACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (8)	PAGE (3)	
		YEAR SEQUENTIAL REVISION NUMBER NUMBER		
Washington Nuclear Plant - Unit 2	0 15 0 0 0 3 9 7	8 4 - 1 0  2 - 00	012000	

Plant Conditions

a) Power Level - 70%

b) Plant Mode - Run

### Event

C Form 3864

On 9/29/84, the daily check of WOA-SR-15 indicated that the flow was out of adjustment. After a correction was made, I&C personnel began a recalibration of the chlorine detector. They were unable to zero the unit due to a problem with the electronics module. A spare card was located and installed in WOA-SR-15. The calibration was then completed and the unit was returned to service. These electronics cards are temperature sensitive and as the new card came up to operating temperature the settings began to drift. Approximately 8 hours after the calibration was complete, the settings had drifted enough that the unit alarmed on Hi Chlorine and started the Control Room Emergency Filteration Fan WMA-FN-54B.

## Immediate Corrective Action

The Hi Chlorine alarm was reset and the control room H&V returned to its normal configuration. An I&C technician was sent to investigate the unit and found the alarm setpoint to be much lower than what the calibration procedure requires. The alarm setpoint was readjusted per the calibration procedure and the unit returned to service.

#### Future Corrective Action

A sign will be placed on each division's chlorine detection sample racks to alert maintenance personnel of this characteristic.

#### Safety Significance

This event carries no safety significance as no "Hi Chlorine" concentration existed and all equipment operated as designed.

# Washington Public Power Supply System

P.O. Box 968 3000 George Washington Way Richland, Washington 99352 (509) 372-5000

Docket No. 50-397

October 18, 1984

Document Control Desk U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Subject: NUCLEAR PLANT NO. 2 LICENSEE EVENT REPORT NO. 84-102

Dear Sir:

Transmitted herewith is Licensee Event Report No. 84-102 for WNP-2 Plant. This report is submitted in response to the report requirements of 10CFR50.73 and discusses the item of reportability, corrective action taken, and action taken to preclude recurrence.

This is the follow-up report to the verbal notification given at 0655 hours on September 30, 1984.

Very truly yours,

CM Powers for

J. D. Martin (M/D 927M) WNP-2 Plant Manager

JDM:RK:mm

Enclosure: Licensee Event Report No. 84-102

cc: Mr. John B. Martin, NRC - Region V Mr. A. D. Toth, NRC - Site (901A) Ms. Dottie Sherman, ANI INPO Records Center - Atlanta, GA