



February 29, 1996 3F0296-27

U. S. Nuclear Regulatory Commission Attention: Document Control Desk Washington, D. C. 20555

Subject: Licensee Event Report (LER) 96-006-00

Dear Sir:

Please find the enclosed Licensee Event Report (LER) 96-006-00. This report is submitted by Florida Power Corporation in accordance with 10 CFR 50.73.

Sincerely,

Rim Davis FOR BJ Hicar

B. J. Hickle, Director Nuclear Plant Operations

TWC:ff

Attachment

xc: Regional Administrator, Region II Project Manager, NRR Senior Resident Inspector

9603150215 960229 PDR ADOCK 05000302 5 PDR

150034

TE22

11,

NRC FORM 366 (5~92)									U.S. NU	CLEAR RE	GULA	TORY	COMMISS	NON			AP	PRO	VED OM	B NO.	3150	0-010	04			
and and a			*																EXPIR	ES 5/	31/95	1				
		LIC	CEN	SE	EE I	EV	ENT F	REP	ORT	(LER)						INFORM COMME AND RE REGULI AND TO	TED BUR IATION CO NTS REG PORTS M ATORY CO THE PAP OF MANA	OLLE ARDI ANAC OMMI PERW	CTION I ING BUF GEMENT ISSION, IORK RE	REOU DEN T BRA WASH DUCT	EST ESTIN NCH HINGT	50.0 MAT (MN TON PRO	HOUF E TO T BB 771 DC 20 JECT	B FC HE R 4), U 555- (3150	RWAI ECOR .S. NU 0001, -0104	RD DS ICLEAR
FACILITY NAME	(1)				No. of Concession, Name	-						-	and the second second second					-			-			-	-	
Treater treater	1.9	CB	VST	14	R	VE	R UNIT	- 9	(CP. 3								1.1		TNUMB					-	1	E (3)
TITLE (4)		UT	101	nr.	14	V [_]	n unin	0	(011-0	/		-				and a state of the state of the	0	0	0	0	0 3	3	0 2	11	OF	8 0
Co	onsid	dera	tion	of I	nstr	um	ent Err	or F	lesults	in Unac	cept	table	Margin	for HF	PI FI	ow in §	BLOC	A Ar	nalysis	S						
EVENT DATE	(5)				L	ERI	NUMBER (6)		RE	PORT	DATE	(7)				o	THER	FACILIT	IES I	VOL	VED	(8)	-		
	T					SEC	QUENTIAL		REVISIO	11					FAC	ILITY NA	MES			1	DOCK	ETI	UMBE	R(S)		
MONTH DAY	Y	EAR	YE	AR		N	UMBER	ļ	NUMBE	R MONT	H D	YAY	YEAR		N/A				-		D	5	0 0	0		1
		1	21				1.1.		1.1	1.1.												i.		9	11	č.
0 1 3 0	9	6	9	6		0	1-1-		00	-	1.00	9	9 6		N/A			-		-	0 6	5	0 0	0	1	
OPERATING MODE (9)		1	THIS	REF	PORT	IS S	BUBMITTE	DPU	RSUANT	TO THE P	EQUI	REME	NTS OF 10	CFR 5:	ICHI	ECK ONE C	RMOREO	FTHE	FOLLOW	(ING)	(1	1)				
		1		20	402(1	b)			-	20.40	5(c)				50.	.73(a)(2)(i	()			-	- 1	73.7	1(b)			
POWER				20	405(a	a)(1)	(i)			50.36	(0)(1)			X	50.	73(a)(2)(v)				1	73.7	1(c)			
(10) 1	10	10		20	405(a)(1)	(ii)			50.36	(c)(2)				50	73(a)(2)(v	(ii)						ER (sp			
				20	405(a)(1)	((iii)			60.73	(a)(2)(i)			60.	73(a)(2)((iii)(A)					belo 366	w and it Aj	Tent.	NRC F	1/10
				20	405(1	a)(1)	(iv)		-	60.73	(a)(2)(i	ŋ.			50	73(a)(2)(v	(iii)(B)									
					405(-	-	(a)(2)(i					73(a)(2)()										
	an ann an tai taina.												T FOR TH	IS LER (1						_	-	-		rant en toin		-
NAME					-													L			ELEP	HON	E NUN	BER		
						T)	W Cato	hpr	ie Sr	Nuclea	r Lice	ensir	ng Engir	heer				AR	REA COL	DE						
							m. osno	nips	no, or.	NUCION	i la nor	onan	ig Engi	1001				3	5 5	2	5 €	B	3 -	1 4	6	0 1
							COMPLE	TE	ONE LINE	FOR EAC	H CON	PONE	INT FAILU	RE IN TH	IS RE	PORT (1	3)	and the second se								
CAUSE SYSTEM	M	OMP	ONEN	r			NUFAC- URER	1.000	PORTABL NPRDS	E			CAU	SE SYS	TEM	COM	PONENT		MANU		1.52		RTABL	E		
		í.	[].[1.1								1		11		Ľ.	1						
							1.1.			-							1 1		1 1							
	-	+					SUPPLE	MEN	TAL REP	ORT EXPE	CTED	(14)			L		+	+	EXPE	CTED	-	1	NONTH		AY	YEAR
						-						(14)			-			-	SUBM		IN	-	acourt.	+		TRAM
YES (#)							ON DATE)			and the second se	N	0							DATE	(15)			11		1.	11
1	3)	wa	s i	n	M			(P	OWER	OPER W).	ATI	ON)	porat , op g a re	erati eview	ing	at	100%	6 r	react	tor	p	OW	er erge	ani	t v	

	U.S. NUCL ENSEE EVENT REPORT (L CT CONTINUATION	LEAR REGULATORY COMMISSION	INF CO AN RE AN	ORM/ MMEN D REP GULA	ATION VTS F ORT TORY THE P	BURD N COL S MAI COM PAPE	EN PE LECT RDING NAGEI IMISS RWOR	D OMB I EXPIRES TON RE BURDI MENT E HON, W & REDI VT AND	S 5/31 PONS QUE EN EL SRAN ASHII JCTK	1/95 ETO ST: 50 STIM/ CH (N NGTO ON PF	COM 0.0 HO INBB INBB IN, DO ROJEC	0 THE 7714) 2058	FOR E REC U.S 55-000	WARE ORD: NUC 1, 104).	D S LEAI	
FACILITY NAME (1)		DOCKET NUMBER (2)		1		U	R NU	MBER ((6)				1	AGE	(3)	-
CRYSTAL	RIVER UNIT 3 (CR-3)			Y	EAR		NUM			REVI						
		0 5 0 0 0 3	0 2	9	6	-	0	0 6		0	0	0	2 1	OF	0	8

TEXT (If more apace is required. Use additional NRC Form 366A's (17)

EVENT DESCRIPTION

On January 30, 1996, Florida Power Corporation's Crystal River Unit 3 (CR-3) was in MODE 1 (POWER OPERATION), operating at 100% reactor power and generating 876 megawatts (MW). During a review of Emergency Operating Procedure (EOP) setpoints, engineering personnel determined that application of worst case instrument error to the High Pressure Injection [BQ] (HPI) instrumentation may result in establishing inadequate HPI flow to the reactor core when complying with EOP guidance for preventing HPI pump [BQ,P] runout. The review of EOP related setpoints is part of an overall EOP Enhancement Program designed to ensure EOP steps have a well-defined technical basis.

EOP guidance requires HPI flow to be maintained less than 540 gallons per minute (gpm) per running HPI pump to prevent pump runout. Total instrument error associated with the HPI flow instrumentation could be 36 gpm less than indicated and 30 gpm greater than indicated, such that, with a flow indication of 540 gpm. actual flow could be 570 gpm or 504 gpm. The design basis for HPI pump runout is 575 gpm, which will not be obtained given the existing EOP guidance. The 504 gpm flow rate is less than the 509 gpm specified in the Small Break Loss-of-Coolant Accident (SBLOCA) analysis for Reactor Coolant System [AB] (RCS) pressure less than 200 pounds per square inch absolute (psia). After further investigation, it was determined that the SBLOCA analysis used a RATED THERMAL POWER (RTP) of 2568 MW thermal. Since design RTP for CR-3 is 2544 MW thermal, the lower RTP level requires proportionally less HPI flow to satisfy the SBLOCA analysis. In order to assure 504 gpm is delivered to the core, Reactor Coolant Pump [AB, P] (RCP) seal injection must be isolated early in the SBLOCA event. HPI flow cannot be increased without challenging the design basis HPI pump runout limit of 575 gpm. Due to a previous problem related to seal injection instrument error and qualification, RCP seal injection is required to be closed when establishing full HPI. Prior to the existence of this guidance, RCP seal injection was not isolated while mitigating LOCA's.

This report is being submitted in accordance with 10CFR50.73(a)(2)(v)(D) as a condition that alone could have prevented mitigating the consequences of an accident, in that when RCP seal injection was not previously isolated during the assumed SBLOCA, the analytical results were unacceptable.

EVENT EVALUATION

During normal reactor operation, the Makeup and Purification System [CB] (MU) recirculates reactor coolant for purification and soluble poison management, provides makeup water for normal Reactor Coolant System [AB](RCS) leakage, and provides RCP seal injection. The HPI function of the MU system provides emergency core cooling during SBLOCA's. HPI actuates when RCS pressure decreases below 1500 pounds per square inch gauge (psig) or when containment [NH] pressure

NRC FORM 366A (5-92)	U.S. NUCL	EAR REGULATORY COMMISSION			AP	PROVED OMB I			n de California de La California de La California de California de California de California de California de Ca
	LICENSEE EVENT REPORT (L TEXT CONTINUATION	ER)	INF COL ANI RE(ANI	ORMAT MMENT D REPO BULATO D TO TH	TON CO S REG RTS M DRY CO IE PAP	DEN PER RESP DILECTION RE ARDING BURDE ANAGEMENT B MMISSION, W ERWORK REDU	PONS QUES EN ES IRANI ASHIN JCTIC	E TO COM ST 50.0 HO STIMATE TO CH (MNBB NGTON, DO ON PROJECT	
FACILITY NAME (1)		DOCKET NUMBER (2)			1	LER NUMBER (6)		PAGE (3)
CRYS	STAL RIVER UNIT 3 (CR-3)			YEA	R	SEQUENTIAL NUMBER		REVISION NUMBER	
1. 1. 1. 1. 1.		0 5 0 0 0 3	0 2	9	6	01016		0 0	0 3 OF 0 8

TEXT (If more space is required, Use additional NRC Form 366A # (17)

reaches 4 psig. When HPI actuates, two HPI pumps start with suction aligned to the Borated Water Storage Tank [BP,TK] (BWST) and discharges into the RCS cold leg piping between the RCP's and the reactor vessel [RPV]. Control valves [BQ,FCV] in each of the four HPI lines are used to provide balancing, throttling and isolation in accordance with EOP guidance.

Certain SBLOCA's result in depressurizing the RCS to the point where throttling HPI flow becomes necessary to growent HPI pump runout from occurring. Per the existing Cold Leg Pump Discharge LOCA (CLPD SBLOCA) analysis, 509 gpm of HPI flow is required to be directed to the four HPI nozzles within 10 minutes after Engineered Safeguards (ES) actuation. As noted above, a required HPI flow rate of 504 gpm has been justified based on a proportional decrease in RTP.

Guidance, via Short Term Instruction (STI) was established on November 10, 1995 to isolate RCP seal injection when full HPI is required. This was an immediate corrective action to preclude using an ungualified instrument to prevent HPI pump runout. The effect of seal injection isolation was evaluated by the system engineer who noted the vendor (BW/IP International) instruction manual states the pump and seal cartridge are designed to operate continuously without seal injection flow as long as normal cooling water flow is maintained. In addition, isolating seal injection flow also isolates High Pressure Auxiliary Spray. This line provides an alternate method used to cool down the Pressurizer [AB, PZR] during normal cooldown operations and is not required to mitigate any accidents. With the application of the STI, EOP guidance to throttle HPI flow would now only use the HPI flow instrumentation to determine total HPI pump flow. This also provided assurance that the EOP guidance for throttling HPI to a value of 540 gpm would remain within the instrument error analysis. Licensee Event Report (LER) 95-026-00 was submitted to address this situation.

The STI from November 10, 1995 was still in effect when it was discovered throttling HPI to prevent HPI pump runout could also challenge the limiting SBLOCA analysis by applying instrumed error on the low end. Therefore, operators would isolate RCP seal in ion when full HPI was required, thus assuring all HPI flow would be inject into the RCS at the RCS cold legs. By applying the actual CR-3 licensed RTP level to the SBLOCA analysis and taking credit for the early isolation of RCP seal injection, the minimum flow requirement of 504 gpm can be met.

An operability assessment was initiated on February 6, 1996 in accordance with Compliance Procedure CP-150, "Identifying and Processing Operability Concerns." This procedure provides a structured approach toward determining the operability of plant components required for accident mitigation and safe shutdown of the plant and provides guidelines to ensure no loss of plant system or component safety function. The operability assessment was determined necessary because of concerns identified regarding the ability to close the seal injection flow path within the assumed 10 minutes of the accident.

NRC FORM 366A (6-92)	U.S. NUCLE LICENSEE EVENT REPORT (LI TEXT CONTINUATION	EAR REGULATORY COMMISSION	INI CC AN RE AN	FORMATIO DMMENTS ND REPORT EGULATOR ND TO THE	BURGA IN CO REGA IS MA Y CO PAPE	LLECTION RE ARDING BURDE NAGEMENT B MMISSION, W/ ERWORK REDU	ONS QUE EN ES RAN ASHII JCTK	195 IE TO COM ST: 50.0 HC STIMATE T CH (MNBB NGTON, DO ON PROJEC	IPLY WITH THIS JURS, FORWARD O THE RECORDS 7714), U.S. NUCLEAR 20585–0001, 17 (3150–0104), 4INGTON DC 20503.
FACILITY NAME (1)		DOCKET NUMBER (2)			L	ER NUMBER (6)	Cartocured a Partie south	PAGE (3)
CRY	STAL RIVER UNIT 3 (CR-3)			YEAR		SEQUENTIAL NUMBER		REVISION NUMBER	
		0 5 0 0 0 3	0 2	9 6		0 0 0 6		0 0	0 4 OF 0 8

TEXT (If more space is required. Use additional NRC Form 366A's (17)

Refer to Figure 1. Seal injection can be isolated by closing MUV-18 [BQ,V] or MUV-16 [BQ,FCV]. MUV-18 is powered from ES Motor Control Center [MCC] ES MCC 3AB and MUV-16 is an air operated flow control valve supplied by the Instrument Air System [LD] (IA). In the event of a SBLOCA concurrent with a Loss of Offsite Power (LOOP) and failure of one Emergency Diesel Generator [EK,DG] (EDG), MUV-18 could only be closed if powered from the operable diesel generator. If not powered from the operable EDG, ES MCC 3AB would need to be transferred to the operable ES 4160 Volt bus by depressing the manual transfer on the Main Control Board [MCBD] (MCB) electrical panel. MUV-16 could also be closed provided instrument air is available. During a total LOOP, instrument air would slowly diminish.

The frequency of a SBLOCA concurrent with a LOOP and a failure of one diesel generator, is 1.4E-08 per year; therefore, the problem of potentially having to switch power sources to ES MCC 3AB to effect closure of MUV-18 in this situation is relatively low.

Regarding MUV-16, although the IA system is non-safety related and not diesel backed, pressure in the instrument air header should be available when isolation of RCP seal injection is required. Engineering personnel reached this conclusion by considering that normal air pressure in the instrument air system is 120 psig, and since MUV-16 will operate satisfactorily down to 45 psig, the valve will continue to operate even with a significant loss in header pressure. Also considered was the fact that the IA system is indirectly tested on a quarterly basis. During this quarterly test, any rapid reduction of IA header pressure would be noted by operator/technicians and appropriate actions would be taken to restore system integrity.

CAUSE

The primary cause of this event was inadequate incorporation of design assumptions and appropriate flow instrument error in the EOP program. The EOP Enhancement Program was established because of recognized weaknesses in EOP setpoints. Instrument error has not been consistently applied to EOP setpoint values resulting in various discrepancies. The EOP Enhancement Team discovered the conditions associated with this event while reviewing the results of a revised calculation for Makeup/HPI Flow Loop Accuracy which was issued December 7, 1996. The revised calculation included a modified methodology for determining instrument errors.

IMMEDIATE CORRECTIVE ACTION

Framatome Technologies, Inc. was requested to evaluate the effect of instrument error on the SBLOCA analysis. Their evaluation supported a proportionally

NRC FORM 386A (6-92)	U.S. NUCLEA LICENSEE EVENT REPORT (LE TEXT CONTINUATION	R REGULATORY COMMISSION	AND REG AND	DRIMATIC IMENTS REPOR ULATOR TO THE	BURE DN CO REGA TS MA TS MA CO PAPE	LLECTION RE NOT BURDING BURDINAGEMENT E MMISSION, W RWORK REDI	B 5/31 PONS QUES EN ES BRANS ASHIN JCTIC	/96 E TO COM ST: 60.0 HC STIMATE TI CH (MNBB NGTON, DC ON PROJEC	IPLY WITH THIS JURS. FORWARD O THE RECORDS 7714), U.S. NUCLEAR 2 20555-0001, 77 (3150-0104), 11 (3150-0104), 11 (3150-0104),
FACILITY NAME (1)		DOCKET NUMBER (2)			L	ER NUMBER (6)	and a reason of the second second	PAGE (3)
CRYS	TAL RIVER UNIT 3 (CR-3)			YEAF		SEQUENTIAL NUMBER		REVISION NUMBER	
		0 5 0 0 0 3 0	2	9 6		0 0 0 8		00	0 5 OF 0 8

TEXT (Il more space is required. Use additional HRC Form 366A a (17)

reduced flow requirement based on the ratio of differences between the RTP assumed in the accident analysis and CR-3's licensed RTP.

Short Term Instruction 95-0061 was issued on November 10, 1995 to isolate RCP seal injection when full HPI is required and had an expiration date of February 6, 1996. STI 96-0008 was issued on February 6, 1996 to replace STI 95-0061 to ensure seal injection remains isolated when full HPI is required, pending a CLPD SBLOCA reanalysis to possibly justify lower HPI flows during the CLPD SBLOCA. The STI assures the HPI pump will not be in a runout condition following isolation of seal injection. With seal injection isolated, the EOP setpoint of 540 gpm can remain in the procedure thereby assuring adequate core cooling for the CLPD SBLOCA (504 gpm).

ADDITIONAL CORRECTIVE ACTION

Note: Items 1 through 3, below, are scheduled for completion prior to April 1, 1996. Item 4 has a scheduled completion date of September 17, 1996.

- 1. Determine if HPI pump runout conditions can be achieved with the existing CR-3 Emergency Core Cooling System (ECCS) configurations. This will be accomplished by re-running the computer model in the MU System Hydraulic Analysis for zero RCS pressure.
- 2. A revised CLPD SBLOCA analysis is currently being performed by Framatome Technologies (formerly B&W Nuclear Technologies) to justify a lower required HPI flow rate at reduced RCS pressures to provide additional flow margin in the MU system.
- 3. Based on results of items 1 and 2, the need for revision of EOP's will be determined if it is necessary to direct operators to isolate RCP seal injection.
- 4. If RCP seal injection must be isolated, then plant modifications will be evaluated to determine if automatic RCP seal injection isolation is appropriate to reduce operator burden.

ACTION TO PREVENT RECURRENCE

The EOP Enhancement Program will continue its ongoing effort of actively validating setpoints and steps contained in the EOP's by providing sound engineering bases. In addition, an Analysis/Calculation group is dedicated to the evaluation of instrument string errors. These two efforts will continue to be coordinated.

NFC FORM 306A (5-92)	LICENSEE EVENT REPORT (LE TEXT CONTINUATION	ER)	OFY	CON	MMUS	SION				TIMA FORM MME D REI GULA D TO FICE	ATIO NTS I PORT TOR THE	BURE N CO REGA S MA Y CO PAPE	DEN P LLEC RDIN NAGI MMIS	EXPI ER R TION G BU EMEN SION RK R	RES REC REC IF DE IT BI WA EDU	5/31 DNS UES NES TANC SHIN CTIO	195 E TO ST: 50 STIMA CH (M 4GTO N PR	COM 0 HO TE T NBB N. DO	0URS 0 TH 7714) 205 21 (3	E FIE), U. 55-0	RWA COR 5. NI 001, 0104	RD DS DCLE	
FACILITY NAME (1)		DOC	KET N	UM	BER	(2)		8	-	T		L	ERN	UMBE	ER (6)					PAG	E (3)	
CRYS	TAL RIVER UNIT 3 (CR-3)									Y	EAR			MBER	4		REVI						
		0	5	0	0	0	3	0	2	9	6		0	0	6		0	0	0	6	OF	0	8

TEXT (If more space is required, Use additional NRC Form 366A's (17)

PREVIOUS SIMILAR EVENTS

There have been two similar events involving HPI Pumps and flow instrumentation. LER 89-37 reported instrumentation accuracy inadequacies to perform flow balancing during an HPI Line Break. LER 95-26 reported use of non-Regulatory Guide 1.97 instrumentation for measuring RCP Seal Injection flow.

ATTACHMENTS

Attachment 1 - Abbreviations, Definitions and Acronyms Figure 1 - Makeup & Purification/HPI System (simplified) NEC FORM 366A

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES 5/31/95

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HOURS, FORWARD COMMENT3 REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON DC 20503.

CRYSTAL RIVER UNIT 3 (CR-3)	FACILIT	Y NAME (1)	000	CKE	TNU	MBER	(2)				T	managona	1	ERN	UMB	ER (8)			-	-	PAG	E (3)	-
		CRYSTAL RIVER UNIT 3 (CR-3)									VE	EAR								1		_		
0 5 0 0 0 3 0 2 9 6 0 0 6 0 0 7 OF			0	5	0	0	0	3	0	2	9	6		0	0	6	-	0	0	0	17	OF	0	8

SKT (If more apace is required. Use additional NRC Form 366A a (17)

ATTACHMENT 1 - ABBREVIATIONS, DEFINITIONS AND ACRONYMS

CR-3 Crystal R	iver	Unit	3
----------------	------	------	---

ECCS Emergency Core Cooling Systems

EOP Emergency Operating Procedure

FPC Florida Power Corporation

HPI High Pressure Injection

LOOP Loss of Offsite Power

MODE ONE POWER OPERATION (Greater Than 5 Percent Rated Thermal Power)

MCC Motor Control Center

MU Makeup and Purification System

Runout Operation of a pump beyond its design capacity; indicated by a decrease in discharge head and excessive power consumption.

SBLOCA Small Break Loss-of-Coolant Accident

STI Short-Term Instructions are part of the Shift Order program which provides a means for operations management to communicate short-term information and administrative instructions to shift personnel.

NOTES: ITS defined terms appear capitalized in LER text {e.g. MODE ONE}

Defined terms/acronyms/abbreviations appear in parentheses when first used {e.g. Reactor Building (RB) }.

EIIS codes appear in square brackets {e.g. Makeup Tank [CB,TK] }

