

AVERAGE DAILY UNIT POWER LEVEL

Docket No. 50-272
 Unit Name Salem # 1
 Date Feb. 10, 1985
 Telephone 609-935-6000
 Extension 4455

Completed by J. P. Ronafalvy

Month January 1985

Day Average Daily Power Level
(MWe-NET)

Day Average Daily Power Level
(MWe-NET)

1	<u>7</u>	17	<u>1105</u>
2	<u>838</u>	18	<u>1080</u>
3	<u>1088</u>	19	<u>1096</u>
4	<u>1100</u>	20	<u>1102</u>
5	<u>1086</u>	21	<u>1093</u>
6	<u>1047</u>	22	<u>1087</u>
7	<u>1101</u>	23	<u>1110</u>
8	<u>1104</u>	24	<u>1112</u>
9	<u>1075</u>	25	<u>1110</u>
10	<u>1052</u>	26	<u>1098</u>
11	<u>1097</u>	27	<u>1094</u>
12	<u>1110</u>	28	<u>1110</u>
13	<u>1092</u>	29	<u>1108</u>
14	<u>1102</u>	30	<u>1110</u>
15	<u>1103</u>	31	<u>1104</u>
16	<u>1099</u>		

P. 8,1-7 R1

8502150581 850131
 PDR ADOCK 05000272
 R PDR

IE24
 1/1

OPERATING DATA REPORT

Docket No. 50-272
 Date Feb. 10, 1985
 Telephone 935-6000
 Extension 4455

Completed by J. P. Ronafalvy

Operating Status

1. Unit Name	<u>Salem No. 1</u>	<u>Notes</u>
2. Reporting Period	<u>January 1985</u>	
3. Licensed Thermal Power (MWt)	<u>3338</u>	
4. Nameplate Rating (Gross MWe)	<u>1170*</u>	
5. Design Electrical Rating (Net MWe)	<u>1090</u>	
6. Maximum Dependable Capacity (Gross MWe)	<u>1124</u>	
7. Maximum Dependable Capacity (Net MWe)	<u>1079</u>	
8. If Changes Occur in Capacity Ratings (items 3 through 7) since Last Report, Give Reason * <u>Previous value reported was the turbine rating, not the generator rating as required.</u>		

9. Power Level to Which Restricted, if any (Net MWe) N/A

10. Reasons for Restrictions, if any N/A

	<u>This Month</u>	<u>Year to Date</u>	<u>Cumulative</u>
11. Hours in Reporting Period	<u>744</u>	<u>744</u>	<u>66553</u>
12. No. of Hrs. Reactor was Critical	<u>726.6</u>	<u>726.6</u>	<u>36559.1</u>
13. Reactor Reserve Shutdown Hrs.	<u>0</u>	<u>0</u>	<u>3088.4</u>
14. Hours Generator On-Line	<u>723.7</u>	<u>723.7</u>	<u>34882.3</u>
15. Unit Reserve Shutdown Hours	<u>0</u>	<u>0</u>	<u>0</u>
16. Gross Thermal Energy Generated (MWH)	<u>2382022</u>	<u>2382022</u>	<u>105150019</u>
17. Gross Elec. Energy Generated (MWH)	<u>815390</u>	<u>815390</u>	<u>34731440</u>
18. Net Elec. Energy Generated (MWH)	<u>782864</u>	<u>782864</u>	<u>32880846</u>
19. Unit Service Factor	<u>97.3</u>	<u>97.3</u>	<u>52.4</u>
20. Unit Availability Factor	<u>97.3</u>	<u>97.3</u>	<u>52.4</u>
21. Unit Capacity Factor (using MDC Net)	<u>97.5</u>	<u>97.5</u>	<u>45.8</u>
22. Unit Capacity Factor (using DER Net)	<u>96.5</u>	<u>96.5</u>	<u>45.3</u>
23. Unit Forced Outage Rate	<u>2.7</u>	<u>2.7</u>	<u>32.8</u>
24. Shutdowns scheduled over next 6 months (type, date and duration of each)			

N/A

25. If shutdown at end of Report Period, Estimated Date of Startup:

N/A

26. Units in Test Status (Prior to Commercial Operation):

	<u>Forecast</u>	<u>Achieved</u>
Initial Criticality	<u>9/30/76</u>	<u>12/11/76</u>
Initial Electricity	<u>11/1/76</u>	<u>12/25/76</u>
Commercial Operation	<u>12/20/76</u>	<u>6/30/77</u>

UNIT SHUTDOWN AND POWER REDUCTIONS
 REPORT MONTH January 1985

Docket No. 50-272
 Unit Name Salem No.1
 Date Feb. 10, 1985
 Telephone 609-935-6000
 Extension 4455

Completed by J.P. Ronafalvy

No.	Date	Type 1	Duration Hours	Reason 2	Method of Shutting Down Reactor	License Event Report	System Code 4	Component Code 5	Cause and Corrective Action to Prevent Recurrence
85-010	1-01	F	20.3	A	3	-	HH	VALVEX	Feedwater Regulating Boiler Level Control Valve

1
 F: Forced
 S: Scheduled

2 Reason
 A-Equipment Failure-explain
 B-Maintenance or Test
 C-Refueling
 D-Regulatory Restriction
 E-Operator Training & Licensing Exam
 F-Administrative
 G-Operational Error-explain
 H-Other-explain

3 Method
 1-Manual
 2-Manual Scram.
 3-Automatic Scram.
 4-Continuation of
 Previous Outage
 5-Load Reduction
 9-Other

4 Exhibit G
 Instructions
 for Prepara-
 tion of Data
 Entry Sheets
 for Licensee
 Event Report
 (LER) File
 (NUREG 0161)

5 Exhibit 1
 Salem as
 Source

MAJOR PLANT MODIFICATIONS
REPORT MONTH January 1985

DOCKET NO.: 50-272
UNIT NAME: Salem 1
DATE: February 10, 1985
COMPLETED BY: J. Ronafalvy
TELEPHONE: 609/339-4455

*DCR NO.	PRINCIPLE SYSTEM	SUBJECT
1EC-1417	Over/Under Voltage Check	Remove over/under voltage check restrictions on breaker 11X, 21X, and 31X closing/reclosing control.
1EC-1747	Hydrogen & Seal Oil	Add liquid level sensor with alarm to indicate high water level in moisture separator located in discharge from loop seal drain vapor extractor.
1ET-1940	4KV Power System	Test the 4KV U.V. transfer scheme on the 1B Vital Bus.
1EC-1990	Auxiliary Feedwater	Change relay setting for #11 and #12 Aux. Feed Pump motors.
1SC-0419	Service Water	Revise motor service water cooling piping to the service water pump motor coolers which will allow quick removal and restoration of piping hangers and associated piping during motor change out.
1SC-1341	Service Water Structure	Replace the ladders located between the Service Water Pump inlets and rotating screens. New ladders should be made of non-corrosive material.

MAJOR PLANT MODIFICATIONS
REPORT MONTH JANUARY 1985

DOCKET NO.: 50-272
UNIT NAME: Salem 1
DATE: February 10, 1985
COMPLETED BY: J. Ronafalvy
TELEPHONE: 609/339-4455

*DCR NO. SAFETY EVALUATION 10 CFR 50.59

- 1EC-1417 The temporary jumpers across the overvoltage relay contacts on the 500 KV line do not affect the performance of any safety related equipment. No unreviewed safety or environmental questions are involved.
- 1EC-1747 The addition of a level detector on the moisture separator located in the discharge from the loop seal drain vapor extrator of the Hydrogen Seal Oil System will not affect the function or operation of the system or any safety related equipment. No unreviewed safety or environmental questions are involved.
- 1ET-1940 This DCR is only a test of the 4160 Vital Bus U. V. transfer scheme in order to obtain necessary data for the protective relay evaluation. No unreviewed safety or environmental questions are involved.
- 1EC-1990 This DCR only involves a relay setpoint change. No unreviewed safety or environmental questions are involved.
- 1SC-0419 No basic arrangement, function or operating component has been changed per this DCR. Only the cooling water hard piping to the pump motor coolers has been modified to allow for easier change-out of the pump motors. The flex hose used is supplied in accordance with quality assurance requirements of 10CFR50, including seismic testing. No unreviewed safety or environmental questions are involved.
- 1SC-1341 This DCR replaces carbon steel ladders with stainless steel ladders. Failure of the anchorage units or the ladder assemblies will not affect any system associated with the safe shutdown of either reactor. No unreviewed safety or environmental questions are involved.

*DCR - Design Change Request

PSE&G SALEM GENERATING STATION
SAFETY RELATED WORK ORDER LOG

SALEM UNIT 1

WO NO	DEPT	UNIT	EQUIPMENT IDENTIFICATION
85-01-12-104-3	SMD	1	NO. 11 BORIC ACID TRANSFER PUMP
			FAILURE DESCRIPTION: BAD SEAL LEAK
			CORRECTIVE ACTION: REPLACED SEAL
0099120712	SMD	1	1CV346 (CHARGING LINE DRAIN VALVE)
			FAILURE DESCRIPTION: VALVE IS LEAKING
			CORRECTIVE ACTION: CUT DRAIN SIDE OF VALVE AND INSTALLED A PIPE CAP OVER THE LINES (PER DR #MD84-3352)
84-11-09-054-6	SMD	1	VALVE 1CV144
			FAILURE DESCRIPTION: VALVE LEAKS
			CORRECTIVE ACTION: INSTALLED NEW BONNET ASSEMBLY WITH HANDWHEEL, STEM AND GASKET
009911930-7		1	VITAL HEAT TRACE HEATER #208
			FAILURE DESCRIPTION: HEATER NOT MAINTAINING TEMPERATURE
			CORRECTIVE ACTION: REPLACED HEAT TAPE; INSULATED
85-01-059-2	SMD	1	16 SW PUMP STRAINER
			FAILURE DESCRIPTION: SHEAR PIN BROKEN
			CORRECTIVE ACTION: REPLACED SHEAR KEY AND FILTER ELEMENTS

SALEM UNIT 1

WO NO	DEPT	UNIT	EQUIPMENT IDENTIFICATION
-------	------	------	--------------------------

0099104377

SMD

1

NO. 12 B. U. GROUP - PRESSURIZER HEATERS

FAILURE DESCRIPTION: SEVEN OF THE FOURTEEN ACB'S WILL NOT RESET OR THEY TRIP OUT FREQUENTLY

CORRECTIVE ACTION: REPLACED TWO OF THE ITE CIRCUIT BREAKERS AND RESET THE OTHERS

0099104385

SMD

1

NO. 11 BAT PUMP

FAILURE DESCRIPTION: LEAKING WATER EXCESSIVELY THROUGH SEALS

CORRECTIVE ACTION: REPLACED PUMP

0099125307

SMD

1

VALVE 1VC5

FAILURE DESCRIPTION: VALVE WON'T CLOSE FROM CONTROL ROOM BEZEL

CORRECTIVE ACTION: REPLACED SOLENOID VALVE

0099124319

SIC

1

R41A

FAILURE DESCRIPTION: THE HI/LO FLOW ALARMS UP

CORRECTIVE ACTION: REPLACED THE APD PUMP

0099123746

SIC

1

1R41C

FAILURE DESCRIPTION: CHANNEL PEGGING HIGH

CORRECTIVE ACTION: INSTALLED NEW PINS IN "J" CONNECTORS FOR THE CONTROLLER AND SCALER

SALEM UNIT 1

WO NO	DEPT	UNIT	EQUIPMENT IDENTIFICATION
-------	------	------	--------------------------

84-09-12-015-1

SIC

1

MAIN STEAM LINE MONITOR

FAILURE DESCRIPTION: CHANNEL SPIKING

CORRECTIVE ACTION: REPAIRED DRAWER AND DRIED OUT THE DETECTOR
CONNECTORS, AND CABLES

84-12-30-015-7

SMD

1

104 PANEL

FAILURE DESCRIPTION: POWER LOSS TO THE ALARMS

CORRECTIVE ACTION: AUDIBLE HORN REPLACED

84-12-24-009-0

SMD

1

INCORE SYSTEM

FAILURE DESCRIPTION: DETECTORS A AND F ARE DRIFTING EXCESSIVELY

CORRECTIVE ACTION: REPLACED A AND F CABLES

0099118777

SMD

1

1RC30

FAILURE DESCRIPTION: BORIC ACID PACKING LEAK

CORRECTIVE ACTION: VALVE WAS FURMANITED

SALEM GENERATING STATION
MONTHLY OPERATING SUMMARY - UNIT NO. 1
JANUARY 1985

SALEM NO. 1

The period began with the Unit power increasing to full power. Monitoring of the Electro-Hydraulic Control (EHC) System was continuing. On 12/31/84 at 2123 hours, the Unit tripped due to No. 11 Steam Generator Steam Flow/Feed Flow mismatch combined with Steam Generator Low Level. This mismatch was a result of partial closure of No. 11 Steam Generator Feedwater Control valve 11BF19 caused by a malfunctioning solenoid. Following replacement of the solenoid, the Unit was returned to service on 1/1/85 at 2017 hours. Full power operation was achieved on 1/2/85 and continued for the remainder of the period. On 1/11/85, the additional monitoring of the Electro-Hydraulic Control (EHC) System, instituted after the reactor trips of 11/06/84 and 11/11/84, was discontinued. No abnormal readings were identified during the entire monitoring period that could have caused the two (2) reactor trips associated with the EHC System. It has been assumed that the cards replaced, after the trips, contributed to the cause of the reactor trips. No significant freeze problems have occurred during the current extreme cold weather conditions.

REFUELING INFORMATION

COMPLETED BY: J. Ronafalvy DOCKET NO.: 50-272
 UNIT NAME: Salem 1
 DATE: February 10, 1985
 TELEPHONE: 609/935-6000
 EXTENSION: 4455

Month January 1985

1. Refueling information has changed from last month:
 YES _____ NO X
2. Scheduled date for next refueling: February 22, 1986
3. Scheduled date for restart following refueling: May 4, 1986
4. A) Will Technical Specification changes or other license amendments be required?
 YES _____ NO _____
 NOT DETERMINED TO DATE 10/1/84
- B) Has the reload fuel design been reviewed by the Station Operating Review Committee?
 YES _____ NO X
 If no, when is it scheduled? January 1986
5. Scheduled date(s) for submitting proposed licensing action:
January 1986 if required
6. Important licensing considerations associated with refueling:
NONE

7. Number of Fuel Assemblies:
 A) Incore 193
 B) In Spent Fuel Storage 296
8. Present licensed spent fuel storage capacity: 1170
 Future spent fuel storage capacity: 1170
9. Date of last refueling that can be discharged to spent fuel pool assuming the present licensed capacity: September 2001



Public Service Electric and Gas Company P.O. Box E Hancocks Bridge, New Jersey 08038

Salem Generating Station

February 10, 1985

Director, Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Dear Sir:

MONTHLY OPERATING REPORT
SALEM NO. 1
DOCKET NO. 50-272

In Compliance with Section 6.9, Reporting Requirements for the Salem Technical Specifications, 10 copies of the following monthly operating reports for the month of January 1985 are being sent to you.

Average Daily Unit Power Level
Operating Data Report
Unit Shutdowns and Power Reductions
Major Plant Modification
Safety Related Work Orders
Operating Summary
Refueling Information

Sincerely yours,

J. M. Zupko, Jr.
General Manager - Salem Operations

JR:sbh

cc: Dr. Thomas E. Murley
Regional Administrator USNRC
Region I
631 Park Avenue
King of Prussia, PA 19406

Director, Office of Management
Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Enclosures
Page of
8-1-7.R4

IERA
11

The Energy People