

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Susquehanna Steam Electric Station - Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 3 8 8	PAGE (3) 1 OF 0 2
--	--------------------------------------	----------------------

TITLE (4)  
ESF Actuations.

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0 1	1 2	8 5	8 5	0 0 2	0 0	0 1	2 0	8 8 5			0 5 0 0 0
											0 5 0 0 0

OPERATING MODE (9) 1

POWER LEVEL (10) 0 8 1

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 8: (Check one or more of the following) (11)

20.402(b)	<input checked="" type="checkbox"/>	80.73(a)(2)(iv)	<input type="checkbox"/>	73.71(b)
20.406(a)(1)(i)	<input type="checkbox"/>	80.73(a)(2)(v)	<input type="checkbox"/>	73.71(c)
20.406(a)(1)(ii)	<input type="checkbox"/>	80.73(a)(2)(vii)	<input type="checkbox"/>	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
20.406(a)(1)(iii)	<input type="checkbox"/>	80.73(a)(2)(viii)(A)	<input type="checkbox"/>	
20.406(a)(1)(iv)	<input type="checkbox"/>	80.73(a)(2)(viii)(B)	<input type="checkbox"/>	
20.406(a)(1)(v)	<input type="checkbox"/>	80.73(a)(2)(ix)	<input type="checkbox"/>	

LICENSEE CONTACT FOR THIS LER (12)

NAME L.A. Kuczynski, Nuclear Plant Specialist-Level III	TELEPHONE NUMBER 7 1 7 5 4 2 1 - 3 7 5 9
--	---

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
A	*	**	**	N					

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)  NO

EXPECTED SUBMISSION DATE (15)

MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On January 12, 1985, while completing a modification to the 'B' Reactor Protection System (RPS) alternate source transformer, a non-licensed, non-utility electrician caused the RPS motor generator (M-G) set to trip when his wrench slipped and came in contact with an energized conductor. This resulted in the start of the Standby Gas Treatment System (SGTS) and Control Room Emergency Outside Air Support System (CREOASS), which are Engineered Safety Features (ESF). Also, the reactor Water Cleanup (RWCU) Pump Suction Inboard and Outboard Isolation valves shut. These valves are part of the Primary Containment Isolation System, another ESF. The electrician failed to use proper protective equipment, did not isolate the equipment being worked upon, and did not insulate the tools being used. The craft electricians received a briefing about the event. Work on the system modification was successfully completed on January 14, 1985.

- \* Reactor Protection System
- \*\* Not Applicable

8502150654 850208  
PDR ADOCK 05000388  
S PDR

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Susquehanna Steam Electric Station Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 3 8 8	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8 5	- 0 0 2	- 0 0	0 2	OF 0 2

TEXT (If more space is required, use additional NRC Form 366A's) (17)

On January 12, 1985, a non-licensed, non-utility electrician was installing an instrument ground as part of a modification to the 'B' Reactor Protection System (RPS) alternate source transformer. The wrench being used by the electrician to tighten the ground connection slipped and came in contact with an energized conductor. This caused the 'B' RPS motor-generator to trip and resulted in the following unanticipated Engineered Safety Feature (ESF) actuation:

- the Standby Gas Treatment System (SGTS) started
- the Control Room Emergency Outside Air Supply System (CREOASS) started
- the Reactor Water Cleanup System (RWCU) pumps suction inboard and outboard isolation valves closed. These valves are part of the Primary Containment Isolation System (PCIS).

The electrician failed to use proper protective equipment, did not isolate the energized conductor and did not insulate the tools being used. These were cognitive errors; he had received training on November 8, 1984, regarding proper work practices when working in energized equipment. The modification was completed after the non-utility electricians received re-training on the use of rubber goods on electrical equipment and work practices around energized equipment and apparatus in tight or close areas. A follow-up training session was held after completion of the modification using before and after pictures of the area where the event occurred. Emphasis was placed on how to protect tools and prevent personnel from coming in contact with energized equipment and the proper use of rubber goods. A Safety Memo dated February 1, 1985, was issued to the appropriate utility supervisors for their use in tailboard safety meetings.

February 8, 1985


U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION  
LICENSEE EVENT REPORT 85-002-00  
ER 100450 FILE 841-23  
PLAS- 037

---

Docket No. 50-388  
License No. NPF-22

Attached is Licensee Event Report 85-002-00. This event was determined reportable per 10CFR50.73(a)(2)(iv), in that the Unit experienced an unanticipated actuation of the Standby Gas Treatment System (SGTS) and the Control Room Emergency Outside Air Supply System (CREOASS), which are Engineered Safety Features. Also affected were two primary containment isolation valves.



H.W. Keiser  
Superintendent of Plant-Susquehanna

LAK/pjg

cc: Dr. Thomas E. Murley  
Regional Administrator, Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

Mr. R.H. Jacobs  
Senior Resident Inspector  
U.S. Nuclear Regulatory Commission  
P.O. Box 52  
Shickshinny, PA 18655

IE22  
1/1